2SSO10138	Active	716374 Tony Pullin	Certified
2SSO10138	Active	731850 david Partida	Certified
2SSO10138	Active	737110 DavidPartida	Certified
2SSO10138	Active	748515 pmcgowan	Certified
2SSO10138	Active	748923 Tony Pullin	Certified
2SSO10138	Active	749212 nelson sandoval	Certified
2SSO10138	Active	756275 nelson sandoval	Certified
2SSO10138	Active	756795 nelson sandoval	Certified
2SSO10138	Active	760434 David Partida	Certified
	Active	772989 David Partida	
2SSO10138			Certified
2SSO10138	Active	786807 john j. szabo	Certified
2SSO10138	Active	789296 tim costello	Certified
2SSO10138	Active	789570 nelson sandoval	Certified
2SSO10138	Active	791731 David Partida	Certified
2SSO10138	Active	791764 nelson sandoval	Certified
2SSO10138	Active	792290 David Partida	Certified
2SSO10138	Active	797045 nelson	Certified
2SSO10138	Active	800431 David Partida	Certified
2SSO10139	Active	650752 Tony Pullin	Certified
2SSO10139	Active	650756 Tony Pullin	Certified
2SSO10139	Active	715186 Tony Pullin	Certified
2SSO10139	Active	715187 Tony Pullin	Certified
2SSO10139	Active	715592 Tony Pullin	Certified
2SSO10139	Active	716220 Tony Pullin	Certified
2SSO10139	Active	716995 Tony Pullin	Certified
2SSO10139	Active	718501 Tony Pullin	Certified
2SSO10139	Active	728739 Tony Pullin	Certified
2SSO10139	Active	728740 Tony Pullin	Certified
2SSO10139	Active	731858 nelson sandoval	Certified
2SSO10139	Active	736599 Nelson Sandoval	Certified
2SSO10139	Active	738356 nelson	Certified
2SSO10139	Active	742211 nelson	Certified
2SSO10139	Active	743162 nelson	Certified
2SSO10139	Active	745372 nelson	Certified
2SSO10139	Active	746099 nelson	Certified
2SSO10139	Active	746643 nelson	Certified
2SSO10139	Active	747441 nelson	Certified
2SSO10139	Active	747866 nelson	Certified
2SSO10139	Active	748016 David Partida	Certified
2SSO10139	Active	748410 DavidPartida	Certified
2SSO10139	Active	749125 Pat McGowan	Certified
2SSO10139	Active	751008 Tony Pullin	Certified
2SSO10139	Active	755991 David Partida	Certified
2SSO10139	Active	756274 nelson sandoval	Certified
2SSO10139	Active	759999 nelson sandoval	Certified
2SSO10139 2SSO10139	Active	760368 David Partida	Certified
2SSO10139 2SSO10139	Active	761335 nelson sandoval	Certified
2SSO10139	Active	766170 nelson sandoval	Certified
288010139	Active	766171 nelson sandoval	Certified
2SSO10139	Active	766857 David Partida	Certified
2SSO10139	Active	770038 nelson sandoval	Certified
2SSO10139	Active	771701 nelson sandoval	Certified
2SSO10139	Active	772135 nelson sandoval	Certified
2SSO10139	Active	773019 john j. szabo	Certified
2SSO10139	Active	774252 Nelson Sandoval	Certified

Supervisor

Collection Worker

collection worker

collections

Technical Services Supervisor

collection

collection s

collections

Collection Worker

Collection Maintenance Worker

collections III

operator

collections

Collection Worker

collections

Collection Worker

collections

Collection Worker

Technical Services Supervisor

Technical Services Supervisor

Supervisor

Technical Services Supervisor

Supervisor

Technical Services Supervisor

collection

Collections Worker

collections

collections

collections

collections

collections

collections

collections

collections

Collection maintenance 2

Maintenance

Lead Collectins Worker

Technical Services Supervisor

Collection Worker

collections

collections

Collection worker

collections

collections

collections

Collection Worker

collections

collection

collection

collection worker III

Collections Worker

	20:40	158152
SAM		421185
4:30pm		651877
sam	47.40	571774
	17:48	741031
sam		616914
sam		243387
sam		214020
14:40 SAM		403394
SAM 14:15	740	745114
	743	621062
@0:00 04/00/40	150	526336
sam @8:29am 01/02/13		961920
SAM 11:52		654127
sam @8:48 am		899937
SAM 14:16		860533 588348
sam@1:40 pm SAM 10:33		658105
Sewer Authority Mid-Coastside		521643 758797
Sewer Authority Mid-Coastside	10:00	965399
	16:08	237337
	16:26	435190
	13:46	738728
	15:10	542543
	13:54	940148
	19:20	168405
	17:50	245792
sam	17.50	202939
Juli	10:15	252637
	12/8/2009	353349
	12/8/2009	877667
	12/8/2009	358453
	12/8/2009	289320
	12/8/2009	331726
12/08/2009		556770
1115p		274368
sam		720982
1:24pm		701771
10:00am		334432
	14:07	533145
	8:05	827167
	13:22	203015
sam		938050
sam		329878
16:50 SAM		460162
sam		899292
sam		910376
sam		521123
SAM 14:02		230475
sam		108296
sam		377556
sam		801047
sewer authority mid coastside		679154
	11:30 AM	616486

22-Apr-08		21-Mar-08	3/21/2008
14-Jan-09		14-Jan-09	1/14/2009
5-May-09		8-Dec-09	12/8/2009
21-Jan-10		21-Jan-10	1/21/2010
28-Jan-10		28-Jan-10	1/28/2010
9-Feb-10		9-Feb-10	2/9/2010
23-Aug-10	8/23/2010	23-Aug-10	8/23/2010
15-Sep-10	9/15/2010	15-Sep-10	9/15/2010
7-Jan-11	1/7/2011	7-Jan-11	1/7/2011
10-Nov-11	11/10/2011	10-Nov-11	11/10/2011
1-Oct-12	10/1/2012	1-Oct-12	10/2/2012
24-Dec-12	12/24/2012	24-Dec-12	12/24/2012
2-Jan-13	1/2/2013	2-Jan-13	1/2/2013
15-Feb-13	2/15/2013	15-Feb-13	2/15/2013
19-Feb-13	2/19/2013	19-Feb-13	2/19/2013
1-Mar-13	3/1/2013	1-Mar-13	3/1/2013
19-Jul-13	7/19/2013	19-Jul-13	7/19/2013
31-Oct-13	10/31/2013	31-Oct-13	10/31/2013
21-May-07		21-May-07	5/21/2007
21-May-07		21-May-07	5/21/2007
23-Mar-08		28-Mar-08	3/28/2008
23-Mar-08		4-Apr-08	4/4/2008
31-Mar-08		31-Mar-08	3/31/2008
16-Apr-08		16-Apr-08	4/16/2008
6-May-08		19-May-08	5/19/2008
30-May-08		30-May-08	5/30/2008
30-Oct-08		29-Oct-08	10/29/2008
30-Oct-08		30-Oct-08	10/30/2008
14-Jan-09		14-Jan-09	1/14/2009
21-Apr-09		21-Apr-09	4/21/2009
2-Jun-09		8-Dec-09	12/8/2009
31-Jul-09		8-Dec-09	12/8/2009
17-Aug-09		8-Dec-09	12/8/2009
5-Oct-09		8-Dec-09	12/8/2009
26-Oct-09		8-Dec-09	12/8/2009
9-Nov-09		8-Dec-09	12/8/2009
10-Dec-09		10-Dec-09	12/10/2009
23-Dec-09		23-Dec-09	12/23/2009
30-Dec-09		30-Dec-09	12/30/2009
19-Jan-10		19-Jan-10	1/19/2010
4-Feb-10		4-Feb-10	2/4/2010
26-Mar-10		26-Mar-10	3/26/2010
12-Aug-10	8/12/2010	12-Aug-10	8/12/2010
23-Aug-10	8/23/2010	23-Aug-10	8/23/2010
30-Dec-10	12/30/2010	30-Dec-10	12/30/2010
6-Jan-11	1/6/2011	6-Jan-11	1/6/2011
16-Jan-11	1/16/2011	16-Jan-11	1/16/2011
4-May-11	5/4/2011	4-May-11	5/4/2011
4-May-11	5/4/2011	4-May-11	7/20/2011
24-May-11	5/24/2011	24-May-11	5/24/2011
20-Aug-11	8/22/2011	22-Aug-11	8/22/2011
4-Oct-11	10/4/2011	4-Oct-11	10/4/2011
18-Oct-11	10/18/2011	18-Oct-11	10/18/2011
14-Nov-11	11/14/2011	14-Nov-11	11/14/2011
17-Dec-11	12/17/2011	17-Dec-11	12/17/2011
00 . 1		200	

Category 3		250	200
Category 3		10	0
Category 3		200	200
Category 3		500	500
Category 1	1	000	700
Category 3		5	5
Category 3		75	0
Category 3		5	5
Category 3		5	5
Category 3		40	20
Category 3		5	5
Category 1	1	125	0
Category 3		1	0
Category 3		25	25
Category 3		150	50
Category 3		25	0
Category 3		50	0
Category 3	400	400	350
Category 3		650	0
Category 3		50	0
Category 1		121	60
Category 1	2	2000	1990
Category 3		2	0
Category 3		10	10
Category 2	2	2000	300
Category 3		5	5
Category 3		800	0
Category 3		100	100
Category 3		5	0
Category 3		25	25
Category 3		20	20
Category 1	3	8675	200
Category 3		5	5
Category 3		5	5
Category 3		5	0
Category 3		100	0
Category 3		50	50
Category 3		80	50
Category 3		1	0
Category 3		50	50
Category 3		5	5
Category 1		175	150
Category 3		5	0
Category 3		10	10
Category 3		200	200
Category 1		500	0
Category 3		5	5
Category 3		500	400
Category 3		20	10
Category 3		25	0
Category 1		329	329
Category 3		25	25
Category 3		15	0
Category 2	3	3000	300
Category 3		625	0
			J

0 No	No
0 No	No
0 No	No
0 No	No
300 Yes	Yes
0 No	No
0 No	No
0 No	No
0 No 0 No	No No
0 No 0 No	No No
1125 Yes	No
0 No	No
No	No
No	No
61 Yes	Yes
10 Yes	Yes
0 No	No
0 No	No
0 No	No
0 No 0 No	No No
0 No	No
3475 Yes	Yes
0 No	No
0 No 25 Yes	No
0 No	Yes No
0 No	No
0 No	No
500 Yes	Yes
0 No	No
1 Yes	Yes
0 No	No

No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Pullman & Washington Ave

212 Dolores

315 columbus

corner of Isabella & Elgranda Blvd

431 The Alemeda

173 Del Monte Road

523 el granada blvd

263 Yale Avenue

557 Isabella ave

838 Ferdinand ave

260 balboa ave., el granada, ca. 94019

West Point and Stanford Ave.

columbus

Corner of Columbus st and Portola Ave

35 valencia st

523 Balboa ave

san pablo lift station in el granada

San Pablo Ave

542 Metzgar Street

533 Grove Street

Ocean and Valdez

Main Street at Hwy 92

407 Casa Del Mar

542 Metzgar

623 Grove Street

750 3rd Avenue

641 Highland Avenue

11th hole, HMB Golf Links

16 hole on golf course

411 bayhill road

Lutheran Church

Ocean Colony LS

253 myrtle st

413 Granelli

turnberry

pilarcitos ave

golf course hole #16 half moon bay

golf course #16 half moon bay

Golf Course between 15th and 16th hole

Golf course 16th hole

111 main st

196 Main Street

751 First Ave

217 miramontes ave

444 oak avenue

401 Greenbrier rd

casa de mar

416 grove

600 grove st

Corner of Stone pine rd and Main st

901 alsace lorraine


307 church st

170 correas

Oak st

bayhill road

37.49003	-122.45211 San Mateo
37.50859	122.46933 San Mateo
37.50624	-122.47596 San Mateo
37.50658	-122.46573 San Mateo
37.50476	-122.4713 San Mateo
37.3054	-122.28006 San Mateo
37.30696	-122.27896 San Mateo
37.30311	-122.29392 San Mateo
37.50658	-122.46645 San Mateo
37.5091	-122.47312 San Mateo
37.30322	-122.2839 San Mateo
37.50338	-122.49463 San Mateo
37.30455	-122.28371 San Mateo
37.30486	-122.28122 San Mateo
37.29631	-122.27344 San Mateo
37.30427	-122.28485 San Mateo
37.29405	-122.27332 San Mateo
37.49029	-122.45539 San Mateo
37.45861	122.43305 San Mateo
37.458057	122.433334 San Mateo
37.46467	-122.44177 San Mateo
37.46729	122.42954 San Mateo
37.47695	122.44465 San Mateo
37.45549	122.43352 San Mateo
37.45565	122.43151 San Mateo
37.45864	122.43535 San Mateo
37.47468	-122.43065 San Mateo
37.43816	122.43498 San Mateo
37.43746	122.43678 San Mateo
37.43878	-122.43196 San Mateo
37.474887	-122.43986 San Mateo
37.435014	-122.442616 San Mateo
37.459	-122.43983 San Mateo
37.46009	-122.43691 San Mateo
37.26247	-122.26206 San Mateo
37.2813	-122.26175 San Mateo
37.43682	-122.43682 San Mateo
37.43767	-122.43682 San Mateo
37.43767	-122.43682 San Mateo
37.43769	-122.43682 San Mateo
37.510278	-122.508056 San Mateo
37.28095	-122.25845 San Mateo
37.45823	-122.43951 San Mateo
37.27825	-122.26474 San Mateo
37.46822	-122.43629 San Mateo
37.43539	-122.43513 San Mateo
37.43599	-122.43599 San Mateo
37.45432	-122.43654 San Mateo
37.4549	-122.43205 San Mateo
37.46673	-122.4291 San Mateo
37.2754	-122.26384 San Mateo
37.27958	-122.25848 San Mateo
37.27936	-122.26564 San Mateo
37.28092	-122.26175 San Mateo
37.46878	-122.432 San Mateo





Manhole

Other sewer system structure

Other sewer system structure

Manhole

Other sewer system structure

Manhole

Manhole

Building or structure

Gravity sewer; Manhole

Manhole

Manhole

Gravity sewer

Building or structure

Gravity sewer; Manhole

Manhole

Gravity sewer

Other (specify)

Gravity Mainline

Other (specify)

Building or structure

Manhole

Manhole

Manhole

Other sewer system structure

Other sewer system structure

Manhole

Manhole

Manhole

Force main or pressure sewer

Other sewer system structure

Other sewer system structure

Manhole

Other sewer system structure

Other sewer system structure

Other sewer system structure

Manhole

Force main or pressure sewer

Force main or pressure sewer

Other sewer system structure

Force main or pressure sewer

Other (specify)

Gravity sewer; Other sewer system structure

Other (specify)

Manhole

Manhole

Gravity sewer; Manhole

Building or structure

Building or structure

Gravity sewer; Manhole; Other sewer system structure

Gravity sewer; Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

main line was plugged so it was coming out of lateral clean out Toilet bubble up
(Lamphole)
spill happend at clean out but was a result of being lowest point area. Main line blockage. Used eyeball method to determ at lift station Spill appearance was out of a residential clean out as a result of a main line blockage caused by roots. Lateral Sewer Cleanout
from clean out
Air release valve
Air release valve Air release valve Lateral Sewer Cleanout
Property lateral line clean out
Sewer stoppage caused water to come out of the lamppole in the street

Other paved surface

Unpaved surface

Unpaved surface

Other paved surface

Beach

Unpaved surface

Unpaved surface

Building or structure

Other paved surface

Unpaved surface

Street/curb and gutter

Beach

Building or structure

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Paved Surface; Street/Curb and Gutter; Unpaved surface

Unpaved surface

Building or structure

Separate storm drain

Other paved surface; Storm drain; Street/curb and gutter; Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface; Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface; Unpaved surface

Other paved surface; Unpaved surface

Unpaved surface

Unpaved surface

Beach; Surface water

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Other paved surface

Other paved surface

Other paved surface; Unpaved surface

Other paved surface

Storm drain

Unpaved surface

Street/curb and gutter

Unpaved surface

Beach; Separate storm drain; Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Separate storm drain; Street/curb and gutter

Unpaved surface

Other paved surface

Unpaved surface

Separate storm drain



3/21/2008 19:55	3/21/2008 19:55	3/21/2008 20:35	3/21/2008 20:40
1/12/2009 8:32	1/12/2009 8:32	1/12/2009 9:00	1/12/2009 9:31
4/20/2009 9:30	4/20/2009 9:30	4/20/2009 9:30	4/20/2009 9:36
1/19/2010 3:19	1/19/2010 3:19	1/19/2010 3:30	1/19/2010 3:40
1/28/2010 10:00	1/28/2010 10:00	1/28/2010 10:05	1/28/2010 10:15
2/8/2010 10:07	2/8/2010 10:10	2/8/2010 10:20	2/8/2010 10:30
8/22/2010 7:30	8/22/2010 7:30	8/22/2010 8:05	8/22/2010 8:15
9/9/2010 4:00	9/9/2010 4:00	9/9/2010 4:00	9/9/2010 4:05
1/7/2011 9:15	1/7/2011 9:15	1/7/2011 9:30	1/7/2011 9:35
11/10/2011 9:20	11/10/2011 9:20	11/10/2011 9:35	11/10/2011 10:00
9/27/2012 17:45	9/27/2012 17:45	9/27/2012 18:10	9/27/2012 18:10
12/23/2012 22:15	12/23/2012 20:30	12/23/2012 20:30	12/23/2012 23:00
11/19/2012 17:00	11/19/2012 17:00	11/19/2012 17:30	11/19/2012 17:30
2/14/2013 14:15	2/14/2013 14:20	2/14/2013 14:23	2/14/2013 14:25
2/16/2013 17:30	2/16/2013 17:35	2/16/2013 18:20	2/16/2013 14:23
3/1/2013 10:33	3/1/2013 11:33	3/1/2013 11:42	3/1/2013 11:47
7/16/2013 8:55			
	7/16/2013 8:57	7/16/2013 9:10	7/16/2013 9:30
10/19/2013 21:30	10/19/2013 21:58	10/19/2013 22:30	10/19/2013 22:50
5/19/2007 13:00	5/19/2007 13:00	5/19/2007 13:20	5/19/2007 13:35
5/19/2007 13:00	5/19/2007 16:30	5/19/2007 17:00	5/19/2007 13:35
3/23/2008 9:00	3/23/2008 9:00	3/23/2008 9:45	3/23/2008 9:45
3/23/2008 11:06	3/23/2008 11:06	3/23/2008 11:30	3/23/2008 11:45
2/23/2008 16:30	2/23/2008 16:30	2/23/2008 16:45	2/23/2008 16:55
4/4/2008 8:41	4/4/2008 8:41	4/4/2008 9:00	4/4/2008 9:15
5/4/2008 7:40	5/4/2008 7:40	5/4/2008 8:20	5/4/2008 9:25
5/22/2008 9:12	5/22/2008 9:12	5/22/2008 9:45	5/22/2008 9:45
10/29/2008 18:10	10/29/2008 18:10	10/29/2008 18:30	10/29/2008 19:10
10/9/2008 8:10	10/9/2008 8:10	10/9/2008 8:40	10/9/2008 9:15
12/18/2008 10:19	12/18/2008 10:19	12/18/2008 10:30	12/18/2008 10:45
4/8/2009 9:46	4/8/2009 9:46	4/8/2009 10:00	4/8/2009 10:15
5/9/2009 10:48	5/9/2009 10:48	5/9/2009 11:10	5/9/2009 11:20
7/30/2009 11:04	7/30/2009 11:04	7/30/2009 11:15	7/30/2009 11:30
8/8/2009 5:17	8/8/2009 5:17	8/8/2009 5:37	8/8/2009 5:37
9/19/2009 4:45	9/19/2009 4:45	9/19/2009 5:15	9/19/2009 5:15
10/19/2009 9:56	10/19/2009 9:56	10/19/2009 10:15	10/19/2009 10:45
11/7/2009 11:30	11/7/2009 11:30	11/7/2009 11:45	11/7/2009 11:55
12/10/2009 9:35	12/10/2009 9:35	12/10/2009 9:45	12/10/2009 10:30
12/23/2009 9:40	12/23/2009 9:40	12/23/2009 9:50	12/23/2009 10:11
11/13/2009 13:30	11/13/2009 13:30	11/13/2009 13:50	11/13/2009 14:00
1/15/2010 10:06	1/15/2010 10:06	1/15/2010 10:30	1/15/2010 10:45
2/4/2010 8:58	2/4/2010 8:58	2/4/2010 9:20	2/4/2010 9:25
3/23/2010 9:18	3/23/2010 9:18	3/23/2010 9:18	3/23/2010 10:03
8/11/2010 10:26	8/11/2010 10:26	8/11/2010 11:00	8/11/2010 11:00
8/20/2010 10:33	8/20/2010 10:33	8/20/2010 10:45	8/20/2010 10:52
12/29/2010 9:04	12/29/2010 9:04	12/29/2010 9:30	12/29/2010 9:40
1/5/2011 21:00	1/5/2011 21:00	1/5/2011 21:30	1/5/2011 21:45
1/15/2011 4:47	1/15/2011 4:47	1/15/2011 5:35	1/15/2011 5:40
5/3/2011 8:41	5/3/2011 8:41	5/3/2011 9:00	5/3/2011 11:00
5/2/2011 10:30	5/2/2011 10:30	5/2/2011 10:45	5/2/2011 11:00
5/22/2011 10:18	5/22/2011 10:18	5/22/2011 10:45	5/22/2011 10:55
8/20/2011 10:00	8/20/2011 10:00	8/20/2011 10:35	8/20/2011 10:35
10/2/2011 10:20	10/2/2011 10:20	10/2/2011 11:00	10/2/2011 11:10
10/16/2011 10:45	10/16/2011 10:45	10/16/2011 11:15	10/16/2011 11:20
11/13/2011 13:15	11/13/2011 13:15	11/13/2011 14:15	11/13/2011 14:30
12/17/2011 9:30	12/17/2011 9:30	12/17/2011 10:10	12/17/2011 10:20

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Debri-Rags

Other (specify below)

Root intrusion

Root intrusion

Other (specify below)

Pipe structural problem/failure

Root intrusion

Root intrusion

Root intrusion

Debri-Rags

Pipe structural problem/failure

Root Intrusion

Grease deposition (FOG)

Grease deposition (FOG)

Debri-General

Grease deposition (FOG)

Root intrusion

Root intrusion

Pipe structural problem/failure

Debri-General

Pipe structural problem/failure

Pump station failure

Root intrusion

Root intrusion

Pipe structural problem/failure

Grease deposition (FOG)

Other (specify below)

Other (specify below)

Other (specify below)

Pipe structural problem/failure

Debri-General

Debri-General

Grease deposition (FOG)

Grease deposition (FOG)

Grease deposition (FOG)

Root intrusion

Grease deposition (FOG)

Grease deposition (FOG)

Grease deposition (FOG)

Grease deposition (FOG)

Debri-Rags

Grease deposition (FOG)

Grease deposition (FOG)

Grease deposition (FOG)

Debri-Rags

while we were flushing in the area we blew out a home owners toilet this was on a route flushing schedule.
roots coming in from pipe joint There was no evidence of an actual SSO,no paper or debris in manhole or on street etc. Only moisture around manhole a
Air release valve held partially open by small piece of debris problem in air release valve in force main
Force Main Air Relief Valve leaked Air release valve leaked, will be repaired soon.
Grease build up
Grease along with rags and debris
the plug was caused by grease built up broke plug and restored flow

Main
Main
Main
Main Main
Main
Main
Other (specify below)
Main
Upper Lateral
Main
Main
Main
Main
Gravity Mainline
Main
Main
iviali i
Main
Main
Main
Other (specify below)
Main
Other (specify below)
Other (specify below)
Main
Lower Lateral
Main
Main
Main
Lower Lateral
Main

Main



6 VCP

be safe

No 6 vcp 6 VCP

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Restored flow

Contained all or portion of spill

Contained all or portion of spill

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Contained all or portion of spill

Restored flow

Other (specify below)

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Restored flow

Cleaned-up (mitigated effects of spill);Restored flow;Returned all or portion of spill to sanitary sewer system

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;ReRestored flow

Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill); Restored flow; Returned all or portion of spill to sanitary sewer system

Contained all or portion of spill

Cleaned-up (mitigated effects of spill)

Restored flow

Restored flow

Contained all or portion of spill; Returned all or portion of spill to sanitary sewer system

Contained all or portion of spill

Other (specify below)

Cleaned-up (mitigated effects of spill): Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill); Restored flow

Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow


Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit

Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanitary sewer system

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow;Returned all or portion of spill to sanitary sewer system

Restored flow



1/28/2010 11:45		
12/24/2012 0:00		
3/23/2008 10:00 3/23/2008 13:30		
5/4/2008 0:00		
7/30/2009 15:00		
3/23/2010 10:23 1/5/2011 23:00		
8/20/2011 12:00		
11/13/2011 16:45		

Other (specify below)
Repaired sewer
Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance
Added sewer to preventive maintenance program
Other (specify below)
Adjusted schedule/method of preventive maintenance
Adjusted seriodale/metrical of preventive maintenance
Adjusted schedule/method of preventive maintenance
Adjusted schedule/method of preventive maintenance
Adjusted schedule/method of preventive maintenance




Yes Yes Yes No Yes Yes Yes Yes No No




Yes No No No No Yes No No No No

Surfer's Beach
NA NA
NA NA
Unk. Beach adjacent to Ritz Carlton Hotel
NA NA
n/a not the beach but a small pond at the golf course not sure yet until we look into it some more

Pacific Ocean
none NONE Pacific ocean / Princeton Harbor
Ditch NA
NA .
Golf Course Pond
Pilarcitos Creek
pacific ocean
storm drain system
none





None of the above
Not applicable to this spill
No water quality samples taken No water quality samples taken
No water quality samples taken
None of the above
None of the above
None of the above
Not applicable to this spill
None of the above





90292	1/14/2009 7:30	
100753	1/28/2010 11:45	
127868	12/23/2012 23:55	
82216 82263	3/23/2008 10:50 3/23/2008 12:55	
83239	5/4/2008 10:50	
88994	12/18/2008 11:30	
95349	7/30/2009 12:50	
404054	0/00/00 40 40 00	
101954	3/23/2010 10:30	
110085	1/5/2011 23:34	
114957	8/20/2011 12:09	
116756 117445	11/13/2011 16:30 12/17/2011 11:25	

David partida/Collection Worker

6507260124

2SSO10139	Active	775005 David Partida	Certified
2SSO10139	Active	775914 nelson	Certified
2SSO10139	Active	776850 David Partida	Certified
2SSO10139	Active	777065 David Partida	Certified
2SSO10139	Active	781589 David Partida	Certified
2SSO10139	Active	782248 nelson sandoval	Certified
2SSO10139	Active	789048 nelson sandoval	Certified
2SSO10139	Active	789292 David Partida	Certified
2SSO10140	Active	708258 mike higares	Certified
2SSO10140	Active	708313 Al Swithenbank	Certified
2SSO10140	Active	708685 Stacy Swithenbank	Certified
2SSO10140	Active	712541 Stacy Swithenbank	Certified
2SSO10140	Active	712673 Stacy Swithenbank	Certified
2SSO10140	Active	721177 stacy swithenbank	Certified
2SSO10140	Active	726180 mike higares	Certified
2SSO10140	Active	726182 mike higares	Certified
2SSO10140	Active	726275 mike higares	Certified
2SSO10140	Active	726873 mike higares	Certified
2SSO10140	Active	728119 mike.higares	Certified
2SSO10140	Active	731990 mike higares	Certified
2SSO10140	Active	738685 mike higares	Certified
2SSO10140	Active	738825 mike.higares	Certified
2SSO10140	Active	739041 mike higares	Certified
2SSO10140	Active	745679 mike higares	Certified
2SSO10140	Active	748026 mike higares	Certified
2SSO10140	Active	748744 mike.higares	Certified
2SSO10140	Active	748902 mike higares	Certified
2SSO10140	Active	750999 mike higares	Certified
2SSO10140	Active	753394 Al Swithenbank	Certified
2SSO10140	Active	765108 mike higares	Certified
2SSO10140	Active	767607 Robert Gerena	Certified
2SSO10140	Active	767987 Robert Gerena	Certified
2SSO10140	Active	771918 Joe Delacruz	Certified
2SSO10140	Active	773494 Robert Gerena	Certified
2SSO10140	Active	773555 Robert Gerena	Certified
2SSO10140	Active	776239 Robert Gerena	Certified
2SSO10140	Active	776790 Robert Gerena	Certified
2SSO10140	Active	778288 Robert Gerena	Certified
2SSO10140	Active	781662 Robert Gerena	Certified
2SSO10140	Active	787801 Robert Gerena	Certified
2SSO10140	Active	787898 Greg Shreeve	Certified
2SSO10140	Active	790189 Robert Gerena	Certified
2SSO10140	Active	790684 Robert Gerena	Certified
2SSO10140	Active	793550 Robert Gerena	Certified
2SSO10140	Active	795763 Robert Gerena	Certified
2SSO10140	Active	797919 Robert Gerena	Certified
2SSO10141	Active	771587 Jeff Brown	Certified
2SSO10141	Active	787626 Jeff Brown	Certified
2SSO10141	Active	792191 Jeff Brown	Certified
2SSO10142	Active	650524 Tony Geraldi	Certified
2SSO10142	Active	650529	Work In Progress
2SSO10142	Active	651087 Tony Geraldi	Certified
2SSO10142	Active	652663 Tony Geraldi	Certified
2SSO10142	Active	654505 Tony Geraldi	Certified
2SSO10142	Active	655590 Tony Geraldi	Certified

Collection Worker

collections

Collection Worker

Collection Worker

Collection Worker

collections

collections

Collection Worker

utilities supt

Sr Utility Leader

Sr Utility Leader

Sr Utility Leader

Sr Utility Leader

sr utillity leader

utilities supt

util supt

utilities supt

utility supt

utilities supt

utility supt

utilities supt

utilities supt

utility supt

utilities supt

utilities superintendent

utility supt

utility supt

utilities supt

Sr Utility Leader

utilities manager

Utilities Maintenance Supervisor

Utilities Operations & Maintenance Supervisor

Utilities maintenance mechanic

Utilities Operations & Maintenance Supervisor

Utilities Operations & Maintenance Supervisor

Utilities Operations & Maintenance Supervisor

Utilities Operations & Maintenance Supervisor

Utilities O&M Supervisor

Utilities Operations & Maintenance Supervisor

Utilities Operations & Maintenance Supervisor

Manager

Utilities Operations & Maintenance Supervisor

Utilities Operations & Maintenance Supervisor

Utilities Operations & Maintenance Supervisor

Utilities O&M Supervisor

Utilities Operations & Maintenance Supervisor

Oeration Manager

Operation Manager

Operations Manager

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

SAM 15:45 sam @9:28am		701931 342062
SAM 7:52		748227
	10:30	161950
SAM 13:40		413854
sam@10:50 am		180168
sam@15:15		632158
SAM 19:38		747783
	10:45	985691
de	11/28/2007	383670
work		990681
10.25 am		879534
Utility center City of Hayward		201160 823115
11am		345166
i idiii	16:15	518224
09:40am	10.10	834574
	16:19	877601
	10:55	676208
	16:18	308484
011:45		616443
	1600	112671
	16:29	529521
	13:45	777824
	8:12	785779
	17:20	910846
	17:05	317182
	16:26	954123
24499 Soto Road Hayward Ca	44.40	741734
Harmond	14:42	613212
Hayward CA		958633
Hayward CA Office		658722 696650
Office	9:15	725728
Hayward CA	9.15	189766
Hayward 10:12 AM		131589
, , , , , , , , , , , , , , , , , , ,	10:30	323099
	13:49	164862
09:27 in Hayward.		155832
Hwyawrd CA		827659
Hayward		162551
Hayward CA		746728
Hayward CA		317071
Hayward CA		642778
Hayward CA		420459
Hayward CA		526304
Hercules		252427
Hercules		517256
Hercules	8:32 AM	923253 961730
	6.32 AIVI	
09;17		144233
	9:30	107794
0.40 A M	9:10	442092
8:48 A.M.		161605

29-Dec-11	12/29/2011	29-Dec-11	12/29/2011
17-Jan-12	1/17/2012	17-Jan-12	1/17/2012
6-Feb-12	2/6/2012	6-Feb-12	2/6/2012
9-Feb-12	2/9/2012	9-Feb-12	2/9/2012
23-May-12	5/23/2012	23-May-12	5/23/2012
19-Jun-12	6/19/2012	19-Jun-12	6/19/2012
14-Dec-12	12/14/2012	14-Dec-12	12/14/2012
23-Dec-12	12/23/2012	23-Dec-12	12/23/2012
28-Nov-07		24-Feb-11	2/24/2011
28-Nov-07		28-Nov-07	11/28/2007
4-Dec-07		4-Dec-07	12/4/2007
7-Feb-08		7-Feb-08	2/7/2008
10-Feb-08		21-Feb-08	2/26/2008
2-Jul-08		2-Jul-08	7/2/2008
12-Sep-08		15-Sep-08	2/15/2011
12-Sep-08		15-Sep-08	2/28/2011
15-Sep-08		15-Feb-11	2/15/2011
25-Sep-08		25-Sep-08	2/28/2011
20-Oct-08		20-Oct-08	2/24/2011
16-Jan-09		16-Jan-09	2/28/2011
8-Jun-09		9-Jun-09	6/9/2009
9-Jun-09		9-Jun-09	2/28/2011
11-Jun-09		11-Jun-09	2/28/2011
16-Oct-09		16-Oct-09	10/16/2009
30-Dec-09		31-Dec-09	12/31/2009
25-Jan-10		29-Jan-10	2/28/2011
28-Jan-10		12-Feb-10	2/28/2011
25-Mar-10	0.45/0040	25-Mar-10	3/25/2010
15-Jun-10	6/15/2010	15-Jun-10	6/15/2010
4-Apr-11	4/5/2011	5-Apr-11	4/5/2011
20-Jun-11	6/20/2011	20-Jun-11	6/20/2011
29-Jun-11	6/29/2011	10-Dec-12	12/10/2012
11-Oct-11	10/11/2011	11-Oct-11	10/11/2011
28-Nov-11	11/28/2011	28-Nov-11	11/28/2011
29-Nov-11	11/29/2011	29-Nov-11	12/10/2012
23-Jan-12	1/23/2012	23-Jan-12	1/23/2012
2-Feb-12	2/2/2012	2-Feb-12	2/2/2012
2-Mar-12	3/2/2012	2-Mar-12	3/2/2012
29-May-12	5/29/2012	29-May-12	5/29/2012
1-Nov-12	11/1/2012	2-Nov-12	12/4/2012
6-Nov-12	11/6/2012	6-Nov-12	11/6/2012
14-Jan-13	1/14/2013	14-Jan-13	1/14/2013
23-Jan-13	1/23/2013	23-Jan-13	1/23/2013
22-Apr-13	4/22/2013	22-Apr-13	4/22/2013
19-Jun-13	6/19/2013	19-Jun-13	6/19/2013
15-Aug-13	8/15/2013	15-Aug-13	8/15/2013
30-Sep-11	9/30/2011	30-Sep-11	9/30/2011
28-Oct-12	10/28/2012	28-Oct-12	10/28/2012
28-Feb-13	2/28/2013	28-Feb-13	2/28/2013
15-May-07		15-May-07	5/15/2007
15-May-07		15-May-07	0/00/0044
30-May-07		30-May-07	3/29/2011
22-Jun-07		22-Jun-07	3/29/2011
23-Jul-07		23-Jul-07	3/29/2011
9-Aug-07		16-Jan-09	1/16/2009

Catagory 1	500	0
Category 1	500 25	0
Category 3	150	25 150
Category 3	4	4
Category 3	750	150
Category 1		
Category 3	3	0
Category 3	200	0
Category 2	10125	500
Category 2	1800	0
Category 2	1800	0
Category 2	1200	1000
Category 3	500	500
Category 1	6000	5250
Category 2	1000	1000
Category 1	1798	998
Category 2	1775	1775
Category 3	200	200
Category 2	4050	4050
Category 2	1125	1125
Category 1	7500	6500
Category 3	60	60
Category 2	3000	2900
Category 1	3200	1600
Category 1	3300	0
Category 2	2250	2000
Category 1	3000	0
Category 2	9000	9000
Category 2	2000	2000
Category 3	350	0
Category 2	4125	0
Category 2	6750	100
Category 3	250	0
Category 2	2000	2000
Category 3	500	500
Category 1	190000	4000
Category 3	400	400
Category 3	800	800
Category 3	500	500
Category 3	75	75
Category 3	20	0
Category 3	25	25
Category 3	15	0
Category 3	15	0
Category 3	200	0
Category 1	600	200
Category 3	25	0
Category 1	500	200
Category 1	100	50
Category 1	1000	0
Category 3	350	0
Category 3	960	0
Category 2	1500	0
Category 3	210	0
Category 3	75	0
Category 3	900	0
.		•

500 Yes 0 No 0 No 0 No 600 Yes 0 No 0 No 0 No 0 No		Yes No No No Yes No No No No
0 No 0 No No		No Yes No
750 Yes 0 No	3	Yes Yes
800 Yes 0 No	5	Yes Yes
0 No 0 No 0 No		No Yes No
1000 No 0 No		Yes Yes
0 No 1600 No		Yes Yes
3300 Yes 0 No 3000 Yes		No Yes No
0 No 0 No	•	Yes Yes
0 No 0 No		No No
0 No 0 No 0 No		No Yes
0 No 186000 Yes	3	No No Yes
0 No 0 No		No Yes
0 No 0 No 0 No		Yes No No
0 No 0 No		No No
0 No 0 No 400 No		No No Yes
0 No 300 Yes		No Yes
50 Yes 1000 Yes No		Yes No No
0 No 0 No		Yes No
0 No 0 No 0 No		No No No

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe No Yes No Yes Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Yes No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Yes Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes Yes Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe No

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe 509 Ocean

kelly ave

815 First ave

717 Main st

15th hole golf course

363 poplar

half moon bay state park

St Francis State Beach

28010 Nob Hill

Nob Hill

E Street

1281 Highland Blvd

Cypress

Willimet

Hayward Blvd

275 Industrial Parkway

937 Simon Ave

Industrial Blvd

Campus and Oaks Drive

Tyrell Ave

Zaballos ct

whitman

Skyline drive

1137 walpert street

510 Corrine

St Annes Place

25837 Gettysburg ave.

E street

Intersection of Tyrrell and Shepherd ave

Oakes Dr

Hayward Golf Course

22676 Beech St

1388 Dst Hayward Ca 94544

3589 Skyline Drive

Daisy Court Whitestone Easment Line

26030 Gading Road

795 Sandoval Ave

25013 Lucien Way, Hayward CA 94544

22654 Main Street

27098 St. Frances Avenue

1755 Dahill Lane

22597 Chestnut Street

3029 Oakes Drive

1562 D Street on south side of house.

Intersection of Palisade St & Overlook Ave

22228 Montgomery Street

Victoria Lift Station

Hercules Ca.

Reugio Valley Rd by Miramar Ave

40 Bluebell easement

2375 Skyfarm Dr.

2415 Skyfarm Drive

105 Denise Rd.

350 El Portal Rd.

crystal springs

37.27715	-122.26542 San Mateo
37.27842	-122.25935 San Mateo
37.27434	-122.24364 San Mateo
37.46168	-122.42947 San Mateo
37.26284	-122.26098 San Mateo
37.45624	-122.43734 San Mateo
37.28168	-122.26766 San Mateo
37.28168	-122.26766 San Mateo
37.651944	-122.034722 Alameda
37.660556	122.034722 Alameda
37.670833	122.077778 Alameda
37.665833	122.069444 Alameda
37.669167	122.088333 Alameda
37.647222	122.093611 Alameda
37.656408	-122.04115 Alameda
37.6275	-122.049167 Alameda
37.676667	122.088056 Alameda
37.635258	-122.111617 Alameda
37.665739	-122.056044 Alameda
37.635833	-122.073611 Alameda
37.679167	-122.067778 Alameda
37.640556	-122.064722 Alameda
37.671111	-122.026667 Alameda
37.66826	-122.07339 Alameda
37.618889	-122.033889 Alameda
37.616944	-122.046389 Alameda
37.637778	-122.109167 Alameda
37.670831	-122.078003 Alameda
37.636111	-122.093056 Alameda
37.66193	-122.04042 Alameda
37.627844	-122.047206 Alameda
37.681444	-122.0651 Alameda
37.675156	-122.074028 Alameda
37.649	-122.025 Alameda
37.651464	-122.037339 Alameda
37.646006	-122.080278 Alameda
37.619167	-122.050939 Alameda
37.65317	-122.08316 Alameda
37.67232	
	-122.08208 Alameda
37.63695	-122.07667 Alameda
37.682133	-122.070114 Alameda
37.67843	-122.07445 Alameda
37.66323	-122.04618 Alameda
37.676278	-122.071289 Alameda
37.661864	-122.069489 Alameda
37.67531	-122.08966 Alameda
38.02815	-122.27603 Contra Costa
38.004758	-122.261771 Contra Costa
37.9941	-122.23861 Contra Costa
37.538333	122.3525 San Mateo
37.56727	-122.37321 San Mateo
37.56653	-122.37413 San Mateo
37.54791	-122.36297 San Mateo
37.56389	-122.34528 San Mateo
37.5632	122.328889 San Mateo

Corner of valdez and ocean

Sewer did not reach storm drain ,all was contained and recovered. Street was washed down and vacumed as well. Three different buildings had their toilet water blown out. 717 main st, 731 main st, and 542 main st. This resulted from o blockage between upstream MH25056 and downstream MH25042. It took 15 minutes from when we got the call to when clean out on the side of the house was overflowing

the public restrooms at the state beach

Manhole at north end restroom campground backing up reason being its the lowest point, and too much flow at main line. easement MH in the hilly portion of the city. lots of vegitation and very steep terrain

Apartment complex driveway

manhole is located in the #1 lane of the west bound roadway. Area is 100% residential. Roadway is very steep incline

Spill inside house at 937 Simon Ave. Estimate of 200 gallons was spilled inside of house and confined to interior premise: the spill manhole is located in the N-bound traffic lane of a 4 lane road that runs N-S. General area is a combination of light spill was from an manhole on an easement line

this street runs N-S and there are many muti family units on this street

backyard easement

residential/flat

residential, low traffic hilly

the spill site is at the east end of a condiminum complex. area is dirt

Manhole in front of address 510 Corrine Street

residential culdesac

spill was on a residential street, low traffic.

two lane surface street

manhole located in a canyon will thick vegatation Mission Hills golf course, hole #3

corner of D st and Fourth st two homes basement flodded

Manhole at 3589 Skyline Drive

Daisy Court Whitestone Easment main

Inside residential apartment complex

Spill out of manhole @ 795 Sandoval Ave

Cleanout in street in front of 25013 Lucien Way

Deck drain in shop

Toilet overflow due to line backing up.

Cleanout on resident property.

Cleanout in back yard of residence

Manhole in back yard behind fence.

Cleanout on south side of house

Manhole @ intersection of Palisade Street & Overlook Avenue.

Customer's cleanout

Victoria Lift Station Located at end of Tresle Cove

Sewer manhole locate in Crosswalk on Lavender Place

West bound land Refugio Valley Rd

Land easement area.

Easement-trail area

Clean out overflowed on property.

roadway ditch

SSO still continuing; High flow capacity s. Restorative emergency services was nt industrial and residential.

ne event, from the cleaning crew that have broke the plug. SSO was about 50 g $\,$

Manhole

Building or structure

Gravity sewer; Manhole

Building or structure; Other (specify)

Gravity sewer; Manhole

Building or structure

Manhole

Gravity sewer; Manhole

Manhole

Manhole

Manhole

Building or structure

Other sewer system structure

Manhole

Manhole

Manhole

Building or structure

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Gravity sewer; Manhole

Manhole

Manhole

Gravity sewer; Manhole; Other sewer system structure; Pump station; Other (specify)

Manhole

Manhole

Manhole

Manhole

Manhole

Other sewer system structure

Gravity sewer

Manhole

Gravity sewer

Manhole

Gravity sewer

Building or structure

Building or structure

Building or structure; Other (specify)

Other sewer system structure

Manhole

Other sewer system structure

Manhole

Gravity sewer

Pump station

Manhole

Gravity sewer; Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Other (specify)

Manhole

City contractor televising crew plugged main line to televise on 12-1-2011 and SAM received callout on 12-4-2011. Water inside toilet bowl was blown out onto bathroom floor. Caused by high water pressure of sewer cleaning truck. the manhole in front of the restroom was overflowing onto the grass area upon our arrival We will amend report when the flow capacity goes down. 10125 gallons spilled onto ground. dirt. Apartment complex 4 inch clean out Clean out cover Sewage flowed out of manhole cover. Coming out of clean out at the rear of the property Manhole at 3589 Skyline Drive Manhole behind 3340 Daisy Court Cleanout Manhole in street in front of 795 Sandoval Ave Cleanout in front of 25013 Lucien Way Spill emanated from deck drain in lingerie shop. Toilet overflowed due to sewer main backup. Cleanout on resident property. Customers bathtub and cleanout. Manhole in back yard behind fence. Cleanout Manhole Spill resulted when resident opened property cleanout while line was backed up. Clean out overflowed.

Beach; Separate storm drain; Street/curb and gutter

Building or structure

Street/curb and gutter

Building or structure; Other (specify below)

Other paved surface; Separate storm drain; Surface water; Unpaved surface

Other (specify below)

Other (specify below)

Other paved surface; Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Other paved surface; Unpaved surface

Storm drain; Street/curb and gutter; Surface water

Storm drain

Surface water

Other (specify below)

Other (specify below)

Separate storm drain

Unpaved surface

Separate storm drain

Storm drain

Separate storm drain

Unpaved surface

Other (specify below)

Storm drain

Other (specify below)

Other paved surface; Separate storm drain; Street/curb and gutter; Surface water

Storm drain

Other (specify below)

Unpaved surface

Unpaved surface

Other (specify below)

Building or structure

Other paved surface

Surface water

Unpaved surface

Separate storm drain; Street/curb and gutter

Other paved surface

Building or structure

Unpaved surface

Building or structure; Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Separate storm drain

Unpaved surface

Surface water

Surface water

Surface water

Unpaved surface

Separate storm drain

Unpaved surface

Unpaved surface

Other paved surface

Street/curb and gutter

Bathrooms inside three different buildings. Manhole #s for building 717 main and 731 main are H14002-H14001, MH #s

about 3 gallon overflowed onto the ground in there back yard area

the flow going into the 18 inch mainline was to much which resulted in the back up of the restroom line that ties into the SSO spill is going onto ground (soil).

alameda county drinage ditch, drains to sf bay

Open drainage ditch that we sandbagged, then vacuumed. house carpets

liquid spread out over a hillside with lots of vegitation hillside and some to Ward Ceek

Spill was estimated at 2250 Gallons, we recoverd 2000 gallons of the sewage with nothing passing buy us. sewage went into a flood control ditch behind St Annes Place that was flowing violently because of the severe storm

Spill was contained and retuned to City Sewer

Spill onto golf course, soaked into turf.

Alameda Flood Control

In street, cleaned up by crew with Vactor truck.

Ziele Creek

Large planting area.

Spill partially entered storm drain, storm drain was blocked, and spill was recovered.

Along curb & gutter at 25013 Lucien Way

Spill from deck drain in shop. Crew cleaned up and returned to sanitary sewer.

Crawl space under home. Had contractor clean and disinfected crawl space for resident.

Cleanout on resident property.

In grass of residence. Sewer Collection crews cleaned up debris that did not soak into the ground.

Back yard of residence. Unpaved lawn.

Side of house in weeds and dirt

Storm drain on Carlos Bee Blvd.

Resident's lawn

San Pablo Bay via Storm drain System

Refugio Creek

Clean out overflowed onto front yard.

12/4/2011 8:45	12/4/2011 8:45	12/4/2011 9:35	12/4/2011 9:35
1/16/2012 8:55	1/16/2012 8:55	1/16/2012 9:40	1/16/2012 9:40
2/4/2012 8:45	2/4/2012 8:45	2/4/2012 9:15	2/4/2012 9:30
2/9/2012 12:54	2/9/2012 12:54	2/9/2012 13:15	2/9/2012 12:54
5/23/2012 8:25	5/23/2012 8:25	5/23/2012 8:35	5/23/2012 12:00
6/19/2012 9:01	6/19/2012 9:01	6/19/2012 9:20	6/19/2012 9:30
12/2/2012 10:51	12/2/2012 10:51	12/2/2012 11:20	12/2/2012 14:00
12/23/2012 14:30	12/23/2012 14:30	12/23/2012 14:45	12/23/2012 16:40
11/27/2007 0:00	11/27/2007 0:00	11/27/2007 0:00	11/27/2007 0:00
11/27/2007 8:30	11/27/2007 8:45	11/27/2007 9:00	11/27/2007 12:00
12/3/2007 11:00	12/3/2007 11:10	12/3/2007 11:25	12/3/2007 12:00
2/7/2008 7:40	2/7/2008 7:50	2/7/2008 8:00	2/7/2008 8:15
2/10/2008 4:15	2/10/2008 4:15	2/10/2008 4:45	2/10/2008 5:30
7/1/2008 11:30	7/1/2008 11:30	7/1/2008 11:40	7/1/2008 15:00
9/10/2008 23:30	9/10/2008 23:30	9/10/2008 23:50	9/11/2008 4:00
9/10/2008 7:50	9/10/2008 8:00	9/10/2008 8:10	9/10/2008 8:45
8/30/2008 23:45	8/30/2008 23:45	8/30/2008 23:59	8/31/2008 0:30
9/22/2008 8:08	9/22/2008 8:08	9/22/2008 8:35	9/22/2008 8:35
10/16/2008 8:20	10/16/2008 8:20	10/16/2008 8:20	10/16/2008 8:40
1/14/2009 8:52	1/14/2009 8:57	1/14/2009 9:15	1/14/2009 10:15
6/2/2009 13:20	6/2/2009 13:20	6/2/2009 13:35	6/2/2009 14:20
6/4/2009 18:00	6/4/2009 18:00	6/3/2009 18:15	6/4/2009 19:00
6/8/2009 18:00	6/8/2009 18:00	6/8/2009 18:45	6/8/2009 19:00
10/13/2009 21:33	10/13/2009 21:00	10/13/2009 21:33	10/13/2009 22:38
12/28/2009 10:45	12/28/2009 10:45	12/28/2009 10:59	12/28/2009 11:45
1/20/2010 12:55	1/20/2010 12:55	1/20/2010 1:10	1/20/2010 2:55
1/27/2010 5:45	1/27/2010 5:45	1/27/2010 6:15	1/27/2010 6:45
3/20/2010 11:00	3/20/2010 11:00	3/20/2010 11:30	3/20/2010 11:45
6/13/2010 13:30	6/13/2010 13:30	6/13/2010 13:59	6/13/2010 18:30
4/2/2011 16:30	4/2/2011 16:30	4/2/2011 17:30	4/2/2011 19:15
6/19/2011 12:00	6/19/2011 12:00	6/19/2011 12:15	6/19/2011 12:45
6/28/2011 15:00	6/28/2011 15:00	6/28/2011 15:25	6/28/2011 15:35
10/8/2011 10:15	10/8/2011 10:15	10/8/2011 11:00	10/8/2011 11:15 11/23/2011 22:00
11/23/2011 21:00	11/23/2011 21:00	11/23/2011 22:00	
11/26/2011 12:00	11/28/2011 11:15	11/28/2011 11:25	11/28/2011 12:15
1/5/2012 14:25 2/1/2012 14:45	1/5/2012 14:30 2/1/2012 14:45	1/5/2012 14:35 2/1/2012 14:45	1/5/2012 15:00 2/1/2012 15:15
3/1/2012 14:45	3/1/2012 14:45	3/1/2012 14:45	3/1/2012 15:30
5/18/2012 15:00	5/18/2012 14:48	5/18/2012 14:55	5/18/2012 15:00
10/29/2012 11:00	10/29/2012 11:03	10/29/2012 11:15	10/29/2012 11:15
11/5/2012 11:56	11/5/2012 11:56	11/5/2012 11:15	11/5/2012 11:15
1/7/2013 13:00	1/7/2013 14:30	1/7/2013 14:45	1/7/2013 15:15
1/18/2013 16:30	1/18/2013 17:00	1/18/2013 18:00	1/18/2013 18:30
4/19/2013 8:41	4/19/2013 8:45	4/19/2013 18:59	4/19/2013 18:30
6/16/2013 12:15	6/16/2013 12:15	6/16/2013 12:30	6/16/2013 13:45
8/13/2013 19:55	8/13/2013 19:58	8/13/2013 12:30	8/13/2013 20:00
9/29/2011 2:00	9/29/2011 2:15	9/29/2011 2:30	9/29/2011 3:00
10/27/2012 10:00	10/27/2012 10:15	10/27/2012 10:30	10/27/2012 11:00
2/27/2013 14:30	2/27/2013 14:35	2/27/2013 14:36	2/27/2013 15:30
5/9/2007 0:00	5/9/2007 9:30	5/9/2007 9:45	5/9/2007 9:55
5/14/2007 0:00	5/14/2007 19:45	5/14/2007 19:50	5/14/2007 20:30
5/29/2007 0:00	5/29/2007 10:00	5/29/2007 10:15	5/29/2007 10:30
6/21/2007 0:00	6/22/2007 9:10	6/22/2007 9:30	6/22/2007 10:15
7/22/2007 0:00	7/22/2007 18:30	7/22/2007 18:45	7/22/2007 20:20
8/9/2007 8:15	8/9/2007 8:15	8/9/2007 8:20	8/9/2007 8:51

Other (specify below)

Other (specify below)

Debri-Rags

Other (specify below)

Root intrusion

Debri-Rags

Rainfall exceeded design (Separate CS Only)

Flow exceeded capacity (Separate CS Only)

Root intrusion

Root intrusion

Grease deposition (FOG)

Root intrusion

Grease deposition (FOG)

Debris

Other (specify below)

Root intrusion

Root intrusion

Grease deposition (FOG)

Root intrusion

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Grease deposition (FOG)

Other (specify below)

Grease deposition (FOG)

Root intrusion

Root intrusion

Other (specify below)

Debri-General

Grease deposition (FOG)

Root intrusion

Grease deposition (FOG)

Debri-Rags

Grease deposition (FOG)

Grease deposition (FOG)

Root intrusion

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Pump station failure

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

City contractor plugged main line to televise, and that led manhole to overflow.(lowest point)12-1-2011 Response from main line was plugged the plug broke it self not sure what caused it when we arrived the flow was restored already but

Resulted from high water pressure cleaning of sewage main line.

due to heavy rains

SSO is still going on due to weather. Flow capacity in the main line is too high. update at 19:30 the manhole stoped overf

Grease blockage, multiple apartment complexes near spill

a root ball from an upper segment of this pipe made its way to this MH and blocked the discharge side of the MH

Spill at 937 Simon Ave. Estimate of 200 gallons was spilled inside of house and confined to interior premises. Restorative

root ball from some location in the upper sewer main

Roots and grease in line. Line was chemically treated, roots may have become brittle and clogged line. Drain Rock in line

Grease in line.

Root intrusion into manhole.

Grease in lateral caused backup.

Found rags and grease in line.

Heavy grease in line from restaurant.

Heavy grease in downtown sewer mains.

Roots and grease in sewer main.

Grease in line at lift station inlet.

Roots, grease and rags in sewer main.

Rootball in manhole.

Roots and pipe offsets

Root intrusion in City sewer main.

Grease and corn cobs found in line.

failure of lift station controls and Alarm

cleaning rags (swifters)

Main Other (specify below) Main Main Main Main Upper Lateral Upper Lateral Main Other (specify below) Upper Lateral Main Main Main Main Main Main Main

Main Main

Main stoppage, sewage flowed from upstream manhole.

Gravity main clogged with grease.

Manhole joint

Main backed up and spilled from cleanout in apartment complex.

Main blocked approximately 50' upstream of manhole at intersection of San Antonio Street & Huntwood Ave.

Jackson St & Park St. backup was original location of stoppage. After clearing stoppage, grease went down stream, block Main clogged with grease backed up and spilled out customer's deck drain.

Overflow from customer toilet due to sewer main stoppage.

Line clog at lift station influent due to grease.

Manhole

Cleanout at resident's home.

Roots entered joint in pipe.

Main clogged, backed up and when resident opened cleanout sewage escaped to resident's lawn.

8 VCP 8 8 ac 10 vcp 8 vcp 12 HDPE 8 vcp 8 vcp 8 ac 15 ac 8 vcp 10 vcp 8 vcp 8 vcp 8 VCP 6 VCP 6 8 VCP 8 AC 8 VC 8 VCP ed a line and caused surcha 8 VCP 8 VCP 4 ACP 6 ACP 6 VCP 8 VCP 6 VCP 8 VCP 6 VCP 8 plastic 8 Plastic 6 clay 6 clay

> 6 clay 8

Cleaned-up (mitigated effects of spill); Other (specify below)

Contained all or portion of spill

Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Restored flow

Cleaned-up (mitigated effects of spill)

Restored flow

Cleaned-up (mitigated effects of spill):Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Returned all or portion of spill to sanitary sewer system

Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re

Cleaned-up (mitigated effects of spill):Restored flow

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Restored flow; Returned all or portion of spill to sanitary sewer system

Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Restored flow; Returned all or portion of spill to sanitary sewer system

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill);Restored flow

Returned all or portion of spill to sanitary sewer system

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Cleaned-up (mitigated effects of spill)

Restored flow

Cleaned paper around manhole.
Sandbagged drainage ditch contined spill, Vaccumed and flushed stormdrain at same time. Cleaned sewer line removed
Traced spill to dry stormdrain manhole set up vacum truck and hydro cleaned out storm drains all the way from spill to cle
Contained area, cleaned up debris, vactored sewage to extent possible, washed down walkway and grass area, raked gra
Sampled creek upstream and down stream of spill for coliform. Instructed resident of reporting procedures during off hour Cleared blockage, televised main, recovered all spilled sewage, cleaned area and had remediation company remove all s Crew responding to odor complaint, found manhole starting to overflow. Crew implemented BMP's to contain spill, blocke Posted signs on street, cleaned street, cleaned storm drain catch basin, televised affected line that caused blockage and Contained spill, captured all of spill and returned to sanitary sewer. Cleaned lines, televised lines. Cleaned and disinfected customer crawl space.
Broke stoppage, cleaned up spill in resident yard, had Restoration Management disinfect shower where spill appeared. Cleaned yard, broke stoppage, cut roots from pipe, televised line. Spill on dirt and weeds, absorbed into ground. Cleaned up area, disinfected and hired Restoration Management Services Cleaned spill and storm drains where sewage entered. Inspected storm water pump station approximately 1/4 mile from s Called Roto Rooter, broke stoppage and restored flow. Sewage spilled into lawn. Back up by system was put in operation returning function of lift station. Sewage cantain within area of Station returned to
Just barely seaping out of manhole.

5/23/2012 12:00

12/23/2012 17:06 11/27/2007 0:00 11/27/2007 0:00 12/4/2007 12:00

2/21/2008 3:00 7/1/2008 20:00 9/11/2008 11:30 9/10/2008 11:57

9/22/2008 20:00 10/16/2008 14:00 1/14/2009 14:30

6/4/2009 22:30 6/8/2009 22:00 10/15/2009 16:00 12/28/2009 17:00 1/20/2010 5:00 1/28/2010 12:00 3/20/2010 14:00

4/2/2011 20:00 6/19/2011 12:45 6/28/2011 17:00 10/8/2011 8:00

11/29/2011 14:00

9/29/2011 4:00 10/27/2012 13:00 2/27/2013 16:29 5/14/2007 20:30 5/29/2007 11:00 Other (specify below)

Added sewer to preventive maintenance program

Other (specify below)

Added sewer to preventive maintenance program

Adjusted schedule/method of preventive maintenance

Added sewer to preventive maintenance program

Added sewer to preventive maintenance program

Other (specify below)

Other (specify below)

Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance; Plan rehabilitatic

Adjusted schedule/method of preventive maintenance

Repaired sewer

Adjusted schedule/method of preventive maintenance

Enforcement action against FOG source; Plan rehabilitation or replacement of sewer

Adjusted schedule/method of preventive maintenance

Plan rehabilitation or replacement of sewer

Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance

Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance

Added sewer to preventive maintenance program

Plan rehabilitation or replacement of sewer

Adjusted schedule/method of preventive maintenance

Other (specify below)

Other (specify below)

Other (specify below)

Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance; Plan rehabilitatic

Other (specify below)
Adjusted schedule/method of preventive maintenance
Added sewer to preventive maintenance program

Other (specify below)

Added sewer to preventive maintenance program

Contractor pulled plug to restore flow.Line was flushed by SAM as well on 12-4-2011
none
spill was originally overestimated. Volume was calculated using vactor truck and time spent containing spill untill stoppag upstream sewer main will be CCTV inspected to determine root intrusion point and then chemically trated for roots. To be determined after CCTV inspectionwe know the cause was roots.
TV line to determine action required. Rock found in line. Additional flushing of line Romoved plastic debris causing overflow
Cut roots out of manhole and restored flow. Added all easement mains and manholes to annual inspection list. Will start (
Repairs underway at Lift Station & Planned instalation of additional back up alarm systen
Root foaming/town web site about dumping swifters down sewer lines Will add this area of sewer easement to our root foaming program.

Yes

Yes

Yes

No

No

No

Yes

No No

No

No No

No

No

No No

No

No

No

No

No

No

No No

Yes

Yes

No

No

No

No

na
no evidence of sewage realted material could be observed. Because flow from impacted MH flowed from the holes in the
at the point where this particular SD pipe discharges into the flood control channel a visual inspection indicated that no se site was restored to pre spill condition no impact observed none none
no observable floating material from our vantage point. bad weather and terrain made it unsafe to get close to the actual
significant flow in channel un-able to collect samples. Did not see any flow sewage debri. Manhole acted as a shive so or city crews spent an entire day hydro cleaning and vacumming the SD pipeline between the spill point and the entry to the traced storm drain pipe to channel discharge with no visible liquid at this point. flushed SD pipe with 3-4 K of clean water
NA Water appeared clean. Area was free of debris. No signs of contamination or wildlife impact. NA
NA N/A N/A N/A
N/A N/A
N/A
Creek inspected down stream for any negative effects no negative effects found

No

No

No No

No

No

No

No No

No

No

No

No

No

No No

No

No

No

No

No

No No

No

No

No No

No

No

No

Francis state beach

na

na

na

n/a

na

NA

n/a

na

NA

na

na

na

na n/a

NA

na

na

NA

NA

NA

N/A

N/A

N/A

N/A

N/A

N/A

N/A

NA

pacific ocean golf course pond that leads to pacific ocean na na na San fransisco Bay 750 gallons na Ziele Creek Small Drainage Ditch inside golf course. did not reach surface water na na Ziele Creek, creek was inspected and no visual impacted noted. Mosquito abatement will also walk the creek and inform Ward Creek n/a sf bay alameda county flood control na None NA Ziele Creek NA NA NA N/A N/A N/A N/A N/A N/A San Pablo Bay Refugio Creek Refugio Creek N/A NA

Not applicable to this spill

Other (specify below)

Not applicable to this spill Not applicable to this spill Not applicable to this spill Not applicable to this spill

Dissolved oxygen;Biological indicator(s) - specify below

Not applicable to this spill

Dissolved oxygen;Other chemical indicator(s) - specify below;Biological indicator(s) - specify below No water quality samples taken

Dissolved oxygen;Other chemical indicator(s) - specify below;Biological indicator(s) - specify below No water quality samples taken No water quality samples taken

Not applicable to this spill No water quality samples taken Not applicable to this spill

Not applicable to this spill Not applicable to this spill No water quality samples taken Not applicable to this spill

Biological indicator(s) - specify below

Not applicable to this spill No water quality samples taken No water quality samples taken

No water quality samples taken Not applicable to this spill

Ammonia Nitrogen, Fecal Coliform	
DO, E Coli, NH3 at the entry and exit of creek	
DO,NH3 and fecal coli none	
no samples due high flows and to safety concerns	
Tested for coliform.	

coliform, colilert, enterolert

No water quality samples taken

County Health Agency

Not applicable to this spill Not applicable to this spill Not applicable to this spill Not applicable to this spill

None of the above Not applicable to this spill County Health Agency;Regional Water Quality Control Board;None of the above None of the above

None of the above No water quality samples taken None of the above

None of the above None of the above None of the above None of the above None of the above

No water quality samples taken

Not applicable to this spill None of the above No water quality samples taken None of the above

None of the above

None of the above None of the above None of the above

None of the above Not applicable to this spill





117648	12/29/2011 15:30
173044	5/23/2012 9:40
127851	12/23/2012 16:45
77484	12/4/2007 8:21
81232	2/10/2008 8:38
84854	7/1/2008 14:30
86642	9/11/2008 1:20
86616	9/10/2008 10:55
86877	9/22/2008 9:39
87476	10/16/2008 10:08
90307	1/14/2009 11:10
94080	6/2/2009 15:05
94147	6/4/2009 18:45
94225	6/8/2009 20:00
96936	10/13/2009 21:30
98594	12/28/2009 11:47
100485 739	1/20/2010 2:35 1/27/2010 7:00
101911	3/20/2010 7:00
103610	6/13/2010 11:40
112141	4/2/2011 18:00
113670	6/19/2011 15:30
113891	6/28/2011 16:55
116052	10/11/2011 9:00
	11/23/2011 23:45
117039	11/28/2011 13:00
120659	2/1/2012 16:43
121199	3/1/2012 17:20
122954	5/18/2012 16:20
126542	10/30/2012 8:53
130404	1/18/2013 20:30
100 10 1	1, 10,20 10 20.00
133662	6/16/2013 14:40
131224	2/28/2013 8:25
·	
0 73272	11/11/1111 00:00 5/29/2007 8:30



2SSO10142	Active	657662 Tony Geraldi	Certified
2SSO10142	Active	706940 Tony Geraldi	Certified
2SSO10142	Active	708384 Tony Geraldi	Certified
2SSO10142	Active	709154 Tony Geraldi	Certified
2SSO10142	Active	710145 Tony Geraldi	Certified
2SSO10142	Active	710791 Tony Geraldi	Certified
2SSO10142	Active	710804 Tony Geraldi	Certified
2SSO10142	Active	710818 Tony Geraldi	Certified
2SSO10142	Active	711269 Tony Geraldi	Certified
2SSO10142	Active	711272 Tony geraldi	Certified
2SSO10142	Active	711277 Tony Geraldi	Certified
2SSO10142	Active	711392 Tony Geraldi	Certified
2SSO10142	Active	711578 Tony Geraldi	Certified
2SSO10142	Active	711587 Tony Geraldi	Certified
2SSO10142	Active	711593 Tony Geraldi	Certified
2SSO10142	Active	711922 Tony Geraldi	Certified
2SSO10142	Active	712087 Tony Geraldi	Certified
2SSO10142	Active	712090 Tony Geraldi	Certified
2SSO10142	Active	712116 Tony Geraldi	Certified
2SSO10142	Active	712131 Tony Geraldi	Certified
2SSO10142	Active	712217 Tony Geraldi	Certified
2SSO10142	Active	712221 Tony Geraldi	Certified
2SSO10142	Active	712227 Tony Geraldi	Certified
2SSO10142	Active	712271 Tony Geraldi	Certified
2SSO10142	Active	712285 Paul Capovilla	Certified
2SSO10142	Active	714477 Tony Geraldi	Certified
2SSO10142	Active	714678 Tony Geraldi	Certified
2SSO10142	Active	714952 Tony Geraldi	Certified
2SSO10142	Active	714989 Tony Geraldi	Certified
2SSO10142	Active	716149 Tony Geraldi	Certified
2SSO10142	Active	717321 Tony Geraldi	Certified
2SSO10142	Active	719181 Tony Geraldi	Certified
2SSO10142	Active	720068 Tony Geraldi	Certified
2SSO10142	Active	721555 THOMAS BARRY	Certified
2SSO10142	Active	724458 Paul Capovilla	Certified
2SSO10142	Active	724535 Tony Geraldi	Certified
2SSO10142	Active	724594 Paul Capovilla	Certified
2SSO10142	Active	724835 Tony Geraldi	Certified
2SSO10142	Active	725118 thomas barry	Certified
2SSO10142	Active	725522 Craig West	Certified
288010142	Active	725527 Craig West	Certified
2SSO10142	Active	725528 Craig West	Certified
2SSO10142 2SSO10142	Active Active	727304 Tony Geraldi	Certified Certified
2SSO10142 2SSO10142	Active	727706 Martha Debry	
		727759 Martha Debry	Certified Certified
2SSO10142	Active Active	727761 Martha Debry	Certified
288010142	Active	728085 Tony Geraldi	
2SSO10142 2SSO10142	Active	729827 Tony Geraldi 730274 Tony Geraldi	Certified Certified
2SSO10142 2SSO10142	Active	731107 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	731107 Tony Geraldi 731362 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	731362 Tony Geraldi 732219 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	732485 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	733550 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	733551 Tony Geraldi	Certified
	, 100140	700001 Tony Column	Jordinod

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

jSupervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Ouper viso

Supervisor

Maintanance Worker 2

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

- Supervisor

Supervisor

LEADMAN

Sewer Maint.

Supervisor

Sawer Maint.

supervisor

leadman

Supervisor

Public Works Supervisor

Public Works Supervisor

supervisor

Public Works Director

Public Works Director

Public Works Director

Supervisor

Supervisor

supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

	2:23 PM	047627
Lillaharaugh	2.23 PIVI	947637
Hillsborough		525523
2:33pm		563075
3:25 p.m.	0.40	563333
40.00	2:49	644592
12:09 P.M.		421914
2:42 P.M.		998919
2:29 P.M.		402922
2:52 p.m.		695819
3:37 p.m.		603125
4:41p.m.		808458
2:54p.m.		371802
11:42 A.M.		995366
11:59 A.M.		354755
2:15 P.M.		124589
12:12 P.M.		860178
2:49 P.M.		690394
3:25 P.M.		923792
9:18 A.M.		940820
12:29 P.M.		850773
1:56 P.M.		246661
2:54P.M.		956655
2:47 P.M.		533187
11:01 A.M.		485814
11:26am		808682
2:16 p.m.		499824
9:58 A.M.		938253
226 P.M.		188864
11:54 a.m.		301985
8:44 A.M.		547055
11:32 A.M.	44.40	656053
0.50 4.44	14:40	737452
9:59 A.M.		267047
	8:01 AM	982087
	20:08	344390
	8/11/2008	777436
	10:24	217424
4:17p.m.		313474
	1637	821004
9:58 a.m.		119842
	18:10	248863
	18:30	225869
	16:19	874398
hillsborough		458283
Hillsborough		520146
Hillsborough CA		991192
10:47 A.M.		532237
	14:31	235920
	14:38	446469
	14:08	387938
	14:22	508076
	11:19	298713
	11:44	570863
	15:11	248538
	15:40	749743
	, . , , ,	

18-Sep-07	18-Sep-07	9/18/2007
31-Oct-07	31-Oct-07	10/31/2007
29-Nov-07	29-Nov-07	11/29/2007
12-Dec-07	12-Dec-07	12/12/2007
20-Dec-07	20-Dec-07	12/20/2007
7-Jan-08	7-Jan-08	1/7/2008
7-Jan-08	7-Jan-08	1/23/2008
7-Jan-08	7-Jan-08	1/23/2008
15-Jan-08	15-Jan-08	1/15/2008
15-Jan-08	15-Jan-08	1/15/2008
15-Jan-08	15-Jan-08	1/15/2008
17-Jan-08	17-Jan-08	1/17/2008
23-Jan-08	23-Jan-08	1/23/2008
23-Jan-08	23-Jan-08	1/23/2008
23-Jan-08	23-Jan-08	1/23/2008
28-Jan-08	29-Jan-08	1/29/2008
30-Jan-08	30-Jan-08	1/30/2008
30-Jan-08	30-Jan-08	1/30/2008
31-Jan-08	31-Jan-08	1/31/2008
31-Jan-08	31-Jan-08	1/31/2008
		2/1/2008
1-Feb-08	1-Feb-08	
1-Feb-08	1-Feb-08	2/1/2008
1-Feb-08	1-Feb-08	2/1/2008
4-Feb-08	4-Feb-08	2/4/2008
4-Feb-08	4-Feb-08	2/4/2008
4-Mar-08	4-Mar-08	3/4/2008
10-Mar-08	10-Mar-08	3/10/2008
17-Mar-08	17-Mar-08	3/17/2008
18-Mar-08	18-Mar-08	3/18/2008
15-Apr-08	15-Apr-08	4/15/2008
13-May-08	13-May-08	5/13/2008
9-Jun-08	9-Jun-08	6/9/2008
23-Jun-08	23-Jun-08	6/23/2008
7-Jul-08	8-Jul-08	7/8/2008
9-Aug-08	9-Aug-08	8/9/2008
11-Aug-08	11-Aug-08	8/11/2008
13-Aug-08	13-Aug-08	8/13/2008
18-Aug-08	18-Aug-08	8/18/2008
22-Aug-08	22-Aug-08	8/22/2008
30-Aug-08	30-Aug-08	8/30/2008
31-Aug-08	31-Aug-08	8/31/2008
31-Aug-08	31-Aug-08	8/31/2008
2-Oct-08	6-Oct-08	10/6/2008
9-Oct-08	4-Nov-08	11/4/2008
11-Oct-08	14-Oct-08	10/14/2008
12-Oct-08	4-Nov-08	11/4/2008
20-Oct-08	1-Feb-11	2/1/2011
25-Nov-08	5-Jan-09	1/5/2009
8-Dec-08	5-Jan-09	1/5/2009
27-Dec-08	5-Jan-09	1/5/2009
2-Jan-09	5-Jan-09 5-Jan-09	1/5/2009
21-Jan-09	24-Feb-09	2/24/2009
24-Jan-09	24-Feb-09 24-Feb-09	2/24/2009
15-Feb-09		
	24-Feb-09	2/24/2009
15-Feb-09	24-Feb-09	2/24/2009

Category 3	150	0
Category 3	265	0
Category 3	100	0
Category 3	420	100
Category 3	750	700
Category 1	2700	0
Category 1	2700	Ō
Category 1	18000	0
	10000	0
Category 1		
Category 1	100000	0
Category 1	13500	0
Category 1	5250	0
Category 1	5250	0
Category 1	5250	0
Category 1	21000	0
Category 1	1923000	0
Category 1	122000	0
Category 1	122000	0
Category 1	115000	0
Category 1	33000	0
-	33000	0
Category 1		
Category 1	20000	0
Category 1	21000	0
Category 1	9600	0
Category 1	18000	0
Category 3	210	0
Category 3	50	50
Category 3	175	0
Category 3	5	0
Category 3	20	0
Category 3	3	0
Category 1	150	75
Category 3	10	0
Category 1	600	250
Category 3	750	0
Category 3	200	50
	300	0
Category 3		
Category 3	150	140
Category 2	2250	0
Category 1	999	0
Category 1	730	0
Category 1	550	0
Category 1	30	25
Category 3	450	0
Category 3	50	50
Category 1	500	250
Category 3	150	10
Category 1	125	100
Category 3	50	50
Category 1	150	75
	10	
Category 3		0
Category 3	150	0
Category 1	200	75
Category 1	12000	0
Category 1	6000	0

0	No No No	No No Yes
	No	No
	No	No
2700		Yes
2700		Yes
18000		Yes
100000		Yes
100000		Yes
13500		Yes
5250 5250		Yes
5250		Yes Yes
21000		Yes
1923000		Yes
122000		Yes
122000		Yes
115000		Yes
33000		Yes
33000		Yes
20000	Yes	Yes
21000	Yes	Yes
9600	Yes	Yes
18000	Yes	Yes
	No	No
0	No	Yes
	No	No
	Yes	Yes
	No	No
350		Yes
	No	No
•	No	No
	No	No
	No	No
999	No You	No No
730		Yes
550		Yes
	Yes	Yes
	No	No
	No	Yes
500		No
	No	No
	Yes	Yes
	No	No
	No	Yes
0	No	No
0	No	No
125	Yes	Yes
12000		Yes
6000	Yes	Yes

Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No No Not Applicable - Spill did not reach storm drainpipe Yes Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No No

5 Cottonwood Court easaement

Easement area

Pullman Dr.

40 Shady Lane

750 El Cerrito Ave

766 El Cerrito Ave

750 El Cerrito

1600 Floribunda Ave

Crystal Springs Rd.

1050 Crystal Springs Rd.

777 El Cerrito

750 El Cerrito Ave

766 El Cerrito

777 El Cerrito

1050 Crystal Springs Rd.

Redington Easement

Crystal Springs road

Crystal Springs Road

El Cerrito Ave

El Cerrito Ave

El Cerrito

Floribunda

Hayne Road

El Cerrito Ave

El Cerrito Ave

15 Cottonwood

Hayne

Braemar Dr.

El Cerrito

550 Remillard Drive

Hillsborough Blvd.

80 Del Monte dr.

Bowhill Rd.

2235 Ralston ave

Bates

Hillsborough

Lydia

Hillsborough

cottonwood

85 Orange Court

575 Pullman Road

575 Laurent Road

Tartan Trail

560 Pullman

1020 Parrot Drive, Hillsborough. California.94010

95 Lookout Road, Hillsborough. Ca. 94010

Laurent Rd.

Hillsborough

1285 Cardigan Rd

665 Chateau Drive

405 remillard


Mountainwood Ct

Hillsborough

El Cerrito

760 El Cerrito

37.5654	122.3723 San Mateo
37.5655	122.3754 San Mateo
37.5558	122.3745 San Mateo
37.5456	122.3584 San Mateo
37.555	122.3391 San Mateo
37.555	122.3391 San Mateo
37.555	122.3391 San Mateo
37.5777	122.3557 San Mateo
37.5483	122.3464 San Mateo
37.5483	122.3464 San Mateo
37.555	122.339 San Mateo
37.55	122.3391 San Mateo
37.555	122.3391 San Mateo
37.555	122.339 San Mateo
37.5483	122.3464 San Mateo
37.5709	122.3694 San Mateo
37.5483	122.3464 San Mateo
37.5483	122.3464 San Mateo
37.555	122.339 San Mateo
37.555	122.339 San Mateo
37.555	122.339 San Mateo
37.5777	122.3557 San Mateo
37.5527	122.3588 San Mateo
37.555	122.339 San Mateo
37.555	122.3391 San Mateo
37.5654	122.3723 San Mateo
37.558	122.3439 San Mateo
37.5406	122.356 San Mateo
37.555	122.3391 San Mateo
37.5546	122.3715 San Mateo
37.566	122.3547 San Mateo
37.5739	122.3824 San Mateo
37.5548	122.3402 San Mateo
37.5691	122.3595 San Mateo
37.5551	122.3523 San Mateo
37.5608	122.3516 San Mateo
37.5394	122.3518 San Mateo
37.577	122.3655 San Mateo
37.5654	122.3723 San Mateo
37.564427	-122.369573 San Mateo
37.55772	-122.371799 San Mateo
37.558459	-122.370325 San Mateo
37.5423	122.3597 San Mateo
37.5577	122.3711 San Mateo
37.541996	-122.344059 San Mateo
37.549724	-122.359407 San Mateo
37.5587	122.3705 San Mateo
	122.3703 San Mateo
37.5384	
37.550792	-122.354728 San Mateo
37.560382	-122.371519 San Mateo
37.5522	122.3684 San Mateo
37.5454	122.3334 San Mateo
37.5507	122.3648 San Mateo
37.555	122.339 San Mateo
37.555	122.3391 San Mateo
31.333	122.3331 Salt WaleO





Gravity sewer Manhole Manhole Building or structure Gravity sewer Manhole Manhole

Manhole Manhole

Manhole

Manhole Manhole

Manhole

Other (specify)

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Other (specify)

Manhole

Manhole


Manhole

Manhole

Manhole

Manhole

Manhole



Unpaved surface

Unpaved surface

Storm drain

Building or structure

Other (specify below)

Surface water

Surface water

Storm drain

Surface water

Surface water

Storm drain

Surface water

Surface water

Surface water

Surface water

Odilace Water

Surface water

Surface water

Surface water

Storm drain

Unpaved surface

Storm drain

Unpaved surface

Other paved surface

Unpaved surface

Unpaved surface

Storm drain

Street/curb and gutter

Storm drain

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Unpaved surface

Other (specify below)

Storm drain

Storm drain

Storm drain

Unpaved surface

Other (specify below)

Other (specify below)

Unpaved surface

Storm drain

Other paved surface; Unpaved surface

Storm drain; Street/curb and gutter

Other paved surface

Unpaved surface

Storm drain

Storm drain

Storm drain

Just barely trickling out of M/H down gutter to catch basin.
Rerouted overflowing sewer to the next downstream manhole.
Heavy storm, High winds and heavy rain, creek was flowing like a river. Heavy storm, high winds and heavy rain, creek was flowing like a river. Sewer main could not handle capacity.
Sewer main is submerged fromn creek inlet being clogged, which has formed a lake.
Spilled into a dry creek Storm Drain, that leads to a dry creek
Hillside location Catch basin which is a Sediment basin, sewage was contained within the catch basin and was vaccumed out of the catc Spill went into a dry creek, clean-up will comence first thing in the morning by flushing the creek and capturing the sewag
Catch basin drains into a dry creek, 50% of sewage was captured and released back into the sanitary sewer system by va
Storm drain Storm drain captured most SSO volume and transferred almost immediatley to creek.

9/18/2007 0:00	9/18/2007 8:25	9/18/2007 8:35	9/18/2007 8:45
10/26/2007 0:00	10/26/2007 9:48	10/26/2007 10:01	10/26/2007 10:41
11/28/2007 0:00	11/28/2007 10:30	11/28/2007 10:35	11/28/2007 10:40
12/10/2007 0:00	12/10/2007 11:20	12/10/2007 11:30	12/10/2007 11:40
12/18/2007 0:00	12/18/2007 11:20	12/18/2007 11:25	12/18/2007 11:30
1/4/2008 0:00	1/4/2008 11:00	1/4/2008 11:15	1/4/2008 7:30
1/4/2008 0:00	1/4/2008 11:00	1/4/2008 11:15	1/4/2008 19:30
1/4/2008 0:00	1/4/2008 14:30	1/4/2008 14:40	1/4/2008 17:00
1/4/2008 0:00	1/4/2008 11:00	1/4/2008 11:15	1/4/2008 19:30
1/4/2008 0:00	1/4/2008 11:00	1/4/2008 11:15	1/4/2008 19:30
1/4/2008 0:00	1/4/2008 11:00	1/4/2008 11:15	1/4/2008 19:30
1/5/2008 0:00	1/5/2008 14:50	1/5/2008 15:00	1/5/2008 18:00
1/5/2008 0:00	1/5/2008 14:50	1/5/2008 15:00	1/5/2008 18:00
1/5/2008 0:00	1/5/2008 14:50	1/5/2008 15:00	1/5/2008 18:00
1/5/2008 0:00	1/5/2008 14:50	1/5/2008 15:00	1/5/2008 18:00
1/25/2008 0:00	1/26/2008 15:00	1/26/2008 15:30	1/28/2008 21:00
1/25/2008 0:00	1/25/2008 11:20	1/25/2008 11:30	1/25/2008 22:00
1/25/2008 0:00	1/25/2008 11:20	1/25/2008 11:30	1/25/2008 22:00
1/25/2008 0:00	1/25/2008 11:20	1/25/2008 11:30	1/25/2008 22:00
1/25/2008 0:00	1/25/2008 11:20	1/25/2008 11:30	1/25/2008 22:00
1/25/2008 0:00	1/25/2008 11:20	1/25/2008 11:30	1/25/2008 22:00
1/25/2008 0:00	1/25/2008 17:25	1/25/2008 17:40	1/25/2008 21:00
1/25/2008 0:00	1/25/2008 14:20	1/25/2008 14:35	1/25/2008 21:00
2/3/2008 0:00	2/3/2008 9:45	2/3/2008 9:55	2/3/2008 11:30
2/3/2008 0:00 3/4/2008 0:00	2/3/2008 9:45 3/4/2008 12:45	2/3/2008 9:56 3/4/2008 12:50	2/3/2008 11:30
3/8/2008 0:00	3/8/2008 14:15	3/8/2008 14:30	3/4/2008 13:00 3/8/2008 14:50
1/4/2008 0:00	1/4/2008 0:00	1/4/2008 0:00	1/4/2008 0:00
3/17/2008 0:00	3/17/2008 0:00	3/17/2008 0:00	3/17/2008 0:00
4/14/2008 0:00	4/14/2008 0:00	4/14/2008 0:00	4/14/2008 0:00
5/12/2008 0:00	5/12/2008 9:30	5/12/2008 9:35	5/12/2008 0:00
6/9/2008 0:00	6/9/2008 12:05	6/9/2008 12:10	6/9/2008 12:30
6/23/2008 0:00	6/23/2008 8:00	6/23/2008 8:10	6/23/2008 8:15
7/6/2008 0:00	7/6/2008 13:00	7/6/2008 13:15	7/6/2008 14:15
8/9/2008 0:00	8/9/2008 16:30	8/9/2008 16:30	8/9/2008 19:00
8/11/2008 0:00	8/11/2008 11:30	8/11/2008 11:40	8/11/2008 12:30
8/13/2008 0:00	8/13/2008 8:15	8/13/2008 8:30	8/13/2008 9:30
8/18/2008 0:00	8/18/2008 9:20	8/18/2008 9:25	8/18/2008 9:30
8/22/2008 0:00	8/22/2008 10:15	8/22/2008 10:15	8/22/2008 11:45
8/30/2008 0:00	8/30/2008 6:30	8/30/2008 7:00	8/30/2008 8:45
8/31/2008 0:00	8/31/2008 13:00	8/31/2008 13:20	8/31/2008 16:00
8/31/2008 0:00	8/31/2008 16:00	8/31/2008 16:10	8/31/2008 18:00
10/2/2008 0:00	10/2/2008 10:05	10/2/2008 10:10	10/2/2008 10:10
10/9/2008 0:00	10/9/2008 14:00	10/9/2008 14:10	10/9/2008 14:40
10/11/2008 0:00	10/11/2008 1:45	10/11/2008 2:05	10/11/2008 2:25
10/12/2008 0:00	10/12/2008 18:30	10/12/2008 19:00	10/12/2008 21:30
10/19/2008 0:00	10/19/2008 17:50	10/19/2008 18:30	10/19/2008 18:45
11/25/2008 0:00	11/25/2008 7:35	11/25/2008 7:40	11/25/2008 7:50
12/7/2008 0:00	12/7/2008 11:00	12/7/2008 11:10	12/7/2008 11:15
12/27/2008 0:00	12/27/2008 9:00	12/27/2008 9:15	12/27/2008 9:27
1/2/2009 0:00	1/2/2009 12:15	1/2/2009 12:18	1/2/2009 12:00
1/21/2009 9:00	1/21/2009 9:10	1/21/2009 9:15	1/21/2009 9:45
1/24/2009 12:25	1/24/2009 12:30	1/24/2009 12:35	1/24/2009 12:50
2/15/2009 0:00	2/15/2009 9:00	2/15/2009 9:15	2/15/2009 13:00
2/15/2009 9:00	2/15/2009 9:00	2/15/2009 9:15	2/15/2009 13:00

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Debris

Flow exceeded capacity

Other (specify below)

Flow exceeded capacity

Other (specify below)

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Grease deposition (FOG)

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Debris

Grease deposition (FOG)

Other (specify below)

Root intrusion

Debris

Root intrusion

Root intrusion

Root intrusion

Flow exceeded capacity

Flow exceeded capacity

Heavy thunder storms. Heavy thunder storms.
Creek inlet plugged up causing a lake to form and submerged our sewer main by about 15' of water. Main could not hand
swifter towels, clogging mouth of channel.
swifter towels
Lots of papers
Root intrusion and heavy paper debris Line had already freed itself by the time we got their.
1030 Parrot Drive had a plumber clearing blockage out of residents lateral on Thursday, October 9, 2008, and appears the
papers

le all the creek water and caused manhole's to Main Other (specify below) Main Other (specify below)



```
6 clay
```

- 6 clay
- 6 liner
- 6 clay
- 8 clay
- 8 clay
- 8 clay
- 15 clay
- 15
- 15
- 15 clay
- 8 clay
- 8 clay
- 15 clay
- 15 liner
- 6 clay
- 15 Liner
- 15 Liner
- 15 clay
- 8 clay
- 8 clay
- clay
- 8 clay
- 15 clay
- 8 clay
- 6 clay
- 6 liner
- 6 clay
- 6 clay
- 6 clay
- 6 clay

6

- 6 clay
- 6 VCP
- 6 VCP
- 6 VCP
- 6 clay
- 6 уср
- 6 CIPP-Lined VCP
- 6 VCP
- 6 liner
- 6 vcp
- 6 VCP
- 6 VCP
- 6 clay
- 6 vcp
- 15 HDPE
- 8 clay

50 5

44

45

45

15 45

45 45

32


44

2

35

Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill) Restored flow Returned all or portion of spill to sanitary sewer system Other (specify below) Other (specify below) Cleaned-up (mitigated effects of spill) Other (specify below) Other (specify below) Other (specify below) Cleaned-up (mitigated effects of spill) Other (specify below) Cleaned-up (mitigated effects of spill) Contained all or portion of spill Cleaned-up (mitigated effects of spill) Restored flow Restored flow Restored flow Restored flow Contained all or portion of spill Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Restored flow; Other (specify below) Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Restored flow Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill)



11/28/2007 0:00
1/4/2008 8:30 1/4/2008 20:30 1/4/2008 18:30 1/4/2008 20:30 1/4/2008 20:30 1/4/2008 20:30 1/4/2008 9:00 1/7/2008 9:00 1/7/2008 9:00 1/7/2008 9:00 1/7/2008 9:00 1/28/2008 18:00 1/28/2008 9:00 1/28/2008 9:00 1/28/2008 9:00 1/28/2008 9:00 1/28/2008 9:00 1/28/2008 9:00 1/28/2008 9:00 1/25/2008 9:00 1/25/2008 8:40 2/4/2008 8:40 2/4/2008 8:40
3/8/2008 15:30
6/9/2008 12:40 7/6/2008 14:00
8/22/2008 11:45 8/30/2008 8:45 8/31/2008 16:00 8/31/2008 18:00 10/2/2008 10:44
10/13/2008 17:00
11/25/2008 8:20
12/27/2008 9:45
1/24/2009 13:30 2/15/2009 13:00 2/15/2009 13:00

Other (specify below) Plan rehabilitation or replacement of sewer Other (specify below) Other (specify below) Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Other (specify below) Adjusted schedule/method of preventive maintenance Other (specify below) Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance; Plan rehabilitatic Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer

Will TV main line to see why their is root intrusion on the new liner. Future upgrade of sewer main when all responsible parties and Water Regional Board can come up with an agreement. Future upgrade of sewer main when all responsible agencies and Water Regional Board can come up with an agreement To much heavy rain and runoff. Futre upgrade of sewer main when all cities and Regional Board can come up with an agreement. Future upgrade of sewer main when all cities and Water Regional Board can come up with an agreemnt. Future upgrade of sewer main when all agencies and Water Regional Board can come up with an agreement. Once all Responsible agencies and the Water Regional Board can come up with an agreement. Then we can do a future Future upgrade of sewer main when all responsible agencies, and the Water Board can come up with an agreement. Future upgrade of sewer main when all responsible agencies, and the Water Board can come up with an agreement. Future upgrade of sewer main when all responsible agencies, and Water Board can come to an agreement. To try and keep creek inlet pipes free and clear from flowing debri. When all responsible agencies and the Regional Water Board can come up with an agreement. When all responsible agencies and the Water Regional Board can come up with an agreement. When all responsible agencies and the Water Regional Board can come to an agreement. When all responsible agencies and Regional Water Board can come up with an agreement. When all responsible agencies and the Water Regional Board can come to an agreement. To much heavy rain and runoff. Checking sewer lift station pump data, to see why they were having trouble keeping up with the flow, even though it was r When all responsible agencies and the Water Regional Board can come up with an agreemnt. When All Responsible Agencies And The Water Regional Board Can Come Up With An Agreement. Will be adding Smartcover device to manhole. Will foam this section of pipe.

Line to rodded every six months and be included in foaming program spring 2009. Main scheduled for replacement by 2013.

No Yes No No No No No No Yes No No Yes No No No No No No No No

No

No

No No No

ED_006495_00001080-02509

Creek flowing like a river. Creek flowing like a river and very dangerous.
Creek was clean and flowing like a river. Creek was clean and flowing like a river.
Creek was running full and clear. Creek was running full and clear. Creek was running full and clear. Creek was running clear and full.
Did not reach the waters of the state Sewage is contained in a dry creek, no flow of water is in the creek, sewage was cleaned up at daylight of Monday, Octob
Did not impact receiving waters.
SSO was quickly diluted by creek with heavy flows from the storm. SSO was quickly diluted by creek which had heavy flows from storm.

No No

No

No

No No

No No

No

No

No

No

No Yes

Yes

N/A

NA NA

NA

NA

NA

N/A

N/A

NA

NΑ

N/A

n/a

NA NA

NA

NA

NA

NA

NA

N/A

N/A

N/A

San Mateo Creek San Mateo Creek N/A San Mateo Creek Redington Creek San Mateo Creek NA NA

San Mateo Creek San Mateo Creek

N/A

na

NA

n/a

n/a

NA

NA NA

NA

NA

NA

NA

San Mateo Creek San Mateo Creek

Not applicable to this spill

No water quality samples taken No water quality samples taken Not applicable to this spill No water quality samples taken No water quality samples taken

No water quality samples taken

No water quality samples taken

No water quality samples taken

No water quality samples taken Not applicable to this spill Not applicable to this spill Not applicable to this spill No water quality samples taken

Not applicable to this spill

Not applicable to this spill

Not applicable to this spill

Not applicable to this spill No water quality samples taken No water quality samples taken



None of the above No water quality samples taken No water quality samples taken None of the above

None of the above Not applicable to this spill Not applicable to this spill Not applicable to this spill None of the above

None of the above

None of the above

None of the above

None of the above None of the above None of the above





80155 80156 80157 80153 80152 80154 8252 8251 80250 80249 80842 80767 80768 80770 80771 80773 80774 81061 81062	1/5/2008 10:00 1/5/2008 10:00 1/5/2008 10:00 1/5/2008 10:00 1/5/2008 10:00 1/5/2008 10:00 1/5/2008 10:00 1/7/2008 15:15 1/7/2008 15:15 1/7/2008 15:15 1/7/2008 15:15 1/28/2008 14:30 1/26/2008 14:00 1/26/2008 14:10 1/26/2008 14:20 1/26/2008 14:22 1/26/2008 14:25 1/26/2008 14:27 2/4/2008 10:00
84109	6/9/2008 13:54
84959 85781 85824 85877 86035 86139 86349 86370 86376 87127 87322 87358 87373 87547 88428 88752 89168	8/9/2008 19:20 8/11/2008 16:15 8/13/2008 9:50 8/18/2008 16:00 8/22/2008 16:15 8/30/2008 9:30 8/31/2008 17:53 8/31/2008 17:58 10/2/2008 11:30 10/9/2008 16:20 10/11/2008 0:00 10/20/2008 9:15 11/25/2008 9:24 12/8/2008 9:25 12/27/2008 10:59
90627 90739 91284 91285	1/21/2009 16:10 1/24/2009 14:53 2/15/2009 10:47 2/15/2009 10:47

2SSO10142	Active	733560 Tony Geraldi	Certified
2SSO10142	Active	733979 Tony Geraldi	Certified
2SSO10142	Active	734285 Tony Geraldi	Certified
2SSO10142	Active	734400 Tony Geraldi	Certified
2SSO10142	Active	734417 thomas barry	Certified
2SSO10142	Active	734451 Tony Geraldi	Certified
2SSO10142	Active	734541 Tony Geraldi	Certified
2SSO10142	Active	736313 TONY GERALDI	Certified
2SSO10142	Active	736552 Tony Geraldi	Certified
2SSO10142	Active	736555 Tony Geraldi	Certified
2SSO10142	Active	736926 Tony Geraldi	Certified
2SSO10142	Active	737067 Tony Geraldi	Certified
2SSO10142	Active	737294 Tony	Certified
2SSO10142	Active	740158 Tony Geraldi	Certified
2SSO10142	Active	740878 Tony Geraldi	Certified
2SSO10142	Active	742501 Tony Geraldi	Certified
2SSO10142	Active	743066 Tony Geraldi	Certified
2SSO10142	Active	743081 Tony Geraldi	Certified
2SSO10142	Active	745653 Tony Geraldi	Certified
2SSO10142	Active	745740 Tony Geraldi	Certified
2SSO10142	Active	746282 Tony Geraldi	Certified
2SSO10142	Active	746575 Tony Geraldi	Certified
2SSO10142	Active	746603 Tony Geraldi	Certified
2SSO10142	Active	746867 Tony Geraldi	Certified
2SSO10142	Active	747143 Tony Geraldi	Certified
2SSO10142	Active	747254 Tony Geraldi	Certified
2SSO10142	Active	748420 Tony Geraldi	Certified
2SSO10142	Active	748455 Tony Geraldi	Certified
2SSO10142	Active	748523 Tony Geraldi	Certified
2SSO10142	Active	748768 Tony Geraldi	Certified
2SSO10142	Active	748979 Tony Geraldi	Certified
2SSO10142	Active	749275 Tony Geraldi	Certified
2SSO10142	Active	749717 Tony Geraldi	Certified
2SSO10142	Active	750816 Tony Geraldi	Certified
2SSO10142	Active	751548 Tony Geraldi	Certified
2SSO10142	Active	751735 Tony Geraldi	Certified
2SSO10142	Active	751779 Tony Geraldi	Certified
2SSO10142	Active	751782 Tony Geraldi	Certified
2SSO10142	Active	753209 Tony Geraldi	Certified
2SSO10142	Active	753282 Tony Geraldi	Certified
2SSO10142	Active	753734 Tony Geraldi	Certified
2SSO10142	Active	754030 Tony Geraldi	Certified
2SSO10142	Active	755704 Tony Geraldi	Certified
2SSO10142	Active	756104 Tony Geraldi	Certified
2SSO10142	Active	756885 Tony Geraldi	Certified
2SSO10142	Active	757190 Tony Geraldi	Certified
2SSO10142	Active	758189 Tony Geraldi	Certified
2SSO10142	Active	759202 Tony Geraldi	Certified
2SSO10142	Active	759541 Tony Geraldi	Certified
2SSO10142	Active	759555 Tony Geraldi	Certified
2SSO10142	Active	759635 Tony Geraldi	Certified
2SSO10142	Active	759637 Tony Geraldi	Certified
2SSO10142	Active	759936 Tony Geraldi	Certified
2SSO10142	Active	760003 Tony Geraldi	Certified
2SSO10142	Active	760004 Tony Geraldi	Certified

- Supervisor
- Supervisor
- Supervisor
- Supervisor
- public works
- Supervisor
- Supervisor
- Ouper visor
- SUPERVISOR
- Supervisor
- Supervisor
- Supervisor
- Supervisor
- Geraldi
- Supervisor
- aportion
- Supervisor
- Oaporvisor
- Supervisor
- Supervisor Supervisor
- Supervisor
- Supervisor
- Supervisor

	12:25	206011
	14:41	106016
	9:08	446551
	11:07	930075
home		343703
	10:42	671986
	10:50	752911
	12:22	373984
	16:11	430445
	15:41	278353
	11:50	490408
	16:04	524764
	11:43	277458
	13:45	753150
	15:22	289342
	12:29	787734
	12:38	797932
	12:45	989702
	16:30	817936
	16:16	515853
	15:54	287864
	10:23	107111
	10:37	660365
	10:41	677960
	10:16	982348
	10:44	319502
9:17 A.M.	10.44	706014
V.11 / L.M.	10:10	553954
	10:04	551414
	9:57	912826
	9:32	165555
	9:28	272249
	9:24	380483
	9:17	195246
	8:55	525809
	9:10	494388
	8:47	647320
	8:39	545755
	8:29 AM	589463
	8:33 AM	944894
	8:37 AM	199048
	8:42 AM	590702
	8:21 AM	134078
	8:16 AM	457168
	12:13	762306
	12:19	506078
	12:23	353523
	12:36	724172
	10:36	348413
	10:47	643426
	11:51	657269
	11:36	304336
3:31 P.M.	11.50	914478
8:10 A.M.		397641
9:03 A.M.		870981
O,OO A.IVI.		010901

16-Feb-09		24-Feb-09	2/24/2009
23-Feb-09		24-Feb-09	2/24/2009
27-Feb-09		22-May-09	5/22/2009
27-Feb-09		22-May-09	5/22/2009
28-Feb-09		28-Feb-09	2/28/2009
2-Mar-09		22-May-09	5/22/2009
3-Mar-09		22-May-09	5/22/2009
14-Apr-09		10-Dec-09	12/10/2009
21-Apr-09		19-May-09	5/19/2009
21-Apr-09		19-May-09	5/19/2009
28-Apr-09		19-May-09	5/19/2009
4-May-09		19-May-09	5/19/2009
11-May-09		19-May-09	5/19/2009
29-Jun-09		29-Jun-09	6/29/2009
8-Jul-09		30-Jul-09	7/30/2009
5-Aug-09		10-Dec-09	12/10/2009
14-Aug-09		10-Dec-09	12/10/2009
14-Aug-09		10-Dec-09	12/10/2009
15-Oct-09		2-Nov-09	11/2/2009
19-Oct-09		2-Nov-09	11/2/2009
28-Oct-09		2-Nov-09	11/2/2009
5-Nov-09		21-Jan-10	1/21/2010
5-Nov-09		21-Jan-10	1/21/2010
19-Nov-09		21-Jan-10	1/21/2010
27-Nov-09		21-Jan-10	1/21/2010
2-Dec-09		21-Jan-10	1/21/2010
19-Jan-10		1-Feb-11	2/1/2011
20-Jan-10		26-May-10	5/26/2010
21-Jan-10		26-May-10	5/26/2010
25-Jan-10		26-May-10	5/26/2010
1-Feb-10		26-May-10	5/26/2010
10-Feb-10		26-May-10	5/26/2010
23-Feb-10		26-May-10	5/26/2010
21-Mar-10		26-May-10	5/26/2010
13-Apr-10		26-May-10	5/26/2010
15-Apr-10		26-May-10	5/26/2010
20-Apr-10		26-May-10	5/26/2010
20-Apr-10		26-May-10	5/26/2010
8-Jun-10	6/8/2010	18-Aug-10	8/18/2010
10-Jun-10	6/10/2010	18-Aug-10	8/18/2010
22-Jun-10	6/22/2010	18-Aug-10	8/18/2010
28-Jun-10	6/28/2010	18-Aug-10	8/18/2010
3-Aug-10	8/18/2010	18-Aug-10	8/18/2010
17-Aug-10	8/17/2010	18-Aug-10	8/18/2010
19-Sep-10	9/19/2010	22-Dec-10	12/22/2010
27-Sep-10	9/27/2010	22-Dec-10	12/22/2010
27-Oct-10	10/27/2010	22-Dec-10	12/22/2010
9-Dec-10	12/9/2010	22-Dec-10	12/22/2010
18-Dec-10	12/18/2010	22-Dec-10	12/22/2010
19-Dec-10	12/19/2010	22-Dec-10	12/22/2010
20-Dec-10	12/20/2010	22-Dec-10	12/22/2010
20-Dec-10	12/20/2010	22-Dec-10	12/22/2010
28-Dec-10	12/28/2010	28-Dec-10	12/28/2010
30-Dec-10	12/30/2010	30-Dec-10	12/30/2010
30-Dec-10	12/30/2010	30-Dec-10	12/30/2010

		_
Category 1	9900	0
Category 1	3000	0
Category 3	850	0
Category 3	50	50
Category 3	45	0
Category 1	1200	0
Category 1	3000	0
Category 3	40	0
Category 3	20	3
Category 3	40	10
Category 3	20	0
Category 3	100	75
Category 3	30	5
Category 3	25	10
Category 3	25	10
Category 1	750	500
Category 3	75	25
	500	450
Category 3	12000	
Category 1		0
Category 3	100	100
Category 3	3	0
Category 3	35	10
Category 3	65	10
Category 3	5	2
Category 3	50	0
Category 3	15	5
Category 1	22500	0
Category 1	38250	5000
Category 1	74400	1000
Category 1	108000	67200
Category 3	25	8
Category 3	100	0
Category 3	250	5
Category 2	6000	100
Category 1	9000	7000
Category 3	30	10
Category 3	80	20
Category 1	450	0
Category 3	20	Ŏ
Category 3	30	10
Category 3	80	0
	20	5
Category 3		
Category 3	225	0
Category 3	40	35
Category 1	535	0
Category 3	2	0
Category 3	30	5
Category 1	1200	0
Category 1	1350	0
Category 1	135000	121500
Category 1	2775	0
Category 1	2900	0
Category 1	46500	41850
Category 1	37500	0
Category 2	12000	0
• •		

9900	Yes	Yes
3000		Yes
	No	No
0	Yes	Yes
0	No	No
1200		Yes
3000		Yes
0	No	No
0	No	No
Ω	No	No
	No	No
0	No	Yes
0	No	No
0	No	No
	No	No
250	Yes	Yes
0	No	No
0	No	No
12000		Yes
	No	Yes
0	No	No
0	No	No
0	No	No
	No	No
0	No	No
0	No	No
22500	Yes	Yes
33250	Yes	Yes
	Yes	Yes
40800		
		Yes
	No	No
0	No	No
0	No	No
0	No	Yes
2000		Yes
	No	No
	No	Yes
450	Yes	Yes
0	No	No
0	No	No
	No	No
	No	No
0	No	No
0	No	No
535	No	Yes
	No	No
	No	No
1200		Yes
1350	Yes	Yes
13500	Yes	No
2775		Yes
2900		
		Yes
4650		Yes
37500		Yes
0	No	Yes

No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Yes Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Yes Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No Not Applicable - Spill did not reach storm drainpipe No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe No No No No

No

1040 Crystal Springs

El Cerrito Rd.

Hillsborough

Hillsborough

45 Willard av

777 El Cerrito

manhole

Hillsborough

Hillsborough

Hillsborough

Hillsborough

745 Clydesdale Dr.

Hillsborough

1460 Buckingham Way

Hillsborough

777 el cerrito ave manhole

777 El Cerrito Ave manhole

Hillsborough

Hillsborough

Hillsborough

Hillsborough

HILLSBOROUGH

1835 Willow Road

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

810 Darrell Road

Hillsborough

35 Brooke Court

Hillsborough

Hillsborough

Hillsborough

720 Chateau Drive

777 El Cerrito Avenue

1980 Forrestview Drive

1110 Hayne Road

Hillsborough

1040 Crystal Springs Rd/ Merner

Hillsborough

37.5483	122.3464 San Mateo
37.555	122.339 San Mateo
37.5628	-122.3727 San Mateo
37.5696	-122.3619 San Mateo
37.555638	122.349465 San Mateo
37.555	-122.339 San Mateo
37.555	-122.339 San Mateo
37.5648	-122.3593 San Mateo
37.5717	-122.3555 San Mateo
37.5594	-122.3794 San Mateo
37.574	-122.3692 San Mateo
37.547491	-122.331186 San Mateo
37.5533	-122.3692 San Mateo
37.5476	-122.359 San Mateo
37.555	-122.339 San Mateo
37.5691	-122.3595 San Mateo
37.5317	-122.3585 San Mateo
37.5337	-122.3547 San Mateo
37.55301	-122.33993 San Mateo
37.5576	-122.35921 San Mateo
37.55308	-122.37052 San Mateo
37.57076	-122.37535 San Mateo
37.55961	-122.36885 San Mateo
37.55534	-122.3401 San Mateo
37.535938	-122.354681 San Mateo
37.53957	-122.35525 San Mateo
37.5549	-122.339 San Mateo
37.5549	-122.339 San Mateo
37.55293	-122.33952 San Mateo
37.55293	-122.33952 San Mateo
37.56332	-122.36561 San Mateo
37.55021	-122.34082 San Mateo
37.54769	-122.34279 San Mateo
37.5756	-122.363244 San Mateo
37.55293	-122.33952 San Mateo
37.56753	-122.35758 San Mateo
37.5736	-122.37987 San Mateo
37.55586	-122.33881 San Mateo
37.55956	-122.34379 San Mateo
37.5556	-122.34169 San Mateo
37.55431	-122.35663 San Mateo
37.57458	-122.36772 San Mateo
37.559409	-122.379449 San Mateo
37.55433	-122.33943 San Mateo
37.534855	-122.34128 San Mateo
37.55224	-122.35019 San Mateo
37.55556	-122.37061 San Mateo
37.55327	-122.33974 San Mateo
37.557681	-122.374011 San Mateo
37.554773	-122.339023 San Mateo
37.578052	-122.366013 San Mateo
37.55389	-122.357182 San Mateo
37.55433	-122.33943 San Mateo
37.54868	-122.3461 San Mateo
37.57734	-122.36735 San Mateo
	indico

Easement area

manhole

End of driveway in the easement area.

In dirt parking strip area.

In easement location.

Backyard

Manhole behind 745 Clydesdale Drive, in easement, surcharged and spilled into landscape area where some of sewage v Easement area in backyard.

Street

In easement area.

Parking strip area off road way.

Behind property on Crystal Springs Drive.

Behind property on Crystal Springs Rd.

Road Shoulder

Corporation yard wash rack area.

Parking strip area.

Easement, firetrail area.

Easement area inside property.

Homeowners Yard

Easement behind 1460 Buckingham Way, sewer main runs along backside of property.

Manhole

manhole

manhole

Road Shoulder

Road Shoulder

Road shoulder

Roadway

PRIVATE DRIVEWAY MANHOLE OVER FLOW

Manhole in front of 1835 Willow Road, sewage was discharging at an approximate rate of 5 gpm. Total gallons reported w

Road Shoulder

Backyard easement

Roadway

San Mateo Creek

Easement area

backyard cleanout

Spill was located in an easement on a flat grassy area. The sewage did not reach any drainage channel, it ponded in the a Road shoulder

Spill discharged out of a manhole in front of 35 Brooke Court. Approximately 535 gallons discharged out of the manhole &

Manhole in Ithe intersection.

Road shoulder/spill happened in the middle of the night., not overflowing when I found it. Water was below the manhole r Spill discharged out of a manhole in front of 720 Chateau Drive in the roadway.

Spill discharged out of a manhole in front of 777 El Cerrito Avenue, Hillsborough,, in the roadway, Hillsborough Sewer Div Spill discharged out of a manhole in the roadway in front of 1980 Forrestview Drive during a major rain event (storm).

Spill discharged out of a manhole in the roadway in front of 1110 Hayne Road due to a major rain event (storm), the flow Road shoulder

Road shoulder

Manhole in the middle of the roadway in front of 1980 Forestview.



Manhole

Gravity sewer

Gravity sewer

Manhole

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Gravity sewer

Other (specify)

Manhole

Other sewer system structure

Gravity sewer

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Gravity sewer; Manhole

Manhole

Gravity sewer; Manhole

Manhole

Manhole

Manhole

Manhole water sitting on top of manhole lid. Manhole in hilly eaesement area. Steep terrain, can not get equipment back there. Same as above Manhole behind 745 Clydesdale Drive, in easement. See above Wet spot in the street. see above Wash rack grate that is tied into lift station pit. See above See above Seeping out of ground on trail. Cleanout see above M/H See above see above See above See #16-Spill Location Description See above See above See above see above This manhole has a SMART cover device to alarm for surcharges, although the antenna is defective and has been on orc See above See above See above

Surface water

Surface water

Unpaved surface

Storm drain

Unpaved surface

Storm drain

Storm drain

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Storm drain; Street/curb and gutter; Unpaved surface

Unpaved surface

Other paved surface

Unpaved surface

Storm drain

Other paved surface

Street/curb and gutter

Surface water

Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Separate storm drain

Storm drain

Surface water

Surface water

Unpaved surface

Other paved surface

Unpaved surface

Storm drain

Surface water

Unpaved surface

Storm drain

Surface water

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Separate storm drain

Other paved surface

Other paved surface

Surface water

Other (specify below)

Street/curb and gutter; Other (specify below)

Separate storm drain

Separate storm drain; Surface water

Surface water

Surface water

Unpaved surface

Flow traveled from manhole to side of road and down embankment to San Mateo Creek. Bulk of volume enterd San Ma SSO transfered to stormdrain and into creek.
City easement area.
Vaccumed out of catch basin and returned to the sanitary sewer system.

Easement area in the dirt.
Dirt parking strip area.

Backyard easement area.

Trickeled out in easment area.

Back in lift station pit. In dirt parking strip area. On Firetrail easement area. Easement area dirt trail.

Spill discharged onto neighbors hillside onto dirt, where 100% of sewage water soaked into the dirt and grey matter (toilet See above

Flow exceeding capacity. Bypassing about 80% of surcharge to the downstream manhole which was about seventy perce Cleaned up disinfected area after removing top soil.

SPILLED FROM DRIVEWAY TO UNPAVED SURFACE

See above

Grass in backyard

Soaked into the ground at the end of the storm drain outfall pipe.

See above

See above

See above

Easement

See above

See #16-Spill Location Description

See above

Dry seasonal creek

See above

See above

Private lake, Crocker Lake, in Hillsborough. This lake is used strictly for irrigation for the Burlingame Country Club Golf C 10% of the sewage not recovered was washed down with rain water in the gutters during periods of rain, estimating the vo

Cherry Creek in Hillsborough

About 10% of sewage mixed with rain water that was not recovered went down storm sewer to the creek. About 90% of se Flow exceeded capacity durinfg heavy rain event.

SSO flowed into unpaved swale along side of the roadway.

2/15/2009 0:00	2/15/2009 16:30	2/15/2009 16:50	2/15/2009 22:00	
2/22/2009 0:00	2/22/2009 14:25	2/22/2009 14:40	2/22/2009 16:30	
2/26/2009 16:15	2/26/2009 16:20	2/26/2009 16:30	2/26/2009 16:45	
2/27/2009 11:15	2/27/2009 11:18	2/27/2009 11:20	2/27/2009 11:25	
2/28/2009 12:30	2/28/2009 12:35	2/28/2009 13:00	2/28/2009 13:15	
3/2/2009 11:15	3/2/2009 11:30	3/2/2009 11:50	3/2/2009 15:15	
3/3/2009 14:45	3/3/2009 14:45	3/3/2009 14:45	3/3/2009 16:45	
4/13/2009 8:35	4/13/2009 8:45	4/13/2009 8:58	4/13/2009 9:10	
4/20/2009 7:55	4/20/2009 8:15	4/20/2009 8:20	4/20/2009 8:30	
4/20/2009 9:15	4/20/2009 9:30	4/20/2009 9:40	4/20/2009 9:55	
4/28/2009 10:45	4/28/2009 10:45	4/28/2009 10:50	4/28/2009 11:00	
5/3/2009 17:50	5/3/2009 17:50	5/3/2009 18:20	5/3/2009 19:50	
5/10/2009 12:30	5/10/2009 13:00	5/10/2009 13:25	5/10/2009 14:00	
6/28/2009 18:35	6/28/2009 18:40	6/28/2009 19:00	6/28/2009 19:05	
7/8/2009 11:45	7/8/2009 11:59	7/8/2009 12:12	7/8/2009 12:15	
8/4/2009 12:15	8/4/2009 12:18	8/4/2009 12:20	8/4/2009 12:30	
8/13/2009 4:00	8/13/2009 4:00	8/13/2009 4:10	8/13/2009 4:15	
8/14/2009 10:10	8/14/2009 14:30	8/14/2009 10:10	8/14/2009 10:20	
10/13/2009 0:00	10/13/2009 13:30	10/13/2009 13:45	10/13/2009 15:30	
10/13/2009 13:10	10/13/2009 13:15	10/13/2009 13:15	10/13/2009 13:20	
10/26/2009 15:05	10/26/2009 15:15	10/26/2009 15:20	10/26/2009 15:27	
10/31/2009 10:00	10/31/2009 10:05	10/31/2009 10:30	10/31/2009 10:47	
11/4/2009 15:45	11/4/2009 16:00	11/4/2009 16:20	11/4/2009 17:50	
11/17/2009 15:20	11/17/2009 15:25	11/17/2009 15:30	11/17/2009 16:00	
11/26/2009 17:00	11/26/2009 18:00	11/26/2009 18:25	11/26/2009 18:35	
11/23/2009 9:50	11/23/2009 9:50	11/23/2009 9:55	11/23/2009 10:05	
1/19/2010 0:00	1/19/2010 6:30	1/19/2010 7:30	1/19/2010 11:30	
1/19/2010 0:00	1/19/2010 15:00	1/19/2010 7:30	1/19/2010 15:00	
1/20/2010 0:00	1/20/2010 7:30	1/20/2010 8:00	1/20/2010 15:00	
1/21/2010 0:00	1/21/2010 9:15	1/21/2010 9:15	1/23/2010 11:00	
1/30/2010 8:47	1/30/2010 9:05	1/30/2010 9:25	1/30/2010 9:40	
2/10/2010 7:45	2/10/2010 7:46	2/10/2010 7:53	2/10/2010 8:05	
2/23/2010 9:35	2/23/2010 9:35	2/23/2010 9:40	2/23/2010 9:45	
3/20/2010 12:00	3/21/2010 9:00	3/21/2010 9:25	3/21/2010 9:45	
4/12/2010 0:00	4/12/2010 14:15	4/12/2010 14:30	4/12/2010 17:00	
4/6/2010 15:55	4/6/2010 16:15	4/6/2010 16:22	4/6/2010 16:33	
4/17/2010 15:00	4/17/2010 15:30	4/17/2010 15:55	4/17/2010 17:00	
4/17/2010 11:00	4/17/2010 11:15	4/17/2010 11:44	4/17/2010 12:30	
6/8/2010 0:00	6/8/2010 10:00	6/8/2010 10:09	6/8/2010 10:25	
6/7/2010 0:00	6/7/2010 16:15	6/7/2010 16:20	6/7/2010 16:40	
6/21/2010 0:00	6/21/2010 17:05	6/21/2010 17:10	6/21/2010 21:15	
6/28/2010 0:00	6/28/2010 9:15	6/28/2010 9:25	6/28/2010 9:50	
8/2/2010 0:00	8/2/2010 6:10	8/2/2010 6:35	8/2/2010 6:55	
8/17/2010 0:00	8/17/2010 9:25	8/17/2010 9:35	8/17/2010 9:47	
9/19/2010 0:00	9/19/2010 17:00	9/19/2010 17:55	9/19/2010 18:17	
9/27/2010 0:00	9/27/2010 15:05	9/27/2010 15:15	9/27/2010 0:15	
10/20/2010 0:00	10/20/2010 14:35	10/20/2010 14:40	10/20/2010 14:45	
12/8/2010 0:00	12/9/2010 6:05	12/9/2010 6:05	12/9/2010 1:30	
12/18/2010 14:18	12/18/2010 14:18	12/18/2010 14:55	12/18/2010 15:12	
12/19/2010 0:00	12/19/2010 6:55	12/19/2010 6:55	12/19/2010 20:05	
12/19/2010 0:00	12/19/2010 7:44	12/19/2010 7:44	12/19/2010 9:35	
12/19/2010 0:00	12/19/2010 8:20	12/19/2010 8:20	12/19/2010 10:16	
12/25/2010 0:00	12/25/2010 15:45	12/25/2010 16:05	12/25/2010 23:59	
12/28/2010 0:00	12/28/2010 18:15	12/28/2010 18:15	12/29/2010 1:00	
12/28/2010 0:00	12/28/2010 22:55	12/28/2010 22:55	12/28/2010 12:40	

Flow exceeded capacity

Flow exceeded capacity

Root intrusion

Grease deposition (FOG)

Root intrusion

Flow exceeded capacity

Flow exceeded capacity

Grease deposition (FOG)

Debri-Rags

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Root intrusion

Debri-General

Debri-General

Flow exceeded capacity

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Debri-General

Debri-General

Flow exceeded capacity (Separate CS Only)

Flow exceeded capacity

Flow exceeded capacity

Flow exceeded capacity

Debri-Rags

Debri-General

Debri-Rags

Debri-General

Flow exceeded capacity

Grease deposition (FOG)

Root intrusion

Debri-General

Pipe structural problem/failure

Root intrusion

Root intrusion

Root intrusion

Debri-Rags

Debri-Rags

Grease deposition (FOG)

Root intrusion

Root intrusion

Flow exceeded capacity (Seperate CS Only)

Debri-General

Flow exceeded capacity (Seperate CS Only)

Flow exceeded capacity (Seperate CS Only)

Flow exceeded capacity (Seperate CS Only)

Rainfall exceeded design (Seperate CS Only)

Flow exceeded capacity (Seperate CS Only)

Flow exceeded capacity (Seperate CS Only)

Moderate root growth in manhole.

Also roots, and debris.

Capacity issue on Crystal Springs El Cerrito Trunk, subject of CDO Re-2009-0020

grease buildup in the mainline.

Swifter type towels and some minor roots.

grease and some root.

Roots

Crew hit one small root ball in the main.

Seperation in pipe.

Root growing in the bottom of the manhole.

See above.

Power outage in corp yard, backup generator had a weak battery and had to be jump started. Causing the sewer lift statio Four inch private root pulled out of bottom of the manhole that was blocking the channel.

Area was just recently chemically root foamed, something might have broken off and caused the main line to back up. See above.

Main line clogged with root intrusion after c/o tie in.

See above

See above

This total also includes four hrs. of 100gpm flowing out of Crystal Springs Rd. trunk main line MH. = 24000 gallons added Swifter towels, and some roots.

See above

See above

See above

See above

See above

Broken pipe from upper section of main.

See above

See above

Very flat line rags and little grease.

Line was chemicaly root foamed about three weeks earlier and some decayed root s fell off and clogged up the manhole.

See above

See above

Rain event (storm) flow exceeded capacity

Rainfall exceeded pipe capacity.

See above

Flow exceeded capacity during heavy rain event.

Other (specify below) Main Other (specify below) Main Main Other (specify below) Main Main

Manhole
Manhole/ see above See above
Main line mainline
See spill cause box. Only tweo houses were on the line, One house was empty and nobody was home at the other house. So very little came consider the manhole
Corp yard wash rack is tied into the sewer lift station pit, when power failed station backed up and started coming out the
See above.
The total SSO volume includes two manholes on Crystal Springs Rd. also surcharging for two hrs. each. All part of Crystal See #26 See above
RAINY DAY
see above
See above
See above

	15 HDPE 15 clay 6 clay 6 clay
out.	15 clay 15 Clay 6 VCP 12 vcp 6 vcp 6 clay 8 VCP 6 liner 6 clay 6 ductile
work rook mate. All power of	6 vcp 15 VCP
wash rack grate. All sewer st al Springs trunk main line.	6 VCP 6 VCP 6 VCP 6 VCP 6 D.I. 6 VCP 15 VCP 15 VCP 15 VCP 6 VCP 6 VCP
	6 Lined VCP 15 VCP 6 VCP 6 VCP 8 liner 6 VCP 6 VCP 6 VCP 8 VCP 6 VCP 6 VCP 6 VCP 15 VCP 6 VCP 15 VCP

ED_006495_00001080-02543

```
Cleaned-up (mitigated effects of spill)
Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit
Cleaned-up (mitigated effects of spill)
Contained all or portion of spill
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill)
Contained all or portion of spill
Returned all or portion of spill to sanitary sewer system
Cleaned-up (mitigated effects of spill)
Returned all or portion of spill to sanitary sewer system
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause
Cleaned-up (mitigated effects of spill):Inspected sewer using CCTV to determine cause:Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill)
Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit
Other (specify below)
Other (specify below)
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill)
```

Posted barricades with raw sewage advisory/sandbagged M/H covers.

Posted health warnings, and barricades, sandbagged M/H covers.

Will see about adding this portion of easement to summer foaming program.

Used jet truck to vac. out storm drain box, clean and disinfect curbside gutter.

storm overflow capacity Cleaned all of the spill area.

Cleaned up all spill effects.

Cleaned up and picked up ten gallons worth of the spill.

Vacumed out storm drain box, and manhole. Deoderized area and cleaned up.

Crew put up barricades with flashers and warning signs.

Will inspect easement line using CCTV.

Restored normal flow to city main line.

Sewage water had seeped into hillside into dirt and grey matter (toilet Papers, etc.) was cleaned up and disposed of, disir See above

See above

Another big storm due to hit tomorrow.

See #26 See above

Restored flow and cleaned up.

RESTORE FLOW AND CLEAN UP MITIGATED EFFECTS OF SPILL

Ran a bypass to the next downstream manhole, cought around eighty percent of flow. See above

Will have staff return to site on Monday, September 20, 2010 to see if there is any way to retrieve any grey matter or deb See above

See above

Heavy rain overwhelmed the sewer system, once the rain subsided the flow was able to catch up.

Discharge stopped once flow was able to catch up, when rain subsided.

Had are bypass going to to catch 90% of the overflow going to the downstream manhole, about 10% escaped through are Put out flashing barricades and posted raw sewage spill signs around the spill area

Heavy rain overwhelmed the system, once the rain subsided the flow was able to catch up.

2/15/2009 22:00 2/22/2009 16:30 2/27/2009 11:50 3/2/2009 15:15 3/3/2009 16:45 8/4/2009 12:45 10/14/2009 8:30 1/19/2010 11:30 1/19/2010 15:00 1/20/2010 4:30 1/23/2010 11:30 3/21/2010 13:30 4/12/2010 17:00 4/17/2010 17:00 4/17/2010 12:30 9/19/2010 19:40 12/9/2010 8:30 12/18/2010 17:15 12/19/2010 20:35 12/19/2010 9:40 12/19/2010 10:21 12/27/2010 8:30

12/29/2010 8:00 12/29/2010 7:15

Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Other (specify below) Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Other (specify below) Other (specify below) Other (specify below) Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Other (specify below)

No corrective action was taken as pipe is over capacity. Scheduled for above by May 1 2013
Will also add degreaser to this section of main line.
In the next few years as per CDO In the next few years as per CDO.
Will add chemical root foam to the inside of the manhole, and add manhole to the rehab list.
Corrective actions to be taken in the next few years as per CDO.
Corrective actions to taken as per CDO in the next three years. Pipe to be upgraded in future according to CDO with regional board Corrective actions to be taken in the next few years, as per CDO. Corrective actions to be taken in the next three years, as per CDO
Corrective actions to be taken in the payt three years as per CDO
Corrective actions to be taken in the next three years as per CDO. See above
Planned replacement of main in the next three years as per CDO.
See above
Pipe is scheduled to be upgraded in next 2 -3 years, as well as upsized. Storm related event Storm related event

Pipe is scheduled to be up sized in the next two to three years as per. CDO. Planned rehab. of Sewer main as per CDO in the next couple of years.

Storm related event.

No No

No Yes

No

No

No No

No No

No No

No No

No

No No

No

No No

No

No No

Event during heavy rain storm. SSO quickly diluted by creek flowing very rapidly. SSO quickly diluted by creek as heavy flows during storm.
NA
Creek was running fast and clear. Creek was running fast and clear.
N/A
N/A
Creek was running clear and fast.
N/A
Creek was running clear and fast. Creek was flowing like a river.
Creek was running very high and fast. San Mateo Creek was running fast, ckear, and high.
NA
San Mateo creek was flowing like a river.
Crew said that the creek was running full and clear.
NA NA
NA NA
Creek looks nice clear and running fast. Water in the lake was muddy in color, no visual signs of sewage in the water. Took two water samples from the lake. San Mateo Creek was flowing like a river
Cherry Creek was flowing very fast, like a river San Mateo Creek was flowing like a river. Creek was clear and running like a river. NA

Yes No No Yes Yes No No Yes Yes Yes Yes No No

No Yes

No

No No Yes No No Yes Yes N/A NA

NA

n/a

N/A

N/A

N/A

na

NA NA

NA

NΑ

NA

NΑ

NA

NA

NA

NA

NA

NA

NA

NA

San Mateo Creek San Mateo Creek NA san mateo creek San Mateo creek N/A San Mateo Creek crystal springs San Mateo creek San Mateo Creek NA NA NA NA NA NA NA San Mateo Creek Crocker Lake (private lake for golf course irrigation) San Mateo Creek Unknown Cherry Creek

San Mateo Creek San Mateo Creek

Unknown

No water quality samples taken No water quality samples taken Not applicable to this spill No water quality samples taken No water quality samples taken Not applicable to this spill No water quality samples taken Not applicable to this spill No water quality samples taken No water quality samples taken No water quality samples taken Other (specify below) No water quality samples taken Not applicable to this spill

Water samples were not taken due to hazard of approaching creek.			
To dangerous totake water samples.			
None taken Ito dangerous! See above			
Can above			
See above			
See above Took samples, but have not turned them into lab for results until Monday, 12-20-10.			

None of the above None of the above Not applicable to this spill None of the above No water quality samples taken None of the above None of the above None of the above No water quality samples taken None of the above None of the above Not applicable to this spill No water quality samples taken None of the above

None of the above None of the above

Not applicable to this spill



91295	2/15/2009 18:15
91538	2/22/2009 16:35
91718	2/27/2009 12:42
91766	3/2/2009 11:20
91834	3/3/2009 15:00
92994	4/13/2009 11:28
93110	4/20/2009 15:55
93111	4/20/2009 15:55
93302	4/28/2009 15:34
93415	5/3/2009 22:35
95456 95660 96905	8/4/2009 14:00 8/14/2009 0:00 8/14/2009 14:30 10/13/2009 15:35
97957	11/27/2009 12:05
100408	1/19/2010 11:30
100408	1/19/2010 11:00
100450	1/20/2010 8:58
100528	1/21/2010 12:32
101928	3/21/2010 13:54
102325	4/12/2010 16:45
102426	4/17/2010 17:44
102424	4/17/2010 14:20
105637	9/19/2010 21:24
107386	12/9/2010 6:20
107604	12/18/2010 19:56
107649	12/19/2010 21:10
107674	12/20/2010 15:33
107675	12/20/2010 15:33
107852	12/25/2010 18:00
107934	12/28/2010 23:45
107933	12/28/2010 23:45



2SSO10142	Active	760008 Tony Geraldi	Certified
2SSO10142	Active	760010 Tony Geraldi	Certified
2SSO10142	Active	761359 Tony Geraldi	Certified
2SSO10142	Active	762034 Tony Geraldi	Certified
2SSO10142	Active	763178 Tony Geraldi	Certified
2SSO10142	Active	763267 Tony Geraldi	Certified
2SSO10142	Active	763781 Tony Geraldi	Certified
2SSO10142	Active	763788 Tony Geraldi	Certified
2SSO10142	Active	764065 Tony Geraldi	Certified
2SSO10142	Active	764525 Tony Geraldi	Certified
2SSO10142	Active	764531 Tony Geraldi	Certified
2SSO10142	Active	764541 Tony Geraldi	Certified
2SSO10142	Active	764551 Tony Geraldi	Certified
2SSO10142	Active	764731 Tony Geraldi	Certified
2SSO10142	Active	764732 Tony Geraldi	Certified
2SSO10142	Active	764891 Tony geraldi	Certified
2SSO10142	Active	764922 Tony Geraldi	Certified
2SSO10142	Active	764923 Tony Geraldi	Certified
2SSO10142	Active	764944 Tony Geraldi	Certified
2SSO10142	Active	764957 Tony Geraldi	Certified
2SSO10142	Active	764965 Tony Geraldi	Certified
2SSO10142	Active	764971 Tony Geraldi	Certified
2SSO10142	Active	764973 Tony Geraldi	Certified
2SSO10142	Active	764974 Tony Geraldi	Certified
2SSO10142	Active	764997 Tony Geraldi	Certified
2SSO10142	Active	765328 Tony Geraldi	Certified
2SSO10142	Active	765862 Tony Geraldi	Certified
2SSO10142	Active	766392 Tony Geraldi	Certified
2SSO10142	Active	767692 Tony Geraldi	Certified
2SSO10142	Active	768669 Tony Geraldi	Certified
2SSO10142	Active	768737 Tony Geraldi	Certified
2SSO10142	Active	769322 Tony Geraldi	Certified
2SSO10142	Active	771438 Tony Geraldi	Certified
2SSO10142	Active	771635 Supervisor	Certified
2SSO10142	Active	771821 Tony Geraldi	Certified
2SSO10142	Active	772071 Tony Geraldi	Certified
2SSO10142	Active	772536 Tony Geraldi	Certified
2SSO10142	Active	773516 Tony Geraldi	Certified
2SSO10142	Active	773540 Tony Geraldi	Certified
2SSO10142	Active Active	773937 Tony Geraldi	Certified
2SSO10142		776255 Tony Geraldi	Certified
2SSO10142	Active	776274 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	776288 Tony Geraldi	Certified Certified
	Active Active	776873 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	777817 Tony Geraldi 778727 Tony Geraldi	Certified
	Active	•	Certified
2SSO10142 2SSO10142	Active	778734 Tony Geraldi 778827 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	779098 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	780086 Tony Geraldi 780086 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	780103 Tony Geraldi 780103 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	780110 Tony Geraldi 780110 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	782310 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	782693 Tony Geraldi	Certified
2SSO10142 2SSO10142	Active	782715 Tony Geraldi	Certified
2000 10 172	, 101110	rour to rony condidi	Jordinou

Supervisor

Tony Geraldi

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor Supervisor

Supervisor

Supervisor Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

9:43 A.M.		923749
10:19 A.M.	10.01	369773
	12:01 13:51	507220 301091
	7:32	435514
17;54	1.52	728205
17,01	16:56	597909
	16:49	290137
12;29		624191
,	9:53	952804
	10:16	810829
	10:29	224910
	10:49	755577
	18:12	103946
	11:16	588157
	12:37	402881
	17:23	603804
	17:53	839008
	11:26 14:57	741699 960006
	16:04	683580
	16:50	771660
17;54	10.50	162337
17,01	7:43	803254
	11:51	115752
	9:27	229473
	12:49	919247
	10:37	689421
	11:20	118649
	15:02	717454
	14:56	653555
2.42	11:06	246853
9:13 a.m.	45.55	331458
	15:55	305703
	15:42 18:08	500999 373725
	17:40	722911
4:30 P.M.	17.10	826536
	11:50	982563
	8:43 AM	909653
11;05		115120
10;59		942747
10;52		895148
	9:33 AM	737220
	8:48	400727
	14:38	217461
	14:35	169518
15;22	16:01	583111 131829
10,22	8:42 AM	587027
	8:48 AM	736634
	8:52 AM	197684
8:23 A.M.	V.V. / 1171	420237
6:59 A.M.		116646
6:48 A.M.		529217

30-Dec-10	12/30/2010	30-Dec-10	12/30/2010
30-Dec-10	12/30/2010	30-Dec-10	12/30/2010
18-Jan-11	1/18/2011	31-Jan-11	1/31/2011
27-Jan-11	1/27/2011	31-Jan-11	1/31/2011
17-Feb-11	2/17/2011	18-Feb-11	2/18/2011
18-Feb-11	2/18/2011	23-Feb-11	2/23/2011
28-Feb-11	2/28/2011	2-Mar-11	3/2/2011
28-Feb-11	2/28/2011	2-Mar-11	3/2/2011
7-Mar-11	3/7/2011	10-Mar-11	3/10/2011
21-Mar-11	3/21/2011	30-Mar-11	3/30/2011
21-Mar-11	3/21/2011	30-Mar-11	3/30/2011
21-Mar-11	3/21/2011	30-Mar-11	3/30/2011
21-Mar-11	3/21/2011	30-Mar-11	3/30/2011
23-Mar-11	3/23/2011	29-Mar-11	3/29/2011
23-Mar-11	3/23/2011	30-Mar-11	11/10/2011
29-Mar-11	3/29/2011	29-Mar-11	3/29/2011
29-Mar-11	3/29/2011	29-Mar-11	3/29/2011
29-Mar-11	3/29/2011	29-Mar-11	3/29/2011
30-Mar-11	3/30/2011	30-Mar-11	3/30/2011
30-Mar-11	3/30/2011	30-Mar-11	3/30/2011
30-Mar-11	3/30/2011	30-Mar-11	3/30/2011
30-Mar-11	3/30/2011	30-Mar-11	3/30/2011
30-Mar-11	3/30/2011	30-Mar-11	3/30/2011
31-Mar-11	3/31/2011	31-Mar-11	3/31/2011
31-Mar-11	3/31/2011	31-Mar-11	3/31/2011
11-Apr-11	4/11/2011	11-Apr-11	4/11/2011
28-Apr-11	4/28/2011	28-Apr-11	4/28/2011
12-May-11	5/12/2011	8-Aug-11	8/8/2011
21-Jun-11	6/21/2011	28-Jun-11	6/28/2011
20-Jul-11	7/20/2011	21-Jul-11	7/21/2011
20-Jul-11	7/20/2011	21-Jul-11	7/21/2011
1-Aug-11	8/1/2011	1-Aug-11	8/1/2011
26-Sep-11	9/26/2011	26-Sep-11	9/26/2011
2-Oct-11	10/2/2011	10-Oct-11	10/10/2011
6-Oct-11	10/6/2011	10-Oct-11	10/10/2011
16-Oct-11	10/16/2011	18-Oct-11	10/18/2011
29-Oct-11	11/2/2011	2-Nov-11	11/2/2011
28-Nov-11	11/28/2011	28-Nov-11	11/28/2011
29-Nov-11	11/29/2011	29-Nov-11	11/29/2011
12-Dec-11	12/12/2011	14-Dec-11	12/14/2011
23-Jan-12	1/23/2012	24-Jan-12	1/24/2012
23-Jan-12	1/23/2012	24-Jan-12	1/24/2012
23-Jan-12	1/23/2012	24-Jan-12	1/24/2012
6-Feb-12	2/6/2012	7-Feb-12	2/7/2012
21-Feb-12	2/21/2012	22-Feb-12	2/22/2012
15-Mar-12	3/15/2012	19-Mar-12	3/19/2012
15-Mar-12	3/15/2012	19-Mar-12	3/19/2012
19-Mar-12	3/19/2012	26-Mar-12	3/26/2012
26-Mar-12	3/26/2012	28-Mar-12	3/28/2012
13-Apr-12	4/13/2012	23-Apr-12	4/23/2012
16-Apr-12	4/16/2012	23-Apr-12	4/23/2012
16-Apr-12	4/16/2012	23-Apr-12	4/23/2012
21-Jun-12	6/21/2012	27-Jun-12	6/27/2012
29-Jun-12	6/29/2012	10-Jul-12	7/10/2012
29-Jun-12	6/29/2012	10-Jul-12	7/10/2012

Cotogon: 1	63000	50400
Category 1	63000	50400
Category 1	6000 2900	1200
Category 1		1300
Category 3	50 75	30
Category 3	75 2752	75
Category 1	2750	2200
Category 1	18000	0
Category 1	16500	14025
Category 3	30	0
Category 1	279000	223200
Category 1	26200	0
Category 1	19650	0
Category 1	15150	13635
Category 1	18000	16200
Category 1	4500	0
Category 1	18000	0
Category 1	27000	0
Category 1	18000	0
Category 1	41200	0
Category 1	49500	0
Category 1	900	0
Category 1	180000	90000
Category 1	3000	2700
Category 1	13500	12150
Category 1	1325	0
Category 3	5	0
Category 1	200	175
Category 3	450	0
Category 3	100	0
Category 3	30	25
Category 3	60	60
Category 3	25	5
Category 3	25	0
Category 1	4500	0
Category 3	20	20
Category 1	25	0
Category 2	2925	100
Category 3	50	50
Category 3	40	40
Category 2	1400	60
Category 3	360	360
Category 1	36000	35640
Category 1	18000	17820
Category 3	275	0
Category 3	65	65
Category 2	162000	162000
Category 1	810	5
Category 1	135000	121500
Category 2	114000	114000
Category 1	60000	0
Category 1	180000	108000
	27000	00000
Category 3	150	140
Category 3	27	
Category 1	1050	0 500
Category 1	1050	500

12600 6000 1600	Yes	Yes Yes Yes No
	No	Yes
	Yes	Yes
18000		No
2475		Yes
0		No
55800		Yes
26200		No
19650		No
1515		Yes
1800		Yes
4500	Yes	No
18000	Yes	No
27000	No	Yes
18000	No	Yes
41200	Yes	Yes
49500	Yes	No
900		Yes
90000	Yes	Yes
	Yes	Yes
1350		Yes
1325		No
	No	No
	No	No
	No	No
0		No
0		No
0		Yes
0		No
4500		No Yes
4300		Yes
	Yes	Yes
	No	No
	No	No
	Yes	Yes
180	Yes	Yes
0	No	No
0	No	Yes
0	No	No
805	Yes	No
13500	Yes	Yes
	No	No
60000		Yes
72000		Yes
27000		Yes
	No	No
	No	Yes
550	Yes	Yes

No No No Not Applicable - Spill did not reach a separate storm drainpipe Yes No Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No No Not Applicable - Spill did not reach a separate storm drainpipe No No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Yes No No Yes Yes Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe No No No Not Applicable - Spill did not reach a separate storm drainpipe No

No

Hillsborough

Hillsborough

Hillsborough

Hillsborough

i illisborougii

Hillsborough

Hillsborough

Hillsborough

Hillsboroough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

i illisborougii

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Burlingame

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

milisporougn

Hillsborough

Hillsborough

Hillsborough

Hillsborough

635 Hayne Road

Hillsborough

Hillsborough

1270 Tartan Trail

Hillsborough

1040 Crystal Springs rd. / Merner

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

37.5529	-122.33964 San Mateo
37.55448	-122.35614 San Mateo
37.56278	-122.33754 San Mateo
37.57398	-122.36978 San Mateo
37.53941	-122.35378 San Mateo
37.5529	-122.33964 San Mateo
37.54932	-122.34389 San Mateo
37.5529	-122.33964 San Mateo
37.55204	-122.36342 San Mateo
	-122.33964 San Mateo
37.5529	
37.54932	-122.34389 San Mateo
37.54856	-122.34695 San Mateo
37.56161	-122.34042 San Mateo
37.5529	-122.33964 San Mateo
37.54932	-122.34389 San Mateo
37.57734	-122.36735 San Mateo
37.57818	-122.35546 San Mateo
37.55428	-122.35735 San Mateo
37.54856	-122.34695 San Mateo
37.54932	-122.34389 San Mateo
37.57972	-122.36546 San Mateo
37.5529	-122.33964 San Mateo
37.56161	-122.34042 San Mateo
37.5529	-122.33964 San Mateo
37.55012	-122.34222 San Mateo
37.55916	-122.35337 San Mateo
37.55427	-122.36869 San Mateo
37.54669	-122.34031 San Mateo
37.54574	-122.34059 San Mateo
37.54237	-122.36078 San Mateo
37.55472	-122.35093 San Mateo
37.55703	-122.37402 San Mateo
37.55895	-122.34398 San Mateo
37.558003	-122.343883 San Mateo
37.55971	-122.33747 San Mateo
37.56072	-122.35215 San Mateo
37.539835	-122.355153 San Mateo
37.57607	-122.3723 San Mateo
37.56405	-122.34602 San Mateo
37.54455	-122.34109 San Mateo
37.5584	-122.3697 San Mateo
37.5529	-122.33964 San Mateo
37.5529	-122.33964 San Mateo
	-122.33884 San Mateo
37.5469	
37.57636	-122.37517 San Mateo
37.5529	-122.33964 San Mateo
37.55613	-122.33928 San Mateo
37.5529	-122.33964 San Mateo
37.5529	-122.33964 San Mateo
37.54868	-122.3461 San Mateo
37.55327	-122.33974 San Mateo
37.5548	-122.339 San Mateo
37.58135	-122.36116 San Mateo
37.53147	-122.36021 San Mateo
37.55208	-122.35983 San Mateo

Road shoulder

Manhole in the middle of the roadway during major rain event.

Road shoulder

Backyard

Manhole

Manhole along road shouldeer

Manhole in the middle of the roadway.

Road Shoulder

Manhole

Manhole in shoulder of the roadway overflowed due to heavy rains, causing insufficient capacity issues on the main trunk Manhole located in roadway.

Manhole located in the middle of the roadway.

Manhole in the road shoulder

Manhole in shoulder of the roadway overflowed due to heavy rains, causing insufficient capacity issues on the main El Ce

Manhole located in roadway

Manhole in the roadway.

Manhole located in parking lot area of Town Hall

Manhole located in the roadway.

Manhole located in the middle of the roadway.

Manhole located along the road shoulder.

Manhole in Ithe shoulder of the roadway overflowed due to very heavy rainfall, causing flow to exceed capacity.

Manhole in the road shoulder.

Manhole is located in the shoulder of the roadway.

Manhole located in the roadway.

Manhole

SSMH11F20 located in backyard easement area.

Easement area, side of hill.

Backyard easement area.

Manhole

Manhole in easment area.

Manhole in street location.

Driveway and dirt area of property.

Sewer surcharged out of a manhole in the roadway in front of 635 Hayne Road.

House clean out

House clean out

Sewage discharged out of a manhole in front of 1270 Tartan Trail Rd. The manhole is located off the street next to the dri Manhole in driveway.

Manhole located in the parking strip.

Easement area away from any roadway.

Easement area backyard

Manhole is located in the shoulder of the roadway.

Manhole is located in the shoulder of the roadway.

Manhole located in front driveway area of said property.

Driveway approach area of 940 Jackling.

Manhole in shoulder of roadway.

C/O of 731 El Cerrito Ave

Manhole in road shoulder and clean out of 731 El cerrito.

Manhole in shoulder of roadway.

road shoulder

Road shoulder manhole

Road shoulder manhole

Backyard cleanout.

Manhole

Manhole across from 1260 Hayne Rd. in lot area.



Manhole Manhole Manhole Other sewer system structure Manhole Other (specify) Manhole Other (specify) Other (specify) Manhole Manhole Manhole Gravity sewer; Manhole Gravity sewer Gravity sewer; Manhole Gravity sewer; Other sewer system structure Gravity sewer; Manhole; Other sewer system structure Gravity sewer; Manhole Building or structure; Combined sewer D.I.; Force main or pressure sewer

Building or structure

Combined sewer D.I.

Other (specify)

Gravity sewer; Manhole

Gravity sewer; Manhole

See above
See above
See above
City cleanout
See above
Heavy rains caused insufficient capacity problems on the main El Cerrito Crystal Springs Trunk Sewer Line.
See above
Flow exceeded capacity due to heavy rains. Flow was about eightyfive percent rain water. Final spill destination was Sar
See above
See above
See above
See above
See above
Manhole
Dirt area by driveway came out of joint in pipe
Have alone aut
House clean out
House clean out
See above
See above
See above
Manhole
See above
See above
See above
Coming out of a joint in the sewer main.
See above
See question # 16.
See question # 16
See above
see above
see above
see above
House cleanout
See above
See above

Surface water

Surface water

Surface water

Unpaved surface

Other paved surface

Surface water

Surface water

Surface water

Other paved surface

Surface water

Surface water

Surface water

Surface water

Surface water

Surface water

Unpaved surface

Separate storm drain; Street/curb and gutter

Separate storm drain; Street/curb and gutter

Surface water

Surface water

Separate storm drain

Surface water

Surface water

Surface water

Surface water

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface; Street/curb and gutter

Separate storm drain; Unpaved surface

Street/curb and gutter

Other paved surface; Unpaved surface

Surface water

Separate storm drain

Surface water

Separate storm drain

Separate storm drain

Separate storm drain

Unpaved surface

Unpaved surface

Surface water

Surface water

Unpaved surface

Separate storm drain; Street/curb and gutter

Street/curb and gutter; Other (specify below)

Other paved surface; Surface water

Street/curb and gutter; Surface water; Unpaved surface

Other (specify below)

Beach; Building or structure; Combined storm drain (combined CS only)

Combined storm drain (combined CS only); Street/curb and gutter; Surface water

Other paved surface

Unpaved surface

Combined storm drain (combined CS only)

Separate storm drain; Street/curb and gutter; Surface water; Unpaved surface

Have a sewer bypass in place, during the heavy rain event when flow exceeded capacity,we captured about 80% of the S Cherry Creek in Hillsborough

See above

Dirt area in backyard.

See above

San Mateo Creek

Flowed into San Mateo creek off of road shoulder.

We have are bypass going so we were redirecting about eightyfive percent of the flow to the next downstream manhole.

See above

See above

Flowed into San Mateo Creek from manhole in the shoulder of the road.

See above

See above

Flowed into San Mateo Creek from manhole located in the roadway.

Manhole discharged due to flow exceeding capacity due to very heavy rainfall. Once rainfall subsided the flow slowly wer

See above

See above

See above

flowed into San Mateo Creek from Manhole located on the roadway shoulder.

See above

San Mateo Creek

See above

See above

See above

See above

See above

Easement area

See above

Vacked out storm drain and recovered all sewer.

See above

See question sixteen.

Sewage reached a storm drain that flows to San Mateo creek

Vacced out of storm drain box.

The sewage discharged into a catch basin, which connects to a 48 inch storm drain culvert which runs down Tartan Trail I Water ponded up around sunken manhole in driveway, and made its way down the gutter to the storm drain where our jet Storm drain was plugged and crew was able to vack out all of the discharge and return it to the sewer system.

Spill made its way down to a dry creek bed area.

Sewer soaked into yard area.

See above

Planted area along the driveway where sewage just soaked into the vegetation and hillside.

Recovered all of discharge in the catch basin.

Next downstream manhole where we opened up our bypass and redirected overflow into recapturing all of it.Smartcover as San Mateo Creek.

Opened up our bypass when Smartcover alrm notified us that the flow was starting to rise in the manhole, we redirected t Opened up bypass when Smartcover alrm notified on call person that the flow was starting to rise in the manhole, we redi Flow exceeded capacity during heavy rain event

see above

see above

Backyard

See above

See above

12/28/2010 0:00	12/28/2010 19:00	12/28/2010 19:20	12/29/2010 2:30
12/28/2010 0:00	12/28/2010 23:57	12/28/2010 23:57	12/28/2010 2:00
1/16/2011 11:26	1/16/2011 11:31	1/16/2011 11:45	1/16/2011 11:55
1/26/2011 17:45	1/26/2011 17:50	1/26/2011 17:55	1/26/2011 18:05
2/16/2011 14:50	2/16/2011 14:52	2/16/2011 14:55	2/16/2011 15:00
2/17/2011 0:00	2/17/2011 13:37	2/17/2011 13:43	2/17/2011 15:00
2/25/2011 0:00	2/25/2011 9:15	2/25/2011 9:15	2/25/2011 11:00
2/25/2011 0:00	2/25/2011 6:40	2/25/2011 6:50	2/25/2011 11:00
3/3/2011 15:30	3/3/2011 15:45	3/3/2011 15:52	3/3/2011 16:00
3/18/2011 13:30	3/18/2011 13:00	3/18/2011 13:10	3/20/2011 12:30
3/20/2011 1:04	3/20/2011 1:15	3/20/2011 1:30	3/20/2011 3:15
3/20/2011 1:04	3/20/2011 1:15	3/20/2011 1:40	3/20/2011 3:15
3/20/2011 1:04	3/20/2011 1:45	3/20/2011 1:55	3/20/2011 11:10
3/23/2011 7:20	3/23/2011 7:05	3/23/2011 7:15	3/23/2011 9:00
3/23/2011 7:30	3/23/2011 7:20	3/23/2011 7:40	3/23/2011 10:30
3/24/2011 11:24	3/24/2011 11:50	3/24/2011 11:50	3/24/2011 14:30
3/24/2011 11:30	3/24/2011 11:40	3/24/2011 11:55	3/24/2011 14:30
3/24/2011 11:30	3/24/2011 11:40	3/24/2011 11:33	3/24/2011 14:30
3/24/2011 11:30	3/24/2011 12:10	3/24/2011 12:10	3/24/2011 14:30
3/24/2011 11:30			
	3/24/2011 11:50	3/24/2011 11:50	3/24/2011 18:00
3/24/2011 12:30	3/24/2011 12:45	3/24/2011 13:00	3/24/2011 15:30
3/24/2011 8:35	3/24/2011 8:05	3/24/2011 8:15	3/25/2011 8:20
3/26/2011 13:00	3/26/2011 13:10	3/26/2011 13:20	3/26/2011 15:00
3/26/2011 8:17	3/26/2011 8:00	3/26/2011 8:30	3/26/2011 9:57
3/26/2011 9:20	3/26/2011 9:40	3/26/2011 9:40	3/26/2011 10:13
4/9/2011 10:45	4/9/2011 11:00	4/9/2011 11:35	4/9/2011 12:20
4/27/2011 16:00	4/27/2011 16:10	4/27/2011 16:20	4/27/2011 16:40
5/11/2011 14:00	5/11/2011 14:19	5/11/2011 14:30	5/11/2011 15:30
6/21/2011 10:00	6/21/2011 10:10	6/21/2011 10:22	6/21/2011 12:13
7/15/2011 10:30	7/15/2011 10:35	7/15/2011 10:45	7/15/2011 11:00
7/20/2011 13:10	7/20/2011 13:15	7/20/2011 13:20	7/20/2011 13:40
7/17/2011 12:50	7/17/2011 13:05	7/17/2011 13:35	7/17/2011 13:15
9/24/2011 10:15	9/24/2011 10:30	9/24/2011 11:00	9/24/2011 12:47
10/2/2011 9:30	10/2/2011 10:30	10/2/2011 12:00	10/2/2011 12:30
10/6/2011 13:45	10/6/2011 13:50	10/6/2011 13:50	10/6/2011 14:05
10/16/2011 17:30	10/16/2011 17:45	10/16/2011 18:45	10/16/2011 19:15
10/29/2011 16:00	10/29/2011 16:30	10/29/2011 17:30	10/29/2011 17:57
11/28/2011 7:55	11/28/2011 7:55	11/28/2011 7:55	11/28/2011 8:05
11/2/2011 14:05	11/2/2011 14:25	11/2/2011 14:30	11/2/2011 14:45
12/11/2011 11:00	12/11/2011 11:30	12/11/2011 12:30	12/11/2011 13:20
1/22/2012 20:15	1/22/2012 20:30	1/22/2012 21:05	1/22/2012 22:15
1/20/2012 22:55	1/20/2012 22:34	1/20/2012 23:50	1/21/2012 5:00
1/23/2012 3:00	1/23/2012 2:24	1/23/2012 2:50	1/23/2012 9:00
2/5/2012 18:01	2/5/2012 18:15	2/5/2012 18:45	2/5/2012 18:56
2/21/2012 10:00	2/21/2012 10:30	2/21/2012 10:45	2/21/2012 11:05
3/14/2012 18:00	3/14/2012 10:10	3/14/2012 10:20	3/15/2012 14:00
3/14/2012 18:00	3/14/2012 17:40	3/14/2012 18:25	3/15/2012 7:30
3/16/2012 13:30	3/16/2012 13:00	3/16/2012 13:45	3/17/2012 12:00
3/24/2012 21:00	3/24/2012 20:00	3/24/2012 20:35	3/25/2012 16:00
4/13/2012 1:00	4/13/2012 7:00	4/13/2012 8:00	4/13/2012 11:00
4/13/2012 1:00	4/13/2012 5:00	4/13/2012 8:00	4/13/2012 16:00
4/13/2012 8:00	4/13/2012 8:15	4/13/2012 8:30	4/13/2012 11:00
6/20/2012 16:00	6/20/2012 16:20	6/20/2012 16:30	6/20/2012 17:00
6/29/2012 11:00	6/29/2012 11:01	6/29/2012 11:07	6/29/2012 11:28
6/29/2012 16:15	6/29/2012 11:01	6/29/2012 16:25	6/29/2012 11:20
0/20/2012 TO. 13	012012012 TU.20	512312012 TU.25	5/25/2012 10.45

Flow exceeded capacity (Seperate CS Only)

Flow exceeded capacity (Seperate CS Only)

Debri-Rags

Root intrusion

Pipe structural problem/failure

Flow exceeded capacity (Separate CS Only)

Flow exceeded capacity (Separate CS Only)

Flow exceeded capacity (Separate CS Only)

Root intrusion

Flow exceeded capacity (Separate CS Only)

Flow exceeded capacity (Separate CS Only) Flow exceeded capacity (Separate CS Only)

Flow exceeded capacity (Separate CS Only)

Debri-Rags

Root intrusion

Debri-General

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Debri-Rags

Root intrusion

Root intrusion

Root intrusion

Debri-Rags

Grease deposition (FOG)

Debri-General

Root intrusion

Grease deposition (FOG)

Flow exceeded capacity (Separate CS Only)

Flow exceeded capacity (Separate CS Only)

Root intrusion

Root intrusion

Flow exceeded capacity (Separate CS Only)

Grease deposition (FOG)

Root intrusion

Debri-Rags

Smartcover sent us an alarm that the water level was rising in the manhole, so we opened up the bypass around 7:20 p.r See above

And also some roots

Root intrusion coming out of a buried city cleanout.

Buried manhole piece of manhole ring fell into channel.

See above

See above

See above

See above

SmartCover alarm notified the sewer crew at 1p.m. telling them that the water was starting to rise in the manhole. They o

See above

See above

See above

SmartCover alarm notified the Sewer Crew that the manhole was beginning to rise. So the crew opened up are Sewer by SmartCover alarm notifies the sewer crew ahead of time. That the manhole will soon be surcharging. Due to heavy rains See above

Flow exceeded capacity due to very heavy rainfall. Once the rainfall subsided the flow slowly returned to normal.

Flow exceeded capacity due to very heavy rainfall. Once the rainfall subsided the flow slowly returned to normal.

See # 19

Flow exceeded capactly due to very heavy rainfall. The final spill destination was San Mateo Creek.

Flow exceeded capacity due to very heavy rainfall.

Our smartcover alarm lets us know ahead of time when the manhole is begining to rise out of the channel before it actual Manholes downstream were all holding causing this one of th shallowest manholes to surcharge.

See above

Surcharging due to rain and heavy ground saturation. No way to redirect this overflow because of its location. This sso flc Swifter towels, and a little bit of root.

See above

See above

Some grease, mostly roots.

Crew found four inch roots released from plumber, causing our main to back up.

See above

Surcharge had already freed itself by the time the crew got there.

See above

See above

see above

Grease and household cleaning rags caused the spill.

Grease.

Debri in main line.

See above

See above

See above

See above

See above.

See above

See above

See above

Major storm, flow exceeded capacity.

See above

see above

Storm capacity issues

see above

See above.

See above

See above

Main

Main Main

Main

Main

Main

Main

Main

Main Main

Main

Main Main

Main

Main

Main

See above
See above
See above
See above
See above
We ran are overflow bypass and recaptured around eighty percent of the overflow.
See above
See above
See above
See above
See above
Flow exceeded capacity due to heavy rains.
See above
Smartcover alarms notifies oncall person that the flow is beginning to rise out of the channel, before the actual SSO begin
See above
See above
Manhole was located in the corner of yard where most of the sewer puddled up against the fence. Root was located just d
See above
See above
See above
In street
See above
in main line
See above
See above
See above
Smartcover alarms notifies on call person that the flow is beginning to rise out of the channel in the manhole. Before the a
Smartcover alarm notifies the on call person that the flow is beginning to rise out of the channel in the manhole. Before the
See above.
See above
House lateral ties into manhole that was up causing surcharge to come out of home owners clean out.
See above.
See above
main line blockage caused house cleanout to discharge.
See above

	15 VCP 6 Lined VC 12 VCP 6 VCP 6 VCP 15 VCP 15 VCP 15 VCP 15 VCP 15 Liner 15 Liner 12 VCP 15 VCP 15 Liner 12 VCP 15 Liner 15 Liner 16 VCP 15 VCP 15 Liner 6 VCP 15 VCP
ns to surcharge. They went o	15 VCP 12 VCP 15 VCP 15 Liner
ownstream from the manhol	6 PVC 6 liner 6 VCP 6 VCP 8 VCP 6 VCP
	6 VCP 8 VCP 6 VCP 6 VCP 6 liner 6 VCP 6 VCP 6 Liner
actual SSO begins to surchange actual SSO begins to surc	15 VCP 15 VCP 6 VCP 6 VCP 15 VCP 15 VCP 15 VCP 15 VCP 15 VCP 15 VCP 6 VCP 6 VCP
	8 pvc

```
Cleaned-up (mitigated effects of spill)
Returned all or portion of spill to sanitary sewer system
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill)
Contained all or portion of spill
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit
Cleaned-up (mitigated effects of spill); Contained all or portion of spill
Cleaned-up (mitigated effects of spill); Restored flow; Returned all or portion of spill to sanitary sewer system
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanil
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause
Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill
Cleaned-up (mitigated effects of spill); Contained all or portion of spill
Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause
Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Returned all or portion of spill to sanitary sewer syst
Cleaned-up (mitigated effects of spill); Returned all or portion of spill to sanitary sewer system
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Returned all or portion of spill to sanitary sewer syst
Restored flow; Returned all or portion of spill to sanitary sewer system
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Returned all or portion of spill to sanitary sewer syst
Cleaned-up (mitigated effects of spill)
```

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;ReCleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;ReCleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit

See above Dislcharge stopped once flow was able to catch up, and rain subsided See above See above See above See guestion 37 See above See above Will also CCTV main line. See above See above See above Recaputured about ninety percent of the overflow with a diversion dam to the 15" sewer main located close to the 12" se See above See above Cleaned up and disinfected the whoe area in the roadway and swale area. See above See above See above See above See above See above See # 35, also recaptured around ninety percent of the overflow with a diversion dam to the fifteen inch sewer main locat-See above See above See above See above #37 Cleaned up and mitigated the effects of the spill. Will be adding this area of mainline to are clean and video project in July. See above Crew jetted the main even though the surcharge had already released itself. See above Crew identified problem, cleared blockage and restored flow. Crew inspected storm drain system and was not able to cap See above Cleaned up the effected area around the manhole, vacuumed up sewage and grey matter, recovered approximately 100 See above. See above. See above. See above See above. Root intrusion See above See above As rain subsides sewer flow went down in the manhole returning to more normal flow. As the heavy rains subsided the flow slowly returned to normal. Cleaned all curb and gutters on Monday morn the 19th . As the heavy rains subsided the flows slowly returned to normal. Cleaned all curb and gutters Monday morn. put out barricades and posted raw sewage signs around spill area Crew opened up bypass line to recapture some of the spill. see above See above See above

See above

12/	9/20 29/2 6/20	010	7:	05	
2/2	7/20 5/20 5/20	111	13:	45	
3/2 3/2 3/2 3/2 3/2 3/2 3/ 3/3 3/2 3/2 3	0/20 0/20 0/20 0/20 3/20 3/20 25/2 5/20 5/20 6/20 28/2 9/20	011 011 011 011 011 011 011 011 011	15: 15: 11: 11: 11: 10: 10: 16: 16:	00 10 59 00 10 00 30 45 00 15 00 30	
10/	2/20	111	12:	30	
10/1 10/2					
12/1	1/20	111	17:	00	
	21/2 3/20				
3/1 3/1 3/	5/20 5/20 9/20 26/2 3/20)12)12 !012)12	14: 10: 2 8: 12:	05 00 30	

4/13/2012 16:00 4/13/2012 11:00

7/2/2012 11:46 6/29/2012 19:30

12/29/2010 15:00

Plan rehabilitation or replacement of sewer Other (specify below) Other (specify below)

Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer

Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Other (specify below)

Other (specify below)

Other (specify below)

Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer

Other (specify below)

Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer

Adjusted schedule/method of preventive maintenance

Adjusted schedule/method of preventive maintenance; Other (specify below) Adjusted schedule/method of preventive maintenance; Other (specify below)

Adjusted schedule/method of preventive maintenance

Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer

Plan rehabilitation or replacement of sewer; Other (specify below)

Plan rehabilitation or replacement of sewer

Adjusted schedule/method of preventive maintenance

Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance Other (specify below)

Replacement of sewer main in the next couple of years as per CDO.

Storm related event

Will be CCTVing this section of pipe in the next week.

Planned rehab of sewer main as per CDO.

Planned rehab of sewer main as per CDO

Planned rehab of sewer main as per CDO.

Storm related event.

Storm related event.

Storm related event

Planned rehab of sewer main as per CDO.

Planned rehab of sewer main as per CDO.

After heavy rainfall subsided the flow slowly returned to normal.

Planned rehab of sewer main as per CDO.

Planned rehab of the sewer main as per CDO.

Planned rehab of sewer main as per CDO.

Planned rehab of sewer main as per CDO.

See above

Will also be root foaming this line soon.

Public outreach and education about household cleaning rags and wipes that cause blockages in the mainline.

See above

Planned rehab of sewer main as per CDO.

Planned rehab of sewer main as per CDO.

[Planned rehab of sewer main as per CDO.

planned rehab of sewer main in a few years as per CDO

Planned rehab of sewer main as per CDO.

see above

See above

Will CCTV main the following week.

No

No

Yes

No

No

No

No

No

No

No No

No

No

No

No

No

No

No

No

No

No

No

No

No

Yes

No

No

No

No

No

No

No No

No

No

No

No

Creek was clear and running like a river. Cherry Creek was flowing very fast, like a river. Water looked very clear and running fast. NA NA San Mateo Creek was running clear and fast. San Mateo Creek was running clear and very fast. San Mateo Creek was running clear and very fast. NA San Mateo creek was running clear and fast, just like a river. Creek was running clear and fast. Creek was running clear and fast. Creek was running clear and fast. San Mateo Creek was running clear and very fast. Creek was running clear and fast. NA NA NA Creek was running clear and fast. San Mateo Creek was running clear and fast more like a river then a creek. NA San Mateo creek was running fast and clear like a river, also water was being released from the dam above. Dam release was going on, San Mateo Creek was running clear and fast.. San Mateo Creek was running clear and fast, Dam release was also going on from Crystal Springs Reservoir. San Mateo Creek was running clear and fast. also dam release was going on from Crystal Springs Reservoir. NA NA NA NA NA NA NA NA The crew said that they did not see any sewage discharge in the creek, and cleaned and vacuumed out residual sewage i NA To dark No visual signs of sewage, there were fish swimming in the creek where the water samples were taken the morning of 10, NA NA NA NA San Mateo Creek was running clear and fast. San Mateo Creek was running clear and fast. NA NA NA San Mate Creek was running clear and fast like a river. San Mateo crfeek was running clear and fast. NA Creek was clear and running like a river Creek looks clear running fast Creek was running fast looked clear NA

Unknown creek was looking clear.

Yes

No

Yes

No

No

No

Yes

Yes

No

Yes

Yes

Yes

Yes

No

No

No

No

Yes

Yes

Yes

No

Yes Yes

Yes

Yes

Yes

No

No

NA

NA

NA

NA

NA

NA NA

NA NA

NA

NA

NA

NA

NA

NA

NA

NA

NA

NA. NA

NA

NA

NA

NA NA

NA

NA

NA

NA

NA NA

NA

NA

NA

NA

NA

NA

NA

NA NA

NA

NA

NA

NA

NA NA

NA

NA

NA

NA

NA

NA

San Mateo Creek

Cherry Creek

San Mateo Creek

NA

NA

San Mateo Creek

San Mateo Creek

San Mateo Creek

NA

San Mateo Creek

Unknown creek area.

NA

NA

San Mateo Creek

San Mateo Creek

NA

San Mateo Creek

San Mateo Creek

San Mateo Creek

San Mateo Creek

NA

NA

NA

NA NA

NA

NA

NA

San Mateo Creek

NA

Cherry Creek

San Mateo Creek

NA

NA

NA

NA

San Mateo Creek

San Mateo Creek

NA

NA

NA

San Mateo Creek

San Mateo Creek

NA

San Mateo creek

San Mateo creek

San Mateo creek

NA

NA

Unknown

No water quality samples taken No water quality samples taken Other (specify below)

No water quality samples taken No water quality samples taken No water quality samples taken

No water quality samples taken No water quality samples taken No water quality samples taken No water quality samples taken No water quality samples taken No water quality samples taken No water quality samples taken Not applicable to this spill Not applicable to this spill No water quality samples taken No water quality samples taken Not applicable to this spill No water quality samples taken No water quality samples taken No water quality samples taken No water quality samples taken

Biological indicator(s) - specify below

No water quality samples taken Biological indicator(s) - specify below

Not applicable to this spill

No water quality samples taken No water quality samples taken

Not applicable to this spill
No water quality samples taken
No water quality samples taken
No water quality samples taken;Not applicable to this spill
No water quality samples taken
No water quality samples taken
No water quality samples taken

No water quality samples taken Dissolved oxygen

No water samples were taken because the creek is all fenced off in the spill area, and there was no other access except ϵ See above See above

To dangerous to take samples, creek was flowing like a river.

To dangerous to take water samples.

To dangerous

To dangerous, creek was running like a river clear, and fast.

To dangerous to take samples creek was flowing like a river.

To dangerous to take water samples.

See above

To dangerous to take water samples. the creek was more like a river then a creek.

See above

See above

To dangerous, creek was a river.

To dangerous creek was flowing like a river and no creek access in the area.

See above

See above

Fecal Coliform Analyses

To dark

Total Coliform and E coli

NA

jTo dangerous to take water samples creek was flowing like a river at the time.

To dangerous to take water samples creek was flowing full and fast.

See above

To dangerous to take water samples, creek was flowing like a river.

No samples taken it was to dangerous!

see above

see above

Need to analyzed

None of the above None of the above No water quality samples taken

None of the above

No water quality samples taken

None of the above

None of the above

None of the above

Not applicable to this spill

None of the above

Regional Water Quality Control Board

None of the above Regional Water Quality Control Board

Not applicable to this spill

None of the above

No water quality samples taken

None of the above

County Health Agency; Regional Water Quality Control Board

See above See above
See above See above See above
to dangerous to take water samples, creek was running clear and very fast. See above See above
See above To dangerous to take water samples. See above See above See 1.8
To dangerous to take samples creek was flowing like a river. To dangerous to take samples due to creek flowing very fast and more like a river.
See above
See above As soon as samples results come back we will notify the above agency.
To dangerous to take samples.

See above

107931	12/28/2010 23:45
107943	12/29/2010 6:40
110294	1/16/2011 15:20
110978	2/17/2011 15:30
111161	2/25/2011 10:30
111155	2/25/2011 8:30
111629 111697 111695 111694 111803 111804 111929 111928 111926 111925 111924 111922 111841 111972 111955 111956	3/18/2011 14:30 3/20/2011 12:15 3/20/2011 12:15 3/20/2011 12:15 3/23/2011 9:35 3/23/2011 9:35 3/25/2011 10:50 3/25/2011 10:50 3/25/2011 10:50 3/25/2011 10:50 3/25/2011 10:50 3/25/2011 10:50 3/25/2011 10:50 3/25/2011 10:50 3/26/2011 11:25 3/26/2011 10:10 3/26/2011 9:35
112917	5/11/2011 16:02
115846	10/2/2011 13:47
116174	10/16/2011 20:30
116472	10/29/2011 19:30
117319	12/11/2011 17:27
120468	1/23/2012 12:21
120470	1/23/2012 12:24
121523	3/15/2012 15:10
121522	3/15/2012 15:10
121556	3/16/2012 15:00
121771	3/26/2012 10:15
122191	4/13/2012 10:00
121290	4/13/2012 10:00
122192	4/13/2012 10:00
123808	6/29/2012 14:05
123813	6/29/2012 20:06



2SSO10142	Active	785636 Tony Geraldi	Certified
2SSO10142	Active	786288 Tony Geraldi	Certified
2SSO10142	Active	787064 Tony Geraldi	Certified
2SSO10142	Active	788693 Tony Geraldi	Certified
2SSO10142	Active	788699 Tony Geraldi	Certified
2SSO10142	Active	788718 Tony Geraldi	Certified
2SSO10142	Active	788721 Tony Geraldi	Certified
2SSO10142	Active	788725 Tony Geraldi	Certified
2SSO10142	Active	789138 Tony Geraldi	Certified
2SSO10142	Active	789279 Tony Geraldi	Certified
2SSO10142	Active	789293 Tony Geraldi	Certified
2SSO10142	Active	789294 Tony Geraldi	Certified
2SSO10142	Active	789295 Tony Geraldi	Certified
2SSO10142	Active	789560 Tony Geraldi	Certified
2SSO10142	Active	792339 Tony Geraldi	Certified
2SSO10142	Active	792702 Tony Geraldi	Certified
2SSO10142	Active	793253 Tony Geraldi	Certified
2SSO10142	Active	793766 Tony Geraldi	Certified
2SSO10142	Active	794671 Tony Geraldi	Certified
2SSO10142	Active	796065 Tony Geraldi	Certified
2SSO10142	Active	797692 Tony Geraldi	Certified
2SSO10142	Active	798431 Tony Geraldi	Certified
2SSO10142	Active	799321 Thomas Barry	Certified
2SSO10142	Active	800721 Thomas Barry	Certified
2SSO10143	Active	719184	Submit Draft
2SSO10143	Active	719274	Submit Draft
2SSO10143	Active	725565	Ready To Certify
2SSO10143	Active	729009 Tom Roberts	Certified
2SSO10143	Active	731395 Tom Roberts	Certified
2SSO10143	Active	731397 Tom Roberts	Certified
2SSO10143	Active	731405 Tom Roberts	Certified
2SSO10143	Active	731416 Tom Roberts	Certified
2SSO10143	Active	731419 Tom Roberts	Certified
2SSO10143	Active	733129 Tom Roberts	Certified
2SSO10143	Active	748064 Tom Roberts	Certified
2SSO10143	Active	750038 Tom Roberts	Certified
2SSO10143	Active	751165 Tom Roberts	Certified
2SSO10143	Active	753082	Ready To Certify
2SSO10143	Active	763682 Tom Roberts	Certified
2SSO10143	Active	765142 Tom Roberts	Certified
2SSO10143	Active	796582	Ready To Certify
2SSO10145	Active	650104 Kent G. Peterson	Certified
2SSO10145	Active	650993 Dale McDonald	Certified
2SSO10145	Active	657116 Kent Peterson	Certified
2SSO10145	Active	708205 Kent Peterson	Certified
2SSO10145	Active	710554 Kent Peterson	Certified
2SSO10145	Active	711141 Kent Peterson	Certified
2SSO10145	Active	711347 Kent Peterson	Certified
2SSO10145	Active	714883 Dale McDonald	Certified
2SSO10145	Active	715308 Kent G. Peterson	Certified
2SSO10145	Active	715832 Kent G. Peterson	Certified
2SSO10145	Active	733491 Kent Peterson	Certified
2SSO10145	Active	735010 Dale McDonald	Certified
2SSO10145	Active	740852 Kent Peterson	Certified
2SSO10145	Active	740859 Kent Peterson	Certified

Supervisor

Supervisor

10/15/2012

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Tony Geraldi

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Supervisor

Leadman

Leadman

Manager

District Manager

Manager

General Manager

Genereal Manager

C.EO A M		624160
6:59 A.M.	7:02 AM	634160 726690
	7:18 AM	991504
	11:44	383636
	11:52	760492
	11:57	313242
	12:12	568821
	12:17	997228
	6:53	638641
	10:34 AM	745327
	10:29 AM	317148
	10:22 AM	395318
	10:14 AM	358242
	8:10	440219
	15:58	823458
	9:34	729186
8:29 A.M.		540362
	14:52	167814
44.44.8.88	8:14	307790
11:11 A.M.	C-27 ANA	148623
	6:37 AM	474901
	14:24	217713
	8:21 AM 1349	990194 948350
	1049	940330
Mill Valley, Marin County		846734
Mill Valley, Marin County		947105
Mill Valley, Marin County		468678
Mill Valley, Marin County		149355
Mill Valley, Marin County		231861
Mill Valley, Marin County		919861
Mill Valley, Marin County Mill Valley, Marin Co.		984593 926689
Mill Valley, Marin Co. Mill Valley, Marin County		209456
Mill Valley, Marin County		298949
will valicy, warm county		
Mill Valley, Marin County	5/8/2012	868538 751749
Crockett, CA	40/40/0040	583999
	12/10/2010	616955
Crackett CA	10:22	549091
Crockett, CA		514069
Crockett, CA Crockett		118207 572584
Crockett		810743
OTOORGIL	12/10/2010	204396
Crockett, CA	12/10/2010	292447
Crockett, CA		820022
and distribution of the second	14:12	111404
	12/10/2010	389756
	2:15 PM	749182
	2:41 PM	408915

28-Aug-12	8/28/2012	30-Aug-12	8/30/2012
18-Sep-12	9/18/2012	25-Sep-12	9/25/2012
9-Oct-12	10/9/2012	15-Oct-12	10/15/2012
3-Dec-12	12/3/2012	5-Dec-12	12/5/2012
3-Dec-12	12/3/2012	5-Dec-12	12/5/2012
3-Dec-12	12/3/2012	5-Dec-12	12/5/2012
3-Dec-12	12/3/2012	5-Dec-12	12/5/2012
3-Dec-12	12/3/2012	5-Dec-12	12/5/2012
18-Dec-12	12/18/2012	19-Dec-12	12/19/2012
22-Dec-12	12/22/2012	2-Jan-13	1/2/2013
23-Dec-12	12/23/2012	2-Jan-13	1/2/2013
23-Dec-12	12/23/2012	2-Jan-13	1/2/2013
23-Dec-12	12/23/2012	2-Jan-13	1/2/2013
31-Dec-12	1/2/2013	2-Jan-13	1/2/2013
4-Mar-13	3/4/2013	20-Mar-13	3/20/2013
18-Mar-13	3/19/2013	27-Mar-13	3/27/2013
9-Apr-13	4/9/2013	15-Apr-13	4/15/2013
30-Apr-13	5/8/2013	8-May-13	5/8/2013
3-Jun-13	6/3/2013	17-Jun-13	6/17/2013
25-Jun-13	6/25/2013	2-Jul-13	7/2/2013
8-Aug-13	8/20/2013	20-Aug-13	8/20/2013
4-Sep-13	9/11/2013	11-Sep-13	10/21/2013
1-Oct-13	10/2/2013	25-Oct-13	10/25/2013
13-Nov-13	11/14/2013	14-Nov-13	11/14/2013
9-Jun-08			
10-Jun-08			
2-Sep-08			
6-Nov-08		6-Nov-08	11/6/2008
5-Jan-09		5-Jan-09	1/5/2009
4-Feb-09		4-Feb-09	2/4/2009
1-Jan-10		1-Jan-10	1/1/2010
3-Mar-10		3-Mar-10	3/3/2010
31-Mar-10	0/0/2010	31-Mar-10	3/31/2010
6-Jun-10	6/6/2010	9 May 19	E1010040
24-Feb-11	2/24/2011	8-May-12	5/8/2012
5-Apr-11 9-Jul-13	4/5/2011 7/9/2013	5-Apr-11	4/5/2011
9-3ul-13 3-May-07	7/9/2013	8-May-07	5/8/2007
3-May-07 25-May-07		6-May-07 8-Jun-07	12/10/2010
11-Sep-07		11-Sep-07	9/11/2007
27-Nov-07		27-Nov-07	11/27/2007
31-Dec-07		31-Dec-07	12/31/2007
11-Jan-08		14-Jan-08	1/14/2008
17-Jan-08		17-Jan-08	1/17/2008
17-5an-08		17-3an-06 14-Mar-08	12/10/2010
25-Mar-08		25-Mar-08	3/25/2008
5-Apr-08		5-Apr-08	4/5/2008
12-Feb-09		12-Feb-09	2/12/2009
16-Mar-09		16-Mar-09	12/10/2010
8-Jul-09		8-Jul-09	7/8/2009
8-Jul-09		8-Jul-09	7/8/2009
2 04, 00		3 341 33	,,5,2000

Category 3		40	0
Category 1		275	32
Category 3		360	0
Category 1		67500	64800
Category 1		24000	0
Category 1		99000	95000
Category 1		450	0
Category 1		57600	0
Category 1		330	200
Category 1		12000	0
Category 1		40500	0
Category 1		6000	0
Category 1		6000	0
Category 1		1500	0
Category 3		840	0
Category 1		150	0
Category 1		1625	10
Category 3		75	0
Category 3		324	0
Category 1		420	20
Category 1		321	25
Category 3	0	3	0
Category 3	450	450	Ö
Category 1	68	218	89
Category 3	00	15	0
		20	0
Category 3		20	0
Category 3			
Category 3		15	0
Category 3		5	0
Category 3		50	50
Category 3		5	0
Category 3		5	0
Category 3		20	20
Category 3		500	0
Category 3		200	0
Category 3		30	0
Category 3		5	0
Category 1		325	325
Category 3		75	75
Category 1		900	0
Category 3		100	100
Category 2		2400	540
Category 1		200	25
Category 3		2	0
Category 3		2	0
Category 3		10	0
Category 3		50	0
Category 3		5	0
Category 1		150	0
Category 3		10	0
Category 3		10	0
Category 1		50	0
Category 1		150	0
Category 3		10	0
Category 3		15	0
~ ,			_

n	No	No
243		No
	No	Yes
2700		Yes
24000		Yes
4000		Yes
450		Yes
57600		Yes
130		No
12000		Yes
40500		Yes
6000		Yes
6000		Yes
1500		Yes
	No	No
150		Yes
1615		Yes
	No	No
	No	No
400		No
296		No
	No	No
	No	No
125		Yes
	No	No
0	No	No
_	No	No
•	No	No
325		No
	No	Yes
900		No
	No	No
	No	No
175		Yes
175	No	No
	No	No
150		Yes
	No	No
	No	No
	Yes	Yes
150		Yes
	No	No
	No	No
J		

```
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
No
No
No
No
No
No
Not Applicable - Spill did not reach a separate storm drainpipe
No
No
No
No
No
Not Applicable - Spill did not reach a separate storm drainpipe
No
No
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
No
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Yes
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
No
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
No
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
No
No
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
```

Hillsborough

Hillsbrough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

Hillsborough

981 greenhill road

Castle Rock Road

121 Reed St.

568 Montford Drive

405 Montford Ave

115 Reed Street

949 Greenhill Road

338 N. Ferndale Ave.

179 Homestead Blvd.

420 LaVerne Ave.

Greenhill Rd at Loring Ave

39 Castle Rock Dr.

514 Pixie Trail

LaVerne Ave. & Montford Ave., Mill Valley, Marin County, CA

981 Greenhill Road, Mill Valley

320 LaVerne Ave.

Intersection of LaVerne & Montford Aves.

Wanda Street, Crockett

Kendall Avenue, Crockett

Emerson Avenue

Emerson alley

1845 Pomona St

Emerson Avenue easement

EMERSON AVENUE

Merchant Street

Crolona Heights Drive

6 Crolona Heights Drive

Emerson Avenue easement

Merchant St.

Merchant Street

Pomona and Fifth Ave

37.53107	-122.35767 San Mateo
37.56429	-122.3731 San Mateo
37.53998	-122.35471 San Mateo
37.5529	-122.33964 San Mateo
37.54868	-122.3461 San Mateo
37.5529	-122.33964 San Mateo
37.57805	-122.36653 San Mateo
37.54868	-122.3461 San Mateo
37.53614	-122.34907 San Mateo
37.55583	-122.33889 San Mateo
37.55583	-122.33889 San Mateo
37.57734	-122.36735 San Mateo
37.55428	-122.35735 San Mateo
37.55588	-122.33886 San Mateo
37.5386	-122.35155 San Mateo
37.53877	-122.35337 San Mateo
37.57003	-122.35946 San Mateo
37.57083	-122.35569 San Mateo
37.55528	-122.34693 San Mateo
37.54887	-122.35154 San Mateo
37.57038	-122.37113 San Mateo
37.54164	-122.343 San Mateo
37.57038	-122.37113 San Mateo
37.55326	-122.36787 San Mateo
37.522222	122.543056 Marin
37.8825	122.55825 Marin
37.894444	122.5375 Marin
37.899722	122.551194 Marin
37.898333	122.547222 Marin
37.894333	122.543333 Marin
37.889528	122.534028 Marin
37.893889	122.545 Marin
37.891667	122.538194 Marin
37.897778	122.548611 Marin
37.889111	-122.533333 Marin
37.900833	-122.548056 Marin
37.899722	
	-122.550278 Marin
37.899722	-122.552778 Marin
37.89026	-122.54001 Marin
37.896778	-122.543958 Marin
37.89912	-122.5507 Marin
38.053889	122.2275 Contra Costa
38.053056	-122.233333 Contra Costa
38.051111	122.211944 Contra Costa
38.051389	122.211111 Contra Costa
38.053992	122.229097 Contra Costa
38.050861	122.21175 Contra Costa
38.050761	122.212092 Contra Costa
38.053489	-122.230567 Contra Costa
38.054722	122.219167 Contra Costa
38.054722	122.219167 Contra Costa
38.050861	122.21175 Contra Costa
38.053194	-122.230167 Contra Costa
38.053194	-122.230167 Contra Costa
38.052311	-122.225367 Contra Costa

Easement area on hill along side roadway.

Located in easement area behind all the homes.

Manhole on hill ajacent to driveway.

Manhole is located in the shoulder of the roadway.

Roadway

Manhole is located in the shoulder of the roadway.

Manhole in roadway.

Roadway

Easement area on side of a hill.

Manhole

Manhole along road shoulder and manhole at the intersection of Crystal Springs and Merner Rd.

Manhole in the roadway.

Manhole in roadway.

Manhole located in the shoulder of the roadway

Located in city easement area behind all the homes. Where sewage just soaked into the ground.

Manhole overflow in street

Manhole located in parking strip.

Manhole in street.

Easement area.

In easement area located across the street from 257 Woodridge. In dry creek bed area.

On fire trail in easement area behind 2280 Skyfarm Dr.

Manhole in the street located out 1020 Tournament Dr. in Hillsborough.

On fire trail in easement behind 2280 Skyfarm Dr

manhole overflow

Manhole overflow

Residential

Overflowing manhole

Overflow in Sewer Easement

Overflowing manhole

Overflowing manhole in paved roadway, unpaved shoulders on both sides.

Overflowing manhole

Manhole in road

Sewer cleanout

Overflow from manhole in road, flowed into drainage channel

Stoppage of sewer main resulting in overflow of manhole

Under house and in rear yard area of single family residence.

Intersection of LaVerne Ave. with Montford Ave.

Carquinez Bridge construction area under excavation by contractor for Caltrans. A dirt hillside area under the bridge.

Sewage was initially leaking intermittently thru private retaining wall along road. First report investigated on 5/19. Secon-

Manhole in the road

Dirt/gravel alley behind address.

Sidewalk area

Hillside easement, from cleanout E-03-15.

Spill occurred in the road from manhole E-03-10A.

Sewer cleanout W-10-01 located in a paved road.

Rodding inlet N-01-12 on a paved road was leaking.

Rodding inlet N-01-12 on Crolona Heights Dr. was found leaking for the second time. This is a repeat on an incident that Cleanout in hillside easement.

Manhole in street overflowed.

Spill located in the road trickling from a crack in the pavement.

Sidewalk at end of Fifth Ave



Gravity sewer; Manhole

Gravity sewer; Other (specify)

Gravity sewer; Manhole

Gravity sewer; Manhole

Gravity sewer; Manhole

Gravity sewer; Manhole

Gravity sewer

Gravity sewer; Manhole

Manhole; Gravity sewer

Gravity Mainline

Manhole

Manhole

Pump station

Other sewer system structure

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Manhole

Gravity sewer

Manhole

Manhole

Gravity sewer

Gravity sewer

Gravity sewer

Other (specify)

Manhole

Gravity sewer

Other sewer system structure

Other sewer system structure

Manhole

Other sewer system structure

Other sewer system structure

Other sewer system structure

Other sewer system structure

Manhole

Other (specify)

Manhole

See above
See above
See above.
See above
Manhole
See above
Manhole
Manhole
Fracture in sewer main caused by a fallen tree.
See above
See above.
See above.
See above
see above
Manhole
Manhole
See above
Manhole
See above
See above.
See above
See above
see above
coming out of manhole
· · · · · · · · · · · · · · · · · · ·
Rod Hole overflowing on hillside below 121 Reed St.
Sewer cleanout
Sewer Cleanout
Sewage overflowed from ground floor plumbing fixtures and from rear yard cleanout.
Intermittent spill was first thought to be coming from a private lateral, as determined by dye test. Owner was notified of the
Material San from a placed place of
Water was trickling from a closed cleanout.
Dodding inlat N 04.49
Rodding inlet N-01-12
Small crack in the pavement of the street.
and order in the parential of the erect.

Unpaved surface

Unpaved surface

Separate storm drain; Street/curb and gutter; Unpaved surface

Separate storm drain; Street/curb and gutter; Surface water; Unpaved surface

Surface water;Unpaved surface

Street/curb and gutter; Surface water

Separate storm drain

Surface water; Unpaved surface

Unpaved surface

Separate storm drain; Street/curb and gutter; Surface water

Street/curb and gutter; Surface water; Unpaved surface

Separate storm drain; Street/curb and gutter

Separate storm drain; Street/curb and gutter

Combined storm drain (combined CS only)

Unpaved surface

Separate storm drain

Separate storm drain; Street/curb and gutter; Unpaved surface

Other paved surface

Unpaved surface

Unpaved surface

Unpaved surface

Paved Surface

Drainage Channel

Paved Surface; Separate Storm Drain

Other (specify below)

Unpaved surface

Other (specify below)

Separate storm drain

Surface water

Other (specify below)

Unpaved surface

Separate storm drain

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Separate storm drain

Street/curb and gutter

Street/curb and gutter

Surface water

Separate storm drain; Street/curb and gutter

Street/curb and gutter

Other paved surface; Unpaved surface

Spill soaked into dirt area along the side of the roadway. Spill soaked into the ground. See above. See above
See above See above See above See above See above See above San Mateo Creek Flow exceeded capacity due to heavy rains, went into storm drain. See above. see above See question sixteen. see 16 See above See above. Spill ran down the fire trail.
See above. spill ran down fire trail and off the road to Sanchez creek which is a dry creek bed in summer months
Unpaved roadside ditch. Unpaved dirt channel, yard/land
Spillage flowed into drainage channel, not carrying water at the time of the SSO. Spillage contained in natural pockets in
Spill flowed into waterway at rear of property, and thence into Richardson Bay, about 1 mile downstream. Dry creek bed
Spill was able to dry in the roadside gutter.
Other paved surface was sidewalk with slight slope to dirt embankment.

8/28/2012 7:45	8/28/2012 7:55	8/28/2012 8:00	8/28/2012 8:05
9/8/2012 20:00	9/8/2012 20:10	9/8/2012 20:35	9/8/2012 20:55
10/7/2012 11:45	10/7/2012 12:00	10/7/2012 13:00	10/7/2012 13:45
11/30/2012 8:30	11/30/2012 8:00	11/30/2012 8:10	11/30/2012 15:00
11/30/2012 10:00	11/30/2012 11:00	11/30/2012 11:20	11/30/2012 14:00
12/2/2012 7:00	12/2/2012 6:00	12/2/2012 6:30	12/2/2012 20:00
12/2/2012 8:00	12/2/2012 8:17	12/2/2012 8:35	12/2/2012 9:00
12/2/2012 10:00	12/2/2012 10:35	12/2/2012 10:35	12/2/2012 16:00
12/6/2012 14:45	12/6/2012 15:15	12/6/2012 15:30	12/6/2012 17:30
12/22/2012 7:00	12/22/2012 7:30	12/22/2012 7:30	12/22/2012 11:00
12/23/2012 10:30	12/23/2012 11:00	12/23/2012 12:30	12/23/2012 18:30
12/23/2012 14:00	12/23/2012 14:45	12/23/2012 15:15	12/23/2012 18:00
12/23/2012 15:00	12/23/2012 15:00	12/23/2012 15:20	12/23/2012 17:30
12/31/2012 11:30	12/31/2012 11:30	12/31/2012 11:30	12/31/2012 12:00
3/2/2013 13:30	3/2/2013 16:30	3/2/2013 17:30	3/2/2013 20:30
3/17/2013 22:15	3/17/2013 22:30	3/17/2013 23:15	3/17/2013 23:30
4/6/2013 9:40	4/6/2013 10:00	4/6/2013 10:30	4/6/2013 10:45
4/30/2013 13:25	4/30/2013 13:30	4/30/2013 13:35	4/30/2013 13:40
5/30/2013 9:45	5/30/2013 11:15	5/30/2013 11:30	5/30/2013 12:27
6/16/2013 10:30	6/16/2013 10:45	6/16/2013 11:30	6/16/2013 2:00
8/7/2013 13:50	8/7/2013 14:45	8/7/2013 15:05	8/7/2013 15:37
8/27/2013 18:16	8/27/2013 18:35	8/27/2013 19:10	8/27/2013 19:15
10/1/2013 10:30	10/1/2013 10:45	10/1/2013 11:00	10/1/2013 11:15
11/13/2013 13:46	11/13/2013 14:06	11/13/2013 14:11	11/13/2013 14:16
6/5/2008 9:20	6/5/2008 9:20	6/5/2008 9:30	6/5/2008 10:30
5/2/2008 9:30	5/2/2008 9:33	5/2/2008 9:30	5/2/2008 10:30
8/15/2008 8:15	8/15/2008 8:30	8/15/2008 8:47	8/15/2008 9:01
10/13/2008 9:10	10/13/2008 9:10	10/13/2008 9:15	10/13/2008 9:40
12/6/2008 11:30	12/6/2008 11:30	12/6/2008 12:00	12/6/2008 12:00
12/6/2008 1:00	12/6/2008 1:00	12/6/2008 1:00	12/6/2008 2:00
12/12/2008 11:55	12/12/2008 11:55	12/6/2008 12:25	12/12/2008 12:50
12/29/2008 10:05	12/29/2008 10:05	12/29/2008 10:15	12/29/2008 10:45
12/31/2008 10:00	12/31/2008 10:00	12/31/2008 10:20	12/31/2008 11:15
1/14/2009 4:00	1/14/2009 4:00	1/14/2009 4:30	1/14/2009 7:30
12/5/2009 12:05	12/5/2009 12:05	12/5/2009 12:55	12/5/2009 2:30
2/8/2010 15:30	2/8/2010 15:30	2/8/2010 15:45	2/8/2010 16:15
3/6/2010 8:57	3/6/2010 8:57	3/6/2010 8:57	3/6/2010 9:45
5/12/2010 11:00	5/12/2010 11:00	5/12/2010 11:10	5/12/2010 11:40
2/23/2011 13:15	2/23/2011 13:15	2/23/2011 13:30	2/23/2011 13:35
3/22/2011 20:30	3/22/2011 20:30	3/22/2011 21:15	3/22/2011 22:15
6/8/2013 8:45	6/8/2013 8:45	6/8/2013 9:00	6/8/2013 9:20
5/3/2007 8:30	5/3/2007 9:10	5/3/2007 9:20	5/3/2007 10:25
5/24/2007 6:30	5/24/2007 9:00	5/24/2007 9:30	5/24/2007 9:58
9/10/2007 16:00	9/10/2007 16:05	9/10/2007 16:30	9/10/2007 16:40
11/25/2007 8:00	11/25/2007 14:34	11/25/2007 15:01	11/26/2007 13:45
12/26/2007 0:00	12/26/2007 13:25	12/26/2007 13:55	12/26/2007 14:02
1/10/2008 0:00	1/10/2008 18:03	1/10/2008 18:12	1/10/2008 18:46
1/16/2008 8:00	1/16/2008 8:37	1/16/2008 8:52	1/16/2008 9:00
3/14/2008 6:00	3/14/2008 8:07	3/14/2008 8:17	3/14/2008 9:08
3/24/2008 15:30	3/24/2008 16:00	3/24/2008 16:20	3/24/2008 19:15
3/27/2008 10:00	3/27/2008 11:15	3/27/2008 12:25	3/27/2008 14:10
2/12/2009 11:18	2/12/2009 11:20	2/12/2009 11:00	2/12/2009 11:18
3/16/2009 0:00	3/16/2009 12:20	3/16/2009 13:45	3/16/2009 0:00
7/5/2009 0:00	7/5/2009 12:30	7/5/2009 12:58	7/5/2009 14:40
7/8/2009 0:00	7/8/2009 11:10	7/8/2009 11:14	7/8/2009 11:30
17012000 0.00	77072000 11.10	77072000 11.14	77072000 11.00

Other (specify below)

Root intrusion

Root intrusion

Flow exceeded capacity (Separate CS Only)

Pipe structural problem/failure

Flow exceeded capacity (Separate CS Only)

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Debri-Rags

Debri-Rags

Root intrusion

Debri-Rags

Grease deposition (FOG)

Debris from Lateral

Root Intrusion

Other (specify below)

Root intrusion

Root intrusion

Other (specify below)

Debris

Debris

Root intrusion

Debris

Grease deposition (FOG)

Root intrusion

Debri-General

Other (specify below)

Other (specify below)

Other (specify below)

Grease deposition (FOG)

Root intrusion

Other (specify below)

Other (specify below)

Pipe structural problem/failure

Root intrusion

Root intrusion

Debris

Root intrusion

Debris

Debri-General

Root intrusion

Root intrusion

Other (specify below)

Debri-Rags

Debri-Rags

Debri-Rags

Some debri such as roadway buttons, and some root intrusion. See above
Root intrusion at the base of the eighteen foot deep manhole.
See above
See above
See above
See above.
See above.
See above
See above
Flow exceeded capacity due to big storm.
Heavy rains caused the sewer main to overflow due to flow exceeding capacity.
Flow exceeded capacity due to heavy rains.
Doing routine maint. on sewer main and line started backing up as we were doing it.
See above
construction debris metal band & heavy dirt concentration
Root intrusion. Some root intrusion also.
See above
See above See above
See above.
See above.
see above
see above
grease and roots
Grease, grit/gravel
Orado, griugiavoi
Croase, gridgiaver
Cause of stoppage not determined
Cause of stoppage not determined Wipes, tree root intrusion
Cause of stoppage not determined
Cause of stoppage not determined Wipes, tree root intrusion
Cause of stoppage not determined Wipes, tree root intrusion
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation. Pipe failure was due to multiple illegal, defective lateral connections and illegal lateral materials.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation. Pipe failure was due to multiple illegal, defective lateral connections and illegal lateral materials.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation. Pipe failure was due to multiple illegal, defective lateral connections and illegal lateral materials.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation. Pipe failure was due to multiple illegal, defective lateral connections and illegal lateral materials.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation. Pipe failure was due to multiple illegal, defective lateral connections and illegal lateral materials. This line had been cleaned by rodder just one day earlier. Investigation in progress.
Cause of stoppage not determined Wipes, tree root intrusion Paper, roots, grit/gravel Grit, gravel, grease Contractor for Caltrans broke well-marked sewer with bulldozer during site excavation. Pipe failure was due to multiple illegal, defective lateral connections and illegal lateral materials.

Main		
Upper Lateral		
Main		
Gravity Mainline		
Gravity Mainline		
Main		
Main		
Main		
Main Main		
Main Main Main		
Main Main		
Main Main Main Main		
Main Main Main Main		
Main Main Main Main Main		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main Main Main Other (specify below)		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main Main Main Other (specify below)		
Main Main Main Main Main Main Main Other (specify below) Other (specify below)		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main Main Main Other (specify below) Other (specify below)		
Main Main Main Main Main Main Main Main		
Main Main Main Main Main Main Main Other (specify below) Other (specify below)		
Main Main Main Main Main Main Main Main		

See above Smartcover alarm notifies the Town Public Works crew the flow is beginning to rise out of the channel in the manhole
Smartcover alarm notifies Town Public Works crew the flow is beginning to rise out of the channel in the manhole. Before See above.
See above See above. See above.
See above See above See above See above
See above. See above. CCTVD main line segment and pipe was in good condition. Four inch roots that must have come from a clogged lateral that a plumber unclogged for a home owner and caused are r
Failed illegal lateral connections to main line
Cleanout

	6 VCP 6 VCP 6 VCP
. Before the actual SSO begi	15 VCP
	15 Liner
∍ the actual SSO begins to s∟	15 VCP
	6 HDPE
	15 Liner
	8 VCP
	15 VCP
	15 VCP
	6 VCP
	8 HDPE
	15 VCP
	6 VCP
	6 VCP
	10 liner
	8 VCP
	6 liner
	6 liner
No	6 VCP 6 VCP
No No	6 VCP
No	6 VCP
NO	6 clay
	6 plastic
	6 Clay
	Clay
	Olay

6 Clay
6 VCP
4 steel
Plastic
6 Clay
6 clay
6 Clay
8 DIP
6 VCP
6 HDPE
6 VCP
4 VCP
6 VCP
6 VCP
4 VCP
6 VCP
6 VCP
6 VCP
4 VCP
4 VCP

4 VCP

ED_006495_00001080-02623

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill):Inspected sewer using CCTV to determine cause:Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-Up; Mitigated Effects of Spill; Contained all or portion of spill

Restored flow

Restored flow

Restored flow

Restored flow

Restored flow

Contained all or portion of spill

Restored flow

Restored flow

Restored flow

Restored flow; Returned all or portion of spill to sanitary sewer system

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill)

Contained all or portion of spill

Restored flow; Returned all or portion of spill to sanitary sewer system

Restored flow

Cleaned-up (mitigated effects of spill)

Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanitary sewer system

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow;Returned all or por

Restored flow

Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

See above. See above. See above. Se above Put out barricades and posted raw sewage spill signs around spill area. See above
See above. CCTV the main line and did a temparary fix, will be pipe bursting the main line weather permitting within the next three weather subsided flows slowly went back to normal. As the heavy rains subsided the flows slowly returned to normal. As the rains subsided the flows slowly returned to normal. See above. see above
See above. Restored Flow Inspected seRestored Flowwer using CCTV Cleaned up mitigated effects of spill Pulled out roots that were growing at the base of the manhole. Also main line had some root growing in it so we recleaned the line with the power rodder and jetted it. Will be having che Will be CCTVing main line this week some time. Very steep easement area, crew cleaned up and mitagated the effects of the spill. Very hard area to CCTV because of the spill is the country of the spill is the count
After CCTVing, the main looks to be in good condition, the cause was just rags and debri in the line.
Removed blockage, restored flow thru pipe, vacuumed spillage from dry creek bed, cleaned up site.
Minor seepage was noted in a dirt/gravel alley and contained there.

10/8/2012 11:00 12/3/2012 11:30 11/30/2012 11:59 12/3/2012 12:00 12/3/2012 8:30 12/3/2012 12:00 12/22/2012 11:30 12/23/2012 18:30 12/23/2012 18:30 12/23/2012 17:33 12/31/2012 12:00 3/18/2013 10:00 4/8/2013 14:30

11/13/2013 14:16

5/13/2010 10:45

3/22/2011 21:30

5/3/2007 10:25 5/24/2007 10:25

3/14/2008 9:30

2/12/2009 12:00 3/16/2009 14:45

Other (specify below) Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Other (specify below) Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer Other (specify below) Other (specify below) Plan rehabilitation or replacement of sewer Other (specify below) Adjusted schedule/method of preventive maintenance Inspected Sewer Using CCTV to Determine Cause Repaired sewer Adjusted schedule/method of preventive maintenance Other (specify below) Repaired sewer Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance; Plan rehabilitation or replacement of sewer

Planned rehab of sewer main as per CDO. Planned rehab of sewer main in a few years as per CDO. Planned rehab of sewer main as per CDO. Capacity issues all the way downstream into Burlingame area. planned rehab of sewer main in a few years as per CDO. Planned rehab of sewer main as per CDO. Planned rehab of Sewer main as per CDO. To much storm surge for the sewer main capacity. Heavy rains causing capacity problems on sewer main line. Planned rehab of sewer main as per CDO This section of mainline is under chemical root foaming and after CCTVing line the pipe looks very good inside, SSO was See above chemically treat line Sewer is being relocated by contractor for Caltrans. Sewer was repaired on May 31, 2007. Preventive maintenance of this sewer was behind schedule because the County had paved over our access structure. W

Pulled out root mass that was growing at the bottom of the manhole and treated the base of the manhole with chemical rc

No No

No

No

No

No

No

No No

No

No

Yes Yes

Yes

CCTV

No

No

No No

Yes

No No

ED_006495_00001080-02629

NA NA San Mateo Creek was running clear and fast. Creek was clear and running like a river. Creek was running clear and fast. NA Creek was running clear and fast. NA Creek was running fast and clear. San Mateo Creek was running clear and fast.
San Mateo creek was running clear and fast. Dam release going on from Crystal Springs Dam NA
NA
Storm water runoff extremely high due to heavy rainfall Spill did not reach receiving waters.
Not applicable

No Yes

Yes

Yes

No Yes

Yes

Yes

No

No Yes

No No

No

No

No

No

No No

No

No

No

NA Spill did not reach any beaches. NA NA NA

NA NA

ED_006495_00001080-02632

NA NA NA San Mateo Creek San Mateo Creek San Mateo Creek Have no name for this creek. San Mateo Creek NA San Mateo Creek San Mateo Creek Creek name unknown. San Mateo Creek San Mateo Creek NA NA NA NA NA

NA

NA NA

Richardson Bay No surface waters were impacted NA Carquinez Strait

Carquinez Strait

Carquinez Strait Carquinez Strait Not applicable to this spill No water quality samples taken No water quality samples taken No water quality samples taken Not applicable to this spill No water quality samples taken No water quality samples taken No water quality samples taken Not applicable to this spill No water quality samples taken Not applicable to this spill Not applicable to this spill No water quality samples taken; Not applicable to this spill No water quality samples taken; Not applicable to this spill No water quality samples taken No water quality samples taken

No water quality samples taken; Not applicable to this spill

To dangerous to take water samples creek was flowing full and fast.

To dangerous to take water samples creek was running like a river.

To dangerous to take water samples creek was flowing more like a river then a creek. Many calls coming in.

No samples taken to dangerous. To dangerous to take water samples.

see above

See above

Not applicable to this spill None of the above None of the above None of the above None of the above	
None of the above	
None of the above None of the above	
None of the above	
None of the above	
None of the above	
None of the above	
None of the above	
Regional Water Quality Control Board	
Not applicable to this spill	
County Health Agency	
None of the above None of the above	
None of the above	
No water quality samples taken	
None of the above	

Picture sewer overflow charts

Measurement of spill & manhole overflow picture charts

126036	10/7/2012 15:25
127246	11/30/2012 11:10
127248	11/30/2012 11:10
127377	12/3/2012 14:34
127379	12/3/2012 2:34
127378	12/3/2012 14:34
127817	12/22/2012 13:57
127862	12/23/2012 19:10
127863	12/23/2012 19:10
127864	12/23/2012 19:10
128017	12/31/2012 15:45
121646	3/18/2013 10:00
131646	
132066	4/6/2013 15:00

137023 11/13/2013 15:10

82056 3/14/2008 9:46

92295 3/16/2009 13:29

Tony Geraldi thomas Barry Thomas Barry

6503757507 6503757507 18008527550

2SSO10145	Active	745477 Kent Peterson	Certified
2SSO10145	Active	746819 Kent Peterson	Certified
2SSO10145	Active	758851 Dale McDonald	Certified
2SSO10145	Active	767998 Dale McDonald	Certified
2SSO10145	Active	774250 Dale McDonald	Certified
2SSO10145	Active	775583 Dale McDonald	Certified
2SSO10145	Active	775915 Dale McDonald	Certified
2SSO10145	Active	776553 Dale McDonald	Certified
2SSO10145	Active	778556 Dale McDonald	Certified
2SSO10145	Active	782169 Dale McDonald	Certified
2SSO10145	Active	785627 Dale McDonald	Certified
2SSO10145	Active	788811 Dale McDonald	Certified
2SSO10145	Active	789237 Dale McDonald	Certified
2SSO10145	Active	790387 Dale McDonald	Certified
2SSO10145	Active	791644 Dale McDonald	Certified
2SSO10145	Active	792863 Dale McDonald	Certified
2SSO10145	Active	793375 Michael Kirker	Certified
2SSO10145	Active	797698 Dale McDonald	Certified
2SSO10145	Active	798598 Dale McDonald	Certified
2SSO10145	Active	800653 Dale McDonald	Certified
2SSO10145	Active	800658 Dale McDonald	Certified
2SSO10147	Active	654298 Mark Williams	Certified
2SSO10147	Active	655946 Mark Williams	Certified
2SSO10147	Active	657190 Mark Williams	Certified
2SSO10147	Active	657906 Mark Williams	Certified
2SSO10147	Active	706711 Mark Williams	Certified
2SSO10147	Active	706713 Mark Wiliams	Certified
2SSO10147	Active	710648 Mark Williams	Certified
2SSO10147	Active	710763 Mark Williams	Certified
2SSO10147	Active	711378 Mark Williams	Certified
2SSO10147	Active	716141 Mark Williams	Certified
2SSO10147	Active	718494 Mark Williams	Certified
2SSO10147	Active	733945 Mark Williams	Certified
2SSO10147	Active	741413 Mark Williams	Certified
2SSO10147	Active	742206 Mark Williams	Certified
2SSO10147	Active	742561 Mark Williams	Certified
2SSO10147	Active	744524 Mark Williams	Certified
2SSO10147	Active	749433 Mark Williams	Certified
2SSO10147	Active	750874 Mark Williams	Certified
2SSO10147	Active	764761 Mark Williams	Certified
2SSO10147	Active	769397 Mark Williams	Certified
2SSO10147	Active	779642 Mark Williams	Certified
2SSO10147	Active	785346 Mark Williams	Certified
2SSO10147	Active	786834 Mark Williams	Certified
2SSO10147	Active	787647 Mark Williams	Certified
2SSO10147	Active	788533 Mark Williams	Certified
2SSO10147	Active	788658 Mark Williams	Certified
2SSO10147	Active	788668 Mark Williams	Certified
2SSO10147	Active	789284 Mark Williams	Certified
2SSO10147	Active	796333 Mark Williams	Certified
2SSO10147	Active	799920 Janice Mandler	Certified
2SSO10148	Active	657916 Karl Kraft	Certified
2SSO10148	Active	704866 Karl Kraft	Certified
2SSO10148	Active	708467 Karl Kraft	Certified
2SSO10148	Active	711662 Karl Kraft	Certified

General Manager

General Manager General Manager

Manager

General Manager

General Manager

General Manager

General Manager

District Manager

General Manager

District Manager

District Manager

General Manager

District Manager

District Manager

General Manager

District Manager

District Manager

District Manager

General Manager

Collections System Manager

Public Works Supervisor

Public Works Supervisor

Public Works Supervisor

Public Works Supervisor-Collections

	3:28 PM	766736
	3:07 PM	291750
Crockett CA		680333
Crockett CA		431646
Crockett, CA		906612
Crockett, CA		753736
Crockett, CA		491994
Crockett, CA		997048
Crockett, CA		918784
Crockett, CA		767092
Crockett, CA		246873
Crockett, CA		686977
Crockett, CA		576123
Crockett, CA		421479
Crockett, CA		343409
Crockett, CA		992398
Crockett		694711
Crockett, CA		255970
Crockett, CA		343857
Crockett, CA		668846
Crockett, CA		291184
		682615
Las Gallinas Valley Sanitary District San Rafael		
		637631
Las Gallinas Valley Sanitary District	40.50	735110
One Defect	10:50	725896
San Rafael	0.00	855853
1 0 W 1 0 W 10 W	8:30	210447
Las Gallinas Valley Sanitary District		826898
San Rafael		272640
Las Gallinas		376682
Las Gallinas		178183
Las Gallinas		859049
San Rafael		479385
San Rafael		120732
San Rafael		425156
San Rafael		256748
Las Gallinas		499453
San Rafael		485552
Las Gallinas		878403
San Rafael		342169
San Rafael		147307
San Rafael		994564
San Rafael		552035
San Rafael		210546
San Rafael		757611
San Rafael		236831
San Rafael		607505
San Rafael		487298
San Rafael		277781
San Rafael		722891
San Rafael		294076
Livermore, CA		465869
City of Livermore		915050
City of Livermore		250848
City of Livermore		162700

7-Oct-09		7-Oct-09	10/7/2009
17-Nov-09		17-Nov-09	11/17/2009
22-Nov-10	11/22/2010	23-Nov-10	11/23/2010
29-Jun-11	7/22/2011	22-Jul-11	7/22/2011
17-Dec-11	12/17/2011	20-Dec-11	12/20/2011
9-Jan-12	1/9/2012	9-Jan-12	1/9/2012
17-Jan-12	1/17/2012	17-Jan-12	1/17/2012
28-Jan-12	1/28/2012	28-Jan-12	1/28/2012
9-Mar-12	3/9/2012	9-Mar-12	3/9/2012
14-Jun-12	6/14/2012	14-Jun-12	6/14/2012
28-Aug-12	8/28/2012	28-Aug-12	8/28/2012
5-Dec-12	12/5/2012	5-Dec-12	12/5/2012
21-Dec-12	12/21/2012	21-Dec-12	12/21/2012
16-Jan-13	1/16/2013	16-Jan-13	1/16/2013
13-Feb-13	2/13/2013	13-Feb-13	2/13/2013
25-Mar-13	3/25/2013	25-Mar-13	3/25/2013
15-Apr-13	4/15/2013	15-Apr-13	4/15/2013
8-Aug-13	8/8/2013	8-Aug-13	8/8/2013
9-Sep-13	9/9/2013	9-Sep-13	9/9/2013
12-Nov-13	11/12/2013	12-Nov-13	11/12/2013
12-Nov-13	11/12/2013	12-Nov-13	11/12/2013
18-Jul-07		19-Jul-07	7/19/2007
17-Aug-07		17-Aug-07	4/1/2011
11-Sep-07		11-Sep-07	9/11/2007
24-Sep-07		24-Sep-07	9/24/2007
29-Oct-07		29-Oct-07	12/2/2010
29-Oct-07		29-Oct-07	10/29/2007
3-Jan-08		3-Jan-08	1/3/2008
7-Jan-08		26-Jun-08	12/6/2010
17-Jan-08		17-Jan-08	1/17/2008
15-Apr-08		18-Apr-08	4/18/2008
30-May-08		30-May-08	5/30/2008
23-Feb-09		2-Mar-09	12/2/2010
18-Jul-09		20-Jul-09	12/6/2010
31-Jul-09		31-Jul-09	12/6/2010
6-Aug-09		6-Aug-09	12/13/2010
10-Sep-09		10-Sep-09	9/10/2009
18-Feb-10		18-Feb-10	2/19/2010
23-Mar-10		23-Mar-10	3/23/2010
24-Mar-11	3/24/2011	24-Mar-11	5/2/2011
1-Aug-11	8/1/2011	2-Aug-11	8/2/2011
5-Apr-12	4/5/2012	9-Apr-12	4/9/2012
21-Aug-12	8/21/2012	21-Aug-12	8/21/2012
1-Oct-12	10/1/2012	10-Oct-12	10/10/2012
29-Oct-12	10/29/2012	30-Oct-12	10/30/2012
28-Nov-12	11/28/2012	29-Nov-12	11/29/2012
2-Dec-12	12/2/2012	3-Dec-12	12/3/2012
3-Dec-12	12/3/2012	3-Dec-12	12/6/2012
23-Dec-12	12/23/2012	31-Dec-12	12/31/2012
1-Jul-13	7/1/2013	2-Jul-13	7/2/2013
18-Oct-13	10/18/2013	22-Oct-13	10/22/2013
24-Sep-07		24-Sep-07	9/24/2007
9-Oct-07		10-Oct-07	10/10/2007
30-Nov-07		30-Nov-07	11/30/2007
24-Jan-08		24-Jan-08	1/24/2008

Category 3		50	0
Category 3		5	0
Category 2		3700	0
Category 1		1044	0
Category 1		1560	0
Category 3		15	0
Category 3		834	0
Category 2		1275	0
Category 3		313	0
Category 3		420	0
Category 3		300	0
Category 1		325	65
Category 3		5	0
Category 1		5297	10
Category 1		850	0
Category 3		180	25
Category 3		40	0
• •			
Category 3	4 =	528	0
Category 3	45	45	0
Category 3	60	60	0
Category 3	20	20	0
Category 3		40	0
Category 3		51	0
Category 3		100	0
Category 1		180	0
Category 3		50	0
Category 3		1	1
Category 3		150	0
Category 3		8	0
Category 3		200	
Category 3		50	0
Category 3		1	0
Category 1		1200	0
Category 1		1700	1600
Category 1		30	0
Category 1		800	300
Category 3		225	112
Category 3		150	150
Category 3		75	0
Category 1		780	0
Category 2		1440	0
Category 3		72	20
Category 3		300	0
		52500	37000
Category 1		52500	480
Category 1			
Category 1		100	0
Category 1		2000	0
Category 3		238	238
Category 1		480	0
Category 1	• -	875	0
Category 1	32	192	0
Category 3		600	600
Category 3		145	145
Category 3		725	725
Category 3		405	405

0 0 1044 50 0 0 0 260 0 5287 850 0 0	Yes No No No No No No Yes No Yes		No No Yes Yes No No Yes No No Yes No No No Yes No
180	No No		No Yes
	No		Yes
	No No		No No
0	No		No
	No		No
	No		No
	No		No
200			No
100			Yes
30 500	No No		Yes Yes
	No		No
	No		Yes
	No		No
780	Yes		No
	No		Yes
	No		No
ں 13500	No		No Yes
	No		Yes
100			Yes
2000	No		Yes
	No		No
480			Yes
875			No
160	Yes		Yes
	No No		No No
	No		No
	No		No
			-

Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Yes Not Applicable - Spill did not reach storm drainpipe Yes Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No No No Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe

W-10-05 RI easement between houses near 1906 Vista Del Rio

519 Vallejo Street

Rolph Park Court Easement MH S-01-05

925 First Ave

219 Winslow

1845 Pomona RI W-04-04

V-21-07 5th and Pomona

Rose and Third

W-10-05 easement between Vista Del Rio and Carquinez Way

MH N-01-11 in street near 4 Crolona Heights, Crockett

714 Alhambra N-05-06 LH

N-00-32 to N-00-31

V-22-08 3rd Street Easement

Merchant St and Kendall Ave - MH W-00-10

235 Kendall Ave MH W-00-09

Manhole N-00-30 near 300 Winslow

5th Ave

Pomona and Baldwin MH E-00-09

W-04-04 1849 Pomona

E-03-15 Emerson

V-21-07

North San Pedro and Oakcrest

El Faisan Drive

13 Meadow Dr

60 Park Ridge

Tarrant Court

595 Los Colindas

708 Butternut Dr

823 La Playa

2 Jeannette Prandi Wy

67 Los Ranchitos

19 Jefferson

700 Monticello Road

McGinnis Parkway and Waterside Cir

118 N. San Pedro Rd. San Rafael, CA 94903

McGinnis Parkway and Waterside Cir

685 Blackberry Lane

3769 Redwood Highway

2200 Idylberry

Las Gallinas Avenue

35 Elda Dr

50 Merrydale Rd.

9 Edgehill Way

811 Descanso Way

2130 Elderberry

Los Ranchitos and Northgate Dr

301 Las Gallinas

Los Ranchitos/Northgate Dr

Las Gallinas Avenue / Manual T Freitas Pkwy

1010 Northgate Dr.

30 North San Pedro Rd

In front of 6372 Almaden Way, cross of Eagle Ct.

4352 Davis Way, Livermore CA

N. Livermore Ave @ Portola

1249 Hansen Rd. cross of Impruneta Ct.

38.05283	-122.23097 Contra Costa
38.054269	-122.211828 Contra Costa
38.05075	-122.22005 Contra Costa
38.05122	-122.22455 Contra Costa
38.05441	-122.20839 Contra Costa
38.05408	-122.22926 Contra Costa
38.05223	-122.22525 Contra Costa
38.04931	-122.22301 Contra Costa
38.05297	-122.23079 Contra Costa
38.0548	-122.21943 Contra Costa
38.05462	-122.21706 Contra Costa
38.05502	-122.21026 Contra Costa
38.05227	-122.223 Contra Costa
38.05338	-122.23079 Contra Costa
38.05385	-122.23033 Contra Costa
38.05512	-122.21068 Contra Costa
38.05236	-122.22537 Contra Costa
38.052389	-122.209086 Contra Costa
38.054034	-122.229132 Contra Costa
38.050825	-122.211791 Contra Costa
38.052326	-122.225377 Contra Costa
38	122.516667 Marin
38.00042	-122.54763 Marin
38.00198	122.52388 Marin
38.01185	122.5558 Marin
38.00083	-122.55036 Marin
38.1925	122.961944 Marin
38.012222	122.563611 Marin
38.01405	-122.51196 Marin
38.02147	122.57204 Marin
37.98703	122.53875 Marin
37.99465	122.53219 Marin
38.01277	-122.5629 Marin
38.00783	-122.52655 Marin
37.99725	-122.52766 Marin
38.00783	-122.52655 Marin
38.02773	-122.5565 Marin
37.99766	-122.53562 Marin -122.58415 Marin
38.0366	
38.0024 38.00531	-122.55288 Marin -122.56043 Marin
37.99295	-122.58043 Marin
37.99293 37.99569	-122.53206 Marin
38.0162	-122.52372 Marin
38.02692	-122.51421 Marin
38.00121	-122.5396 Marin
37.99722	-122.54254 Marin
38.00121	-122.53976 Marin
38.00962	-122.54895 Marin
38.01016	-122.54093 Marin
37.99531	-122.54239 Marin
37.713056	121.719444 Alameda
37.683333	121.683333 Alameda
37.691931	121.773194 Alameda
37.638056	121.773194 Alameda 121.793056 Alameda
37.030030	12 1.7 93030 Alameda

Easement between houses starting at W-10-05 Rodding Inlet and continuing down dirt hill to Carquinez Way.

Retaining wall in front of property

Overflowing MH on hillside easement between homes, flow down trail to embankment in gated and fenced off wooded are

MH in easement at rear of property, dirt hillside. Waste water flowed through drainage pipe to curb/gutter.

Rodding inlet

Rodding Inlet with sewage 10' along dirt embankment

Clean-out near Rose and Third

Spill coming from ground approx 50' downstream from RI W-10-05. Running along ground for approx 5' then enters frenc Public sewer manhole in private street near 4 Crolona Heights. Wastewater (no solids, no odor, clear) weeping from MH Lamp hole sewer structure in back yard

Manhole N-00-32 in front of 325 Winslow St, Crockett, CA

Manhole W-00-10 at intersection of Merchant and Kendall Sewer access box W-00-09
Manhole N-00-30 in street near 300 Winslow common walkway, hillside

Rodding inlet E-03-15 on Emerson

Water pooling on manhole
In open field dirt behind 110 La Alondra Ct townhouse

1gpm of sewage coming from manhole

Homeowners yard (dirt)
Wastewater seeped out from toilet seal.

Toilet burped while crew was flushing causing 1 gallon of toilet water to spray the bathroom wall.

Marin Water Dept was digging trench to replace water main and hit sewer line. Ditch filled with water and excess water w Contractor attempting to repair air release valve broke force main pipe

Excessive rain caused MH to surcharge. Wastewater flowed from pick hole at the rate of 15 gpm

Sewer manhole MHS101.31.

Coming out of manhole

The Las Gallinas Valley Sanitary District had a sewer spill on December 23, 2012. The spill was located at the intersection North parking lot of the Four Points Sheraton

Manhole located in parking lot was not spilling on arrival. SSO traveled down parking lot directly into storm drain. One la Middle of street in front of 6372 Almaden Way from manhole

From lamphole in front of 4352 Davis Way

M/H overflow on N.Livermore Ave. approx. 450 ft. N of Portola

From Manhole in middle of street in front of 1249 Hansen Rd

Other sewer system structure

Other (specify)

Manhole

Other (specify)

Manhole

Other sewer system structure

Manhole

Other (specify)

Gravity sewer

Manhole

Manhole

Manhole

Gravity sewer

Manhole

Manhole

Mainor

Manhole

Gravity sewer

Manhole

Other sewer system structure

Other sewer system structure

Manhole

Manhole

Manhole

Building or structure

Manhole

Manhole

Other (specify)

Other (specify)

Building or structure

Manhole

Manhole

Building or structure

Building or structure

Other sewer system structure

Gravity sewer

Force main or pressure sewer

Manhole

Manhole

Manhole

Manhole

Gravity sewer

Manhole

Manhole

Force main or pressure sewer

Manhole

Gravity sewer

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Rodding Inlet accessed from Christy Sewer Box. Seepage through retaining wall in front of property.
Exfiltration from failed joint mixed with storm water through hole in bottom of storm drain pipe that crosses under sanitary
Clean-out belonging to property 1205 Rose, backup went up lateral from MH to clean-out near Rose St. and Third Ave
Rodding box along sidewalk Rodding inlet on hillside
Cleanout Spill coming from Contra Costa Valve installed in home owner's front yard
Air release valve
Wad of roots from lateral on bench of manhole - possibly plumber initiated.
MH not overflowing upon arrival. Line has 2 houses connected to it - no homeowners at home Force main break at Descanso Pump Station
Legenhale in Otreat in front of 4050 Davis Way, Livergroup, OA
Lamphole in Street in front of 4352 Davis Way, Livermore, CA Manhole in N. Livermore Ave at or near driveway into Albertsons near new Total Sports store

Street/curb and gutter; Unpaved surface

Unpaved surface

Unpaved surface

Separate storm drain

Separate storm drain; Street/curb and gutter; Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface; Street/curb and gutter; Unpaved surface

Street/curb and gutter; Unpaved surface

Street/curb and gutter

Unpaved surface

Separate storm drain; Street/curb and gutter; Unpaved surface

Unpaved surface

Separate storm drain; Street/curb and gutter

Separate storm drain; Street/curb and gutter

Street/curb and gutter; Unpaved surface

Unpaved surface

Street/curb and gutter; Unpaved surface

Unpaved surface

Street/Curb and Gutter

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Storm drain

Separate storm drain

Other paved surface

Other paved surface

Building or structure

Unpaved surface

Unpaved surface

Building or structure

Building or structure; Separate storm drain; Street/curb and gutter; Unpaved surface

Other paved surface; Separate storm drain; Street/curb and gutter

Separate storm drain; Unpaved surface

Separate storm drain; Street/curb and gutter; Surface water

Street/curb and gutter

Storm drain; Street/curb and gutter; Unpaved surface

Street/curb and gutter

Other paved surface

Separate storm drain; Unpaved surface

Street/curb and gutter

Unpaved surface

Other paved surface; Separate storm drain; Street/curb and gutter

Separate storm drain; Street/curb and gutter

Other (specify below)

Separate storm drain

Other paved surface; Street/curb and gutter; Unpaved surface

Surface water

Surface water

Paved Surface; Separate Storm Drain

Other (specify below)

Street/curb and gutter

Storm drain

Other (specify below)

Storm drain dried before enter waters of the state (Marquarite Creek) Water had dissipated upon entrying storm drain - did not leave storm drain or enter water of the State. Small drip from cleanout
Power failure at pump station resulted in sewage backing up and coming out of toilet seal. Extremely heavy rainstorm S
1000 gallons of spill on homeowner's property. Approximately 200 gallons went to gutters during heavy storm (heavy flow
Paved aqueduct
MH in backyard -spill soaked into ground. Ground was hard enough to stand on so it was surmised that spill hadn't been <code>c</code> 13,500 gallons was pumped out of the storm water pump station on Vendola and into the slough going to the San Pablo E
Marsh across from Embassy Suites
The spill flowed into Gallinas Creek which flows to the San Pablo Bay.
Storm drain did not have any water in it but was wet. Manhole was not spilling when crew arrived. Spill captured in Storm drain pipe and returned to Sanitary Sewer
Captured in Storm drain piping Spill fully captured in storm piping and returned to Sanitary Sewer system

9/26/2009 0:00	9/28/2009 10:30	9/28/2009 10:35	9/28/2009 17:08
11/12/2009 13:00	11/12/2009 13:39	11/12/2009 13:50	11/12/2009 15:35
11/22/2010 15:30	11/22/2010 16:36	11/22/2010 16:48	11/22/2010 19:08
6/22/2011 0:00	6/24/2011 11:30	6/24/2011 13:10	6/30/2011 9:18
12/16/2011 8:00	12/16/2011 17:15	12/16/2011 17:22	12/16/2011 19:08
1/9/2012 12:00	1/9/2012 2:22	1/9/2012 2:35	1/9/2012 2:50
1/13/2012 8:00	1/16/2012 13:07	1/16/2012 13:15	1/16/2012 16:00
1/27/2012 18:00	1/28/2012 12:12	1/28/2012 13:35	1/28/2012 16:03
3/3/2012 10:00	3/4/2012 10:22	3/4/2012 10:35	3/4/2012 14:53
6/12/2012 19:00	6/13/2012 11:52	6/13/2012 12:03	6/13/2012 12:58
8/21/2012 0:00	8/27/2012 13:18	8/27/2012 13:25	8/27/2012 16:10
12/5/2012 9:30	12/5/2012 9:54	12/5/2012 10:04	12/5/2012 10:38
12/20/2012 12:15	12/20/2012 12:15	12/20/2012 12:20	12/20/2012 1:15
1/16/2013 6:15	1/16/2013 9:05	1/16/2013 9:14	1/16/2013 10:01
2/13/2013 10:30	2/13/2013 10:46	2/13/2013 11:29	2/13/2013 11:45
2/27/2013 9:00	2/27/2013 10:40	2/27/2013 11:29	2/27/2013 10:00
4/8/2013 15:18	4/8/2013 15:48	4/8/2013 16:13	4/8/2013 16:36
7/31/2013 19:18	7/31/2013 20:18	7/31/2013 20:31	7/31/2013 21:44
8/27/2013 19:00	8/27/2013 19:59	8/27/2013 21:30	8/27/2013 21:35
10/1/2013 0:00	10/8/2013 14:58	10/8/2013 14:58	10/8/2013 15:20
10/14/2013 7:00	10/14/2013 9:11	10/14/2013 9:20	10/14/2013 9:45
7/17/2007 2:40	7/17/2007 3:00	7/17/2007 3:15	7/17/2007 3:20
8/16/2007 9:55	8/16/2007 10:00	8/16/2007 10:05	8/16/2007 10:20
9/10/2007 9:22	9/11/2007 7:45	9/10/2007 10:00	9/11/2007 3:00
9/23/2007 8:00	9/23/2007 9:40	9/23/2007 10:15	9/23/2007 10:40
10/26/2007 9:00	10/26/2007 9:13	10/26/2007 9:25	10/26/2007 9:30
10/26/2007 11:00	10/26/2007 1:50	10/26/2007 2:05	10/26/2007 2:15
1/2/2008 10:15	1/2/2008 10:20	1/2/2008 10:30	1/2/2008 10:37
1/4/2008 9:30	1/4/2008 9:30	1/4/2008 9:30	1/4/2008 9:35
1/16/2008 8:50	1/16/2008 8:53	1/16/2008 9:00	1/16/2008 9:10
4/14/2008 4:45	4/14/2008 5:00	4/14/2008 5:30	4/14/2008 5:35
5/29/2008 10:15	5/29/2008 10:25	5/29/2008 10:30	5/29/2008 10:16
2/22/2009 4:30	2/22/2009 10:30	2/22/2009 10:40	2/22/2009 11:00
7/18/2009 8:50	7/18/2009 8:50	7/18/2009 9:00	7/18/2009 10:20
7/31/2009 10:55	7/31/2009 10:55	7/31/2009 11:10	7/31/2009 11:00
8/6/2009 8:45	8/6/2009 8:45	8/6/2009 9:00	8/6/2009 11:00
9/10/2009 9:10	9/10/2009 9:10	9/10/2009 9:20	9/10/2009 9:25
2/17/2010 10:53	2/17/2010 10:53	2/17/2010 11:10	2/17/2010 11:23
3/22/2010 8:00	3/22/2010 8:00	3/22/2010 8:30	3/22/2010 9:00
3/24/2011 11:25	3/24/2011 11:30	3/24/2011 11:35	3/24/2011 12:17
8/1/2011 13:00	8/1/2011 18:30	8/1/2011 19:15	8/1/2011 19:40
4/5/2012 12:27	4/5/2012 12:27	5/5/2012 0:00	4/5/2012 12:49
8/20/2012 11:50	8/20/2012 1:20	8/20/2012 1:25	8/20/2012 2:20
10/1/2012 12:45	10/1/2012 13:05	10/1/2012 13:25	10/1/2012 14:30
10/29/2012 7:26	10/29/2012 7:37	10/29/2012 7:41	10/29/2012 7:46
11/28/2012 1:17	11/28/2012 1:23	11/28/2012 1:25	11/28/2012 1:27
12/2/2012 8:18	12/2/2012 8:18	12/2/2012 8:40	12/2/2012 8:45
12/2/2012 3:46	12/2/2012 2:56	12/2/2012 3:10	12/2/2012 3:20
12/23/2012 12:30	12/23/2012 12:30	12/23/2012 12:30	12/23/2012 13:50
7/1/2013 8:05	7/1/2013 8:15	7/1/2013 8:23	7/1/2013 8:30
10/17/2013 7:15	10/17/2013 7:15	10/17/2013 7:40	10/17/2013 7:50
9/23/2007 9:25	9/23/2007 9:25	9/23/2007 10:05	9/23/2007 10:25
10/9/2007 11:10	10/9/2007 11:10	10/9/2007 11:20	10/9/2007 11:39
11/29/2007 8:16	11/29/2007 8:16	11/29/2007 8:24	11/29/2007 8:45
1/23/2008 9:43	1/23/2008 9:43	1/23/2008 10:05	1/23/2008 10:10

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Debri-Rags

Debri-Rags

Debri-General

Debri-General

Pipe structural problem/failure

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Other (specify below)

Debri-General

Debri-Rags

Debri-General

Debri-General

Debris-Rags

Other (specify below)

Debris-Rags

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Pump station failure

Root intrusion

Debris

Other (specify below)

Root intrusion

Pipe structural problem/failure

Operator error

Operator error

Root intrusion

Grease deposition (FOG)

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Other (specify below)

Other (specify below)

Other (specify below)

Debri-Rags

Rainfall exceeded design (Separate CS Only)

Root intrusion

Root Intrusion

Debris

Debris

Other (specify below)

Grease deposition (FOG)


Rags, root, grit, and grease noticed. Paper and grease Root debris noticed but believe it may have come from private property where previous private lateral was blocked and c Hydro cleaning identified cracked and partially exposed pipe on hillside. Unknown blockage Unknown blockage, line cleared into blind tee and unable to determine cause. Suspect roots. Paper blockage just past MH V-21-07 Approximately 1/2 pint of sewage had exited manhole, when blockage was removed lower manhole could not contain the Excessive amounts of asphalt due to contractor paving streets and raising manholes. (Team Ghilotti) Line was being flushed at 1200 psi rather than 3000 psi because of condition of lateral. Water still entered lateral causing Pipe on air release valve broke. Vactor trucks were able to remove 3000 gallons from MH before it made it to stormwate Water department hit sewer main when excavating for water main repair. Root ball pushed from lateral into main. MH had large root but excessive grease in the line caused blockage. Line had been cleaned September 2009 Siphon could not handle the excessive rainfall. Linecrew had extended pm from 4 months to 1 year. PM has returned to Roots - line was on a PM and was due to be cleaned 5-29-12. PM has been changed from two years to one year Force main ruptured Hunk of cement Mop head in line Capacity issue - rainfall exceeded design of siphon line. Replacement of line scheduled for Spring of 2013

four conduits directionally bored through sewer main

Roots and grease created blockage in lline. Manhole was surcharged on arrival but not overflowing.

Construction debris, rope and 1X2 lumber pieces plastic bag full of debris lodged in mainline

Main	
Main Main Main Main Main Main Main Main	
Main	
Main	
Main	
Main Other (specify below) Main Main	
Main Main Main Other (specify below) Main Main Main Main Main Main Main Main	



6 VCP

6

4 VCP No 6 VCP No 4 VCP No 6 pvc

6 acp 6 clay

6 pvc

10 clay 8 HDPE

6 уср

8 PVC

8 VCP

8 VCP

8 PVC

No

50

2

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Inspected sewer using CCTV to determine cause; Restored flow

Restored flow

Inspected sewer using CCTV to determine cause; Other (specify below)

Restored flow

Cleaned-up (mitigated effects of spill):Restored flow

Cleaned-up (mitigated effects of spill):Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Contained all or portion of spill;Returned all or portion of spill to sanitary sewer system;Other (specify below)

Restored flow; Other (specify below)

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Inspected sewer using CCTV to determine cause; Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Inspected sewer using CCTV to determine cause; Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Returned all or portion of spill to sanitary sewer syst

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Returned all or portion of spill to sanitary sewer syst

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Other (specify below)

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause

Cleaned-up (mitigated effects of spill):Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Other (specify below)

Restored flow

Cleaned-Up; Mitigated Effects of Spill; Restored flow; Other Enforcement Agency Notified

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanil

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Replaced section of main sewer that crosses storm drain. Notified Public Works Dept of broken storm drain.
Temporary repair diverting any wastewater seeping from bottom of broken pipe back into sewer system. Previously erod Investigated downhill storm drain and nothing to recover.
Air release valve was closed and spill stopped. Water department had pumper truck on site and was able to pump water into sewer manhole.
Excessive rainfall, vactor was set up but tides and rain decreased - stopping flow. Streets were flooded by rainfall - will te
Spill stopped when area flooding stopped. Broke stoppage and retrieved roots. Televised and rodded line. Cleaned sewage on parking lot pavement. After televisi
Spill in street from lamphole, fully contained in curb & gutter with booms, vacuumed and rinsed, vacuumed again, all wit After flow was restored to piping, overflow manhole was plugged and bypassed to a downstream manhole while pipe reparations.

11/22/2010 19:08 7/21/2011 10:30 12/16/2011 19:20

1/28/2012 16:50

12/5/2012 11:00

1/16/2013 10:31 2/13/2013 12:20

9/23/2007 2:30 10/26/2007 11:00

2/22/2009 1:30 7/18/2009 13:00 7/31/2009 0:00 8/6/2009 11:00

3/24/2011 1:12 8/2/2011 10:00

10/1/2012 20:00 10/29/2012 9:50 11/29/2012 10:00 12/2/2012 8:45

12/23/2012 14:53 7/1/2013 9:30 10/18/2013 9:00

Other (specify below) Repaired sewer Adjusted schedule/method of preventive maintenance; Plan rehabilitation or replacement of sewer Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance; Other (specify below) Plan rehabilitation or replacement of sewer; Other (specify below) Other (specify below) Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance Repaired sewer Other (specify below) Other (specify below) Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance Plan rehabilitation or replacement of sewer; Repaired sewer Adjusted schedule/method of preventive maintenance Other (specify below) Plan rehabilitation or replacement of sewer Other (specify below) Other (specify below) Adjusted schedule/method of preventive maintenance; Inspected Sewer Using CCTV to Determine Cause; Other (specify I

Scheduled for CCTV for line segment with blockage
Scheduled for video inspection of problem area Video inspection scheduled
Monitor contractor when City or County has hired company to slurry streets. We have requested that the District be advis
Water department hit sewer line when excavating water main. Break in pipe was caused by contractor working on line
Will be investigating industries in the area that could have had a mop head enter sewer line Safeway siphon had been cleaned 1 week before incident. Siphon line was checked at 7:30am on the day of spill - overfl District is in the process of selecting an engineering firm to study option to increase sewer system capacity and storage. Increased preventive maintenance frequency Rodded line, televised line

Yes

No

Yes

Yes

No

Yes

Yes

No

No

No

No

No

Yes

Yes

No

Yes

No No

Yes

No

No

No

Not Applicable None None

No No

Yes

No

No

No Yes

No No

No Yes No

Yes

No No

Yes No Yes

Yes

Yes Yes

No

No

None NA NA NA n/a NA NA Not Applicable N/A

None storm drain channel Carquinez Straight None None

Carquinez Straight

None

None

Carquinez Strait

Carquinez Strait Carquinez Strait None

none None

NA NA

Santa Margarita Creek

NA NA

Santa Margarita Creek Aqueduct Margarita Creek Not Applicable

Slough that goes into San Pablo Bay Miller Creek Gated marsh across from Embassy Suites Santa Margarita Creek

San Pablo Bay Gallinas Creek / San Pablo Bay No water quality samples taken Biological indicator(s) - specify below No water quality samples taken

No water quality samples taken

No water quality samples taken

No water quality samples taken No water quality samples taken


No water quality samples taken No water quality samples taken

No water quality samples taken No water quality samples taken;Not applicable to this spill Not applicable to this spill Dissolved oxygen

No water quality samples taken Biological indicator(s) - specify below

Biological indicator(s) - specify below Biological indicator(s) - specify below Not applicable to this spill Biological indicator(s) - specify below

Biological indicator(s) - specify below Biological indicator(s) - specify below Not applicable to this spill



No water quality samples taken None of the above None of the above

No water quality samples taken

No water quality samples taken

None of the above No water quality samples taken

None of the above None of the above


None of the above No water quality samples taken; Not applicable to this spill None of the above None of the above

No water quality samples taken County Health Agency

County Health Agency County Health Agency None of the above None of the above

County Health Agency
County Health Agency
Not applicable to this spill





107038	11/22/2010 8:20
114340	7/22/2011 11:20
117435	12/16/2011 18:24
120585	1/28/2012 15:11
127426	12/5/2012 11:12
130336	1/16/2013 10:40
130956	2/13/2013 12:02

91529	2/22/2009 12:45
95081	7/18/2009 10:30
95491	8/6/2009 10:45
111847	3/24/2011 12:05
114560	8/1/2011 19:59
125915	10/1/2012 14:54
126520	10/29/2012 9:23
127179	11/28/2012 14:27
127324	12/2/2012 2:04
127841	12/23/2012 14:05
134033	7/1/2013 9:18
136463	10/17/2013 8:47

Dale McDonald, General Manager Dale McDonald, General Manager Dale McDonald, General Manager

5107872992 5107872992 5107872992

Janice Mandler 4154721734

2SSO10148	Active	729994 Karl Kraft	Certified
2SSO10148	Active	737406 Karl Kraft	Certified
2SSO10148	Active	743259 Karl Kraft	Certified
2SSO10148	Active	746393 Karl Kraft	Certified
2SSO10148	Active	751769 Michael Wells	Certified
2SSO10148	Active	752705 Michael Wells	Certified
2SSO10148	Active	756272 Michael Wells	Certified
2SSO10148	Active	757992 Michael Wells	Certified
2SSO10148	Active	758526 Michael Wells	Certified
2SSO10148	Active	761191 Michael Wells	Certified
2SSO10148	Active	767825 Michael S. Wells	Certified
2SSO10148	Active	767959 Michael S. Wells	Certified
2SSO10148	Active	773273 Michael Wells	Certified
2SSO10148	Active	774513 Michael Wells	Certified
2SSO10148	Active	775301 Michael Wells	Certified
2SSO10148	Active	790754 Michael Wells	Certified
2SSO10148	Active	792849 Michael Wells	Certified
2SSO10148	Active	793141 Michael Wells	Certified
2SSO10149	Active	656781 Michelle Chen for R. Chen	Certified
2SSO10149	Active	657232 Michelle Chen for R. Chen	Certified
2SSO10149	Active	657318 Johnson Chung	Certified
2SSO10149	Active	657339 Michelle Chen	Certified
2SSO10149	Active	657358 Michelle Chen for R. Chen	Certified
2SSO10149	Active	657363 Michelle Chen	Certified
2SSO10149	Active	704413 Michelle Chen	Certified
2SSO10149	Active	704608 Michelle Chen	Certified
2SSO10149	Active	708066 Michelle Chen	Certified
2SSO10149	Active	708679 Michelle Chen	Certified
2SSO10149	Active	710647 Michelle Chen	Certified
2SSO10149	Active	710959 Michelle Chen	Certified
2SSO10149	Active	710967 Michelle Chen	Certified
2SSO10149	Active	712347 Michelle Chen	Certified
2SSO10149	Active	712812 Michelle Chen	Certified
2SSO10149	Active	718266 Michelle Chen	Certified
2SSO10149	Active	718714 Michelle Chen	Certified
2SSO10149	Active	718720 Michelle Chen	Certified
2SSO10149	Active	718725 Michelle Chen	Certified
2SSO10149	Active	719811 M. Chen for J. Chung	Certified
2SSO10149	Active	721171 M. Chen for J. Chung	Certified
2SSO10149	Active	721321 Johnson Chung	Certified
2SSO10149	Active	723831 M. Chen for J. Chung	Certified
2SSO10149	Active	723832 M. Chen for J. Chung	Certified
2SSO10149	Active	723859 M. Chen for J. Chung	Certified
2SSO10149	Active	723868 Johnson Chung	Certified
2SSO10149	Active	730325 M. Chen for J. Chung	Certified
2SSO10149	Active	730327 M. Chen for J. Chung	Certified
2SSO10149	Active	730328 M. Chen for J. Chung	Certified
2SSO10149	Active	730432 M. Chen for J. Chung	Certified
2SSO10149	Active	731178 Michelle Chen for J. Chung	Certified
2SSO10149	Active	734709 Johnson Chung	Certified
2SSO10149	Active	736551 Johnson Chung	Certified
2SSO10149	Active	736914 Johnson Chung	Certified
2SSO10149	Active	743825 Johnson Chung	Certified
2SSO10149	Active	745116 Johnson Chung	Certified
2SSO10149	Active	746194 Michelle Chen	Certified

Public Works Supervisor-Collections

Public Works Supervisor

Public Works Supervisor

Public Works Supervisor

Public Works Supervisor-Collections

Public Works Supervisor-Collections

Public Works Supervisor

Public Works Supervisor-Collections

Public Works Supervisor-Collections

Public Works Supervisor-Collection

Public Works Supervisor

Associate Engineer

Associate Engineer

Engineering Tech.

Associate Engineer

Associate Engineer

Associate Engineer

Associate Eng.

Engineering Tech.

Associate Eng.

Associate Eng.

Associate Eng.

Engineering Tech.

Associate Eng.

Associate Eng.

Associate Eng.

Associate Eng.

Associate Engineer

Engineering Technician

Engineering Tech.

Engineering Tech.

Engineering Tech

Engineering Tech.

Associate Engineer

City of Livermore	285680
City of Livermore	270962
Livermore CA	852829
City of Livermore	102537
City of Livermore	327937
City of Livermore	663434
City of Livermore	456386
City of Livermore	676335
City of Livermore	453841
City of Livermore	804903
City of Livermore	385932
City of Livermore	836405
City of Livermore	359332
City of Livermore	475109
City of Livermore	616029
City of Livermore	151856
City of Livermore	907243
City of Livermore	747328
Town of Los Altos Hills	106718
Town of Los Altos Hills	700231
Los Altos Hills	630405
Town of Los Altos Hills	385954
Town of Los Altos Hills	196327
Town of Los Altos Hills	777171
Town of Los Altos Hills	165583
Town of Los Altos Hills	872467
Town of Los Altos Hills	293877
Town of Los Altos Hills	690427
Town of Los Altos Hills	745203
Town of Los Altos Hills	281979
Town of Los Altos Hills	271955
Town of Los Altos Hills Town of Los Altos Hills	925463
Town of Los Altos Hills	301313 823463
	337591
Town of Los Altos Hills Town If Los Altos Hills	
Town of Los Altos Hills	956636 356886
Town of Los Altos Hills	837972
Town of Los Altos Hills	586676
Los Altos Hills	641495
Town of Los Altos Hills	991389
Town of Los Altos Hills	120590
Town of Los Altos Hills	879099
Los Altos Hills	702019
Town of Los Altos Hills	781820
Town of Los Altos Hills	779609
Town of Los Altos Hills	281322
Town of Los Altos Hills	433974
Town of Los Altos Hills	601152
Los Altos Hills	978391
Los Altos Hills	440971
Los Altos Hills	531496
Los Altos Hills	798117
Los Altos Hills	620920
Los Altos Hills Town Hall	749185

1-Dec-08		1-Dec-08	12/1/2008
13-May-09		13-May-09	5/13/2009
18-Aug-09		18-Aug-09	8/18/2009
30-Oct-09		30-Oct-09	10/30/2009
19-Apr-10		26-Apr-10	4/26/2010
25-May-10	5/25/2010	25-May-10	5/25/2010
23-Aug-10	8/23/2010	23-Aug-10	8/23/2010
21-Oct-10	10/21/2010	21-Oct-10	10/21/2010
15-Nov-10	11/15/2010	15-Nov-10	11/15/2010
13-Jan-11	1/13/2011	13-Jan-11	1/13/2011
24-Jun-11	6/24/2011	24-Jun-11	6/24/2011
28-Jun-11	6/28/2011	28-Jun-11	6/28/2011
18-Nov-11	11/18/2011	18-Nov-11	11/18/2011
21-Dec-11	12/21/2011	21-Dec-11	12/21/2011
4-Jan-12	1/4/2012	4-Jan-12	1/4/2012
25-Jan-13	1/25/2013	25-Jan-13	1/25/2013
22-Mar-13	3/22/2013	22-Mar-13	3/22/2013
3-Apr-13	4/3/2013	3-Apr-13	4/3/2013
4-Sep-07		8-Dec-10	12/8/2010
12-Sep-07		8-Dec-10	12/8/2010
12-Sep-07		8-Dec-10	2/7/2011
12-Sep-07		8-Dec-10	12/8/2010
12-Sep-07		8-Dec-10	12/8/2010
12-Sep-07		8-Dec-10	12/8/2010
1-Oct-07		1-Oct-07	12/9/2010
4-Oct-07		4-Oct-07	12/9/2010
26-Nov-07		26-Nov-07	12/9/2010
3-Dec-07		3-Dec-07	12/9/2010
2-Jan-08		2-Jan-08	12/9/2010
9-Jan-08		9-Jan-08	12/9/2010
9-Jan-08		9-Jan-08	12/9/2010
5-Feb-08		5-Feb-08	12/9/2010
13-Feb-08		13-Feb-08	12/9/2010
28-May-08		28-May-08	12/9/2010
3-Jun-08		3-Jun-08	12/9/2010
3-Jun-08		3-Jun-08	12/9/2010
3-Jun-08		3-Jun-08	12/9/2010
18-Jun-08		18-Jun-08	12/8/2010
1-Jul-08		2-Jul-08	12/8/2010
2-Jul-08		2-Jul-08	2/7/2011
29-Jul-08		29-Jul-08	12/8/2010
29-Jul-08		29-Jul-08	12/8/2010
30-Jul-08		30-Jul-08	12/8/2010
30-Jul-08		20-Dec-10	12/20/2010
9-Dec-08		9-Dec-08	12/8/2010
9-Dec-08		9-Dec-08	12/8/2010
9-Dec-08		9-Dec-08	12/8/2010
11-Dec-08		11-Dec-08	12/8/2010
30-Dec-08		30-Dec-08	12/8/2010
9-Mar-09		11-Mar-09	3/11/2009
21-Apr-09		21-Apr-09	12/20/2010
28-Apr-09		28-Apr-09	4/28/2009
27-Aug-09		27-Aug-09	8/27/2009
28-Sep-09		28-Sep-09	12/20/2010
27-Oct-09		27-Oct-09	10/27/2009

Category 3	450	450
Category 3	640	640
Category 3	50	50
Category 3	310	310
Category 3	10	10
Category 2	2700	2675
Category 3	310	310
Category 3	100	100
Category 3	170	170
Category 3	275	275
Category 2	1150	1150
Category 3	110	110
Category 3	350	350
Category 3	55	55
Category 3	525	525
Category 3	25	25
Category 3	695	475
Category 3	25	25
Category 3	900	900
Category 3	480	0
Category 3	60	0
Category 1	300	300
Category 1	500	400
Category 1	90	90
Category 3	360	0
Category 3	115	0
Category 3	600	0
Category 3	750	0
Category 3	30	0
Category 3	60	0
Category 3	50	0
Category 3	180	0
Category 3	60	0
Category 3	30	0
Category 3	30	0
Category 3	60	0
Category 3	150	0
Category 3	600	450
Category 3	100	0
Category 1	150	0
Category 3	40	0
Category 3	90	0
Category 3	30	0
Category 1	600	0
Category 3	120	0
Category 3	350	0
Category 3	250	145
Category 3	220	0
Category 3	130	0
Category 3	840	0
Category 1	300	0
Category 3	180	0
Category 3	20	14
Category 1	1000	200
Category 1	500	300
3 ,		

0 No	Yes
0 No	Yes
0 No	No
0 No	No
0 No	Yes
0 No	No
0 No	No
0 No	Yes
0 No	No
0 No	Yes
0 No	Yes
0 No	No
150 Yes	Yes
100 No	Yes
90 Yes	No
0 No	No
0 No 0 No	No No
0 No	No No
150 No	Yes
0 No	No
0 No	No
0 No	No
600 Yes	Yes
0 No	No
0 No	Yes
300 Yes	Yes
0 No	No
0 No	No
800 Yes	Yes
200 Yes	Yes

Yes Yes Yes Yes No Yes Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes Yes Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No No

Yes

1137 Hansen Rd

1011 Geneva St

Intersection Holmes St. & 2nd St.

269 Junction Ave Apartment

954 Bellflower St.

In Street across from 2392 Rees Cir

900 Bluebell Drive

942 Wagoner Drive

Rickenbacker Cir

Rincon Ave

Kitty Hawk/ Airway Blvd.

Latour Ave.

3529 First Street

388 Martin Ave.

Intersection Second Street/Holmes Street

600 Maple Street

W. Jack London Blvd, near Airport lift station

715 Delmar Ave

Altamont Road at Altamont Court

Altamont Road near Moody Road

Pathway off Page Mill Road

Manhole 22 on Sheet K, at Dezahara Way

Oak Knoll Circle

Manhole 14 at El Monte Road/Moody Road

MH #64 Ascencion Drive Easement Line

Easement Line MH #12, dwg A

Altamont Road

Todd Lane

26493 Weston Drive

Altamont & Silent Hill

Old Page Mill MH#8

Altamont

Fremont x Donelson Place

Old Pagemill & 2055 Jarvis Way Easement

viscaino court

Fremont Road

MH#12

27161 Fremont Road

Cobetta Lane

Purissima Lift Station

11633-11635 Dawson Drive

11555 Putter Way

Old Page Mill Road and Javis Way Easement

Palo Hills and Fremont Road

Via Ventana Easement

Altadena Drive

Magdalena Avenue and Dawson Drive

Altamont Road

La Loma Drive Easement

14244 Amherst Court

Fremont Road Easement

Intersection of Fremont and Donelson Place

13620 Golden Hill Court

Elena Road and Purssima Road

26595 Anacapa

37.646667	121.78 Alameda
37.671111	-121.772222 Alameda
37.67777	-121.77999 Alameda
37.6864	-121.76616 Alameda
37.7099	-121.732634 Alameda
37.673858	-121.723743 Alameda
37.705392	-121.74016 Alameda
37.670331	-121.785274 Alameda
37.691006	-121.80446 Alameda
37.694829	-121.783281 Alameda
37.696343	-121.805699 Alameda
37.6582	-121.76607 Alameda
37.687613	-121.75735 Alameda
37.690521	-121.76099 Alameda
37.677692	-121.779208 Alameda
37.681908	-121.760169 Alameda
37.690144	-121.823668 Alameda
37.669789	-121.789433 Alameda
37.3575	-122.14052 Santa Clara
37.36108	-122.15114 Santa Clara
37.37196	-122.16859 Santa Clara
37.36172	-122.14881 Santa Clara
37.35399	-122.12048 Santa Clara
37.35829	-122.12986 Santa Clara
37.38357	-122.14247 Santa Clara
37.39309	-122.16374 Santa Clara
37.35897	-122.14426 Santa Clara
37.3778	-122.13229 Santa Clara
37.38948	-122.14108 Santa Clara
37.35778	-122.14714 Santa Clara
37.39808	-122.16498 Santa Clara
37.35831	-122.14378 Santa Clara
37.3826	-122.13595 Santa Clara
37.39621	-122.16325 Santa Clara
37.37575	-122.13857 Santa Clara
37.3826	-122.13593 Santa Clara
37.35143	-122.10977 Santa Clara
37.39291	-122.14355 Santa Clara
37.35945	-122.14213 Santa Clara
37.38039	-122.15434 Santa Clara
37.35372	-122.11365 Santa Clara
37.34982	-122.10729 Santa Clara
37.39808	-122.16498 Santa Clara
37.39009	-122.14269 Santa Clara
37.37247	-122.16733 Santa Clara
37.38579	-122.13353 Santa Clara
37.3514	-122.1098 Santa Clara
37.35611	-122.14357 Santa Clara
37.35253	-122.13421 Santa Clara
37.387389	-122.164 Santa Clara
37.38381	-122.13587 Santa Clara
37.38381	-122.13587 Santa Clara
37.37475	-122.131833 Santa Clara
37.379833	-122.154389 Santa Clara
37.38654	-122.14455 Santa Clara

In street in front of 1137 Hansen Rd. coming from manhole at less than 5 gpm

From manhole in front of 1011 Geneva St.

Manhole in middle of intersection of Holmes St. and 2nd St.

From Private lateral cleanout in front of 269 Junction Ave. but due to blockage in City Sewer Main line.

From manhole in planter strip, middle of street.

Middle of street

In middle of street, from manhole.

Middle of street from manhole

New construction for Isabel/Airway interchange

lower lateral cleanout @ 2189 Latour Ave.

Private parking lot cleanout and bathroom of two businesses

On school property, from grease trap interceptor near auto shop.

Discharge manhole from El Charro lift station, side of roadway on W. Jack London Blvd near Airport lift station

Sidewalk and curb/gutter from lateral in front of residents home.

Manhole #7 overflowing on the street

Overflowing MH on the paved street.

Manhole # 42 of Sheet G on unpaved pathway paralle to Page Mill Road

Manhole 22 on Sheet K, at Dezahara Way

Manhole #76, Sheet P

Manhole is on the shoulder arear along the road

mahnole #64, Page E

easement

MH#8 Page A

MH E 69

MH#66 thru #69

cleanout in lawn area at 11660 Magdalena

MH# D-33

Mh# K-6

Corner of Purissima and Elena Road

MH #79

Clean-out overflow at driveway

Manhole #8 overflow

MH overflow

MH 42 overflow in easement

Manhole #29

MH # 11

Manhole #11A overflow

Sewage overflow from manhole cover

City of Palo Alto trunk line plugged caused the overflow

Sanitary sewer manhole overflow in easement

Sewer manhole overflow

Sewer Cleanout Overflow

Sewer manhole overflow

Area around manhole D613, incl. 200 L.F. of curb & gutter to catch basin

Manhole Manhole Manhole Other sewer system structure Manhole Manhole Manhole Manhole Gravity sewer: Manhole Gravity sewer; Manhole Force main or pressure sewer Other sewer system structure Building or structure; Other sewer system structure Gravity sewer; Manhole Manhole Building or structure; Other sewer system structure Force main or pressure sewer; Gravity sewer; Manhole Gravity sewer; Other sewer system structure Gravity sewer Manhole Gravity sewer Gravity sewer Manhole Manhole Manhole Manhole Manhole Manhole Other (specify) Manhole Manhole Manhole Manhole Manhole Manhole Manhole Manhole Manhole Manhole

Manhole;Other sewer system structure;Pump station

Gravity sewer

Gravity sewer

ED_006495_00001080-02693

Private Lateral Cleanout in front of 269 Junction Ave.
Spill from manhole in middle of street
Spill from new non-active force main Cleanout in parking lot, small amount in bathrooms of two businesses
Grease trap interceptor near auto shop
Cleanout from lateral at property line
manhole H-14 at end of street cul-de-sac
Sewer clean-out

From manhole in front of 1137 Hansen Rd.

Other (specify below)

Storm drain

Storm drain

Other (specify below)

Storm drain; Street/curb and gutter

Storm drain; Street/curb and gutter

Storm drain; Street/curb and gutter

Street/curb and gutter

Other paved surface; Street/curb and gutter

Street/curb and gutter

Unpaved surface

Street/curb and gutter

Other paved surface; Separate storm drain

Street/curb and gutter

Other paved surface; Separate storm drain; Street/curb and gutter

Other paved surface; Separate storm drain

Other paved surface; Unpaved surface

Street/curb and gutter

Other paved surface

Unpaved surface

Unpaved surface

Separate storm drain

Separate storm drain

Unpaved surface; Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Other paved surface

Unpaved surface

Unpaved surface; Other (specify below)

Other paved surface

Unpaved surface

Unpaved surface

Other (specify below)

Unpaved surface

Unpaved surface

Other paved surface; Street/curb and gutter

Street/curb and gutter

Other (specify below)

Other paved surface

Other (specify below)

Other (specify below)

Other (specify below)

Street/curb and gutter

Other paved surface

Other paved surface; Unpaved surface

Unpaved surface

Other paved surface; Storm drain

Unpaved surface

Other paved surface

Unpaved surface

Street/curb and gutter

Storm drain

All sewage returned to sewer system Captured and recovered from Storm Piping and returned to Sanitary Sewer system. Spill was captured in 12 Storm Drain line and fully returned to Sanitary Sewer System Spill captured in storm drain catch basin and returned to Sanitary Sewer system Most of spill was contained on paved street, which was cleaned up and return to system. Approx. 25 gallons did reach his Total spill of 310 gallons onto paved surface/curb/gutter with approx. 10 gallons into storm drain. All areas cleaned or rec Spill was contained on street/curb and gutter due to leaves and parked cars on street. No sewage entered storm system Spill on street and into nearby storm catch basin. catch basin full of debris(leaves, dirt). Spill was contained with spill absorbant @ curb and gutter, cleaned, and return to sanitary sewer system final destination of overflow was the DI at the bottom of the hill. DI near the spill Adobe Creek, the creek was dry and no moving water in summer time. orchard/planting area vegetation unknown by the contractor Seepage into soil Minor seepage into vegetation and soil

Dry creek bed and infiltrated into soil Spill seepage into ground and vegetation

4410710000 10 10	4410710000 10 10	4410710000 40 00	44/07/0000 44 45
11/27/2008 13:10	11/27/2008 13:10	11/27/2008 13:30	11/27/2008 14:40
5/12/2009 9:28	5/12/2009 9:29	5/12/2009 9:40	5/12/2009 10:00
8/15/2009 23:25	8/15/2009 23:25	8/15/2009 23:50	8/16/2009 0:30
10/30/2009 11:37	10/30/2009 11:37	10/30/2009 11:58	10/30/2009 12:08
4/14/2010 22:45	4/14/2010 22:45	4/14/2010 23:40	4/14/2010 23:50
5/24/2010 21:00	5/24/2010 21:00	5/24/2010 21:25	5/24/2010 23:15
8/23/2010 0:00	8/23/2010 10:33	8/23/2010 10:33	8/23/2010 10:59
10/18/2010 11:50	10/18/2010 11:50	10/18/2010 12:00	10/18/2010 12:10
11/10/2010 14:50	11/10/2010 14:54	11/10/2010 15:01	11/10/2010 15:06
1/9/2011 0:00	1/9/2011 10:15	1/9/2011 10:35	1/9/2011 11:30
6/24/2011 0:00	6/24/2011 13:15	6/24/2011 13:15	6/24/2011 14:20
6/28/2011 9:35	6/28/2011 9:35	6/28/2011 9:25	6/28/2011 10:05
11/15/2011 0:00	11/15/2011 11:41	11/15/2011 12:00	11/15/2011 12:08
12/21/2011 11:17	12/21/2011 11:17	12/21/2011 11:40	12/21/2011 11:50
12/29/2011 0:00	12/29/2011 15:20	12/29/2011 15:32	12/29/2011 15:41
		1/22/2013 16:55	1/22/2013 17:38
1/22/2013 15:35	1/22/2013 16:15		
3/11/2013 15:10	3/11/2013 15:15	3/11/2013 15:15	3/11/2013 15:17
3/25/2013 12:15	3/25/2013 13:40	3/25/2013 13:50	3/25/2013 13:50
9/1/2007 0:00	9/1/2007 8:50	9/1/2007 9:00	9/1/2007 10:15
9/11/2007 0:00	9/11/2007 11:25	9/11/2007 11:45	9/11/2007 12:15
6/25/2007 0:00	6/25/2007 10:12	6/25/2007 10:20	6/25/2007 13:20
6/3/2007 0:00	6/3/2007 9:08	6/3/2007 10:00	6/3/2007 10:10
5/16/2007 0:00	5/16/2007 11:00	5/16/2007 11:10	5/16/2007 11:20
6/19/2007 0:00	6/19/2007 13:18	6/19/2007 13:28	6/19/2007 13:48
9/27/2007 0:00	9/27/2007 7:52	9/27/2007 9:00	9/27/2007 14:00
10/1/2007 0:00	10/1/2007 9:20	10/1/2007 10:20	10/1/2007 11:15
11/20/2007 0:00	11/20/2007 9:50	11/20/2007 11:20	11/20/2007 11:30
11/29/2007 0:00	11/29/2007 16:14	11/29/2007 17:15	11/29/2007 19:30
1/1/2008 0:00	1/1/2008 14:34	1/1/2008 15:35	1/1/2008 16:00
1/2/2008 0:00	1/2/2008 16:26	1/2/2008 17:30	1/2/2008 20:00
1/3/2008 0:00	1/3/2008 12:15	1/3/2008 12:45	1/3/2008 15:45
1/18/2008 0:00	1/18/2008 15:39	1/18/2008 16:20	1/18/2008 17:25
2/12/2008 0:00	2/12/2008 11:02	2/12/2008 11:15	2/12/2008 11:30
3/6/2008 0:00	3/6/2008 8:51	3/6/2008 10:00	3/6/2008 15:30
2/20/2008 0:00	2/20/2008 13:39	2/20/2008 13:40	2/20/2008 16:40
2/12/2008 0:00	2/12/2008 11:02	2/12/2008 11:04	2/12/2008 11:30
5/21/2008 0:00	5/21/2008 9:52	5/21/2008 10:25	5/21/2008 12:25
6/12/2008 0:00	6/12/2008 8:55	6/12/2008 9:45	6/12/2008 11:30
6/27/2008 0:00	6/27/2008 12:33	6/27/2008 1:00	6/27/2008 1:20
6/29/2008 0:00	6/29/2008 11:30	6/29/2008 12:30	6/29/2008 4:00
11/8/2008 0:00	11/8/2007 11:10	11/8/2007 11:45	11/8/2007 12:30
11/25/2007 0:00	11/25/2007 6:00	11/25/2007 6:55	11/25/2007 7:23
3/6/2008 0:00	3/6/2008 9:20	3/6/2008 10:15	3/6/2008 15:30
6/2/2008 0:00	6/2/2008 8:16	6/2/2008 8:30	6/2/2008 9:30
12/5/2008 0:00	12/5/2008 14:37	12/5/2008 15:15	12/5/2008 17:35
12/7/2008 0:00	12/7/2008 16:49	12/7/2008 17:10	12/7/2008 20:15
11/17/2008 0:00	11/17/2008 10:45	11/17/2008 11:05	11/17/2008 12:30
12/10/2008 0:00	12/10/2008 8:56	12/10/2008 10:20	12/10/2008 10:50
12/27/2008 0:00	12/27/2008 13:22	12/27/2008 14:20	12/27/2008 17:30
2/13/2009 0:00	2/13/2009 13:40	2/13/2009 14:05	2/13/2009 16:00
4/13/2009 0:00	4/13/2009 14:21	4/13/2009 14:40	4/13/2009 15:58
4/20/2009 0:00	4/20/2009 10:44	4/20/2009 10:50	4/20/2009 11:50
8/17/2009 0:00	8/17/2009 11:30	8/17/2009 11:45	8/17/2009 18:00
9/23/2009 0:00	9/23/2009 13:06	9/23/2009 13:15	9/23/2009 13:40
10/6/2009 0:00	10/6/2009 12:30	10/6/2009 12:30	10/6/2009 13:30
10/0/2009 0.00	10/0/2008 12.30	10/0/2008 12.30	10/0/2008 13.30

Grease deposition (FOG)

Root intrusion

Debri-General

Debri-Rags

Debri-General

Vandalism

Grease deposition (FOG)

Root intrusion

Pipe structural problem/failure

Grease deposition (FOG)

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Debri-General

Debri-Rags

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Debri-General

Debri-General

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Debri-General

Other (specify below)

Root intrusion

Root intrusion

Other (specify below)

Debri-General

Other (specify below)

Root intrusion

Debri-General

Root intrusion

Root intrusion

Root intrusion

Pump station failure

Other (specify below)

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion Root intrusion

Debri-General

Other (specify below)

Debri-General

Root intrusion

Other (specify below)

Root intrusion

Roots growing from manhole buried in a back yard. Manhole was buried more than 3 feet down in the back yard of 1011 (
Soft rag blockage in 6 sewer main
Various types of debris (small tree, rocks, landscape stake, cans)were discovered in Manhole, which had be dumped by s
Construction company(Ghilotti) was driving pylons for new bridge and hit new non-active forcemain.
Spill caused by two pumps running from contractor performing punch list work at newly constructed El Charro lift station.
Switching pumps of the sewer bypass system that was being used for a sewer main emergency replacement at that locati
possibly caused from newly constructed home and sewer line on Newbridge Drive AC rock & concrete
Rocks and wood in MH
Unknown
Rags & debris
Asphalt concrete debris
Unknown
Plastic bottle in main line
Pump turned off

Main Main Main Main Main Main Other (specify below) Lower Lateral Main Main Main Main Other (specify below) Lower Lateral Main Other (specify below) Main Main

Main Main Main

Buried manhole in back yard of 1011 Geneva St.
Main line, just down stream of Aparment complex lateral
forcemain
Failure occurred at discharge mainhole from forcemain, two pumps running with soft blockage downstream restricting flov
Obstruction at 75'
root at 175 feet
Lift station control failure.
Manhole # 29 was bubbling which caused by root intrusion

8 PVC 10 VCP 6 VCP 10 8 VCP 6 VCP 6 6 VCP 8 VCP 8 VCP 6 VCP 6 VCP 6 VCP 6 VCP 6 VCP 8 VCP 6 VCP 6 VCP 6 VCP 6 VCP 6 VCP 8 VCP 6 VCP 6 VCP 6 VCP 6 VCP

6

v, flows exceddded capacity

Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Returned all or portion of spill to sanitary sewer syst Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanil Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanil Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanil Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanil

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow; Other (specify below)

Other (specify below)

Restored flow

Restored flow

Restored flow

Contained all or portion of spill:Restored flow

Contained all or portion of spill

Cleaned-up (mitigated effects of spill): Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause

Cleaned-up (mitigated effects of spill)

Other (specify below)

Cleaned-up (mitigated effects of spill); Contained all or portion of spill

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Returned all or portion of spill to sanitary sewer syst

Cleaned-up (mitigated effects of spill);Restored flow;Returned all or portion of spill to sanitary sewer system

Vac-Con used to break blockage, restore flow. Flow from manhole was blocked on street and plugged in storm piping for Crews using two Vac-Cons were able to block most of flow from entering storm catch basin, one Vac-Con worked the Blo Call was received by Source Control department at 2:54pm; Collection staff was notified and responded. First person on Spill was fully captured in private storm system within business parking lot. Two businesses had small spills inside bathro Blockage in 6 mainline, sewage entered abadoned storm catch basin, area cleaned and all sewage returned to system Cleaned and recovered 475 gallons from spill area, 200+/- gallons absorbed into soil. Mainline jetted and soft blockage c The crew first contained the overflow area, then relieved stoppage and washed down the roadway and vacuuming up the Jet flushed from MH 20 to MH 21 and broke obstruction of heavy roots. Recommend TV to evaluate Jet flusehd from MH#7; rodded from MH#8. Broke obstruction of heavy roots Jet flushed from MH#18 & #19. Broke obstruction in MH #19. There were rocks and wood in channel jet flusehd and broke obstruction of rags & debris Rodded but encounter obstruction. Contractor will evaluate with TV when re-rod line. Rodded with power rodder and broke obstruction of roots 175' upstream from MH #H-26 jet flushed line from MH#66 thru #68 to MH #69. MH# 69 is overflowing; broke obstruction of rags & debris Jet flushed line from MH#11 thru #12 to #13. Jet flushed from MH B-4 through MH D-33 Jet flushed 275 feet from MH #9 to MH #6 and broke abstruction of roots and debris Worked on soft starter and pumped wetwell into vactor tank truck to prevent overflow Manhole #79 was full; slight seepage was invisible on surface. Washed down street on Altadena Drive

Crews cleaned up and vacumn most of the spill on the paved surface areas.


6/24/2011 14:20
6/3/2007 10:10 5/16/2007 11:20 6/19/2007 13:48
6/29/2008 4:00
6/2/2008 12:15

2/13/2009 16:00 4/13/2009 15:58

9/23/2009 15:15 10/6/2009 15:00

5/25/2010 2:45

Adjusted schedule/method of preventive maintenance
Repaired sewer
Added sewer to preventive maintenance program Adjusted schedule/method of preventive maintenance Repaired sewer
Repaired sewer
Added sewer to preventive maintenance program;Plan rehabilitation or replacement of sewer
Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance Plan rehabilitation or replacement of sewer
Other (specify below) Repaired sewer



No

No

No No

No

Yes

Yes

Yes

Yes

No

No

No

No

No No

No

No

No

No

No

Yes

No

N/A

NA

NA

NA

NA NA

NA NA

N/A
NONE N/A NONE N/A
No surface water(s) impacted N/A N/A
N/A NONE NA
Purissima Creek
Adobe Creek - dry creek during summer time
Deer Creek
Barron Creek
NA Dry Creek
Deer Creek Barron Creek

No water quality samples taken
Not applicable to this spill
No water quality samples taken No water quality samples taken No water quality samples taken
No water quality samples taken
No water quality samples taken
No water quality samples taken No water quality samples taken
No water quality samples taken No water quality samples taken;Not applicable to this spill



None of the above		
None of the above		
No water quality samples taken No water quality samples taken None of the above		
Not applicable to this spill		
None of the above		
None of the above No water quality samples taken		
None of the above None of the above		





95693	8/16/2009 1:35
103220	5/24/2010 22:05
113801	6/24/2011 16:10

2SSO10149	Active	746440 Johnson Chung	Certified
2SSO10149	Active	746715 Johnson Chung	Certified
2SSO10149	Active	746720 Johnson Chung	Certified
2SSO10149	Active	747258 Johnson Chung	Certified
2SSO10149	Active	748165 Johnson Chung	Certified
2SSO10149	Active	748166 Johnson Chung	Certified
2SSO10149	Active	748167 Johnson Chung	Certified
2SSO10149	Active	748845 Johnson Chung	Certified
2SSO10149	Active	749065 Johnson Chung	Certified
2SSO10149	Active	751553 Johnson Chung	Certified
2SSO10149	Active	751797 Johnson Chung	Certified
2SSO10149	Active	753059 Johnson Chung	Certified
2SSO10149	Active	755811 Johnson Chung	Certified
2SSO10149	Active	756421 Johnson Chung	Certified
2SSO10149	Active	756669 Johnson Chung	Certified
2SSO10149	Active	757464 Johnson Chung	Certified
2SSO10149	Active	757926 Johnson Chung	Certified
2SSO10149	Active	758293 Johnson Chung	Certified
2SSO10149	Active	758351 Johnson Chung	Certified
2SSO10149	Active	758440 Johnson Chung	Certified
2SSO10149	Active	759154 Johnson Chung	Certified
2SSO10149	Active	759574 Johnson Chung	Certified
2SSO10149	Active	759691 Johnson Chung	Certified
2SSO10149	Active	760917 Johnson Chung	Certified
2SSO10149	Active	761694 Johnson Chung	Certified
2SSO10149	Active	762915 Johnson Chung	Certified
2SSO10149	Active	762999 Johnson Chung	Certified
2SSO10149	Active	765234 Johnson Chung	Certified
2SSO10149	Active	766245 Johnson Chung	Certified
2SSO10149	Active	766807 Johnson Chung	Certified
2SSO10149	Active	767169 Johnson Chung	Certified
2SSO10149	Active	767525 Johnson Chung	Certified
2SSO10149	Active	767534 Johnson Chung	Certified
2SSO10149	Active	768060 Johnson Chung	Certified
2SSO10149	Active	769153 Johnson Chung	Certified
2SSO10149	Active	769487 Johnson Chung	Certified
2SSO10149	Active	769737 Johnson Chung	Certified
2SSO10149	Active	770244 Johnson Chung	Certified
2SSO10149	Active	770349 Johnson Chung	Certified
2SSO10149	Active	771539 Johnson Chung	Certified
2SSO10149 2SSO10149	Active Active	772280 Johnson Chung	Certified Certified
2SSO10149 2SSO10149	Active	773539 Johnson Chung	Certified
2SSO10149 2SSO10149	Active	774044 Johnson Chung	Certified
2SSO10149 2SSO10149		774048 Johnson Chung	
	Active	775720 Johnson Chung	Certified Certified
2SSO10149	Active	776180 Johnson Chung	
2SSO10149 2SSO10149	Active Active	776674 Johnson Chung 778199 Johnson Chung	Certified Certified
2SSO10149 2SSO10149	Active	778612 Johnson Chung	Certified
2SSO10149 2SSO10149	Active	778612 Johnson Chung 778616 Johnson Chung	Certified
2SSO10149 2SSO10149	Active	778678 Johnson Chung 778678 Johnson Chung	Certified
2SSO10149 2SSO10149	Active	780331 Johnson Chung	Certified
2SSO10149 2SSO10149	Active	783535 Michelle Chen	Certified
2SSO10149 2SSO10149	Active	787732 Michelle Chen	Certified
2SSO10149 2SSO10149	Active	787815 Michelle Chen	Certified
2000 10 170	, 101140	7.070 Micholio Orion	Jordinou

- **Engineering Tech**
- Engineering Tech.
- Engineering Teer
- Engineering Tech.
- Engineering reen.
- Engineering Tech. Engineering Tech.
- Engineering Tech.
- Engineering Tech.
 Engineering Tech.
- Associate Engineer
- Associate Engineer
- Associate Engineer

Los Altos Hills	482828
Los Altos Hills	526666
Los Altos Hills	411819
Los Altos Hills	891934
Los Altos Hills	452627
Los Altos Hills	588024
Los Altos Hills	254296
Los altos Hills	822016
Los Altos Hills	190939
Los Altos Hills	984095
Los Altos Hills	112474
Los Altos Hills	407002
Los Altos Hills	827705
Los Altos Hills	811750
Los Altos Hills	653638
Los Altos Hills	664238
Los Altos Hills	691044
Los Altos Hills	992281
Los Altos Hills	185297
Los Altos Hills	530533
Los Altos Hills	339103
Los Altos Hills	644429
Los Altos Hills	167597
Los Altos Hills	555958
Los Altos Hills	804993
Los Altos Hills	587347
Los Altos Hills Los Altos Hills	348583 636885
Los Altos Hills	360490
Los Altos Hills	283229
Los Altos Hills	214943
Los Altos Hills	764866
Los Altos Hills	335223
Los Altos Hills	974946
Los Altos Hills	351320
Los Altos Hills	392968
Los Altos Hills	806788
Los Altos Hills	382081
Los Altos Hills	472297
Los Altos Hills	794395
Los Altos Hills	577096
Los Altos Hills	172194
Los Altos Hills	882058
Los Altos Hills	529454
Los Altos Hills	514219
Los Altos Hills	670249
Los Altos Hills	241290
Los Altos Hills	797130
Los Altos Hills	960580
Los Altos Hills	343772
Los Altos Hills	462062
Los Altos Hills	638754
Los Altos Hills	754332
11:28am	798275
11:20am	910702

3-Nov-09		3-Nov-09	11/3/2009
12-Nov-09		24-Nov-09	12/21/2010
12-Nov-09		24-Nov-09	12/21/2010
2-Dec-09		2-Dec-09	12/2/2009
5-Jan-10		5-Jan-10	1/5/2010
5-Jan-10		5-Jan-10	1/5/2010
5-Jan-10		5-Jan-10	1/5/2010
26-Jan-10		26-Jan-10	1/26/2010
2-Feb-10		3-Feb-10	2/3/2010
13-Apr-10		14-Apr-10	4/14/2010
20-Apr-10		20-Apr-10	12/20/2010
3-Jun-10	6/3/2010	3-Jun-10	6/3/2010
5-Aug-10	8/5/2010	5-Aug-10	8/5/2010
26-Aug-10	8/26/2010	26-Aug-10	12/20/2010
9-Sep-10	9/9/2010	9-Sep-10	9/9/2010
8-Oct-10	10/8/2010	8-Oct-10	10/8/2010
19-Oct-10	10/19/2010	19-Oct-10	10/19/2010
1-Nov-10	11/1/2010	1-Nov-10	11/1/2010
3-Nov-10	11/3/2010	3-Nov-10	11/3/2010
9-Nov-10	11/9/2010	9-Nov-10	11/9/2010
7-Dec-10	12/7/2010	8-Dec-10	12/8/2010
20-Dec-10	12/20/2010	20-Dec-10	12/20/2010
22-Dec-10	12/22/2010	22-Dec-10	12/22/2010
11-Jan-11	1/11/2011	11-Jan-11	1/11/2011
24-Jan-11	1/24/2011	24-Jan-11	1/24/2011
14-Feb-11	2/14/2011	14-Feb-11	2/14/2011
14-Feb-11	2/14/2011	14-Feb-11	2/14/2011
6-Apr-11	4/6/2011	6-Apr-11	4/6/2011
9-May-11	5/9/2011	9-May-11	5/9/2011
23-May-11	5/23/2011	23-May-11	5/23/2011
6-Jun-11	6/6/2011	6-Jun-11	6/6/2011
15-Jun-11	6/15/2011	15-Jun-11	6/15/2011
15-Jun-11	6/15/2011	15-Jun-11	6/15/2011
30-Jun-11	6/30/2011	30-Jun-11	6/30/2011
28-Jul-11	7/28/2011	28-Jul-11	7/28/2011
4-Aug-11	8/4/2011	4-Aug-11	8/4/2011
11-Aug-11	8/11/2011	23-Aug-11	8/23/2011
23-Aug-11	8/23/2011	23-Aug-11	8/23/2011
25-Aug-11	8/25/2011	25-Aug-11	8/25/2011
28-Sep-11	9/28/2011	28-Sep-11	9/28/2011
24-Oct-11	10/24/2011	24-Oct-11	10/24/2011
29-Nov-11	11/29/2011	29-Nov-11	11/29/2011
13-Dec-11	12/13/2011	13-Dec-11	12/13/2011
13-Dec-11	12/13/2011	13-Dec-11	12/13/2011
11-Jan-12	1/11/2012	11-Jan-12	1/11/2012
20-Jan-12	1/20/2012	20-Jan-12	1/20/2012
31-Jan-12	1/31/2012	31-Jan-12	1/31/2012
29-Feb-12	2/29/2012	29-Feb-12	2/29/2012
13-Mar-12	3/13/2012	13-Mar-12	3/13/2012
13-Mar-12	3/13/2012	13-Mar-12	3/13/2012
15-Mar-12	3/15/2012	15-Mar-12	3/15/2012
19-Apr-12	4/19/2012	19-Apr-12	4/19/2012
16-Jul-12	7/16/2012	16-Jul-12	7/16/2012
31-Oct-12	11/6/2012	6-Nov-12	11/6/2012
2-Nov-12	11/2/2012	2-Nov-12	11/2/2012

Category 2	1200	1182
Category 1	50	50
Category 1	50	48
Category 3	75 500	75 500
Category 3	500	500
Category 3	20	20
Category 3	300	300
Category 3	200	200
Category 1	1125	800
Category 3	900	350
Category 1	500	0
Category 3	800	700
Category 1	3750	0
Category 1	1380	1200
Category 2	1375	0
Category 3	640	0
Category 1	200	0
Category 1	720	460
Category 3	50	0
Category 1	85	25
Category 1	800	0
Category 1	600	200
Category 1	50	0
Category 2	1600	0
Category 3	200	0
Category 3	30	0
Category 3	150	0
Category 3	270	0
Category 3	90	0
Category 3	15	0
Category 1	1500	1200
Category 3	11	0
Category 3	10	0
Category 3	37	0
Category 3	150	0
Category 3	11	0
Category 3	100	100
Category 3	5	0
Category 3	35	0
Category 3	60	Ö
Category 3	30	Ö
Category 3	630	ŏ
Category 3	180	Ö
Category 3	90	0
Category 1	675	0
Category 3	250	0
	272	0
Category 3		
Category 3	15 1	0
Category 3	1	0
Category 3	1	0
Category 3	50	0
Category 3	300	0
Category 3	34	0
Category 3	140	0
Category 3	6	0

0 No	No
1 Yes	Yes
2 Yes	Yes
0 No	No
0 No	Yes
0 No	No No
0 No	Yes
0 No	
325 Yes	No Voc
	Yes
0 No	Yes
350 Yes	Yes
0 No	No
3750 Yes	Yes
180 Yes	No
0 No	No
0 No	Yes
200 Yes	No
260 Yes	No
0 No	No
65 Yes	Yes
800 Yes	No
400 Yes	No
20 No	Yes
0 No	No
300 Yes	No
0 No	No
0 No	Yes
0 No	No
0 No	No.
0 No	No
	No
0 No	No
10 Yes	No
0 No	No
0 No	Yes
0 No	No
0 No	No
0 No	No
0 No	Yes
0 No	No

Not Applicable - Spill did not reach storm drainpipe Yes Yes Not Applicable - Spill did not reach storm drainpipe Yes Not Applicable - Spill did not reach storm drainpipe Yes Not Applicable - Spill did not reach storm drainpipe No No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Shady Oaks Court

Corbetta Lane

Corbetta lane

Moody Springs Court

Newbridge Drive

Todd Lane

Altamont Road

Fremont Road Easement

Matadero Creek Court Easement

Emerald Hill Lane

Stonebrook Drive

O'Keefe Lane

Amherst Court

Todd Lane Easement Mainline

Dezahara Way Easement Area

Concepcion Road

Todd Lane Sanitary Sewer Easement

Sanitary Sewer Manhole is Located in a Private Property in the Dirt Area

Altadena Drive and Manuella Road

Priscilla Lane

Todd Lane in the easement MainLine

Moody Road Pedestrian Trail

Winding Way

Via Cerro Gordo Pedestrian Trial in the Easement

Intersection of Taaffe and Altamont Road

Summitwood Court Private Driveway

Matadero Creek Pedestrian Trail

Alta Tierra Easement Main Line

Story Hills Lane Easement

Altamont Road Easement Main Line

Palo Hills Drive Easement

Old Page Mill Road Easement Main Line

Torello Lane Easement Main Line

Yale Court in the Easement Mainline

Summitwood Road Easement

Manuella Road

Arastradero Road and Thendara Way

Anacapa and Ascension Drive

Christopher Lane Easement Line

Intersection of Tepa Way and Summitwood Road

Rhus Ridge Road Easement Mainline

Intersection of Altamont Road and Padre Court

La Cresta Court Easement Line

Tepa Way Right of Way

In a New Development Area

Aric Lane Easement Line

Fremont Pines Lane and Fremont Road

Moody Road Easement

Nina Place easement mainline

La Cresta Drive Easement

Camino Medio Right of Way

Rhus Ridge Road

26010 Altamont Road

11611 Winding Way

Winding Way


37.39287	-122.14255	Santa Clara
37.35862	-122 14294	Santa Clara
37.35862		Santa Clara
37.35498		Santa Clara
37.37639		Santa Clara
37.37812		Santa Clara
37.35782	-122.14081	Santa Clara
37.39107	-122.14257	Santa Clara
37.37138	-122.16312	Santa Clara
37.35449	-122.12336	Santa Clara
37.35773	-122.12435	Santa Clara
37.36552		Santa Clara
37.387389		Santa Clara
37.37777		Santa Clara
		Santa Clara
37.36002		
37.37547		Santa Clara
37.37706		Santa Clara
37.38216		Santa Clara
37.38564	-122.13308	Santa Clara
37.35674	-122.12249	Santa Clara
37.37702	-122.13275	Santa Clara
37.35309	-122.14551	Santa Clara
37.35052		Santa Clara
37.36934		Santa Clara
37.36608		Santa Clara
37.35628		Santa Clara
37.37167		Santa Clara
37.37151		Santa Clara
37.37966	-122.13746	Santa Clara
37.36056	-122.14621	Santa Clara
37.38999	-122.14395	Santa Clara
37.39309	-122.16374	Santa Clara
37.38396	-122.13147	Santa Clara
37.38962		Santa Clara
37.35344		Santa Clara
37.39036		Santa Clara
37.39341		Santa Clara
37.38239		Santa Clara
37.39167		Santa Clara
37.35539		Santa Clara
37.35314	-122.13791	Santa Clara
37.35821	-122.13917	Santa Clara
37.37592	-122.13965	Santa Clara
37.35482	-122.13268	Santa Clara
37.38141		Santa Clara
37.37966		Santa Clara
37.38209		Santa Clara
37.35312		Santa Clara
37.38707		Santa Clara
37.37753		Santa Clara
37.38074		Santa Clara
37.35263		Santa Clara
37.35832	-122.14377	Santa Clara
37.3503	-122.1082	Santa Clara
37.35066	-122.10643	Santa Clara

Sanitary sewer manhole overflow downhill side to a dry creek	
Main line clean out F.I. Sewage spilled from a manhole in the easement area.	
Town manhole overflow due to City of Palo Alto downstream trunk line blockage at Page Mill Road. I put sand bags arou Sewer manhole locates next to a dry creek and was overflowed, fortunately there are a lot of vegetation along the creek v Sanitary sewer manhole overflow is in the easement area, it is located more than 200 feet away from a dry creek. At the	
Sanitary sewer manhole is locate next to a ditch, raw sewage slowly sipped out from a sewer manhole to the surface water	
The spill was seeping out in a resident's backyard in the dirt area.	
manhole overflow Manhole in the street near cul-de-sac	

nd storm drain inlet to protect sewage ϵ which can slow down the flow and the sp time of the spill, we have dig a trench to

er and to the dirt area.

Gravity sewer; Manhole Manhole Manhole Manhole Manhole Manhole Manhole Other (specify) Manhole Gravity sewer; Manhole Manhole Pump station Manhole Gravity sewer; Manhole Gravity sewer; Manhole Gravity sewer; Manhole Manhole Manhole Manhole Manhole Gravity sewer; Manhole Gravity sewer; Manhole Gravity sewer; Manhole Gravity sewer; Manhole Gravity sewer Manhole Manhole Manhole Other (specify) Manhole Manhole Manhole Manhole Manhole Force main or pressure sewer; Manhole Manhole Manhole Manhole Manhole Other (specify) Manhole Manhole Manhole Manhole Other sewer system structure



Other (specify below)

Street/curb and gutter

Separate storm drain; Street/curb and gutter

Street/curb and gutter

Other (specify below)

Street/curb and gutter

Storm drain; Street/curb and gutter; Unpaved surface

Unpaved surface

Other paved surface; Storm drain; Street/curb and gutter; Unpaved surface

Unpaved surface

Surface water; Unpaved surface

Unpaved surface

Other paved surface; Storm drain; Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Surface water; Unpaved surface

Street/curb and gutter;Unpaved surface

Other paved surface; Street/curb and gutter

Surface water; Unpaved surface

Surface water; Unpaved surface; Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Other (specify below)

Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface; Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface; Other (specify below)

Unpaved surface; Other (specify below)

Unpaved surface; Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Other (specify below)

Spill reach to a down hill side to a dry creek
Down 400' away from manhole
The crew placed sand bags around storm drain inlet to keep sewage from enter the inlet and divered the flow to a nearby
Sewer manhole is locate at a pedestrian trail close to Adobe Creek. Sewage was sipped out from the manhole cover and
Sewage seeped into vegetation area. Dirt area. Dirt area
Sewer manhole is located next to a creek. Most of the spilled reached to a dry creek bed and used a protable pump to pu
Infiltrated into dry ditch and vegetation area. Spill infiltrated in the vegetation area. Spill seeped into soil and vegetation area. Approximately 500 gallons went to a dry creek bed and 175 gallons sipped into soil. Infiltrated into dry creek bed. Infiltrated into soil in the dry ditch.
There was no spill when crew arrived.
The final spill destination was to a dry ditch.
On AC and concrete area on the roadway dirt area

10/30/2009 0:00	10/30/2009 9:53	10/30/2009 10:42	10/30/2009 14:00
11/1/2009 0:00	11/1/2009 9:36	11/1/2009 10:30	11/1/2009 12:30
11/1/2009 0:00	11/1/2009 9:36	11/1/2009 10:30	11/1/2009 12:30
11/30/2009 0:00	11/30/2009 10:45	11/30/2009 11:15	11/30/2009 11:45
12/23/2009 0:00	12/23/2009 15:35	12/23/2009 16:10	12/23/2009 16:45
12/25/2009 0:00	12/25/2009 14:08	12/25/2009 14:45	12/25/2009 15:15
12/31/2009 0:00	12/31/2009 10:25	12/31/2009 11:00	12/31/2009 13:04
1/22/2010 0:00	1/22/2010 10:45	1/22/2010 11:30	1/22/2010 12:30
1/30/2010 0:00	1/30/2010 12:50	1/30/2010 13:45	1/30/2010 16:30
4/9/2010 0:00	4/9/2010 11:24	4/9/2010 12:10	4/9/2010 13:30
4/17/2010 0:00	4/17/2010 12:00	4/17/2010 12:30	4/17/2010 13:45
6/3/2010 0:00	6/3/2010 7:45	6/3/2010 8:15	6/3/2010 8:45
8/4/2010 0:00	8/4/2010 9:41	8/4/2010 10:49	8/4/2010 12:12
8/25/2010 0:00	8/25/2010 8:05	8/25/2010 8:30	8/25/2010 9:28
9/8/2010 0:00	9/8/2010 11:06	9/8/2010 11:18	9/8/2010 12:10
10/6/2010 0:00	10/6/2010 16:41	10/6/2010 16:52	10/6/2010 18:49
10/17/2010 0:00	10/17/2010 14:36	10/17/2010 15:10	10/17/2010 17:09
10/29/2010 0:00	10/29/2010 11:10	10/29/2010 12:13	10/29/2010 12:59
10/30/2010 0:00	10/30/2010 15:55	10/30/2010 16:40	10/30/2010 18:30
11/3/2010 0:00	11/3/2010 8:30	11/3/2010 8:45	11/3/2010 9:32
12/4/2010 0:00	12/4/2010 11:38	12/4/2010 12:48	12/4/2010 13:19
12/19/2010 0:00	12/19/2010 16:45	12/19/2010 17:00	12/19/2010 17:30
12/21/2010 0:00	12/21/2010 13:26	12/21/2010 13:54	12/21/2010 14:22
1/7/2011 0:00	1/7/2011 17:13	1/7/2011 18:03	1/7/2011 19:56
1/16/2011 0:00	1/16/2011 14:30	1/16/2011 15:29	1/16/2011 16:06
2/10/2011 0:00	2/10/2011 16:29	2/10/2011 17:17	2/10/2011 18:10
2/11/2011 0:00	2/11/2011 11:00	2/11/2011 12:00	2/11/2011 13:00
4/5/2011 0:00	4/5/2011 11:04	4/5/2011 12:00	4/5/2011 14:00
5/7/2011 0:00	5/7/2011 11:00	5/7/2011 11:45	5/7/2011 12:30
5/22/2011 0:00	5/23/2011 13:07	5/23/2011 14:11	5/23/2011 15:11
5/27/2011 0:00	5/27/2011 7:52	5/27/2011 8:20	5/27/2011 8:40
6/9/2011 0:00	6/9/2011 15:37	6/9/2011 16:15	6/9/2011 17:00
6/8/2011 0:00	6/8/2011 12:27	6/8/2011 12:45	6/8/2011 13:25
6/29/2011 0:00	6/29/2011 9:47	6/29/2011 10:30	6/29/2011 11:00
7/27/2011 0:00	7/27/2011 12:12	7/27/2011 13:00	7/27/2011 17:00
8/2/2011 0:00	8/2/2011 9:44	8/2/2011 10:00	8/2/2011 10:15
8/10/2011 0:00	8/10/2011 10:20	8/10/2011 10:50	8/10/2011 12:20
8/20/2011 0:00	8/20/2011 17:17	8/20/2011 18:15	8/20/2011 18:30
8/23/2011 0:00	8/23/2011 10:34	8/23/2011 10:45	8/23/2011 11:00
9/27/2011 0:00	9/27/2011 14:00	9/27/2011 14:40	9/27/2011 15:00
10/14/2011 0:00	10/14/2011 11:08	10/14/2011 11:45	10/14/2011 12:15
11/26/2011 0:00	11/26/2011 16:06	11/26/2011 17:10	11/26/2011 17:30
12/1/2011 0:00	12/1/2011 9:53	12/1/2011 10:00	12/1/2011 10:45
12/10/2011 0:00	12/10/2011 13:06	12/10/2011 14:10	12/10/2011 14:30
1/7/2012 0:00	1/7/2012 10:55	1/7/2012 11:30	1/7/2012 11:45
1/19/2012 0:00	1/19/2012 13:26	1/19/2012 13:40	1/19/2012 13:40
1/25/2012 0:00	1/25/2012 13:32	1/25/2012 13:52	1/25/2012 13:54
2/23/2012 0:00	2/23/2012 16:00	2/23/2012 16:45	2/23/2012 17:00
3/2/2012 0:00	3/2/2012 10:13	3/2/2012 11:15	3/2/2012 11:36
3/9/2012 0:00	3/9/2012 14:51	3/9/2012 15:40	3/9/2012 15:42
3/12/2012 0:00	3/12/2012 9:35	3/12/2012 10:40	3/12/2012 11:30
4/15/2012 0:00	4/15/2012 19:35	4/15/2012 10:40	4/15/2012 11:30
6/22/2012 0:00	6/22/2012 13:30	6/22/2012 14:26	6/22/2012 14:26
10/23/2012 0:00	10/23/2012 13:38	10/23/2012 14:50	10/23/2012 15:00
10/23/2012 0:00		10/23/2012 14:50	10/23/2012 15:00
10/13/2012 0:00	10/13/2012 17:09	10/13/2012 10:15	10/13/2012 19:10

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Pump station failure

Root intrusion

Other (specify below)

Root intrusion

Pipe structural problem/failure

Root intrusion

Debri-General

Debit-General

Other (specify below)

Root intrusion

Pipe structural problem/failure

Root intrusion

Pump station failure

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Root intrusion

Root intrusion

Heavy roots blocking channel of the sewer main
This is the same location which was overflow back in February 13, 2009 and caused by City of Palo Alto trunk line plugge Spill caused by an under garment cloth caught in the mainline and triggered the overflow, most of the spill was captured v
The spill caused by roots in the mainline and it was partial open at the time of overflow. We have sand bags in place at t The mainline was partially opened at the time of the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the over the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the spill and the sewer was slowly not constantly sipped out from the sewer was slowly not constantly sipped out from the sewer was slowly not constantly sipped out from the sewer was slowly not constantly sipped out from the sewer was slowly not constantly sipped out from the sewer was slowly not constantly sipped out from the sewer was slowly not constantly sipped out from the sewer was slowly not constantly sipped out from the sewer was slowly not constantly slowly not constantly sipped out from the sewer was slowly not constantly
Spill caused by dirt and roots.
Roots in manhole
Unable to determine.
a section of pipe was broken root in manhole channel Town contractor rodded mainline 75' and broke root obstruction

Main Other (specify below) Main Main Main Main Main Main Main

Main Main Main



- 6 VCP
- 8 VCP
- 6 VCP
- 8 VCP
- 6 VCP



Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause;Re Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Restored flow;Returned all or portion of Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Inspected sewer using CCTV to determine cause:Re Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Restored flow;Returned all or portion of Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanil Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill); Inspected sewer using CCTV to determine cause Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanil Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill):Inspected sewer using CCTV to determine cause:Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Restored flow:Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill); Inspected sewer using CCTV to determine cause; Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill); Inspected sewer using CCTV to determine cause; Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow



10/30/2009 14:00 11/1/2009 12:30 11/1/2009 12:30 1/30/2010 19:45 4/9/2010 16:20 4/17/2010 13:45 8/4/2010 13:16 8/25/2010 11:23 9/8/2010 14:10 10/6/2010 19:20 10/17/2010 17:39 10/29/2010 15:05 11/3/2010 11:02 12/4/2010 15:20 12/19/2010 18:42 12/21/2010 15:54 1/7/2011 21:36 5/27/2011 15:30 6/8/2011 14:27

1/7/2012 13:58

1/25/2012 15:32

3/12/2012 11:56

Added sewer to preventive maintenance program; Plan rehabilitation or replacement of sewer Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance; Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer
Added sewer to preventive maintenance program; Plan rehabilitation or replacement of sewer Repaired sewer Added sewer to preventive maintenance program
Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance Added sewer to preventive maintenance program Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance
Repaired sewer Plan rehabilitation or replacement of sewer Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance
Added sewer to preventive maintenance program Plan rehabilitation or replacement of sewer Added sewer to preventive maintenance program; Enforcement action against FOG source Added sewer to preventive maintenance program Adjusted schedule/method of preventive maintenance
Added sewer to preventive maintenance program;Plan rehabilitation or replacement of sewer;Repaired sewer
Added sewer to preventive maintenance program; Adjusted schedule/method of preventive maintenance
Repaired sewer
Adjusted schedule/method of preventive maintenance
Plan rehabilitation or replacement of sewer;Repaired sewer



Yes Yes

Yes

Yes

Yes

Yes

No

No No

No

No

No

No

No

No

No

NA

Adobe Creek

Adobe Creek

The spill from the storm drain inlet reached to a near by swale which has a small amount of flow at the time, but we did flun NA

Hale Creek

Matadero Creek

The estimate volume of spill reached to the Dry Creek.

NA

The spilled reach to dirt area only and did not reach to surface water.

Impacted surface water from a ditch.

Spilled sewage went to a dry creek where the vacumn truck sucked up most of the spills and returned to the sewer systen N/A

Dry Creek

Sewer manhole is locate next to a swale where the spilled went and drained to a nearby dry creek.

Adobe Creek

na

The final destination of the spill went to the dirt area.

Spilled did not reach to surface water

Sewage did not reach to surface water.

Spill did not reach to surface water.

Spill did not reach to surface water

Spill did not reach to surface water

Spill did not reach to surface water

Barron Creek and the creek bed was dry at the time of spilled.

Spill did not reach any surface water

Spill did not reach to any surface water

Spill did not reach to surface water

Spill did not reach to any surface water.

The spill did not reach to surface water.

Spill did not reach to any surface water.

Spill did not reach to any surface water.

Spill did not reach any surface water.

The spill did not reach to any surface water and the final destination is in the dirt area.

Spill did not reach to any surface water.

Spilled did not reach to any surface water.

Spilled did not reach any surface water.

Spilled did not reach to any surface water.

Deer Creek and the creek bed was dry at the time of spilled.

Spill did not reach to any surface water.

Spill did not reach to any surface water, it infiltrated into a dry ditch instead.

Spill did not reach to any surface water.

Spill did not reach to any surface water.

Spill did not reach to any surface water or creek.

Spill did not reach to any surface water.

Spill did not reach to any surface water.

None


None

None

No water quality samples taken No water quality samples taken

No water quality samples taken No water quality samples taken No water quality samples taken None of the above Regional Water Quality Control Board None of the above No water quality samples taken No water quality samples taken County Health Agency; Regional Water Quality Control Board No water quality samples taken County Health Agency; Regional Water Quality Control Board No water quality samples taken None of the above

County Health Agency



102308	4/12/2010 9:16
102477	4/20/2010 10:04
104661	8/4/2010 12:58
105086	8/25/2010 9:08
105404	9/8/2010 12:26
106249	10/17/2010 16:52
106500	10/29/2010 12:03
106595	10/3/2010 9:58
107285	12/4/2010 13:19
107647	12/19/2010 17:49
107714	12/21/2010 14:40
110126	1/7/2011 19:37
113218	5/27/2011 9:25
113437	6/8/2011 14:11
120120	1/7/2012 12:08
120361	1/19/2012 14:55
120529	1/25/2012 15:25
121399	3/12/2012 10:56

1/30/2010 12:50

100890



2SSO10149	Active	787820 Michelle Chen	Certified
2SSO10149	Active	788496 Michelle Chen	Certified
2SSO10149	Active	788813 Michelle Chen	Certified
2SSO10149	Active	790838 Michelle Chen	Certified
2SSO10149	Active	790971 Michelle Chen	Certified
2SSO10149	Active	793606 Michelle Chen	Certified
2SSO10149	Active	794647 Woojae Kim	Certified
2SSO10149	Active	796200 Woojae Kim	Certified
2SSO10149	Active	796634 Woojae Kim	Certified
2SSO10149	Active	798388 Woojae Kim	Certified
2SSO10149	Active	798389 Woojae Kim	Certified
2SSO10149	Active	798849 Woojae Kim	Certified
2SSO10149	Active	800838 Richard Chiu	Certified
2SSO10149 2SSO10149	Active	801102 Richard Chiu	Certified
2SSO10149 2SSO10149	Active	801103	Work In Progress
2SSO10149 2SSO10151	Active	650534 Timothy O'Day	Certified
		•	
2SSO10151	Active	655340 Timothy O'Day	Certified
2SSO10151	Active	656073 Timothy O'Day	Certified
2SSO10151	Active	706495 Tim O'day	Certified
2SSO10151	Active	709027 Timothy O'Day	Certified
2SSO10151	Active	710625 Tony Rubio	Certified
2SSO10151	Active	710628 Timothy O'Day	Certified
288010151	Active	711185 Tony Rubio	Certified
2SSO10151	Active	712665 Tony Rubio	Certified
2SSO10151	Active	712666 Tony Rubio	Certified
2SSO10151	Active	712667 Timothy O'Day	Certified
2SSO10151	Active	712829 Tony Rubio	Certified
2SSO10151	Active	714352 Tony Rubio	Certified
2SSO10151	Active	714807 Tony Rubio	Certified
2SSO10151	Active	714837 Tony Rubio	Certified
2SSO10151	Active	714839 Tony Rubio	Certified
2SSO10151	Active	715048 Tony Rubio	Certified
2SSO10151	Active	716212 Tony Rubio	Certified
2SSO10151	Active	716215 Tony Rubio	Certified
2SSO10151	Active	716233 Tony Rubio	Certified
2SSO10151	Active	717588 Tim O'Day	Certified
2SSO10151	Active	722956 Tim O'Day	Certified
2SSO10151	Active	722958 Tim O'Day	Certified
2SSO10151	Active	722959 Tony Rubio	Certified
2SSO10151	Active	729374 Tim O'Day	Certified
2SSO10151	Active	730619 Tony Rubio	Certified
2SSO10151	Active	730689 Tim O'Day	Certified
2SSO10151	Active	731011 Tony Rubio	Certified
288010151	Active	735936 Tim O'Day	Certified
2SSO10151	Active	736919 Tony Rubio	Certified
2SSO10151	Active	736920 Tim O'Day	Certified
2SSO10151	Active	738323 Tim O'Day	Certified
2SSO10151	Active	738324 Tim O'Day	Certified
2SSO10151	Active	738329 Tim O'day	Certified
2SSO10151	Active	738333 Tony Rubio	Certified
2SSO10151	Active	739357 Tony Rubio	Certified
2SSO10151	Active	740227 Tony Rubio	Certified
2SSO10151	Active	741183 Timothy O'Day	Certified
2SSO10151	Active	741204 Tim O'Day	Certified
2SSO10151	Active	741951 Timothy O'Day	Certified

Associate Engineer

Associate Engineer

Associate Engineer

Associate Engineer

Associate Engineer

Associate Engineer

Senior Engineer

Senior Engineer

Senior Engineer

Senior Engineer

Senior Engineer

Senior Engineer

Public Works Director

Public Works Director

Senior Operator

Senior Operator/Lab. Director

Senior Operator / Lab. Director

Operator

Senior Operator

Wastewater Facilities Manager

Senior Operator

Wastewater Facilities Manager

WFM

Wastewater Facilities Manager

Senior Operator

WFM

WFM

WFM

Wastewater Facilities Manager

Wastewater Facilities manager

WFM

Wastewater Facilities Manager

WFM

Wastewater Facilities manager

Senior Operator

Senior operator

Operator

Wastewater Facilities Manager

Senior Operator

WFM

Senior Operator

WFM

Senior Operator

WFM

Operator

Operator

Operator

Operator

WFM

WFM

Wastewater Facilities manager

Senior Operator

Senior Operator

Operator

2:30pm 11:04am 11:12am 11:12am 185633 11:27am 597322 12:04pm 4:34pm Los Altos Hills Los Altos
11:04am 808108 11:12am 185633 11:27am 597322 12:04pm 588078 4:34pm 924619 Los Altos Hills 700570 Los Altos Hills 502329 Los Altos Hills 586659 Los Altos Hills 540539 Los Altos Hills 555196 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
11:12am 185633 11:27am 597322 12:04pm 588078 4:34pm 924619 Los Altos Hills 700570 Los Altos Hills 502329 Los Altos Hills 586659 Los Altos Hills 540539 Los Altos Hills 555196 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
11:27am 597322 12:04pm 588078 4:34pm 924619 Los Altos Hills 700570 Los Altos Hills 502329 Los Altos Hills 586659 Los Altos Hills 555196 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
12:04pm 588078 4:34pm 924619 Los Altos Hills 700570 Los Altos Hills 502329 Los Altos Hills 586659 Los Altos Hills 555196 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
4:34pm 924619 Los Altos Hills 700570 Los Altos Hills 502329 Los Altos Hills 586659 Los Altos Hills 540539 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 821720 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 700570 Los Altos Hills 502329 Los Altos Hills 586659 Los Altos Hills 555196 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 502329 Los Altos Hills 586659 Los Altos Hills 555196 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 821720 Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 586659 Los Altos Hills 540539 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 821720 Los Altos Hills 877/2007 Tiburon SD5 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 540539 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 555196 Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 251490 Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 821720 Los Altos Hills 588640 Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Los Altos Hills 588640 Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
Tiburon SD5 907674 8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
8/7/2007 584966 8/20/2007 798536 2001 Paradise drive 948671 12/12/2007 912741
2001 Paradise drive 8/20/2007 798536 948671 12/12/2007 912741
2001 Paradise drive 948671 12/12/2007 912741
12/12/2007 912741
2001 Paradise Drive 748371
2001 Paradise Drive 997808
2001 Paradise Drive 691769
2001 Paradise Drive 822444
2001 paradise Drive 209185
2001 Paradise Drive 499749
2001 Paradise Drive 243941
2001 Paradise Drive 183347
2001 Paradise Drive 358784
2001 Paradise Drive 100500
2001 Paradise Drive 716890
2001 Paradise drive 752619
2001 Paradise Drive 103185
2001 Paradise drive 761196
2001 Paradise Drive 351604
2001 Paradise Drive 582061
2001 Paradise Drive 620753
0004 Paradia - Didua
2001 Paradise Drive 186449
2001 Paradise Drive 786548
2001 Paradise Drive 786548 2001 Paradise Drive 161346
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147
2001 Paradise Drive 786548 2001 Paradise Drive 161346
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171 2001 Paradise Drive 213715
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171 2001 Paradise Drive 213715 2001 Paradise Drive 973237
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171 2001 Paradise Drive 213715 2001 Paradise Drive 973237 2001 Paradise Drive 650752
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171 2001 Paradise Drive 213715 2001 Paradise Drive 973237 2001 Paradise Drive 650752 2001 Paradise Drive 637064 2001 Paradise drive 511520
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171 2001 Paradise Drive 213715 2001 Paradise Drive 973237 2001 Paradise Drive 650752 2001 Paradise Drive 637064 2001 Paradise Drive 511520 2001 Paradise Drive 798233
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 213715 2001 Paradise Drive 973237 2001 Paradise Drive 650752 2001 Paradise Drive 637064 2001 Paradise Drive 511520 2001 Paradise Drive 798233 2001 Paradise Drive 546859
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171 2001 Paradise Drive 213715 2001 Paradise Drive 973237 2001 Paradise Drive 650752 2001 Paradise Drive 511520 2001 Paradise Drive 798233 2001 Paradise Drive 546859 2001 Paradise Drive 615160
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 213715 2001 Paradise Drive 973237 2001 Paradise Drive 650752 2001 Paradise Drive 637064 2001 Paradise Drive 798233 2001 Paradise Drive 546859 2001 Paradise Drive 615160 2001 Paradise Drive 179083
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 153171 2001 Paradise Drive 973237 2001 Paradise Drive 650752 2001 Paradise Drive 637064 2001 Paradise Drive 511520 2001 Paradise Drive 546859 2001 Paradise Drive 615160 2001 Paradise Drive 179083 2001 Paradise Drive 522381
2001 Paradise Drive 786548 2001 Paradise Drive 161346 2001 Paradise Drive 460147 2001 Paradise Drive 213715 2001 Paradise Drive 973237 2001 Paradise Drive 650752 2001 Paradise Drive 637064 2001 Paradise Drive 798233 2001 Paradise Drive 546859 2001 Paradise Drive 615160 2001 Paradise Drive 179083

2-Nov-12	11/2/2012	2-Nov-12	11/2/2012
28-Nov-12	11/28/2012	28-Nov-12	11/28/2012
5-Dec-12	12/5/2012	6-Dec-12	12/6/2012
28-Jan-13	1/28/2013	28-Jan-13	1/28/2013
30-Jan-13	1/30/2013	30-Jan-13	1/30/2013
24-Apr-13	4/24/2013	29-Apr-13	4/29/2013
31-May-13	5/31/2013	25-Jun-13	7/23/2013
26-Jun-13	7/9/2013	9-Jul-13	7/23/2013
10-Jul-13	7/10/2013	23-Jul-13	7/23/2013
30-Aug-13	8/30/2013	17-Sep-13	9/17/2013
30-Aug-13	8/30/2013	17-Sep-13	9/17/2013
17-Sep-13	9/17/2013	18-Sep-13	9/18/2013
18-Nov-13	11/20/2013	20-Nov-13	11/20/2013
25-Nov-13	11/25/2013	25-Nov-13	11/25/2013
25-Nov-13			
15-May-07		15-May-07	5/16/2007
7-Aug-07		7-Aug-07	8/7/2007
20-Aug-07		20-Aug-07	8/20/2007
25-Oct-07		2-Dec-10	12/2/2010
12-Dec-07		12-Dec-07	12/12/2007
2-Jan-08		2-Jan-08	2/3/2011
2-Jan-08		2-Jan-08	1/2/2008
14-Jan-08		14-Jan-08	2/3/2011
10-Feb-08		10-Feb-08	2/3/2011
10-Feb-08		10-Feb-08	2/3/2011
10-Feb-08		10-Feb-08	2/10/2008
14-Feb-08		14-Feb-08	2/3/2011
2-Mar-08		2-Mar-08	2/3/2011
12-Mar-08		12-Mar-08	2/3/2011
13-Mar-08		13-Mar-08	2/3/2011
13-Mar-08		13-Mar-08	2/3/2011
19-Mar-08		19-Mar-08	2/3/2011
16-Apr-08		16-Apr-08	2/3/2011
, 16-Apr-08		16-Apr-08	2/3/2011
17-Apr-08		17-Apr-08	2/3/2011
19-May-08		19-May-08	5/19/2008
21-Jul-08		2-Dec-10	12/2/2010
21-Jul-08		2-Dec-10	12/2/2010
21-Jul-08		21-Jul-08	2/3/2011
18-Nov-08		18-Nov-08	11/18/2008
16-Dec-08		16-Dec-08	2/3/2011
18-Dec-08		18-Dec-08	12/18/2008
23-Dec-08		23-Dec-08	2/3/2011
5-Apr-09		5-Apr-09	4/5/2009
28-Apr-09		28-Apr-09	4/28/2009
28-Apr-09		2-Dec-10	12/2/2010
1-Jun-09		1-Jun-09	6/1/2009
16-Jun-09		16-Jun-09	6/16/2009
29-Jun-09		29-Jun-09	2/3/2011
15-Jul-09		15-Jul-09	7/15/2009
15-Jul-09		15-Jul-09	7/15/2009
28-Jul-09		28-Jul-09	7/28/2009
		25 54, 00	., _0, _00

Category 1		210	0
Category 2		1740	0
Category 1		1600	0
Category 3		10	0
Category 3		288	0
Category 1		140	0
Category 1		40	0
Category 3		82	0
Category 3		13	0
Category 3	370	370	0
Category 3	576	576	0
Category 3	3	3	0
Category 3	1	1	0
Category 3	4	4	0
Category 3	299	299	0
Category 3		350	0
Category 3		200	0
Category 3		60	0
Category 3		375	0
Category 3		520	0
Category 3		50	50
Category 3		320	
Category 3		420	0
Category 3		350	0
Category 3		750	0
Category 2		1800	0
Category 3		713	0
Category 1		100	0
Category 1		150	0
Category 3		200	200
Category 3		90	0
Category 1		100	0
Category 3		50	0
Category 3		630	0
Category 3		150	150
Category 3		180	0
Category 3		70	0
Category 3		70	0
Category 3		70	0
Category 3		50	50
Category 1		100	0
Category 3		50	0
Category 3		60	0
Category 3		750	0
Category 3		40	0
Category 3		40	Ō
Category 3		120	0
Category 3		120	0
Category 3		120	0
Category 3		120	0
Category 3		100	0
Category 1		3090	0
Category 3		100	0
Category 3		100	0
Category 3		660	0
Catogory o		300	0

200 No	No
0 No	No
1600 Yes	Yes
0 No	No
0 No	No
140 No	Yes
40 No	Yes
0 No	Yes
0 No	No
No	No
0 No	No
0 No	No
No	No
No	No
0 No	No
No	No
0 No	No
0 No	No
0 No	No
0 No	No
0 No	No
100 Yes	No
150 Yes	Yes
0 No	No
0 No	No
100 Yes	Yes
0 No	No
100 Yes	No
0 No	No
3090 Yes	Yes
0 No	No No
0 No 0 No	No No
O INO	INO

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe

No

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe

No

Yes

Yes

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe No

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

No

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe

Dawson Easement

Fremont Pine Lane

Altamont Road

Arastradero Road Easement

MH #433

Altamont Road

Elena Road and Vinedo Lane

Priscilla Lane near Stonebrook Drive

26327 Esperanza Drive at sewer easement

26485 St. Francis Road at a private cleanout

26344 Esperanza Drive

11676 Dawson Drive

26335 Experanza

12000 Greenhills Ct.

11951 Hilltop Drive

2129 Paradise Drive

327 San Rafael Avenue

Manhole #85

101 Acacia Avenue

Manhole # 194

233 Round Hill

Pagota Lane

101 Kleinart way

211 Round Hill, manhole # 251

233 Round Hill, manhole # 253

280 Round Hill, manhole # 259

10 Tara View, manhole # 242A

84 Lagoon Road

Manhole 71

Manhole #320

Manhole # RA1

Manhole #351

144 Bella Vista

Manhole #90

Cleanout in backyard, 213 Golden Gate

Cleanout # 242A

Manhole # FA15

Manhole # FA15

Manhole # FA15

90 Lyford Drive

Manhole #81

Manhole # 605

Clean out close to Manhole #78

Manhole # 259A

Manhole #FB8

Manhole # FB8

Manhole 330

Manhole 330

Manhole 330

Manhole 330

Manhole # 246

Manhole # 246

Manhole 324

Manhole FA13

Manhole 252

37.35201	-122.11417 Santa Clara
37.38213	-122.13108 Santa Clara
37.35768	-122.13431 Santa Clara
37.39262	-122.14547 Santa Clara
37.38775	-122.14344 Santa Clara
37.35793	-122.14205 Santa Clara
37.36077	-122.13679 Santa Clara
37.35796	-122.12255 Santa Clara
37.38037	-122.14172 Santa Clara
37.38566	-122.14073 Santa Clara
37.38233	-122.14064 Santa Clara
37.3529	-122.11579 Santa Clara
37.38166 37.358397	-122.14173 Santa Clara -122.135997 Santa Clara
37.355917	-122.135997 Santa Ciara -122.11235 Santa Ciara
37.874722	122.449167 Marin
37.875306	122.449107 Marin
37.880175	122.456733 Marin
37.874	122.464008 Marin
37.923333	122.619444 Marin
37.88817	-122.46737 Marin
37.955556	122.679167 Marin
37.88195	-122.46545 Marin
37.88764	-122.46754 Marin
37.88817	-122.46737 Marin
37.984722	122.494444 Marin
37.88564	-122.46368 Marin
37.87778	-122.46373 Marin
37.87681	-122.45401 Marin
37.88353	-122.46939 Marin
37.87089	-122.46392 Marin
37.87464	-122.45968 Marin
37.87032	-122.46462 Marin
37.87894	-122.45286 Marin
37.86884	-122.4653 Marin
37.883369 37.866758	122.450233 Marin 122.46671 Marin
37.866758	122.46671 Marin
37.86822	-122.4652 Marin
37.88274	122.46023 Marin
37.87901	-122.45042 Marin
37.893889	122.522222 Marin
37.87685	-122.45213 Marin
37.883435	-122.466694 Marin
37.868	-122.463 Marin
37.868	-122.463 Marin
37.883	-122.47 Marin
37.883	-122.47 Marin
37.883	-122.47 Marin
37.883	-122.47 Marin
37.886	-122.466 Marin
37.886	-122.466 Marin
37.884	-122.468 Marin
37.87	-122.468 Marin
37.888	-122.467 Marin

Private cleanout overflowing

Manhole overflow on paved street. No overflow upon arrival of Town's maintenance contractor manhole located on a paved street

lamphole in easement

Overflowing manhole was located in a utility & pathway easement behind Pinewood School. Town checked the area and manhole on paved street, at intersection of Altamont and Corbetta. Based on State Board staff's general explanation, Town manhole located on a paved street

Overflow occured from a MH on Priscilla Lane near Stonebrook Drive. The MH was for a force main system and approxing Spill occured from a manhole - EMH1052 (E346) on a sewer easement on private property at 26327 Esperanza Drive. Blockage on the mainline 25' upstream from MH3 EMH1085. Spill happened through a private cleanout at 26485 St. Fra At a easement area in the rear yard of 26344 Esperanza Drive.

Between manholes #33 and #50

Small manhole (# GA1A), located in the back garden of residence. Easement runs along the property line.

Manhole #85 close to 1725 Vistazo West

Manhole # ND15

Manhole # 194

Rodhole # 797A

Rod hole connected to manhole # NC2

Manhole #312

Manhole # 251

Manhole # 253

Manhole # 259

Manhole # 242A located on hillside in vacant lot.

Cleanout on patio

Manhole 71 overflowed, spill ran down grassy bank, entered storm drain.

Manhole #320

Bolted down manhole # RA1

manhole #351

Manhole RA2

Cleanout close to manhole #90

Cleanout in private garden

Sewer 'cleanout' (# 242A)

Overflowing manhole

Overflowing manhole

Overflowing manhole

Slowly and intermittently overflowing manhole. Spill was recovered and returned to collection system, area cleaned and sa

Overflowing manhole #81

Manhole # 605

Cleanout close to manhole #78

Manhole #259A

Manhole FB8

Manhole FB8

Manhole #330

Manhole #330

Manhole 330

Manhole 330

Manhole # 246

Manhole #246 located on Roundhill Road

Manhole overflowing

it was not overflowing at the time of inv wn does not believe this is a category 1

mately 3' in depth.

1 1 1

1

1

anitized.

Force main or pressure sewer; Other sewer system structure Manhole Manhole Other sewer system structure Manhole Manhole Manhole Manhole Manhole Lateral Clean Out (Private) Manhole Lateral Clean Out (Private) Lateral Clean Out (Private) Lateral Clean Out (Private) Manhole Other (specify) Manhole Other (specify) Manhole Manhole Manhole Pump station Manhole Other sewer system structure Other sewer system structure Other sewer system structure Manhole Manhole Manhole Manhole Manhole Pump station Other sewer system structure Manhole Manhole Manhole Manhole Manhole Manhole Manhole Manhole Manhole Manhole

Other (specify) Manhole

Private cleanout oveflow from manhole sewage and heavy rain water coming out from a sewer mainhole Lamphole
Private cleanout from Manhole EMH1042 private cleanout at 11676 Dawson Drive N/A N/A N/A Blocked sewer main leaked via damaged private lateral.
Sewer cleanout located on private residence
Small spill from manhole Cleanout close to manhole # 90.
Broken sewer line on hillside

Other (specify below)

Unpaved surface

Surface water; Unpaved surface

Unpaved surface

Unpaved surface

Other (specify below)

Other (specify below)

Separate storm drain

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Paved Surface; Unpaved surface

Unpaved surface

Other paved surface; Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Other paved surface

Other (specify below)

Separate storm drain

Street/curb and gutter

Street/curb and gutter

Separate storm drain

Other paved surface

Unpaved surface

Other (specify below)

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Other (specify below)

Surface water; Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Separate storm drain

Unpaved surface

Unpaved surface

Unpaved surface

dirt area on private property.

final spill destination at a dry ditch and sewage seeped into soil

the heavy rain caused the rainwater to flow into sewer system and overloaded the sewer system. The overflow spill went seep into soil around lamphole. See pictures

seeped into soil/dirt area

Based on State Board's previous clarifications and interpretations, Town does not believe this is a category 1 spill. Spill r catch basin was dammed with sand bags which diverted some of the spill to vegatative land cover on Elena Road; outfall Town's SS contractor noticed no SSO discharge at the end of the storm drain system which outlets a dry ditch.

Seeped into soil around the MH. The soil around was approximately 25% saturated when the crew showed up.

Spill soaked into area surrounding spill site.

Soaked into garden surrounding manhole.

Soaked into ground.

Spill (almost entirely contents of a swimming pool being emptied) absorbed into hillside.

hillside

Spill ran down private driveway and soaked into garden area

Slow flowing (2.5 gpm) but long lasting (4.75 hrs) soaked into ground of vacant lot on hillside.

Spill may have entered private drainage ditch that flows to Belvedere Lagoon. However, there was no evidence (toilet pa

Spill entered storm drain that feeds to Racoon Straits

Small spill from manhole, bubbling slowly, spill soaked into ground around manhole, 50 gallons maximum.

Spill soaked into grass hillside next to 'cleanout'.

Spill was returned to collection system

Spill soaked into hillside surrounding cleanout.

Returned to collection system

SSO from overflowing manhole for approx 90 mins at 5gpm. Spill soaked into hillside for 70 mins then entered stream for

Soaked into hillside

Soaked into hillside

Hillside

Spill soaked into hillside surrounding broken pipe.

10/20/2012 0:00	10/20/2012 11:26	10/20/2012 11:55	10/20/2012 12:45
11/10/2012 14:42	11/10/2012 17:17	11/10/2012 20:30	11/10/2012 20:30
12/2/2012 9:56	12/2/2012 10:04	12/2/2012 10:50	12/2/2012 11:00
1/4/2013 13:43	1/4/2013 13:48	1/4/2013 15:20	1/4/2013 15:15
1/23/2013 7:55	1/23/2013 7:55	1/23/2013 8:35	1/23/2013 8:25
3/26/2013 11:43	3/26/2013 11:48	3/26/2013 12:05	3/26/2013 12:23
4/28/2013 9:55	4/28/2013 10:30	4/28/2013 11:01	4/28/2013 12:20
6/25/2013 13:35	6/26/2013 14:10	6/26/2013 13:45	6/26/2013 14:00
7/5/2013 8:30	7/5/2013 8:45	7/5/2013 9:25	7/5/2013 9:45
8/23/2013 20:00	8/23/2013 20:30	8/23/2013 21:00	8/23/2013 21:30
8/23/2013 8:30	8/28/2013 9:00	8/28/2013 12:15	8/28/2013 12:45
8/31/2013 21:00	8/31/2013 21:47	9/1/2013 13:00	9/1/2013 13:00
11/2/2013 15:35	11/2/2013 15:40	11/2/2013 16:55	11/2/2013 16:50
11/7/2013 10:35	11/7/2013 10:40	11/7/2013 12:00	11/7/2013 10:55
11/15/2013 8:24	11/15/2013 8:29	11/15/2013 12:00	11/1/2013 11:93
5/9/2007 10:00	5/9/2007 10:00	5/9/2007 10:02	5/9/2007 11:10
8/6/2007 20:00	8/6/2007 20:15	8/6/2007 21:30	8/6/2007 21:30
8/15/2007 13:00	8/15/2007 13:45	8/15/2007 14:02	8/15/2007 15:00
10/18/2007 10:15	10/18/2007 10:15	10/18/2007 10:15	10/18/2007 11:30
12/11/2007 12:40	12/11/2007 12:49	12/11/2007 13:00	12/11/2007 13:06
12/29/2007 10:00	12/29/2007 10:40	12/29/2007 11:15	12/29/2007 11:45
12/29/2007 12:30	12/29/2007 14:00	12/29/2007 14:30	12/29/2007 15:10
1/10/2008 14:30	1/10/2008 14:30	1/10/2008 14:40	1/10/2008 16:15
2/5/2008 14:30	2/5/2008 14:30	2/5/2008 15:00	2/5/2008 17:30
2/6/2008 13:30	2/6/2008 13:30	2/6/2008 13:30	2/6/2008 16:00
2/7/2008 14:30	2/7/2008 14:30	2/7/2008 14:35	2/7/2008 15:00
2/12/2008 13:45	2/12/2008 13:45	2/12/2008 14:00	2/12/2008 18:30
3/2/2008 9:00	3/2/2008 10:30	3/2/2008 10:45	3/2/2008 9:00
3/12/2008 10:30	3/12/2008 10:30	3/12/2008 10:40	3/12/2008 10:50
3/7/2008 15:40	3/7/2008 15:40	3/7/2008 13:55	3/7/2008 13:55
3/11/2008 8:51	3/11/2008 8:51	3/11/2008 9:00	3/11/2008 9:20
3/18/2008 11:25	3/18/2008 11:25	3/18/2008 11:30	3/18/2008 11:45
4/15/2008 8:00	4/15/2008 8:21	4/15/2008 8:30	4/15/2008 9:00
4/15/2008 16:00	4/15/2008 16:30	4/15/2008 17:00	4/15/2008 19:30
4/16/2008 14:30	4/16/2008 14:45	4/16/2008 15:00	4/16/2008 15:00
5/15/2008 14:30	5/15/2008 14:30	5/15/2008 14:45	5/15/2008 20:30
7/16/2008 15:45	7/16/2008 15:45	7/16/2008 15:55	7/16/2008 16:20
7/16/2008 15:45	7/16/2008 15:45	7/16/2008 15:55	7/16/2008 16:20
7/16/2008 15:45	7/16/2008 15:45	7/16/2008 15:55	7/16/2008 16:20
11/14/2008 10:00	11/14/2008 10:00	11/14/2008 10:15	11/14/2008 10:20
12/15/2008 10:00	12/15/2008 10:20	12/15/2008 10:20	12/15/2008 11:30
12/17/2008 17:30	12/17/2008 17:30	12/17/2008 19:00	12/17/2008 19:30
12/20/2008 13:00	12/20/2008 13:25	12/20/2008 13:35	12/20/2008 15:00
4/2/2009 12:00	4/2/2009 12:00	4/2/2009 12:15	4/2/2009 14:33
4/27/2009 10:05	4/27/2009 10:05	4/27/2009 10:25	4/27/2009 11:20
4/27/2009 10:05	4/27/2009 10:05	4/27/2009 10:25	4/27/2009 11:20
5/29/2009 10:30	5/29/2009 10:30	5/29/2009 10:40	5/29/2009 12:30
5/29/2009 10:30	5/29/2009 10:30	5/29/2009 10:40	5/29/2009 12:30
5/29/2009 10:30	5/29/2009 10:30	5/29/2009 10:40	5/29/2009 12:36
5/29/2009 10:30	5/29/2009 10:30	5/29/2009 10:40	5/29/2009 12:36
6/15/2009 13:50	6/15/2009 13:50	6/15/2009 13:56	6/15/2009 14:10
6/27/2009 8:00	6/27/2009 10:00	6/27/2009 10:07	6/27/2009 11:26
7/14/2009 8:00	7/14/2009 8:26	7/14/2009 8:36	7/14/2009 9:30
7/14/2009 9:00	7/14/2009 10:03	7/14/2009 10:16	7/14/2009 10:33
7/27/2009 9:00	7/27/2009 9:00	7/27/2009 9:06	7/27/2009 10:08

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Debris-General

Debris from Construction

Root Intrusion

Troot intradion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Other (specify below)

Root intrusion

Root intrusion Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Deathatasian

Root intrusion

Root intrusion Root intrusion

Pipe structural problem/failure

Pipe structural problem/failure

After video inspection of the line, there are several joints with root intrusion.

Heavy rain entered into sanitary sewer system and overloaded 6 sewer mainline. The spill is likely to consist large volun after video investigation, the spill was due to root and grade misalignment of certain sections.

In addition to roots, the video inspection also showed some cracked joints and minor misalignment of pipe.

Root blockage at about 69' from overflowing manhole

Approximately 122.5 feet d of the manhole, roots were in the joint and broken pipe section

Root obstruction at 25' upstream from EMH#1085
Heavy root blockage
obstruction caused by debris in a severe offset join in the main pipe
Spill may be due to water mainline break. No overflow in progress when crew arrived on site.

Roots.Intermittent spill, indicating partial blokage and spill during high flow period.

Resident emtied swimming pool into sewer collection system

Root intrusion and a cleaning cloth found to be the source of the blockage

Local Water Agency was 'flushing' the city water lines and draining into sewer collection system. This caused the system t

Partial blockage in main sewer line connecting manhole M1 and Pump station 9. Not sure what caused the blockage.

Roots causing intermittent blockage.

Roots, grease, aluminun can

Main Main Main Main Main Main Main Main		
Main		
Main Main Main co overflow via manhole 259 Main Main Main Main Main Main Main Main		
Main		
Main Main		
Main		

Manhole full due to root blockage and affected cleanout in private property heavy roots with broken pipe

obstructing roots near 120' from MH #E426

60' upstream from MH #L338 on Stonebrook Drive
Used hand roder to break up heavy roots 15' downstream from EMH1052, flow went down, removed heavy roots from m:
25' upstream from EMH#1085
Main pipe between Manhole EMH#1042 and #1040

6 VCP 6 VCP 6 VCP 6 VCP 8 VCP 6 VCP&PVC 6 VCP 6 VCP anholes EMH1052 (E346) ar 6 VCP No 6 VCP No 6 VCP No No No No 6 clay 6

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Restored flow;Other (specify below)

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Returned all or portion of spill to sanitary sewer syst Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Restored flow

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow;Returned all or portion of spill to sanitary sewer system

Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Inspected sewer using CCTV to determine cause;Re

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill):Contained all or portion of spill:Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill):Contained all or portion of spill;Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill)

Restored flow

Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re

Cleaned-up (mitigated effects of spill);Restored flow



11/10/2012 21:00 12/2/2012 11:00

3/26/2013 12:23

2/7/2008 15:00

3/2/2008 13:00 3/12/2008 11:30

3/18/2008 11:45

12/15/2008 12:00

6/27/2009 11:26

Plan rehabilitation or replacement of sewer Plan rehabilitation or replacement of sewer;Other (specify below)	
Adjusted schedule/method of preventive maintenance	
Other (specify below)	
Added sewer to preventive maintenance program Added sewer to preventive maintenance program	
Added sewer to preventive maintenance program	
Added sewer to preventive maintenance program	
Added sewer to preventive maintenance program	



No

No

No

No

No No

No

Yes

No

None No apparent impact since the sewage is very diluted due to the heavy rain
Based on State Board's previous clarifications and interpretations, Town does not believe this is a category 1 spill. Spill v
The contractor inspected and took pictures of the dry ditch the storm drain system drained to and it was completely dry. N/A
N/A
No signs of toilet paper etc on stones/rocks where drainage ditch reaches the Lagoon. Followed storm drain to receiving water, located close to 'Elephant Rock,' Tiburon.Difficult public access, climbed down a
Followed storm drain to receiving water, located close to 'Elephant Rock,' Tiburon.Difficult public access, climbed down a
Followed storm drain to receiving water, located close to 'Elephant Rock,' Tiburon.Difficult public access, climbed down a
Followed storm drain to receiving water, located close to 'Elephant Rock,' Tiburon.Difficult public access, climbed down a
Followed storm drain to receiving water, located close to 'Elephant Rock,' Tiburon.Difficult public access, climbed down a

No

No

No

No

No No

No

No

No

N/A None

N/A

NΑ

n/a n/a

N/A

NA


NA

None N/A Adobe Creek None None N/A none N/A none N/A
NA .
Belvedere lagoon Racoon Straits,San Francisco Bay
Racoon Straits
Racoon Straits, San Francisco Bay
Racoon Straits, San Francisco Bay



Very diluted sewage because of the heavy rain.	
Coliform samples taken Coliform (total, fecal and enterococcus) and ammonia samples collected.	
Ammonia, coliform (total, fecal ,enterococcus)	
Coliform, enterococcus,ammonia	
Coliform, enterococcus, ammonia	

Not applicable to this spill No water quality samples taken	
None of the above	
None of the above	
None of the above Regional Water Quality Control Board	
None of the above	
None of the above	
County Health Agency	





127436	12/5/2012 15:10
133906	6/26/2013 15:35
81753 81999	3/2/2008 13:30 3/12/2008 12:05
82142	3/18/2008 12:15
88920	12/15/2008 12:10
94637	6/27/2009 12:38

Woojae Kim	6509472511
Woojae Kim	6509472511
Woojae Kim	6509472511
Richard Chiu, Public Works Director	6509472516
Richard Chiu, Public Works Director	6509417222
Richard Chiu, Public Works Director	6509417222

2SSO10151	Active	742031 Tony Rubio	Certified
2SSO10151	Active	743028 Tony Rubio	Certified
2SSO10151	Active	743783 Tim O'Day	Certified
2SSO10151	Active	746388 Tony Rubio	Certified
2SSO10151	Active	748269 Tim O'Day	Certified
2SSO10151	Active	748413 Timothy O'Day	Certified
2SSO10151	Active	749271 Timothy O'Day	Certified
2SSO10151	Active	749465 Tony Rubio	Certified
2SSO10151	Active	749623 Tim O'Day	Certified
2SSO10151	Active	749631 Tim O'Day	Certified
2SSO10151	Active	749756 Tony Rubio	Certified
2SSO10151	Active	750331 Tony Rubio	Certified
2SSO10151	Active	751482 Tony Rubio	Certified
2SSO10151	Active	757930 Tony Rubio	Certified
2SSO10151	Active	758192 Tony Rubio	Certified
2SSO10151	Active	759664 Tony Rubio	Certified
2SSO10151	Active	765365 Tony Rubio	Certified
2SSO10151	Active	765543 Tony Rubio	Certified
2SSO10151	Active	765586 Tony Rubio	Certified
2SSO10151	Active	766297 Tony Rubio	Certified
2SSO10151	Active	766662 Tony Rubio	Certified
2SSO10151	Active	767999 Tim O'Day	Certified
2SSO10151	Active	768000 Tim D	Certified
2SSO10151	Active	768001 Tony Rubio	Certified
2SSO10151	Active	773013 Tony Rubio	Certified
2SSO10151	Active	773014 Timothy O'Day	Certified
2SSO10151	Active	773289 Tony Rubio	Certified
2SSO10151	Active	778595 Tony Rubio	Certified
2SSO10151	Active	780269 Tony Rubio	Certified
2SSO10151	Active	787926 Dan LaTorre	Certified
2SSO10151	Active	788536 Tony Rubio	Certified
2SSO10151	Active	788865 Tony Rubio	Certified
2SSO10151	Active	788866 Tony Rubio	Certified
2SSO10151	Active	789496 Tony Rubio	Certified
2SSO10151	Active	791053 Tony Rubio	Certified
2SSO10151	Active	791056 Tony Rubio	Certified
2SSO10151	Active	791058 Tony Rubio	Certified
2SSO10151	Active	791059 Tony Rubio	Certified
2SSO10151	Active	791746 Tony Rubio	Certified
2SSO10151	Active	791747 Tony Rubio	Certified
288010151	Active	792710 Tony Rubio	Certified
2SSO10151	Active	796468 Tony Rubio	Certified
2SSO10151	Active	796473 Tony Rubio	Certified
288010151	Active	797986 Tim ODay	Certified
2SSO10151	Active	798005 Tony Rubio	Certified
2SSO10151	Active	799347 Tony Rubio	Certified
2SSO10151	Active	799348 Tony Rubio	Certified
2SSO10154	Active	650446 Jill Barnes	Certified
2SSO10154	Active	651214 Jill Barnes	Certified
2SSO10154	Active	651215 Jill Barnes	Certified
2SSO10154	Active	651471 Jill Barnes	Certified
2SSO10154	Active	651600 Jill Barnes	Certified
2SSO10154	Active	651602 Jill Barnes	Certified
2SSO10154	Active	652594 Jill Barnes	Certified
2SSO10154	Active	652671 Jill Barnes	Certified

Wastewater Facilities Manager

Wastewater facilities manager

Senior Operator

Wastewater Facilities Manager

Senior Operator

Senior Operator

Snr Operator

WFM

Senior Operator

Senior Operator

Wastewater Facilities Manager

Wastewater Facilities Manager

Wastewater Facilities Manager

Wastewater facilities manager

Manager

WFM

WFM

WFM

WFM

WFM

WFM

Operator

Operator

WFM

WFM

Operator

Wastewater Facilities Manager

Manager

Wastewater Facilities Manager

Maintenance

WFM

Wastewater Facilities Manager

Wastewater Facilities Manager Wastewater Facilities Manager

WFM

WFM

WFM

Operator

WFM

WFM

WFM

Senior Civil Engineer

	4450	707005
0004 Paradias Dif	1158	727295
2001 Paradise Drive		169293
2001 Paradise Drive		563700
	12:21	467818
2001 Paradise Drive		655539
2001 Paradise Drive		665023
2001 Paradise drive		220094
2001 Paradise Drive		520457
2001 Paradise Drive		932288
2001 Paradise Drive		609400
2001 Paradise Drive		868651
2001 Paradise Drive		316972
2001 Paradise Drive		702535
10:28am		275201
2001 Paradise Drive		602163
2001 Paradise Drive		807948
2001 Paradise Drive		165295
2001 Paradise Drive		127722
2001 Paradise Drive		659471
2001 P Drive		765030
2001 paradise Drive		938195
2001 Paradise drive		655038
2001 Paradise Drive		589005
2001 Paradise Drive		941369
2001 Paradise Drive		326496
2001 Paradise Drive		232832
20011 diddio Dilvo	1813	990319
2001 Paradise drive	1010	642009
20011 aradise drive	1119	624159
2001 Paradise drive	1119	786846
2001 Paradise Drive		980955
2001 Paradise Drive	051	
	951	126471
	941	589723
	2026	500336
	840	910965
	851	537888
	903	647691
	915	334413
	1516	737749
2004 Paradia Di	2254	249500
2001 Paradise Drive		226173
2001 Paradise Drive		705477
2001 Paradise drive		192856
2001 Paradise Drive		674627
2001 Paradise Drive		204662
2001 Paradise Drive		904570
2001 Paradise Drive		614656
Mill Valley		277455
Mill Valley		866682
Mill Valley		375326
Mill Valley		344695
Mill Valley		483966
Mill Valley		492906
Mill Valley		844540
Mill Valley, CA		275802

29-Jul-09		29-Jul-09	7/29/2009
13-Aug-09		13-Aug-09	2/3/2011
26-Aug-09		26-Aug-09	8/26/2009
30-Oct-09		30-Oct-09	10/30/2009
11-Jan-10		11-Jan-10	1/11/2010
19-Jan-10		19-Jan-10	1/19/2010
10-Feb-10		10-Feb-10	2/10/2010
18-Feb-10		18-Feb-10	2/3/2011
22-Feb-10		22-Feb-10	2/22/2010
22-Feb-10		22-Feb-10	2/22/2010
24-Feb-10		24-Feb-10	2/24/2010
9-Mar-10		9-Mar-10	3/9/2010
12-Apr-10		12-Apr-10	4/12/2010
19-Oct-10	10/19/2010	19-Oct-10	10/19/2010
28-Oct-10	10/28/2010	28-Oct-10	10/28/2010
21-Dec-10	12/21/2010	21-Dec-10	12/21/2010
12-Apr-11	4/12/2011	12-Apr-11	4/12/2011
14-Apr-11	4/14/2011	14-Apr-11	4/14/2011
18-Apr-11	4/18/2011	18-Apr-11	4/18/2011
10-May-11	5/10/2011	10-May-11	5/10/2011
19-May-11	5/19/2011	19-May-11	5/19/2011
30-Jun-11	6/30/2011	1-Dec-11	12/1/2011
30-Jun-11	6/30/2011	1-Dec-11	12/1/2011
30-Jun-11	6/30/2011	30-Jun-11	6/30/2011
13-Nov-11	11/13/2011	21-Dec-11	12/21/2011
13-Nov-11	11/13/2011	13-Nov-11	11/13/2011
20-Nov-11	11/20/2011	20-Nov-11	11/20/2011
13-Mar-12	3/13/2012	13-Mar-12	3/13/2012
18-Apr-12	4/18/2012	18-Apr-12	4/18/2012
7-Nov-12	11/7/2012	7-Nov-12	11/7/2012
28-Nov-12	11/28/2012	28-Nov-12	11/28/2012
7-Dec-12	12/7/2012	7-Dec-12	12/7/2012
7-Dec-12	12/7/2012	7-Dec-12	12/7/2012
27-Dec-12	12/27/2012	27-Dec-12	12/27/2012
1-Feb-13	2/1/2013	1-Feb-13	2/1/2013
1-Feb-13	2/1/2013	1-Feb-13	2/1/2013
1-Feb-13	2/1/2013	1-Feb-13	2/1/2013
1-Feb-13	2/1/2013	1-Feb-13	2/1/2013
15-Feb-13	2/15/2013	15-Feb-13	2/15/2013
15-Feb-13	2/15/2013	15-Feb-13	2/15/2013
18-Mar-13	3/18/2013	18-Mar-13	3/18/2013
3-Jul-13	7/3/2013	3-Jul-13	7/3/2013
3-Jul-13	7/3/2013	3-Jul-13	7/3/2013
18-Aug-13	8/18/2013	18-Aug-13	8/18/2013
19-Aug-13	8/19/2013	19-Aug-13	8/19/2013
2-Oct-13	10/2/2013	2-Oct-13	10/2/2013
2-Oct-13	10/2/2013	2-Oct-13	10/2/2013
11-May-07		7-Jun-07	6/7/2007
31-May-07		7-Jun-07	6/7/2007
31-May-07		7-Jun-07	6/7/2007
7-Jun-07		7-Jun-07	6/7/2007
11-Jun-07		11-Jun-07	6/11/2007
11-Jun-07		11-Jun-07	6/11/2007
21-Jun-07		21-Jun-07	6/21/2007
22-Jun-07		18-Jul-07	7/18/2007

Category 3	10	08 1	0
Category 1	7	75 3	0
Category 3	7	70	0
Category 1	7	75 1	0
Category 3	10		0
Category 3	19		0
Category 1	21		0
	47		0
Category 1			
Category 3			0
Category 3	18		0
Category 3			0
Category 3			0
Category 3			0
Category 3	15	50	0
Category 3	6	60	0
Category 3	2	20	0
Category 1	33	30	0
Category 3	18		0
Category 3	10		0
Category 3	11		0
Category 3	36		0
	12		0
Category 1	12		
Category 1			0
Category 1	12		0
Category 1	50		0
Category 1	50		0
Category 1	27		0
Category 3			0
Category 3			0
Category 3			0
Category 3	20	00	0
Category 3	14	14	0
Category 3	1	2	0
Category 1	1000	00	0
Category 3	20	00	0
Category 3	7	70	0
Category 3			0
Category 3	7		0
Category 1		18	
Category 1	15		0
Category 3			0
Category 3			0
	12		
Category 1			
Category 1	75		0
Category 3		25 21	
Category 3			0
Category 3			0
Category 3		5	
Category 3		25	
Category 3	9	90	
Category 3		5	
Category 3		4	
Category 3	3	80	
Category 3	19		
Category 3		5	
g ,		-	

0	No		Yes
45	No		Yes
0	No		No
65	Yes		Yes
0	No		No
0	No		No
215	Yes		Yes
450	Yes		No
0	No		No
	No		No
330			No
	No		No
125			No
125			No
125			No
500			Yes
500			Yes
250	No.		No
	No		No No
	No		No
5000			Yes
	No		No
	No		No
0	No		No
	No		No
	Yes		Yes
150			Yes
	No		No
0	No		No
20	No		No
750	Yes		Yes
0	No		No
0	No		No
0	No		No

Yes No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe

Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe 1956 Centro West

31 west shore- man hole

Rodhole #31B

82 Eastview Ave.

322 Beach Rd, Belvedere

27 Acacia Ave Belvedere

Manhole at 202 Beach Rd.

Vistazo West and Lyford Drive Mountain Side

1458 Vistazo West

Pagoda Lane, Belvedere

28 Eucalyptus

19 Acacia Ave

82 Sugarloaf Drive

39 Belvedere Ave

120 Round Hill

Phone company

Manhole 221

Manhole 224

121 bay View Ave

Round Hill and Tara Hill

9 Tara Hill

1478 Vistazo West

1478 Vistazo West

1478 Vistazo West

1681 Tiburon Blvd

1681 Tiburon Blvd

328 San Rafael Ave Belvedere CA

85 Mount Tiburon Road

Spring Lane

15 Toyon Belvedere 94920

Manhole # 135

202 Beach Road

333 Belvedere Ave

1600 Mar West

480 Ridge Rd

242 Beach Rd

145 Bayview

1800 Centro West

210 San Rafael Ave

1 Oak Ave

217 Golden Gate

4 Eucalyptus MH FA16

29 Eucalyptus

Mar West Tiburon

49 Belveder Ave. Manhole FA10

45 Bayview

100 Eastview

24 Longfellow Rd

Lovell Ave @ Elma Street

66 Molino

335 Molino Ave

18 Stanton Way

151 Monte Vista

Bernard Street @ Lovell Ave

16 Vasco Drive

37.87422	-122.450877 Marin
37.8760972	-122.473798 Marin
37.87378	-122.44971 Marin
37.87314	-122.45828 Marin
37.86532	-122.45904 Marin
37.87347	-122.46556 Marin
37.86817	-122.46236 Marin
37.88448	-122.4566 Marin
37.8824	-122.45819 Marin
37.8723	-122.46413 Marin
37.86888	-122.46661 Marin
37.87367	-122.46572 Marin
37.88708	-122.45645 Marin
37.8714	-122.46997 Marin
37.88528	-122.46367 Marin
37.88079	-122.46471 Marin
37.88588	-122.46263 Marin
37.88596	-122.46189 Marin
37.8728	-122.46604 Marin
37.88685	-122.46585 Marin
37.88735	-122.46514 Marin
37.88265	-122.45768 Marin
37.88265	-122.45768 Marin
37.88265	-122.45768 Marin
37.8748	-122.45785 Marin
37.8748	-122.45785 Marin
37.87601	-122.46824 Marin
37.88965	-122.46533 Marin
37.885991	-122.467002 Marin
37.953333	-122.703333 Marin
37.882383	-122.541717 Marin
37.868019	-122.462652 Marin
37.866107	-122.463798 Marin
37.87968086	-122.4585669 Marin
37.879388	-122.45037 Marin
37.867472	-122.462095 Marin
37.873272	-122.466297 Marin
37.877026	-122.454683 Marin
37.877987	-122.47101 Marin
37.873979	-122.467963 Marin
37.88685	-122.46585 Marin
37.87245	-122.46971 Marin
37.8715	-122.46883 Marin
	-122.45063 Marin
37.87843	
37.87147	-122.46958 Marin
37.87447	-122.46924 Marin
37.87364	-122.45842 Marin
37.9025	122.522222 Marin
37.906667	122.553333 Marin
37.903333	122.550556 Marin
37.903333	122.530330 Marin
37.913333	122.525556 Marin
37.906944	122.561944 Marin
37.906944	122.548889 Marin
37.915833	122.526389 Marin

Middle of street out of man hole on hill side.

Spill location was in middle of street out of manhole E7 which overflows to the curb and into a close by storm drain Rodhole # 31B

overflow occured at rod hole on 82 eastview ave. and going downhill to main street.

Cleanout in garden of residence

Manhole ND7 located in garden of residence

Manhole opposite 202 Beach Road

Mountain Side with no public access along side seasonal creek

Manhole

Clean out close to 103 Beach Rd., at the base of pagoda Lane

Manhole

Cleanout in back yard Man hole overflowing Cleanout on hillside

Manhole #221
Manholw 224 located in back yard.
Cleanout located in garden
Manhole 245
Back garden of private residence

Manhole 353A Manhole 353A

328 San Rafael Ave clean out overflowing into garden and down to lagoon.

Next to water tank- on spring lane

Rodhole near manhole # ND10

Manhole 135 overflowing

Man Hole overflowing- roots and baby wipes discovered in line causing blockage- not fully plugged some flow was getting minor overflow out of manhole FH8 partial blockage

Ruptured force main caused by weight of heavy storm drain resting on force main was cause of sewage spill, 10,000 gall Overflow coming from cleanout, overflow onto steep hillside- soaked into soil, founf wipes in line causing stoppage and so overflow reported at 242 beach rd- discovered a cracked coupling on the sewer line on the hill side- water soaked into hills water on property- found 6 inch district line backed up- very little water backed up through cleanout and onto homeowners mh#73 overflowing- rodded line and restored flow - cause of back up was root intrusion- contents of spill soaked into aspar Force main crack - leaking water - 48 estimated gallons reached storm drain that is 2 feet away. Bypassing pump station abacked up main due to roots- SSO- 150 gallons estimated overflowed and reached storm drain- line cleared promptly -coil 6 cleanout.

Manhole # FA16

Manhole # 111 located on Mar West

45 Bayview 100 Eastview

) by just not all and combined with the he

ons estimated at time of contacting OES ome roots side dirt- repaired coupling s patio- cleared back up and restored flo uht and hillside- cleaned up site during repair. New section of pipe to be uld not contain contents in storm drain d

> 1 1

Manhole

Gravity sewer

Gravity sewer

Gravity sewer

Other sewer system structure

Manhole

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Other sewer system structure

Other sewer system structure

Manhole

Gravity sewer

Gravity sewer

Gravity sewer

Manhole

Other sewer system structure

Manhole

Gravity sewer

Manhole

Manhole

Manhole

Force main or pressure sewer

Force main or pressure sewer

Other (specify)

Gravity sewer

Gravity sewer

Gravity sewer

Manhole

Manhole

Manhole

Force main or pressure sewer

Gravity sewer

Gravity sewer

Gravity sewer

Gravity sewer

Force main or pressure sewer

Gravity sewer

Gravity sewer

Gravity sewer

Gravity sewer

Other (specify)

Gravity sewer

Gravity Mainline

Manhole

Manhole

Manhole

Manhole

Other (specify)

Other (specify)

Manhole

Manhole

Manhole

Broken sewer line leaked into garden
man hole slowly overflowing from partial blockage of roots
Rodhole
Underneath brick driveway Manhole # 111
Clean Out - 6 clay RH Rod hole

Other (specify below)

Beach

Unpaved surface

Beach

Unpaved surface

Unpaved surface

Storm drain

Other (specify below)

Unpaved surface

Unpaved surface

Street/curb and gutter

Other paved surface

Unpaved surface

Other paved surface

Unpaved surface

Unpaved surface

Surface water

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Surface water

Surface water

Surface water

Surface water

Surface water

Other (specify below)

Unpaved surface

Other paved surface

Unpaved surface

Unpaved surface

Other (specify below)

Street/curb and gutter

Other paved surface; Street/curb and gutter; Unpaved surface; Other (specify below)

Unpaved surface

Unpaved surface

Other (specify below)

Other paved surface

Separate storm drain

Separate storm drain

Other paved surface

Street/curb and gutter

Other paved surface Separate storm drain

Ocparate Storm aram

Street/curb and gutter

Other (specify below)

Unpaved surface

Unpaved surface

Storm drain

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

spill went in both directions, on side of a garden box in which the soil absobed most of the spill and to a storm drain where Spill soaked into private garden. reached the bay at corrinthean yacht club Spill soaked into garden Soaked into bushes Seasonal Creek Soaked into hillside Hillside next to Pagoda Lane Sewage spilled from clenout and soaked into hillside Spill absorbed into hillside. Belvedere Lagoon Destination was on the asphault- minimal overflow- soaked into ground- staff cleaned residue and cleared stoppage quick Earth aroun rodhole Spill absorbed into hillside onto pavement and then to hillside-Diverted flow away from down street stormdrain with rubber diverter other is the marsh lagoon which eventually feeds into sf bay home owners patio Spill soaked into hillside Absorbed into ground Unpaved surface. NOTE: Unable to enter specific selection above Storm drain (unable to select from list) Yard/land (unable to select unpaved surface from list) Yard/Land Yard/Land Yard/Land Street Yard/land

7/28/2009 13:30	7/28/2009 13:33	7/28/2009 13:38	7/28/2009 14:27
8/12/2009 8:05	8/12/2009 8:09	8/12/2009 8:15	8/12/2009 8:30
8/24/2009 14:00	8/24/2009 14:10	8/24/2009 14:15	8/24/2009 14:35
10/30/2009 8:40	10/30/2009 8:42	10/30/2009 8:50	10/30/2009 8:55
1/10/2010 10:30	1/10/2010 10:30	1/10/2010 10:45	1/10/2010 11:45
1/16/2010 8:45	1/16/2010 8:54	1/16/2010 9:06	1/16/2010 10:20
2/10/2010 7:56	2/10/2010 7:56	2/10/2010 7:56	2/10/2010 9:15
2/17/2010 15:00	2/17/2010 15:10	2/17/2010 15:15	2/17/2010 16:35
2/19/2010 8:35	2/19/2010 8:37	2/19/2010 8:46	2/19/2010 9:00
2/21/2010 10:30	2/21/2010 10:30	2/21/2010 10:42	2/21/2010 12:00
2/23/2010 8:30	2/23/2010 8:30	2/23/2010 8:35	2/23/2010 9:15
3/9/2010 9:06	3/9/2010 9:06	3/9/2010 9:12	3/9/2010 9:25
4/11/2010 6:30	4/11/2010 6:30	4/11/2010 7:05	4/11/2010 7:30
10/18/2010 8:00	10/18/2010 8:15	10/18/2010 8:20	10/18/2010 10:30
10/26/2010 15:00	10/26/2010 15:30	10/26/2010 15:50	10/26/2010 16:00
12/20/2010 12:31	12/20/2010 12:33	12/20/2010 12:46	12/20/2010 12:51
4/8/2011 7:30	4/8/2011 7:40	4/8/2011 7:48	4/8/2011 9:32
4/12/2011 10:00	4/12/2011 10:00	4/12/2011 10:12	4/12/2011 13:00
4/16/2011 11:00	4/16/2011 11:30	4/16/2011 12:00	4/16/2011 13:30
5/9/2011 8:06	5/9/2011 8:06	5/9/2011 8:16	5/9/2011 8:29
5/18/2011 9:30	5/18/2011 9:58	5/18/2011 10:00	5/18/2011 12:31
6/28/2011 11:30	6/28/2011 11:15	6/28/2011 11:30	6/28/2011 11:55
6/28/2011 11:30	6/28/2011 11:15	6/28/2011 11:30	6/28/2011 11:55
6/28/2011 11:30	6/28/2011 11:15	6/28/2011 11:30	6/28/2011 11:55
11/12/2011 11:30	11/12/2011 11:30	11/12/2011 11:40	11/12/2011 13:10
11/12/2011 11:30	11/12/2011 11:30	11/12/2011 11:40	11/12/2011 13:10
11/20/2011 15:30	11/20/2011 15:34	11/20/2011 15:40	11/20/2011 17:00
3/12/2012 12:00	3/12/2012 12:00	3/12/2012 12:05	3/12/2012 12:45
4/17/2012 11:30	4/17/2012 11:28	4/17/2012 11:41	4/17/2012 12:06
11/1/2012 17:55	11/1/2012 17:55	11/1/2012 17:55	11/1/2012 18:15
11/28/2012 9:50	11/28/2012 9:38	11/28/2012 9:50	11/28/2012 10:10
12/2/2012 10:54	12/2/2012 10:58	12/2/2012 10:58	12/2/2012 11:30
11/28/2012 13:35	11/28/2012 13:45	11/28/2012 13:48	11/28/2012 14:00
12/27/2012 8:45	12/27/2012 8:55	12/27/2012 8:57	12/27/2012 9:28
1/16/2013 13:30	1/16/2013 13:30	1/16/2013 13:32	1/16/2013 14:10
1/15/2013 12:49	1/15/2013 12:52	1/15/2013 13:00	1/15/2013 14:00
1/9/2013 8:18	1/9/2013 8:19	1/9/2013 8:24	1/9/2013 8:45
1/11/2013 8:30	1/11/2013 8:32	1/11/2013 8:35	1/11/2013 8:45
2/15/2013 13:36	2/15/2013 13:36	2/15/2013 13:38	2/15/2013 14:00
2/15/2013 20:55	2/15/2013 21:00	2/15/2013 21:05	2/15/2013 21:35
2/21/2013 11:50	2/21/2013 11:50	2/21/2013 11:55	2/21/2013 12:50
6/5/2013 9:20	6/5/2013 9:35	6/5/2013 9:35	6/5/2013 9:45
7/1/2013 11:40	7/1/2013 11:40	7/1/2013 11:45	7/1/2013 12:00
8/18/2013 10:15	8/18/2013 10:30	8/18/2013 10:35	8/18/2013 10:45
7/30/2013 10:15	7/30/2013 10:15	7/30/2013 10:20	7/30/2013 10:25
9/17/2013 8:15	9/17/2013 8:15	9/17/2013 8:25	9/17/2013 10:25
9/23/2013 14:45	9/23/2013 14:45	9/23/2013 14:50	9/23/2013 16:50
5/7/2007 8:00	5/7/2007 8:00	5/7/2007 8:15	5/7/2007 9:15
5/31/2007 8:08	5/31/2007 8:08	5/31/2007 8:15	5/31/2007 8:25
5/29/2007 9:55	5/29/2007 10:05	5/29/2007 10:20	5/29/2007 10:50
5/23/2007 12:00	5/23/2007 12:00	5/23/2007 12:30	5/23/2007 16:00
6/7/2007 14:30	6/7/2007 14:30	6/7/2007 15:00	6/7/2007 16:00
6/7/2007 23:00	6/8/2007 9:17	6/8/2007 9:30	6/8/2007 9:42
4/28/2007 20:00 6/20/2007 20:00	4/28/2007 20:00 6/20/2007 20:10	4/28/2007 20:10 6/20/2007 20:30	4/28/2007 20:15 6/20/2007 21:30
0/20/2007 20:00	0/20/2007 20:10	0/20/2007 20:30	0/20/2007 21:30

Root intrusion

Debri-Rags

Root intrusion

Debri-Rags

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root illitusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Root intrusion

Root intrusion

Pipe structural problem/failure

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Grease deposition (FOG)

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Debri-Rags

Root intrusion

Other (specify below)

Debri-General

Other (specify below)

Root intrusion

Root intrusion

Pipe structural problem/failure

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Pump station failure

Root intrusion

Root Intrusion

Root Intrusion

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Cleaning crew found a kitchen towel that was in the line that caused the overflow and some roots
Heavy roots was found in the line- rodded line to clear semiblockage
weight of 24 storm drain resting on pipe caused pipe to fail (burst) at location
cracked connector coupling- seeping water
Gravel Grit
Roots Roots
Paper, grease

Main

Main

Main

Main

Main

Main

Main

Main

Main

Upper Lateral

Main

Maiii

Main

Main Main

Main

Main

Main

Main

Main

Main

Main

Main

Main

Manhole

Manhole

6

6 Clay

6

6 clay

6 6

6 VCP

6 clay

No No

6

6 clay

Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit Restored flow Cleaned-up (mitigated effects of spill); Restored flow Restored flow Cleaned-up (mitigated effects of spill):Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill) Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill);Restored flow Restored flow Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill) Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill); Restored flow; Other (specify below) Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill); Other (specify below) Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow Cleaned-up (mitigated effects of spill):Restored flow Cleaned-up (mitigated effects of spill) Restored flow Contained all or portion of spill Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow

Restored flow

Cleaned-up (mitigated effects of spill)

Restored flow


Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow



8/12/2009 9:15
10/30/2009 8:55
2/10/2010 9:15

2/17/2010 16:40

4/8/2011 9:30

6/28/2011 11:57 6/28/2011 11:57 6/28/2011 11:57 11/12/2011 14:00 11/12/2011 14:00 11/20/2011 17:00

12/27/2012 20:14

2/15/2013 15:00 2/15/2013 22:00

8/18/2013 11:00

Adjusted schedule/method of preventive maintenance
Adjusted schedule/method of preventive maintenance
Added sewer to preventive maintenance program Adjusted schedule/method of preventive maintenance
Added sewer to preventive maintenance program
Added sewer to preventive maintenance program Added sewer to preventive maintenance program Added sewer to preventive maintenance program Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance Adjusted schedule/method of preventive maintenance
Repaired sewer;Other (specify below)
Repaired sewer Adjusted schedule/method of preventive maintenance
Other (specify below)



Yes

Yes

No Yes

No

No

No No

No

No

Yes

Yes

Yes

No

No

Had only reached beach- and not the recieving water as it was low tide.				
clear				
none visually				
yes, marsh laggon has fresh water springs tha run into it 24/7 no visual impacts observed				
none				

No

No

No

No

No

No

No No

No

No

No

Yes

No Yes

No

NA	
crrinthean yacht club- SF bay	
NA NA	
Racoon straits, no beaches Racoon straits, no beaches	
marsh lagoon	
N/A	

Richardson Bay SF bay Racoon Straits Racoon straits, San francisco bay N/A N/A Racoon straits N/A N/A N/A Racoon Straits Racoon Straits Racoon Straits Racoon Straits Racoon Straits Belvedere Lagoon

N/A

N/A

marsh lagoon

belvedere lagoon Belvedere Lagoon N/A N/A

Racoon Straits N/A

Other chemical indicator(s) - specify below; Biological indicator(s) - specify below Biological indicator(s) - specify below

ammonia, e-coli, entercocus
E-coli, coliform, entercocus
Coliform, enterococcus, ammonia Entercocus- E-coli-Coliform- 100ft upstream of entrance point and 100 ft downstream of entrance point to creek
Samples collected for tootal coliform, fecal coliform, enterococcus, E. coli
E Coli , Enterococcus , total and fecal coliform E Coli , Enterococcus , total and fecal coliform E Coli , Enterococcus , total and fecal coliform Fecal coliform. Total coliform and E.coli. Enterococcus. Fecal coliform. Total coliform and E.coli. Enterococcus. Total coliform, fecal coliform and entercocus
E coli, entercoccus and total coliform
Total Coliform, fecal coliform and entercoccus Fecal coliform total coliform and entercocus
Fecal, enterococcus, total coliform, e.coli. Ammonia
recal, enterococcus, total comorni, e.com. Ammonia

County Health Agency
County Health Agency
County Health Agency County Health Agency
None of the above
None of the above None of the above None of the above County Health Agency County Health Agency County Health Agency
County Health Agency
County Health Agency County Health Agency
County Health Agency;Regional Water Quality Control Board



95609	8/12/2009 9:12
97317	10/30/2009 9:32
101061 101249	2/10/2010 9:45 2/17/2010 17:08
112244	4/8/2011 9:32
113878 113878 113878 116744 116744 116906	6/28/2011 12:32 6/28/2011 12:32 6/28/2011 12:32 11/12/2011 14:40 11/12/2011 14:40 11/20/2011 17:30
127940	12/27/2012 10:40
131002 131006	2/15/2013 14:52 2/15/2013 22:35
135100	

Tony Rubio Watewater Facilities Manager Tony Rubio. Wastewater Facilities Manager

4154351501 4154351501

2SSO10154	Active	652811 Jill Barnes	Certified
2SSO10154	Active	653847 Jill Barnes	Certified
2SSO10154	Active	655722 Jill Barnes	Certified
2SSO10154	Active	656753 Jill Barnes	Certified
2SSO10154	Active	656754 Jill Barnes	Certified
2SSO10154	Active	656756 Jill Barnes	Certified
2SSO10154	Active	656757 Jill Barnes	Certified
2SSO10154	Active	656758 Jill Barnes	Certified
2SSO10154	Active	656759 Jill Barnes	Certified
2SSO10154	Active	656761 Jill Barnes	Certified
2SSO10154	Active	656780 Jill Barnes	Certified
2SSO10154	Active	656796 Jill Barnes	Certified
2SSO10154	Active	656802 Jill Barnes	Certified
2SSO10154	Active	656840 Jill Barnes	Certified
2SSO10154	Active	657250 Jill Barnes	Certified
2SSO10154	Active	657579 Jill Barnes	Certified
2SSO10154	Active	658055 Jill Barnes	Certified
2SSO10154	Active	658059 Jill Barnes	Certified
2SSO10154	Active	658174 Jill Barnes	Certified
2SSO10154	Active	704429 Jill Barnes	Certified
2SSO10154	Active	706695 Jill Barnes	Certified
2SSO10154	Active	707183 Jill Barnes	Certified
2SSO10154	Active	707210 Jill Barnes	Certified
2SSO10154	Active	707472 Jill Barnes	Certified
2SSO10154	Active	707959 Jill Barnes	Certified
2SSO10154	Active	707961 Jill Barnes	Certified
2SSO10154	Active	708232 Jill Barnes	Certified
2SSO10154	Active	708234 Jill Barnes	Certified
288010154	Active	708237 Jill Barnes	Certified
2SSO10154	Active	708239 Jill Barnes	Certified
2SSO10154	Active	708244 Jill Barnes	Certified
2SSO10154	Active	708245 Jill Barnes	Certified
2SSO10154	Active	708248 Jill Barnes	Certified
2SSO10154	Active	708250 Jill Barnes	Certified
2SSO10154	Active	708394 Jill Barnes	Certified
2SSO10154	Active	708395 Jill Barnes	Certified
2SSO10154	Active	708399 Jill Barnes	Certified
2SSO10154	Active	708800 Jill Barnes	Certified Certified
2SSO10154 2SSO10154	Active Active	709013 Jill Barnes 709328 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	709326 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	710680 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	710660 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	710685 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	710687 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	710689 Jill Barnes	Certified
2SSO10154	Active	711227 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	711227 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	711232 3ill Barnes	Certified
2SSO10154	Active	711471 Jill Barnes	Certified
2SSO10154	Active	711519 Jill Barnes	Certified
2SSO10154	Active	711907 Jill Barnes	Certified
2SSO10154	Active	712534 Jill Barnes	Certified
2SSO10154	Active	712594 Jill Barnes	Certified
2SSO10154	Active	712677 Jill Barnes	Certified
		· · · · · · · · · · · · · · · · · · ·	23

- Senior Civil Engineer
- Senior Civil Engineer
- Senior Engineer
- Senior Civil Engineer
- Senior Engineer
- Senior Civil Engineeer
- Senior Civil Engineer
- Senior Civil Engineeer
- Senior Civil Engineer
- Senior Civil Engineer Senior Civil Engineer
- Senior Civil Engineer Senior Civil Engineer
- Senior Civil Engineer

Mill Valley	477195
Mill Valley, CA	395551
Mill Valley	340237
Mill Valley	865785
Mill Valley	410525
·	861721
Mill Valley	
Mill Valley	269599
Mill Valley	464883
Mill Valley	658114
Mill Valley	594403
Mill Valley	752413
Mill Valley	269066
Mill Valley	349039
Mill Valley	900585
Mill Valley, CA	357091
Mill Valley, CA	797226
Mill Valley, CA	462769
	821626
Mill Valley, CA	
Mill Valley, CA	793433
Mill Valley, CA	823525
Mill Valley, CA	143176
Mill Valley, CA	564016
Mill Valley, CA	187532
Mill Valley, CA	656881
Mill Valley, CA	340065
Mill Valley, CA	748972
Mill Valley	118596
Mill Valley, CA	683980
Mill Valley	809518
Mill Valley, CA	102733
	647387
Mill Valley, CA	
Mill Valley, CA	427221
Mill Valley, CA	763039
Mill Valley, CA	566095
Mill Valley, CA	234877
Mill Valley, CA	985095
Mill Valley, CA	598836
Mill Valley, CA	680545
MIII Valley, CA	584930
Mill Valley, CA	531458
Mill Valley, CA	301970
Mill Valley, CA	965137
Mill Valley, CA	657435
Mill Valley, CA	132320
Mill Valley, CA	272462
Mill Valley, CA	169687
Mill Valley	901486
Mill Valley	930585
Mill Valley	255156
Mill Valley	276876
Mill Valley	307009
Mill Valley	588771
Mill Valley	123698
Mill Valley	132341
Mill Valley	263018

26-Jun-07	26-Jun-07	6/26/2007
10-Jul-07	18-Jul-07	7/18/2007
13-Aug-07	13-Aug-07	8/13/2007
31-Aug-07	5-Sep-07	9/5/2007
4-Sep-07	6-Nov-07	11/6/2007
4-Sep-07	5-Sep-07	9/5/2007
4-Sep-07	6-Nov-07	11/6/2007
5-Sep-07	5-Sep-07	9/5/2007
12-Sep-07	2-Dec-10	12/2/2010
17-Sep-07	9-Jan-08	1/9/2008
26-Sep-07	9-Jan-08	1/9/2008
26-Sep-07	9-Jan-08	1/9/2008
28-Sep-07	9-Jan-08	1/9/2008
1-Oct-07	9-Jan-08	1/9/2008
26-Oct-07	9-Jan-08	1/9/2008
5-Nov-07	9-Jan-08	1/9/2008
6-Nov-07	9-Jan-08	1/9/2008
8-Nov-07	9-Jan-08	1/9/2008
21-Nov-07	9-Jan-08	1/9/2008
21-Nov-07	9-Jan-08	1/9/2008
27-Nov-07	27-May-08	5/27/2008
27-Nov-07	9-Jan-08	1/9/2008
27-Nov-07	27-May-08	5/27/2008
27-Nov-07	9-Jan-08	1/9/2008
27-Nov-07	20-Dec-07	12/20/2007
27-Nov-07	20-Dec-07 20-Dec-07	12/20/2007
27-Nov-07	20-Dec-07	12/20/2007
27-Nov-07	2-Dec-10	12/2/2010
29-Nov-07	20-Dec-07	12/20/2007
29-Nov-07	20-Dec-07 20-Dec-07	12/20/2007
29-Nov-07	20-Dec-07 20-Dec-07	12/20/2007
6-Dec-07	20-Dec-07 20-Dec-07	12/20/2007
11-Dec-07	20-Dec-07 20-Dec-07	12/20/2007
13-Dec-07	20-Dec-07 20-Dec-07	12/20/2007
13-Dec-07 13-Dec-07	9-Jan-08	1/9/2008
3-Jan-08		
	9-Jan-08 9-Jan-08	1/9/2008
3-Jan-08		1/9/2008
15-Jan-08	12-Mar-08	3/12/2008
15-Jan-08	12-Mar-08	3/12/2008
15-Jan-08	12-Mar-08	3/12/2008
22-Jan-08	12-Mar-08	3/12/2008
22-Jan-08	12-Mar-08	3/12/2008
28-Jan-08	12-Mar-08	3/12/2008
7-Feb-08	12-Mar-08	3/12/2008
7-Feb-08	12-Mar-08	3/12/2008
11-Feb-08	12-Mar-08	3/12/2008

Ontononi 2	2	
Category 3	2	
Category 3	100	•
Category 1	3000	0
Category 3	10	0
Category 3	360	0
Category 3	300	0
Category 3	2	0
Category 3	225	0
Category 3	50	0
Category 3	5	0
Category 3	5	0
Category 3	15	0
Category 3	25	0
Category 3	50	0
Category 3	350	0
Category 3	20	ū
Category 3	20	
Category 3	50	
	30	
Category 3		
Category 3	300	
Category 3	100	
Category 3	55	
Category 3	25	
Category 3	100	
Category 3	25	
Category 3	50	
Category 3	20	
Category 3	500	
Category 3	300	
Category 3	5	
Category 3	10	
Category 3	225	
Category 2	1000	1000
Category 2	1050	0
Category 3	1	•
Category 3	100	
Category 3	180	
Category 3	10	
Category 3	30	
	20	
Category 3 Category 3	900	
Category 3	25	
Category 3	30	
Category 3	200	
Category 3	100	
Category 3	100	
Category 3	45	0
Category 3	50	0
Category 3	30	0
Category 3	20	0
Category 3	80	0
Category 3	30	0
Category 3	105	0
Category 3	65	0
Category 3	90	0
J *- J *-		ŭ

No	No
No	No
3000 Yes	Yes
0 No	No
No	No
0 No	No
No	No
0 No	No
0 No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No	No
No No	No No
No No	No No
0 No	No No
0 No	No No
No	No No
No	No
0 No	No
0 No	No
0 No	No
0 No	No
0 No	No
0 No	No
0 No	No
0 No	No
0 No	No

```
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
```

across from 403 Vista Linda Dr

Ethel Avenue

2 Overhill Road

52 Longfellow Rd

701 Miller Ave

E. Blithedale Ave

117 Tamalpais Avenue

Molino Ave at Cascade Dr

50 Shelley Dr

21 Monte Vista Ave

67 Molino Ave

108 Miller Ave

4 Marsh Drive

107 Wildomar St

50 Shelley Dr - behind address

125 Shelley Drive

225 Tamalpais Ave

352 W. Blithedale Ave

Vista Linda Dr @ Sheridan Ct

Vista Linda Drive

460 Summit Ave

389 Ethel Ave

85 Shelley Drive

2 Shelley Drive

2 Shelley Drive

401 Summit Ave

280 Buena Vista Avenue

12 Oak Lane

427 Summit Avenue

11 Sheridan Court

11 Sunrise Aveue

26 Corte Madera Ave

Bernard Stairs

Alvarado Avenue @ Manor Drive

19 Sunrise Avenue

403 Vista Linda Dr

58 Florence Ave

120 Shelley Drive

Bernard Street @ Lovell Ave

340 W. Blithedale Ave

360 W. Blithedale Ave

233-235 Eldridge Ave

Behind 12 Azalea Dr

14 Glen Drive

116 Rose Ave

56-60 Monta Vista Ave

315 Magee Ave

343 Hazel Ave

60 Monte Vista Ave

10 Glen Drive

80 Cypress Ave

15 Elinor Ave

77 Molino Avenue

775 Redwood Hwy

209 Molino Ave

37.916111	122.535833 Marin
37.904167	122.549167 Marin
37.908889	122.528889 Marin
37.901667	122.523056 Marin
37.891667	122.5275 Marin
37.900833	122.526389 Marin
37.909167	122.553889 Marin
37.904722	122.553611 Marin
37.903333	122.52222 Marin
37.906111	122.559167 Marin
37.903811	122.545239 Marin
37.903794	122.545258 Marin
37.918667	122.554617 Marin
37.901925	122.548664 Marin
37.9033	-122.522125 Marin
37.901889	122.523981 Marin
37.910967	122.557333 Marin
37.917658	122.553344 Marin
37.916233	122.535675 Marin
37.914564	122.537583 Marin
37.913547	122.55775 Marin
37.899903	122.54165 Marin
37.902881	122.523261 Marin
37.903036	122.520267 Marin
37.903006	122.520467 Marin
37.91225	122.555628 Marin
37.909756	122.538228 Marin
37.908439	122.552653 Marin
37.912644	122.557322 Marin
37.916319	122.535697 Marin
37.898536	122.542286 Marin
37.907397	122.548086 Madera
37.907258	122.549453 Marin
37.906019	-122.535208 Marin
37.898258	122.542383 Marin
37.916183	122.535764 Marin
37.903103	122.550969 Marin
37.902033	122.523986 Marin
37.906864	122.549039 Marin
37.917311	122.553139 Marin
37.917811	122.553389 Marin
37.914642	122.550686 Marin
37.906128	122.526547 Marin
37.915925	122.538586 Marin
37.904022	122.561831 Marin
37.906231	122.560294 Marin
37.911097	122.552292 Marin
37.905364	122.561406 Marin
37.906225	122.560314 Marin
37.915572	122.538319 Marin
37.9038	122.561492 Marin
37.908039	122.540767 Marin
37.903706	122.551433 Marin
37.897392	122.5158 Marin
37.902503	122.547353 Marin



Other (specify) Manhole Manhole Other (specify) Manhole Manhole Manhole Manhole Manhole Manhole Other (specify)

Manhole

Other (specify)

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Other (specify)

Other sewer system structure

Other sewer system structure

Manhole

Other sewer system structure

Other sewer system structure

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Other (specify)

Other sewer system structure

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Clean out			
6 clay rod	hole		
Clean Out			
on hillside			
Clean-out			
clean out Clean-out rod hole			
Clean-out Clean out			
Possible h	ole in pipe		
lamp hole Clean-out			
Clean out			
clean out			

Unpaved surface

Other (specify below)

Surface water

Unpaved surface

Street/curb and gutter

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Other (specify below)

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Storm drain

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Storm drain

Unpaved surface

Street/curb and gutter; Other (specify below)

Street/curb and gutter

Unpaved surface

Unpaved surface

Street/curb and gutter

Storm drain

Unpaved surface

Street/curb and gutter

Unpaved surface

Street/curb and gutter

Storm drain

Other (specify below)

Street/curb and gutter

Yard/Land Dirt channel		
hillside		
dirt channel dirt channel		
dirt channel		
dry creek bed		
ary crook bou		
Captured in storm drain		

6/25/2007 10:45	6/25/2007 10:45	6/25/2007 11:30	6/25/2007 12:00
7/6/2007 12:00	7/6/2007 12:00	7/6/2007 12:05	7/6/2007 12:15
7/21/2007 0:00	8/11/2007 1:30	8/11/2007 14:00	8/11/2007 18:00
8/28/2007 10:30	8/28/2007 10:30	8/28/2007 10:50	8/28/2007 13:00
8/24/2007 9:45	8/24/2007 9:45	8/24/2007 9:45	8/24/2007 11:45
8/20/2007 9:30	8/20/2007 9:30	8/20/2007 9:30	8/20/2007 9:50
8/25/2007 7:00	8/25/2007 7:00	8/25/2007 7:30	8/25/2007 8:30
8/25/2007 10:00	8/25/2007 10:00	8/25/2007 10:00	8/25/2007 10:45
8/25/2007 9:30	8/25/2007 9:30	8/25/2007 11:00	8/25/2007 12:30
8/26/2007 14:40	8/26/2007 14:45	8/26/2007 15:15	8/26/2007 15:30
8/30/2007 9:20	8/30/2007 9:20	8/30/2007 9:30	8/30/2007 10:00
8/28/2007 7:40	8/28/2007 7:40	8/28/2007 7:50	8/28/2007 8:10
9/4/2007 7:45	9/4/2007 7:00	9/4/2007 8:00	9/4/2007 8:30
9/5/2007 8:10	9/5/2007 8:15	9/5/2007 8:20	9/5/2007 8:45
9/11/2007 8:50	9/11/2007 9:15	9/11/2007 9:20	9/11/2007 9:45
9/14/2007 13:15	9/14/2007 13:20	9/14/2007 13:30	9/14/2007 13:35
8/2/2007 8:38	8/2/2007 8:48	8/2/2007 9:12	8/2/2007 9:27
7/31/2007 16:38	7/31/2007 16:38	7/31/2007 16:55	7/31/2007 17:30
9/27/2007 8:25	9/27/2007 8:30	9/27/2007 8:40	9/27/2007 9:00
9/28/2007 10:55	9/28/2007 11:00	9/28/2007 11:10	9/28/2007 11:18
10/26/2007 8:57	10/26/2007 9:00	10/26/2007 9:10	10/26/2007 9:20
10/31/2007 16:35	10/31/2007 16:45	10/31/2007 17:00	10/31/2007 17:30
11/5/2007 9:30	11/5/2007 9:40	11/5/2007 9:45	11/5/2007 10:00
11/6/2007 9:30	11/6/2007 9:35	11/6/2007 9:40	11/6/2007 10:10
11/16/2007 8:30	11/16/2007 8:30	11/16/2007 8:45	11/16/2007 10:00
11/19/2007 12:15	11/19/2007 12:15	11/19/2007 13:20	11/19/2007 13:40
11/26/2007 14:55	11/26/2007 14:55	11/26/2007 15:00	11/28/2007 16:00
11/18/2007 7:20	11/18/2007 7:20	11/18/2007 8:00	11/18/2007 9:00
11/18/2007 9:00	11/18/2007 9:00	11/28/2007 9:30	11/28/2007 10:00
11/22/2007 10:05	11/22/2007 10:05	11/22/2007 10:30	11/22/2007 11:45
11/21/2007 11:00	11/21/2007 11:00	11/21/2007 11:30	11/21/2007 15:00
11/23/2007 8:10	11/23/2007 8:10	11/23/2007 9:20	11/23/2007 9:45
11/25/2007 13:25	11/25/2007 13:25	11/25/2007 13:40	11/25/2007 15:30
11/21/2007 17:30	11/21/2007 17:30	11/21/2007 17:30	11/21/2007 21:00
11/28/2007 9:15	11/28/2007 9:15	11/28/2007 9:45	11/28/2007 10:40
11/28/2007 8:00	11/28/2007 8:00	11/28/2007 8:15	11/28/2007 9:00
11/28/2007 21:30	11/28/2007 21:30	11/28/2007 22:00	11/28/2007 23:00
12/5/2007 13:00	12/5/2007 13:00	12/5/2007 13:15	12/5/2007 13:40
12/11/2007 8:00	12/11/2007 8:00	12/11/2007 8:15	12/11/2007 8:40
12/12/2007 9:40	12/12/2007 9:45	12/12/2007 9:50	12/12/2007 10:00
12/9/2007 9:00	12/9/2007 9:00	12/9/2007 9:30	12/9/2007 11:00
12/25/2007 14:00	12/25/2007 14:00	12/25/2007 14:20	12/25/2007 15:00
12/28/2007 11:45	12/28/2007 11:45	12/28/2007 11:55	12/28/2007 12:30
12/30/2007 17:30	12/30/2007 17:30	12/30/2007 17:45	12/30/2007 18:45
12/31/2007 10:30	12/31/2007 10:30	12/31/2007 10:30	12/31/2007 11:00
1/1/2008 9:20	1/1/2008 9:20	1/1/2008 9:45	1/1/2008 10:30
1/9/2008 11:30	1/9/2008 11:30	1/9/2008 11:30	1/9/2008 12:15
1/9/2008 8:30	1/9/2008 8:35	1/9/2008 8:45	1/9/2008 9:00
1/11/2008 9:00	1/11/2008 9:00	1/11/2008 9:15	1/11/2008 9:45
1/21/2008 9:30	1/21/2008 9:30	1/21/2008 10:00	1/21/2008 11:00
1/22/2008 9:10	1/22/2008 9:15	1/22/2008 9:20	1/22/2008 9:45
1/25/2008 11:00	1/25/2008 11:00	1/25/2008 11:15	1/25/2008 11:45
2/6/2008 19:00	2/6/2008 19:00	2/6/2008 19:00	2/6/2008 20:45
2/7/2008 8:00	2/7/2008 8:00	2/7/2008 8:00	2/7/2008 8:15
2/8/2008 8:00	2/8/2008 8:30	2/8/2008 9:00	2/8/2008 9:30

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Grease deposition (FOG)

Grease deposition (FOG)

Other (specify below)

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

1 toot ii iti asioii

Root intrusion

Grease deposition (FOG)

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Root intrusion

Debris

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)


Root intrusion

Paper Paper, grease, roots, grit/gravel, & plastic wrappers.
Not known Also paper products Plastic & paper
also, grease
and paper also grease
also grease and paper products
wipes
Gravel, paper paper
Gravel
Grease Grease
Grit/gravel
Paper

Main

Main





Restored flow Cleaned-up (mitigated effects of spill) Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill):Restored flow Restored flow Restored flow Restored flow Restored flow Restored flow Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Restored flow Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill) Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill); Restored flow Restored flow Restored flow Restored flow Cleaned-up (mitigated effects of spill); Restored flow Restored flow Cleaned-up (mitigated effects of spill); Restored flow Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Restored flow Restored flow; Other (specify below) Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Restored flow;Returned all or portion of spill to sanitary sewer system;Other (specif Cleaned-up (mitigated effects of spill); Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Inspected sewer using CCTV to determine cause; Re Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill);Restored flow Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow Cleaned-up (mitigated effects of spill);Restored flow

Restored flow Restored flow; cleaned up by removing solid waste and washing down with water. Restored flow.					
Swept up and disinfected area					
Pumped out creek					

11/25/2007 15:30 11/21/2007 21:00

Other (specify below)		
Plan rehabilitation or replacement Adjusted schedule/method of prev	t of sewer ventive maintenance	



No No



No No

N/A NA Sutton-Manor Creek

N/A NA



Ammonia

NA

County Health Agency None of the above No water quality samples taken

NA



2SSO10154 Active 713154 Jill Barnes 2SSO10154 Active 714426 Jill Barnes 2SSO10154 Active 714429 Jill Barnes 2SSO10154 Active 714440 Jill Barnes 2SSO10154 Active 715069 Jill Barnes 2SSO10154 Active 715112 Jill Barnes 2SSO10154 Active 715237 Jill Barnes 2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes 2SSO10154 Active 716990 Jill Barnes	
2SSO10154 Active 714429 Jill Barnes 2SSO10154 Active 714440 Jill Barnes 2SSO10154 Active 714771 Jill Barnes 2SSO10154 Active 715069 Jill Barnes 2SSO10154 Active 715112 Jill Barnes 2SSO10154 Active 715237 Jill Barnes 2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 714440 Jill Barnes 2SSO10154 Active 714771 Jill Barnes 2SSO10154 Active 715069 Jill Barnes 2SSO10154 Active 715112 Jill Barnes 2SSO10154 Active 715237 Jill Barnes 2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 714771 Jill Barnes 2SSO10154 Active 715069 Jill Barnes 2SSO10154 Active 715112 Jill Barnes 2SSO10154 Active 715237 Jill Barnes 2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 715069 Jill Barnes 2SSO10154 Active 715112 Jill Barnes 2SSO10154 Active 715237 Jill Barnes 2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 715112 Jill Barnes 2SSO10154 Active 715237 Jill Barnes 2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 715237 Jill Barnes 2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 715510 Jill Barnes 2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 716082 Jill Barnes 2SSO10154 Active 716119 Jill Barnes	Certified
2SSO10154 Active 716119 Jill Barnes	Certified
	Certified
2SSO10154 Active 716990 Jill Barnes	Certified
	Certified
2SSO10154 Active 718016 Jill Barnes	Certified
2SSO10154 Active 718050 Jill Barnes	Certified
2SSO10154 Active 718082 Jill Barnes	Certified
2SSO10154 Active 718784 Jill Barnes	Certified
2SSO10154 Active 719877 Jill Barnes	Certified
2SSO10154 Active 719887 Jill Barnes	Certified
2SSO10154 Active 722402 Jill Barnes	Certified
2SSO10154 Active 722403 Jill Barnes	Certified
2SSO10154 Active 722427 Jill Barnes	Certified
2SSO10154 Active 722764 Jill Barnes	Certified
2SSO10154 Active 722864 Jill Barnes	Certified
2SSO10154 Active 723019 Jill Barnes	Certified
2SSO10154 Active 723444 Jill Barnes	Certified
2SSO10154 Active 723827 Jill Barnes	Certified
2SSO10154 Active 723829 Jill Barnes	Certified
2SSO10154 Active 723858 Jill Barnes	Certified
2SSO10154 Active 724199 Jill Barnes	Certified
2SSO10154 Active 725619 Jill Barnes	Certified
2SSO10154 Active 725918 Jill Barnes	Certified
2SSO10154 Active 726106 Jill Barnes	Certified
2SSO10154 Active 726226 Jill Barnes	Certified
2SSO10154 Active 726263 Jill Barnes	Certified
2SSO10154 Active 726311 Jill Barnes	Certified
2SSO10154 Active 726314 Jill Barnes	Certified
2SSO10154 Active 726477 Jill Barnes	Certified
2SSO10154 Active 726650 Jill Barnes	Certified Certified
2SSO10154 Active 726773 Jill Barnes	
2SSO10154 Active 726784 Jill Barnes 726956 Jill Barnes	Certified Certified
2SSO10154 Active 726956 Jill Barnes 726972 Jill Barnes	Certified
2SSO10154 Active 727005 Jill Barnes	Certified
2SSO10154 Active 727003 3III Barnes 727543 Jill Barnes	Certified
2SSO10154 Active 727545 3lil Barnes 728125 Jill Barnes	Certified
2SSO10154 Active 728396 Jill Barnes	Certified
2SSO10154 Active 728630 Jill Barnes	Certified
2SSO10154 Active 728690 Jill Barnes	Certified
2SSO10154 Active 728693 Jill Barnes	Certified
2SSO10154 Active 728884 Jill Barnes	Certified
2SSO10154 Active 729042 Jill Barnes	Certified
2SSO10154 Active 729228 Jill Barnes	Certified
2SSO10154 Active 729483 Jill Barnes	Certified
2SSO10154 Active 729786 Jill Barnes	Certified
2SSO10154 Active 730568 Jill Barnes	Certified
	Continua

- Senior Civil Engineer
- Senior Civil Engineer Senior Civil Engineer
- Senior Civil Engineer
- Senior Civil Engineer
- Senior Engineer
- Senior Engineer
- Senior Engineer
- Senior Civil Engineer
- Senior Engineer
- Senior Civil Engineer
- Senior Engineer
- Senior Engineer
- Senior Civil Engineer
- Senior Engineer
- Senior Engineer
- Senior Engineer
- Senior Engineer Senior Engineer
- Senior Engineer
- Senior Engineer
- Senior Engineer
- Senior Civil Engineer

Mill Valley	534060
Mill Valley	432764
Mill Valley	727754
Mill Valley	544939
Mill Valley	889474
Mill Valley	880041
Mill Valley	147471
Mill Valley, CA	288141
Mill Valley	166102
Mill Valley	993801
Mill Valley	117734
Mill Valley	991626
Mill Valley	499290
Mill Valley	427588
Mill Valley	271145
Mill Valley	210554
·	347650
Mill Valley, CA	
Mill Valley	706748
Mill Valley	714723
Mill Valley	123791
Mill Valley	514711
Mill Valley	636214
Mill Valley	894747
Mill Valley	441819
Mill Valley	779720
Mill Valley	286929
Mill Valley	396725
Mill Valley	789027
Mill Valley	833660
Mill Valley	604467
Mill Valley	384950
Mill Valley	240973
Mill Valley	499760
Mill Valley	953936
Mill Valley, CA	707529
Mill Valley	649314
Mill Valley	190503
Mill Valley	305363
Mill Valley	685389
Mill Valley	318238
Mill Valley, CA	731139
Mill Valley	566689
Mill Valley, CA	999438
Mill Valley	937256
Mill Valley	888498
Mill Valley	164925
Mill Valley	636864
Mill Valley	838441
Mill Valley	799591
Mill Valley	699873
Mill Valley	842515
Mill Valley	837743
Mill Valley	196396
Mill Valley	414097
Mill Valley, CA	932058
will valiey, OA	902000

20-Feb-08	12-Mar-08	3/12/2008
3-Mar-08	12-Mar-08	3/12/2008
3-Mar-08	12-Mar-08	3/12/2008
4-Mar-08	12-Mar-08	3/12/2008
11-Mar-08	12-Mar-08	3/12/2008
20-Mar-08	27-May-08	5/27/2008
20-Mar-08	15-Jul-08	7/15/2008
24-Mar-08	2-Dec-10	12/2/2010
27-Mar-08	15-Jul-08	7/15/2008
11-Apr-08	15-Jul-08	7/15/2008
14-Apr-08	27-May-08	5/27/2008
6-May-08	27-May-08	5/27/2008
27-May-08	27-May-08	5/27/2008
27-May-08	15-Jul-08	7/15/2008
27-May-08	27-May-08	5/27/2008
3-Jun-08	15-Jul-08	7/15/2008
19-Jun-08	2-Dec-10	12/2/2010
19-Jun-08	15-Jul-08	7/15/2008
15-Jul-08	15-Jul-08	7/15/2008
15-Jul-08	15-Jul-08	7/15/2008
15-Jul-08	15-Jul-08	7/15/2008
17-Jul-08	22-Sep-08	9/22/2008
18-Jul-08	21-Jul-08	7/21/2008
21-Jul-08	21-Jul-08	7/21/2008
24-Jul-08	22-Sep-08	9/22/2008
29-Jul-08	22-Sep-08	9/22/2008
29-Jul-08	22-Sep-08	9/22/2008
30-Jul-08	22-Sep-08	9/22/2008
4-Aug-08	22-Sep-08	9/22/2008
2-Sep-08	22-Sep-08	9/22/2008
8-Sep-08	22-Sep-08	9/22/2008
11-Sep-08	22-Sep-08	9/22/2008
12-Sep-08	22-Sep-08	9/22/2008
15-Sep-08	22-Sep-08	9/22/2008
15-Sep-08	22-Sep-08	10/24/2008
15-Sep-08	22-Sep-08	9/22/2008
17-Sep-08	22-Sep-08	9/22/2008
22-Sep-08	24-Nov-08	11/24/2008
23-Sep-08	24-Nov-08	11/24/2008
23-Sep-08	24-Nov-08	11/24/2008
26-Sep-08	24-Oct-08	10/24/2008
26-Sep-08	24-Nov-08	11/24/2008
29-Sep-08	24-Oct-08	10/24/2008
7-Oct-08	24-Oct-08	11/24/2008
20-Oct-08	24-Nov-08	11/24/2008
23-Oct-08	24-Oct-08	10/24/2008
28-Oct-08	24-Nov-08	11/24/2008
30-Oct-08	24-Nov-08	11/24/2008
30-Oct-08	24-Nov-08	11/24/2008
3-Nov-08	24-Nov-08	11/24/2008
6-Nov-08	24-Nov-08	11/24/2008
13-Nov-08	24-Nov-08	11/24/2008
20-Nov-08	24-Nov-08 24-Nov-08	11/24/2008
24-Nov-08	24-Nov-08	11/24/2008
15-Dec-08	19-Dec-08	12/19/2008
.0 200 00	10-200-00	12/10/2000

Category 3	225	0
Category 3	450	0
Category 3	100	0
Category 3	750	0
Category 3	50	0
Category 2	3000	2000
Category 1	60	0
Category 3	5	0
Category 3	25	0
Category 3	422	0
Category 3	20	0
Category 3	10	0
Category 3	900	0
Category 3	20	0
Category 3	50	Ö
Category 3	10	0
Category 3	250	0
	600	0
Category 3	10	
Category 3		0
Category 3	240	0
Category 3	2	0
Category 3	25	0
Category 3	25	0
Category 3	20	0
Category 3	20	0
Category 3	250	0
Category 3	30	0
Category 3	150	0
Category 3	150	0
Category 3	20	0
Category 3	50	0
Category 3	75	0
Category 3	5	0
Category 3	20	0
Category 3	5	0
Category 3	25	0
Category 3	120	0
Category 3	20	0
Category 3	750	0
Category 3	300	300
Category 3	2	0
Category 3	275	0
Category 3	5	Ö
Category 3	2	0
Category 3	20	0
Category 3	300	0
	25	0
Category 3		
Category 3	20	0
Category 3	100	0
Category 3	90	0
Category 3	200	0
Category 3	60	0
Category 3	150	0
Category 3	75	0
Category 3	20	0

0 No	No
	No
0 No	No
60 Yes	Yes
0 No	No
0 No	Yes
0 No	No
0 No 0 No	No No
0 No 0 No	No
0 No	No No
0 No	No
0 No	Yes
0 No	No
0 No	Yes
0 No	No
	. 70

```
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
No
Not Applicable - Spill did not reach a separate storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Yes
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Yes
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
Not Applicable - Spill did not reach storm drainpipe
```

Not Applicable - Spill did not reach storm drainpipe

280 Buena Vista Ave

10 Underhill Road

3 Wainwright Pl

20 Vasco Dr

Marguerite Ave @ W. Blithedale Ave

30 Shelley Drive

West Blithedale at Lee Street

4 Heather Way

503 W. Blithedale Ave

18 Thalia Street

278 Manor Drive

343 Summit Ave

280 Buena Vista Ave

2 Marsh Drive

326 W Blithedale Ave @ Corte Madera Ave

East Blithedale Ave @ Alta Vista Ave

56 Monte Vista Ave

18 Buena Vista Ave

90 Florence Ave

85 Tamalpais Ave

125 Shelley Dr

1 Throckmorton Ave

1 Throckmorton Ave

56 Monte Vista

21 Monte Vista Ave

1 Throckmorton Ave

29 Vasco Ct

70 Sunrise Ave

1 Barrie Way

369 Marion Avenue

106 Miller Avenue

106 Miller Ave

355 Tamalpais Ave

80 Cypress Ave

55 Alvarado Ave

63 E. Manor Dr.

280 Buena Vista Ave

136 Shelley Dr

280 Buena Vista Ave

136 Lovell Ave

571 Throckmorton Ave

21 Monte Vista Ave

126 Monte Vista Ave

125 Shelley Drive

35 Florence Ave

66 Molino Avenue

159 Monte Vista Ave

67 Molino Avenue

17 Shelley Dr

Bernard Stairs

60 Monte Vista Ave

19 Sunrise Ave

67 Molino Ave

4 Longfellow Road

Magee Ave

37.909756	122.538228 Marin
37.911756	122.524944 Marin
37.907947	
	122.561819 Marin
37.909489	122.525958 Marin
37.917839	122.553408 Marin
37.903378	122.521403 Marin
37.920556	122.554167 Marin
37.915542	-122.53775 Marin
37.921492	122.556006 Marin
37.904272	122.539436 Marin
37.907506	122.538125 Marin
37.910842	122.555633 Marin
37.909756	122.538247 Marin
37.918933	122.554417 Marin
37.916789	122.552528 Marin
37.903864	122.536467 Marin
37.906056	122.560761 Marin
37.906772	122.545658 Marin
37.903169	12.552467 Marin
	122.553272 Marin
37.908828	
37.901278	122.52435 Marin
37.906725	122.546267 Marin
37.906697	122.546247 Marin
37.906056	122.560761 Marin
37.906061	122.559442 Marin
37.906697	122.546247 Marin
37.910739	122.525011 Marin
37.897661	122.540506 Marin
37.916739	122.540842 Marin
37.902403	122.553256 Marin
37.903692	122.545822 Marin
	122.545822 Marin
37.903692	
37.913925	122.559344 Marin
37.903433	122.561603 Marin
37.905519	122.5363 Marin
37.904733	122.535739 Marin
37.914667	122.534078 Marin
37.901242	
	400 EQUEDO Maria
	122.524508 Marin
37.914667	122.534078 Marin
37.914667	122.534078 Marin
37.914667 37.906753 37.910308	122.534078 Marin 122.55315 Marin 122.559458 Marin
37.914667 37.906753 37.910308 37.906053	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin
37.914667 37.906753 37.910308 37.906053 37.905214	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.562403 Marin 122.551378 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889 37.903061	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.562403 Marin 122.551378 Marin 122.521236 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889 37.903061 37.907272	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.551219 Marin 122.551378 Marin 122.521236 Marin 122.549825 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889 37.903061 37.907272 37.906217	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.551219 Marin 122.551378 Marin 122.521236 Marin 122.549825 Marin 122.560314 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889 37.903061 37.907272 37.906217 37.897753	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.562403 Marin 122.551378 Marin 122.521236 Marin 122.549825 Marin 122.560314 Marin 122.560314 Marin 122.542083 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889 37.903061 37.907272 37.906217	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.551219 Marin 122.551378 Marin 122.521236 Marin 122.549825 Marin 122.560314 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889 37.903061 37.907272 37.906217 37.897753	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.562403 Marin 122.551378 Marin 122.521236 Marin 122.549825 Marin 122.560314 Marin 122.560314 Marin 122.542083 Marin
37.914667 37.906753 37.910308 37.906053 37.905214 37.901219 37.902844 37.903408 37.905792 37.903889 37.903061 37.907272 37.906217 37.897753 37.903714	122.534078 Marin 122.55315 Marin 122.559458 Marin 122.559442 Marin 122.562303 Marin 122.523981 Marin 122.550908 Marin 122.551219 Marin 122.551219 Marin 122.551378 Marin 122.521236 Marin 122.549825 Marin 122.549825 Marin 122.542083 Marin 122.542083 Marin 122.551436 Marin

residential area

C-9

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Manhole

Other (specify)

Manhole

Other (specify)

Other (specify)

Manhole

Manhole

Manhole

Manhole

Mainor

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Manhole

04

Other sewer system structure

Manhole

Manhole

Other (specify)

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Clean-out clean out clean out Clean out MH #DE12 MH #FB2AA 4 private clean-out (manhole FH8) FG3 VB2 Clean-out FB-2 DE10 ID #RD1 Clean-out DA-8 Clean out C9 D113 RH; Clean-out LH3 PH3 LG6 pipe LG6 F9A Clean out (svc MH DK1) DE7 DE5 VB2 #FH15 FH3 DE17 Hillside (FH3 to FH2) VF1 BAT43 DE12 CA8 FH3 VG2 E3

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Union and a stand

Unpaved surface

Unpaved surface

Surface water

Separate storm drain

Street/curb and gutter

Unpaved surface

Storm drain

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Storm drain

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Street/curb and gutter

Unpaved surface

Street/curb and gutter

Other paved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Storm drain

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Storm drain

Street/curb and gutter;Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Captured in storm drain Also storm drain

ED_006495_00001080-02896

2/19/2008 7:55	2/19/2008 7:55	2/19/2008 8:00	2/19/2008 8:09	
3/2/2008 2:20	3/2/2008 2:20	3/2/2008 2:30	3/2/2008 4:00	
2/21/2008 14:00	2/21/2008 14:00	2/21/2008 14:15	2/21/2008 14:45	
3/3/2008 11:15	3/3/2008 11:15	3/3/2008 11:30	3/3/2008 12:00	
3/6/2008 13:15	3/6/2008 13:15	3/6/2008 13:30	3/6/2008 13:40	
3/19/2008 13:30	3/19/2008 13:30	3/19/2008 14:00	3/19/2008 15:00	
3/20/2008 16:50	3/20/2008 16:50	3/20/2008 17:35	3/20/2008 17:55	
3/22/2008 20:50	3/22/2008 20:48	3/22/2008 21:05	3/22/2008 22:00	
3/27/2008 11:20	3/27/2008 11:20	3/27/2008 11:35	3/27/2008 11:40	
3/21/2008 17:30	3/21/2008 17:30	3/21/2008 18:00	3/21/2008 21:00	
4/14/2008 9:15	4/14/2008 9:16	4/14/2008 9:22	4/14/2008 9:26	
5/2/2008 8:45	5/2/2008 8:45	5/2/2008 8:50	5/2/2008 9:50	
5/25/2008 14:30	5/25/2008 14:30	5/25/2008 15:15	5/25/2008 16:45	
5/24/2008 17:15	5/24/2008 17:20	5/24/2008 17:30	5/24/2008 17:45	
5/27/2008 8:15	5/27/2008 8:19	5/27/2008 8:55	5/27/2008 8:57	
5/22/2008 7:00	5/22/2008 7:00	5/22/2008 7:10	5/22/2008 7:15	
6/19/2008 8:00	6/19/2008 8:00	6/19/2008 8:10	6/19/2008 8:20	
6/8/2008 9:55	6/8/2008 9:55	6/8/2008 10:26	6/8/2008 11:25	
7/4/2008 15:50	7/4/2008 15:50	7/4/2008 16:00	7/4/2008 17:00	
7/5/2008 19:45 7/5/2008 19:45	7/5/2008 19:45	7/5/2008 21:55	7/5/2008 22:45	
7/17/2008 13:00	7/5/2008 19:45 7/17/2008 13:10	7/5/2008 20:00 7/17/2008 13:15	7/5/2008 20:00	
7/17/2008 13:00	7/17/2008 13:10	7/17/2008 13:15	7/17/2008 13:20 7/17/2008 17:30	
7/21/2008 17:00	7/21/2008 6:30	7/21/2008 17:00	7/21/2008 17:30	
7/24/2008 9:30	7/24/2008 9:30	7/24/2008 9:30	7/24/2008 10:00	
7/18/2008 9:30	7/18/2008 9:35	7/24/2008 9:50	7/18/2008 10:00	
7/25/2008 12:00	7/25/2008 12:00	7/25/2008 12:10	7/25/2008 10:00	
7/29/2008 13:35	7/29/2008 13:35	7/29/2008 14:00	7/29/2008 14:30	
8/4/2008 8:08	8/4/2008 8:08	8/4/2008 8:38	8/4/2008 8:41	
8/10/2008 9:17	8/10/2008 9:17	8/10/2008 9:30	8/10/2008 9:40	
9/5/2008 13:30	9/5/2008 13:30	9/5/2008 13:45	9/5/2008 17:00	
9/11/2008 9:00	9/11/2008 9:00	9/11/2008 9:00	9/11/2008 9:15	
9/12/2008 11:07	9/12/2008 11:08	9/12/2008 11:20	9/12/2008 11:30	
9/11/2008 18:30	9/11/2008 18:30	9/11/2008 19:00	9/11/2008 19:20	
9/13/2008 14:00	9/13/2008 14:15	9/13/2008 15:30	9/13/2008 17:00	
9/15/2008 8:55	9/15/2008 9:57	9/15/2008 9:00	9/15/2008 9:05	
9/16/2008 8:00	9/16/2008 8:00	9/16/2008 8:55	9/16/2008 9:55	
9/17/2008 18:00	9/17/2008 18:00	9/17/2008 18:00	9/17/2008 20:00	
9/23/2008 7:55	9/23/2008 7:55	9/23/2008 8:10	9/23/2008 8:40	
9/20/2008 9:00	9/20/2008 9:00	9/20/2008 9:00	9/20/2008 10:00	
9/25/2008 14:20	9/25/2008 14:20	9/25/2008 14:20	9/25/2008 14:30	
9/26/2008 7:08	9/26/2008 7:08	9/26/2008 7:16	9/26/2008 7:27	
9/27/2008 12:00	9/27/2008 12:00	9/27/2008 12:50	9/27/2008 13:45	
10/3/2008 19:00	10/3/2008 19:00	10/3/2008 19:30	10/3/2008 20:30	
10/26/2008 13:45	10/26/2008 13:45	10/26/2008 14:00	10/26/2008 14:04	
10/21/2008 8:45	10/21/2008 8:50	10/21/2008 9:03	10/21/2008 9:15	
10/27/2008 19:30	10/27/2008 19:30	10/27/2008 19:45	10/27/2008 19:55	
10/26/2008 18:45	10/26/2008 19:00	10/26/2008 19:45	10/26/2008 19:45	
10/26/2008 11:30	10/26/2008 11:30	10/26/2008 11:30	10/26/2008 12:30	
11/1/2008 18:45	11/1/2008 18:45	11/1/2008 19:00	11/1/2008 22:00	
11/5/2008 9:55	11/5/2008 9:55	11/5/2008 9:59	11/5/2008 10:07	
11/12/2008 13:55	11/12/2008 13:55	11/12/2008 13:55	11/12/2008 14:55	
11/19/2008 8:30	11/19/2008 8:30	11/19/2008 8:50	11/19/2008 9:15	
11/8/2008 10:30	11/8/2008 10:30	11/8/2008 10:30	11/8/2008 11:00	
12/5/2008 15:30	12/5/2008 15:30	12/5/2008 15:30	12/5/2008 16:00	

Root intrusion

Root intrusion

Grease deposition (FOG)

Root intrusion

Root intrusion

Other (specify below)

Debris

Root intrusion

Debris

Other (specify below)

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Other (specify below)

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Other (specify below)

Paper			
also handi-wipes			
grit/gravel			
Grit/Gravel Grit/Gravel			
Paper Paper			
Unknown			
Paper Paper			
Clothing			
Grit/Gravel			
Paper			
Paper			
Unknown			
Paper			
also paper			
Unknown			
Unknown			
Unknown			
also grease Paper			

Main





Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Contained all or portion of spill; Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow; Returned all or portion of spill to sanit

Restored flow

Contained all or portion of spill

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow; Returned all or portion of spill to sanitary sewer system

Restored flow

Restored flow

Other (specify below)

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill)

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Cleaned-up (mitigated effects of spill); Restored flow

Restored flow

Restored flow

Returned all or portion of spill to sanitary sewer system

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow

Cleaned-up (mitigated effects of spill);Restored flow

Restored flow; Other (specify below)

Restored flow



3/19/2008 15:00 3/20/2008 18:00





No Yes clear

No Yes N/A NA

N/A

N/A Arroyo Corte Madera del Presidio Not applicable to this spill Other (specify below) Not applicable to this spill



None of the above None of the above

Not applicable to this spill





82216 3/20/2008 18:30

2SSO10154	Active	730573 Jill Barnes	Certified
2SSO10154	Active	730662 Jill Barnes	Certified
2SSO10154	Active	730681 Jill Barnes	Certified
2SSO10154	Active	730992 Jill Barnes	Certified
2SSO10154	Active	731037 Jill Barnes	Certified
2SSO10154	Active	731776 Jill Barnes	Certified
2SSO10154	Active	732143 Jill Barnes	Certified
2SSO10154	Active	732511 Jill Barnes	Certified
2SSO10154	Active	732636 Jill Barnes	Certified
2SSO10154	Active	732641 Jill Barnes	Certified
2SSO10154	Active	732741 Jill Barnes	Certified
2SSO10154	Active	732836 Jill Barnes	Certified
2SSO10154	Active	732850 Jill Barnes	Certified
2SSO10154	Active	732912 Jill Barnes	Certified
2SSO10154	Active	732913 Jill Barnes	Certified
2SSO10154	Active	732978 Jill Barnes	Certified
2SSO10154	Active	733264 Jill Barnes	Certified
2SSO10154	Active	733493 Jill Barnes	Certified
2SSO10154	Active	734203 Jill Barnes	Certified
2SSO10154	Active	734967 Jill Barnes	Certified
2SSO10154	Active	735531 Jill Barnes	Certified
2SSO10154	Active	735588 Jill Barnes	Certified
2SSO10154	Active	735712 Jill Barnes	Certified
2SSO10154	Active	736018 Jill Barnes	Certified
2SSO10154	Active	736019 Jill Barnes	Certified
2SSO10154	Active	736149 Jill Barnes	Certified
2SSO10154	Active	736611 Jill Barnes	Certified
288010154	Active	737228 Jill Barnes	Certified
2SSO10154	Active	737259 Jill Barnes	Certified
2SSO10154	Active	737304 Jill Barnes	Certified
2SSO10154	Active	738019 Jill Barnes	Certified
2SSO10154	Active	738886 Jill Barnes	Certified
2SSO10154	Active	739996 Jill Barnes	Certified
2SSO10154	Active	741327 Jill Barnes	Certified
2SSO10154	Active	743165 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	743586 Jill Barnes	Certified
	Active	745392 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	745393 Jill Barnes	Certified Certified
2SSO10154 2SSO10154	Active Active	745910 Jill Barnes 745911 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	745911 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	745912 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	746169 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	746179 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	746429 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	746794 Jill Barnes	Certified
2SSO10154	Active	746990 Jill Barnes	Certified
2SSO10154	Active	747030 Jill Barnes	Certified
2SSO10154 2SSO10154	Active	747031 Jill Barnes	Certified
2SSO10154	Active	747645 Jill Barnes	Certified
2SSO10154	Active	747736 Jill Barnes	Certified
2SSO10154	Active	7477944 Jill Barnes	Certified
2SSO10154	Active	748055 Jill Barnes	Certified
2SSO10154	Active	748409 Jill Barnes	Certified
2SSO10154	Active	749413 Jill Barnes	Certified
	_		

- Senior Civil Engineer
- Oction Olvir Engineer
- Senior Civil Engineer
- Senior Civil Engineeer
- Senior Civil Engineer
- o : o: :: = :
- Senior Civil Engineer
- Senior Civil Engineeer
- Senior Civil Engineer
- Acting City Engineer

Mill Valley, CA	395872
Mill Valley, CA	557970
Mill Valley	394496
Mill Valley, CA	633698
Mill Valley, CA	641667
Mill Valley, CA	466723
Mill Valley, CA	879984
Mill Valley, CA	517606
Mill Valley, CA	311952
Mill Valley, CA	708147
Mill Valley, CA	726510
Mill Valley, CA	751271
Corte Madera, CA	845282
Mill Valley, CA	516104
Mill Valley, CA Mill Valley, CA	337450 575550
Mill Valley, CA	113286
Mill Valley, CA	603665
Mill Valley, CA	699658
Mill Valley, CA	601227
Mill Valley, CA	356519
Mill Valley, CA	133890
Mill Valley, CA	750824
Mill Valley, CA	787511
Mill Valley, CA	102789
Mill Valley, CA	883519
Mill Valley, CA	349661
Mill Valley, CA	139499
Mill Valley, CA	406890
Mill Valley, CA	855426
Mill Valley, CA	119050
Mill Valley, CA	428230
Mill Valley, CA	356839
Mill Valley, CA	835012
Mill Valley, CA	857504
Mill Valley, CA	291906
Mill Valley, CA Mill Valley, CA	386619 257168
Mill Valley, CA	162001
Mill Valley, CA	701304
Mill Valley, CA	223384
Mill Valley, CA	535245
Mill Valley, CA	587283
Mill Valley, CA	909491
Mill Valley, CA	612636
Mill Valley, CA	258420
Mill Valley, CA	144036
Mill Valley	459980
Mill Valley, CA	806952
Mill Valley, CA	708272
Mill Valley, CA	464133
Mill Valley	480098
Mill Valley	286545
Mill Valley	250601
Mill Valley	248929

15-Dec-08	19-Dec-08	12/19/2008
17-Dec-08	19-Dec-08	12/19/2008
18-Dec-08	19-Dec-08	12/19/2008
22-Dec-08	20-Jan-09	1/20/2009
23-Dec-08	20-Jan-09	1/20/2009
13-Jan-09	20-Jan-09	1/20/2009
20-Jan-09	20-Jan-09	1/20/2009
26-Jan-09	7-Apr-09	4/7/2009
27-Jan-09	7-Apr-09	4/7/2009
27-Jan-09	7-Apr-09	4/7/2009
28-Jan-09	7-Apr-09	4/7/2009
30-Jan-09	7-Apr-09	4/7/2009
31-Jan-09	31-Jan-09	1/31/2009
2-Feb-09	7-Apr-09	4/7/2009
2-Feb-09	7-Apr-09	4/7/2009
3-Feb-09	7-Apr-09	4/7/2009
9-Feb-09	7-Apr-09	4/7/2009
12-Feb-09	7-Apr-09	4/7/2009
26-Feb-09	7-Apr-09	4/7/2009
16-Mar-09	7-Apr-09	4/7/2009
26-Mar-09	7-Apr-09	4/7/2009
27-Mar-09	7-Apr-09	4/7/2009
30-Mar-09	7-Apr-09	4/7/2009
7-Apr-09	7-Apr-09	4/7/2009
7-Apr-09	10-Apr-09	12/2/2010
9-Apr-09	10-Apr-09	4/10/2009
22-Apr-09	29-Apr-09	4/29/2009
8-May-09	2-Dec-10	12/2/2010
9-May-09	9-May-09	5/9/2009
11-May-09	27-May-09	5/27/2009
27-May-09	27-May-09	5/27/2009
10-Jun-09	6-Oct-09	10/6/2009
25-Jun-09	6-Oct-09	10/6/2009
16-Jul-09	6-Oct-09	10/6/2009
17-Aug-09	6-Oct-09	10/6/2009
24-Aug-09	6-Oct-09	10/6/2009
6-Oct-09	12-Oct-09	10/12/2009
6-Oct-09	12-Oct-09	10/12/2009
21-Oct-09	29-Dec-09	12/29/2009
21-Oct-09	29-Dec-09	12/29/2009
21-Oct-09	29-Dec-09	12/29/2009
27-Oct-09	29-Dec-09	12/29/2009
27-Oct-09	29-Dec-09	12/29/2009
27-Oct-09	29-Dec-09	12/29/2009
2-Nov-09	29-Dec-09	12/29/2009
16-Nov-09	29-Dec-09	12/29/2009
23-Nov-09	29-Dec-09	12/29/2009
24-Nov-09	13-Aug-10	8/13/2010
7-Dec-09	29-Dec-09	12/29/2009
18-Dec-09	29-Dec-09	12/29/2009
22-Dec-09	29-Dec-09	12/29/2009
29-Dec-09	13-Aug-10	8/13/2010
31-Dec-09	13-Aug-10	8/13/2010
19-Jan-10	13-Aug-10	8/13/2010
17-Feb-10	13-Aug-10	8/13/2010

Category 3	150	150
Category 3	5	0
Category 3	20	0
Category 3	325	0
Category 3	20	0
Category 3	150	0
Category 3	5	0
Category 3	75	0
Category 3	500	0
Category 3	375	0
Category 3	25	2
Category 3	25	0
Category 1	1000	0
Category 3	850	0
Category 3	200	0
Category 3	240	0
Category 3	70	0
Category 3	100	0
Category 3	25	0
Category 3	1	0
Category 3	375	Ō
Category 3	25	Ō
Category 3	100	0
Category 3	25	Ö
Category 1	50	40
Category 2	1500	1500
Category 3	20	0
Category 3	450	0
Category 1	1750	0
	20	0
Category 3	150	0
Category 3	375	0
Category 3	20	0
Category 3		
Category 3	200	0
Category 3	30	
Category 3	225	0
Category 3	30	0
Category 1	1000	0
Category 3	25	0
Category 3	75	0
Category 3	100	0
Category 3	50	0
Category 3	150	0
Category 3	40	0
Category 3	300	250
Category 3	5	0
Category 3	35	0
Category 3	100	0
Category 3	25	0
Category 3	5	0
Category 3	285	0
Category 3	5	0
Category 3	10	0
Category 3	360	0
Category 3	20	0

0 No	Yes
0 No	No
0 No	Yes
0 No	No
1000 Yes	No
0 No	No No
0 No 0 No	No
	No No
	No
0 No 0 No	No No
10 No	Yes
0 No	No
0 No	No
0 No	No
1750 Yes	No
0 No	No
1000 Yes	No
0 No	No No
0 No 0 No	No No
	No No
0 No 0 No	No No
0 No	No No
UNU	INO

Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach storm drainpipe

Yes

Underhill Rd @ Coach Rd

52 Longfellow Dr

395 Marion Ave

75 Mirabel Ave

122 Bolsa Ave

325 Tamalpais Ave

172 Oakdale Ave

561 Summit Ave

561 Summit Ave

280 Buena Vista Ave

5 Monte Vista Ave

Bernard Stairs

49 Cascade Drive

Molino Avenue @ Mirabel Avenue

55 Cascade Dr

401 Summit Ave

278 Summit Ave

16 Glen Drive

36 Hillcrest Road

85 Fairway Drive

59 Wildomar Street

7 Beverly Terrace

40 Molino Avenue

Beverly Terrace

172 Kipling Dr

342 W Blithedale Ave

60 Hazel Ave

10 Lockwood Lane

342 W. Blithedale

20 Elaine Ave

16 Underhill Road

10 Lower Dr

410 Lovell Ave

211 Helens Lane

16 Glen Drive

110 Tamalpais Ave

110 Shelley Drive

224 Corte Madera

5 Monte Vista Ave

370 Marion Ave

775 Redwood Hwy

65 Kipling Drive

15 Elinor Ave

2 Shelley Dr

759 E. Blithedale Ave

6 Wainwright Pl

466 Summit Avenue

30 Bayview Ave

Throckmorton Ave @ Old Mill Street

80 Cypress Ave

275 Summit Ave

W. Blithedale Ave./Marguerite Ave.

335 Molino Ave.

312 Oakdale Ave

99 Hillside Ave

37.913847	122.521167 Marin
37.901792	122.5232 Marin
37.902289	122.553069 Marin
37.900469	122.544522 Marin
37.911167	122.543561 Marin
37.913453	122.558564 Marin
37.909369	122.542178 Marin
37.916158	-122.558858 Marin
37.916411	-122.558547 Marin
37.909764	-122.538228 Marin
37.9058	-122.559014 Marin
37.907272	-122.549825 Marin
37.905306	122.55435 Marin
37.900178	-122.544786 Marin
37.905067	-122.554706 Marin
37.91225	-122.555964 Marin
37.910686	-122.553717 Marin
37.916364	-122.538911 Marin
37.908033	-122.539503 Marin
37.912003	-122.533817 Marin
37.902244	-122.548972 Marin
37.912714	-122.553617 Marin
37.905592	-122.546461 Marin
37.912714	-122.553617 Marin
37.899058	-122.522389 Marin
37.917386	-122.552589 Marin
37.902639	-122.555736 Marin
37.902031	-122.549914 Marin
37.917386	-122.552589 Marin
37.916025	-122.5549 Marin
37.912322	-122.524342 Marin
37.913661	-122.522597 Marin
37.912989	-122.559308 Marin
37.902489	-122.551669 Marin
37.916364	-122.538911 Marin
37.909558	-122.553594 Marin
37.902075	-122.524222 Marin
37.91316	-122.55142 Marin
37.905794	-122.559239 Marin
37.902192	-122.554083 Marin
37.899625	-122.516133 Marin
37.902517	-122.520317 Marin
37.908478	-122.540728 Marin
37.903233	-122.520394 Marin
37.903281	-122.524489 Marin
37.907783	-122.562439 Marin
37.913519	-122.557428 Marin
37.907492	-122.549397 Marin
37.905442	-122.552533 Marin
37.903433	-122.561603 Marin
37.910014	-122.554008 Marin
37.90604	-122.54498 Marin
37.90022	-122.54394 Marin
37.907322	-122.541769 Marin
37.907933	-122.545108 Marin

MH H20A		
french drain in backyard at 224 Corte Madera		
Sewage flowing in street 6 Rod Hole		

Manhole

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

.....

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Other (specify)

Other sewer system structure

Manhole

Manhole

Manhole

Other (specify)

Other (specify)

Manhole

Other (specify)

Other (specify)

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Manhole

Other (specify)

Other sewer system structure

Manhole

Manhole

SB1

VD4

CC6

hillside

G32

NA4E

G39

G39

L38

Out of ground

CC6

D9

Clean out

G14

L50

Clean out

Clean out

FK6

HGH6

FK5

clean out

Clean out

H20A

DB5

FL1

10A

R11

D19

FH12

L50

FG7

Clean out

french drain in backyard

DE5

DA8

plumbing inside building

VG3

Y9

V11

V7

D20B

G32

UNK101 - clean out

FD9

DE29, also rod-hole

G14

Clean Out

NB1

JA5

59

Storm drain

Unpaved surface

Storm drain

Unpaved surface

Surface water

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Separate storm drain; Street/curb and gutter

Unpaved surface

Unpaved surface

Unpaved surface

Surface water

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Unpaved surface

Storm drain; Unpaved surface

Unpaved surface

Surface water

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Street/curb and gutter

Other (specify below)

Other (specify below)

Unpaved surface

Street/curb and gutter

Yard/land

Dirt Channel Yard/Land

12/14/2008 7:30	12/14/2008 7:30	12/14/2008 8:00	12/14/2008 8:30
12/8/2008 12:00	12/8/2008 12:00	12/8/2008 12:00	12/8/2008 12:15
12/17/2008 13:00	12/17/2008 13:15	12/17/2008 14:08	12/17/2008 14:12
12/22/2008 10:50	12/22/2008 10:52	12/22/2008 11:00	12/22/2008 11:13
12/19/2008 15:20	12/19/2008 15:25	12/19/2008 15:45	12/19/2008 16:15
1/9/2009 8:50	1/9/2009 8:50	1/9/2009 9:00	1/9/2009 9:30
1/16/2009 15:00	1/16/2009 15:30	1/16/2009 15:30	1/16/2009 16:30
1/22/2009 10:20	1/22/2009 10:20	1/22/2009 10:30	1/22/2009 10:45
1/26/2009 14:30	1/26/2009 14:30	1/26/2009 14:45	1/26/2009 15:05
1/27/2009 8:00	1/27/2009 8:00	1/27/2009 8:15	1/27/2009 8:30
1/22/2009 20:40	1/22/2009 20:40	1/22/2009 21:00	1/22/2009 21:15
1/30/2009 8:30	1/30/2009 8:30	1/30/2009 8:40	1/30/2009 8:45
1/31/2009 15:00	1/31/2009 15:00	1/31/2009 16:00	1/31/2009 17:05
1/31/2009 15:40	1/31/2009 15:40	1/31/2009 16:30	1/31/2009 18:30
2/1/2009 11:00	2/1/2009 11:00	2/1/2009 11:10	2/1/2009 11:45
2/1/2009 15:44	2/1/2009 15:44	2/1/2009 15:44	2/1/2009 17:44
2/9/2009 8:55	2/9/2009 8:57	2/9/2009 9:06	2/9/2009 9:20
2/12/2009 10:00	2/12/2009 10:30	2/12/2009 11:10	2/12/2009 11:30
2/25/2009 7:30	2/25/2009 7:30	2/25/2009 8:00	2/25/2009 11:30
	3/13/2009 13:15	3/13/2009 13:30	3/13/2009 14:30
3/13/2009 13:15			
3/26/2009 9:48	3/26/2009 9:48	3/26/2009 10:15	3/26/2009 10:30
3/26/2009 13:35	3/26/2009 13:35	3/26/2009 13:50	3/26/2009 13:55
3/28/2009 15:00	3/28/2009 15:00	3/28/2009 15:26	3/28/2009 15:45
3/30/2009 13:15	3/30/2009 13:15	3/30/2009 13:30	3/30/2009 13:35
4/2/2009 22:45	4/2/2009 22:45	4/2/2009 23:00	4/2/2009 23:25
4/4/2009 9:35	4/4/2009 9:38	4/4/2009 10:05	4/4/2009 11:04
4/22/2009 8:05	4/22/2009 8:05	4/22/2009 8:31	4/22/2009 8:35
5/7/2009 9:45	5/7/2009 9:50	5/7/2009 10:00	5/7/2009 10:45
5/9/2009 9:00	5/9/2009 9:00	5/9/2009 9:30	5/9/2009 10:05
5/10/2009 11:30	5/10/2009 11:30	5/10/2009 11:45	5/10/2009 12:00
5/19/2009 11:00	5/19/2009 11:00	5/19/2009 11:00	5/19/2009 11:30
6/10/2009 8:30	6/10/2009 8:30	6/10/2009 9:00	6/10/2009 9:15
6/25/2009 11:50	6/25/2009 11:50	6/25/2009 12:10	6/25/2009 12:14
7/15/2009 14:45	7/15/2009 14:50	7/15/2009 15:15	7/15/2009 15:35
8/17/2009 8:05	8/17/2009 8:05	8/17/2009 8:30	8/17/2009 8:36
8/22/2009 10:15	8/22/2009 10:15	8/22/2009 10:40	8/22/2009 11:00
10/5/2009 9:40	10/5/2009 9:40	10/5/2009 10:00	10/5/2009 10:30
9/17/2009 8:00	9/21/2009 8:30	9/21/2009 9:00	9/25/2009 15:00
10/19/2009 9:50	10/19/2009 9:50	10/19/2009 10:15	10/19/2009 10:20
10/19/2009 14:45	10/19/2009 14:46	10/19/2009 14:58	10/19/2009 15:13
10/19/2009 18:10	10/19/2009 18:10	10/19/2009 18:15	10/19/2009 18:35
10/25/2009 18:30	10/25/2009 18:30	10/25/2009 18:30	10/25/2009 19:45
10/26/2009 10:40	10/26/2009 10:41	10/26/2009 10:55	10/26/2009 11:10
10/26/2009 15:57	10/26/2009 16:05	10/26/2009 16:45	10/26/2009 16:45
11/2/2009 8:15	11/2/2009 8:16	11/2/2009 8:30	11/2/2009 8:40
11/12/2009 10:30	11/12/2009 10:30	11/12/2009 11:45	11/12/2009 12:25
11/23/2009 9:55	11/23/2009 9:55	11/23/2009 10:24	11/23/2009 10:31
11/24/2009 8:27	11/24/2009 8:27	11/24/2009 8:57	11/24/2009 9:07
12/3/2009 12:10	12/3/2009 12:10	12/3/2009 12:40	12/3/2009 12:45
12/13/2009 13:50	12/13/2009 13:50	12/13/2009 14:18	12/13/2009 14:25
12/21/2009 12:55	12/21/2009 12:55	12/21/2009 13:43	12/21/2009 14:02
12/26/2009 10:26	12/26/2009 10:00	12/26/2009 11:30	12/26/2009 11:45
12/30/2009 4:15	12/30/2009 4:15	12/30/2009 4:15	12/30/2009 5:15
1/17/2010 18:15	1/17/2010 18:15	1/17/2010 18:15	1/18/2010 12:30
2/10/2010 10:13	2/10/2010 10:15	2/10/2010 11:00	2/10/2010 11:20
	_, 10, _0 10 10.20	_, 10, _0 10 11.00	

Grease deposition (FOG)

Other (specify below)

Root intrusion

Other (specify below)

Pipe structural problem/failure

Root intrusion

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Root intrusion

Grease deposition (FOG)

Root intrusion

Grease deposition (FOG)

Root intrusion

7 () () ()

Root intrusion

Debri-General

Root intrusion

Root intrusion

Grease deposition (FOG)

Root intrusion

Root intrusion

Grease deposition (FOG)

Root intrusion

Root intrusion

Pipe structural problem/failure

Grease deposition (FOG)

Root intrusion

Grease deposition (FOG)

Other (specify below)

Root intrusion

Pipe structural problem/failure

Other (specify below)

also paper Unknown
Paper
Grit/Gravel
Paper products (baby wipes)
and grease
Grease
also paper
also paper
also paper
Paper, wipes also paper
also, grit/gravel
also dirt
Grit/gravel & baby wipes

Other (specify below)		
Main		
Main Main		
Main		
Other (specify below) Other (specify below)		
()/		

Separated 6 line; repaired

D19

FH12

L50

FG7

VC1

DE5

DA8

VG3

Υ9

V11

V7

D20B G32

UNK101 FD9

DE29

G14

Plastic Pipe

Cleanout

NB1

4 plastic

6 clay

4 Plastic

6 Clay



```
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill):Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Restored flow
Restored flow
Cleaned-up (mitigated effects of spill); Returned all or portion of spill to sanitary sewer system
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow; Other (specify below)
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow;Returned all or portion of spill to sanitary sewer system
Restored flow
Inspected sewer using CCTV to determine cause
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill); Restored flow; Other (specify below)
Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill);Restored flow
Restored flow
Restored flow
Restored flow
Restored flow
```



1/22/2009 21:15

1/31/2009 19:30

4/2/2009 23:25 4/4/2009 11:04

5/9/2009 10:05

9/25/2009 15:00





No

Yes

No

No

No

Yes



No

Yes

No

No

Yes


Yes

NA
Old Mill Park

N/A
N/A
NA

Miller Redwood Grove

NA		
Old Mill Creek		
N/A		
N/A		
Arroyo Corte Madera del Presidio		
Arroyo Corte Madera del Presidio		





Not applicable to this spill		
None of the above		
Not applicable to this spill Not applicable to this spill		
County Health Agency		
County Health Agency		



90940 1/31/2009 19:09

93552 5/9/2009 12:28

96554 9/26/2009 18:11



2SSO10154	Active	749780 Jill Barnes	Certified
2SSO10154	Active	751796 Jill Barnes	Certified
2SSO10154	Active	751821 Jill Barnes	Certified
2SSO10154	Active	751991 Jill Barnes	Certified
2SSO10154	Active	753460 Jill Barnes	Certified
2SSO10154	Active	754049 Jill Barnes	Certified
2SSO10154	Active	755225 Jill Barnes	Certified
2SSO10154	Active	755228 Jill Barnes	Certified
2SSO10154	Active	755535 Jill Barnes	Certified
2SSO10154	Active	756046 Jill Barnes	Certified
2SSO10154	Active	756527 Jill Barnes	Certified
2SSO10154	Active	756679 Jill Barnes	Certified
2SSO10154	Active	757204 Jill Barnes	Certified
2SSO10154	Active	757208 Jill Barnes	Certified
2SSO10154	Active	757261 Jill Barnes	Certified
2SSO10154	Active	757483 Jill Barnes	Certified
2SSO10154	Active	758207 Jill Barnes	Certified
2SSO10154	Active	758333 Jill Barnes	Certified
2SSO10154	Active	758930 Jill Barnes	Certified
2SSO10154	Active	759013 Jill Barnes	Certified
2SSO10154	Active	759448 Jill Barnes	Certified
2SSO10154	Active	759636 Jill Barnes	Certified
2SSO10154	Active	761320 Jill Barnes	Certified
2SSO10154	Active	761321 Jill Barnes	Certified
2SSO10154	Active	761514 Jill Barnes	Certified
2SSO10154	Active	763872 Jill Barnes	Certified
2SSO10154	Active	763919 Jill Barnes	Certified
2SSO10154	Active	765202 Jill Barnes	Certified
2SSO10154	Active	765581 Jill Barnes	Certified
2SSO10154	Active	765694 Jill Barnes	Certified
2SSO10154	Active	767151 Jill Barnes	Certified
2SSO10154	Active	770950 Jill Barnes	Certified
2SSO10154	Active	771532 Jill Barnes 771533 Jill Barnes	Certified
2SSO10154 2SSO10154	Active		Certified Certified
	Active	771909 Bianca Gomez	
2SSO10154 2SSO10154	Active Active	771928 Bianca Gomez 773342 Bianca Gomez	Certified Certified
2SSO10154 2SSO10154	Active	776582 Bianca Gomez	Certified
2SSO10154 2SSO10154	Active	776588 Bianca Gomez	Certified
2SSO10154 2SSO10154	Active	778117 Bianca Gomez	Certified
2SSO10154	Active	778430 Bianca Gomez	Certified
2SSO10154	Active	778434 Bianca Gomez	Certified
2SSO10154	Active	778730 Bianca Gomez	Certified
2SSO10154	Active	778732 Bianca Gomez	Certified
2SSO10154	Active	779070 Bianca Gomez	Certified
2SSO10154	Active	779808 Bianca Gomez	Certified
2SSO10154	Active	780034 Bianca Gomez	Certified
2SSO10154	Active	780156 Bianca Gomez	Certified
2SSO10154	Active	781974 Bianca Gomez	Certified
2SSO10154	Active	784325 Bianca Gomez	Certified
2SSO10154	Active	784961 Bianca Gomez	Certified
2SSO10154	Active	785349 Bianca Gomez	Certified
2SSO10154	Active	785351 Bianca Gomez	Certified
2SSO10154	Active	785430 Bianca Gomez	Certified
2SSO10154	Active	786150 Bianca Gomez	Certified
	-	-	

- Acting City Engineer
- Acting City Engineer Acting City Engineer
- Senior Civil Engineeer
- Director of Public Works Director of Public Works
- Associate Engineer
- Associate Engineer Associate Engineer

Mill Valley	656511
Mill Valley	426626
·	
Mill Valley	595944
Mill Valley	239220
Mill Valley	781622
Mill Valley	594947
Mill Valley	303956
Mill Valley	715113
Mill Valley	300543
·	
Mill Valley	214044
Mill Valley	891942
Mill Valley	770852
Mill Valley	693803
Mill Valley	459811
Mill Valley	432152
Mill Valley, CA	576184
Mill Valley, CA	523977
Mill Valley, CA	832227
Mill Valley, CA	353509
Mill Valley, CA	436552
Mill Valley, CA	227753
Mill Valley, CA	165658
Mill Valley, CA	249859
Mill Valley, CA	690500
•	
Mill Valley, CA	950204
Mill Valley, CA	475331
Mill Valley, CA	244540
Mill Valley, CA	817644
Mill Valley, CA	555351
Mill Valley, CA	605105
Mill Valley, CA	113056
Mill Valley, CA	403958
	719813
Mill Valley, CA	
Mill Valley, CA	670539
City of Mill Valley	982586
City of Mill Valley	486478
City of Mill Valley	563808
City of Mill Valley	801904
City of Mill Valley	666156
City of Mill Valley	402995
City of Mill Valley	837251
City of Mill Valley	956383
City of Mill Valley	962103
City of Mill Valley	244653
City of Mill Valley	475699
City of Mill Valley	387029
City of Mill Valley	615543
City of Mill Valley	206097
City of Mill Valley	990438
City of Mill Valley	173001
City of Mill Valley	634047
City of Mill Valley	908276
City of Mill Valley	567865
City of Mill Valley	169699
City of Mill Valley	288944
•	

24-Feb-10		13-Aug-10	8/13/2010
20-Apr-10		13-Aug-10	8/13/2010
21-Apr-10		13-Aug-10	8/13/2010
27-Apr-10		13-Aug-10	8/13/2010
16-Jun-10	6/16/2010	13-Aug-10	8/13/2010
28-Jun-10	6/28/2010	13-Aug-10	8/13/2010
19-Jul-10	7/19/2010	13-Aug-10	8/13/2010
19-Jul-10	7/19/2010	13-Aug-10	8/13/2010
28-Jul-10	7/28/2010	13-Aug-10	8/13/2010
16-Aug-10	8/16/2010	6-Oct-10	10/6/2010
1-Sep-10	9/1/2010	6-Oct-10	10/6/2010
9-Sep-10	9/9/2010	6-Oct-10	10/6/2010
28-Sep-10	9/28/2010	6-Oct-10	10/6/2010
28-Sep-10	9/28/2010	6-Oct-10	10/6/2010
30-Sep-10	9/30/2010	6-Oct-10	10/6/2010
11-Oct-10	10/11/2010	2-Dec-10	12/2/2010
28-Oct-10	10/28/2010	2-Dec-10	12/2/2010
2-Nov-10	11/2/2010	2-Dec-10	12/2/2010
29-Nov-10	11/29/2010	2-Dec-10	12/2/2010
1-Dec-10	12/1/2010	2-Dec-10	12/2/2010
16-Dec-10	12/16/2010	27-Sep-11	9/27/2011
20-Dec-10	12/20/2010	27-Sep-11	9/27/2011
14-Jan-11	1/14/2011	27-Sep-11	9/27/2011
14-Jan-11	1/14/2011	27-Sep-11	9/27/2011
20-Jan-11	1/20/2011	27-Sep-11	9/27/2011
28-Feb-11	2/28/2011	27-Sep-11	9/27/2011
1-Mar-11	3/1/2011	27-Sep-11	9/27/2011
6-Apr-11	4/6/2011	27-Sep-11	9/27/2011
18-Apr-11	4/18/2011	27-Sep-11	9/27/2011
21-Apr-11	4/21/2011	27-Sep-11	9/27/2011
3-Jun-11	6/3/2011	27-Sep-11	9/27/2011
13-Sep-11	9/13/2011	27-Sep-11	9/27/2011
27-Sep-11	9/27/2011	27-Sep-11	9/27/2011
27-Sep-11	9/27/2011	27-Sep-11	9/27/2011
10-Oct-11	10/10/2011	15-Mar-12	3/15/2012
11-Oct-11	10/11/2011	19-Mar-12	3/19/2012
21-Nov-11	12/20/2011 1/30/2012	19-Mar-12 19-Mar-12	3/19/2012 3/19/2012
30-Jan-12 30-Jan-12	1/30/2012	19-Mar-12	3/19/2012
28-Feb-12	2/28/2012	19-Mar-12	3/19/2012
6-Mar-12	3/6/2012	19-Mar-12	3/19/2012
6-Mar-12	3/6/2012	19-Mar-12	3/19/2012
15-Mar-12	3/15/2012	19-Mar-12	3/19/2012
15-Mar-12	3/15/2012	19-Mar-12	3/19/2012
23-Mar-12	3/23/2012	11-Apr-12	4/11/2012
9-Apr-12	4/9/2012	11-Apr-12	4/11/2012
12-Apr-12	4/12/2012	12-Apr-12	4/12/2012
16-Apr-12	4/16/2012	1-Jun-12	6/1/2012
6-Jun-12	6/6/2012	19-Sep-12	9/19/2012
30-Jul-12	7/30/2012	19-Sep-12	9/19/2012
9-Aug-12	8/9/2012	19-Sep-12	9/19/2012
21-Aug-12	8/21/2012	19-Sep-12	9/19/2012
21-Aug-12	8/21/2012	19-Sep-12	9/19/2012
22-Aug-12	8/22/2012	19-Sep-12	9/19/2012
12-Sep-12	9/12/2012	19-Sep-12	9/19/2012
1		- · 	

Category 3	375	0
Category 3	300	0
Category 3	10	0
Category 3	10	0
Category 3	40	0
Category 3	200	0
Category 3	250	0
	700	0
Category 3		
Category 3	25	20
Category 3	300	0
Category 3	36	0
Category 3	12	0
Category 3	11	0
Category 3	25	0
Category 3	75	75
Category 3	5	0
Category 3	25	25
Category 3	100	0
Category 3	50	50
Category 3	10	0
Category 3	900	0
	600	0
Category 3	75	67
Category 3		
Category 3	225	200
Category 3	6	0
Category 3	50	0
Category 3	638	0
Category 3	25	18
Category 1	200	0
Category 3	50	0
Category 3	150	0
Category 3	15	0
Category 3	5	0
Category 3	10	0
Category 3	100	90
Category 3	25	0
Category 3	100	95
Category 3	60	60
Category 3	500	0
Category 3	150	Ō
Category 3	5	0
Category 3	515	0
	12	0
Category 3	105	0
Category 3	32	
Category 3		0
Category 3	75	75
Category 1	100	100
Category 3	20	0
Category 3	100	0
Category 3	60	0
Category 3	15	0
Category 3	25	0
Category 3	50	50
Category 3	10	0
Category 3	21	0

0 No	No
0 No	No
0 No	No
0 No	Yes
0 No	No
0 No	No
0 No	No
0 No	Yes
0 No	No
0 No	Yes
0 No	No
0 No	Yes
0 No	No
0 No	No
	No
0 No	Yes
0 No	Yes
0 No	No
200 Yes	No
200 Yes 0 No	
	No
0 No	No No
0 No 0 No	No No No
0 No 0 No 0 No 0 No	No No No No
0 No 0 No 0 No 0 No 0 No	No No No No No
0 No 0 No 0 No 0 No	No No No No No Yes
0 No 0 No 0 No 0 No 0 No 0 No 0 No	No No No No No Yes No
0 No 0 No 0 No 0 No 0 No 0 No 0 No 0 No	No No No No No Yes No Yes
0 No 0 No 0 No 0 No 0 No 0 No 0 No 0 No	No No No No No Yes No Yes Yes
0 No 0 No 0 No 0 No 0 No 0 No 0 No 0 No	No No No No No Yes No Yes Yes
0 No	No No No No No Yes No Yes Yes
0 No	No No No No No Yes No Yes No No No
0 No	No No No No No Yes No Yes Yes No No No
0 No	No No No No No Yes No Yes Yes No No No
0 No	No No No No No Yes No Yes No No No No
0 No	No No No No No Yes No Yes No No No No No
0 No	No No No No No Yes No Yes No No No No No No
0 No	No No No No No Yes No No No No No No No No Yes
0 No	No No No No No Yes No No No No No No No No No No No
0 No	No No No No No Yes No No No No No No No No No No No No No
0 No	No No No No No Yes No No No No No No No No No No No
0 No	No No No No No Yes No No No No No No No No No No No No No
0 No	No No No No No Yes No No No No No No No No No No No No No
0 No	No No No No No Yes No No No No No No No No No No No No No
0 No	No No No No No Yes Yes No No No No No No No No No No No No No
0 No	No No No No No Yes Yes No No No No No No No No No No No No No

```
Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe No
```

Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Not Applicable - Spill did not reach storm drainpipe Yes

Not Applicable - Spill did not reach a separate storm drainpipe Yes

Not Applicable - Spill did not reach a separate storm drainpipe Yes

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe No

No

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe

Not Applicable - Spill did not reach a separate storm drainpipe No

Yes

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes

No

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Yes

Not Applicable - Spill did not reach a separate storm drainpipe Not Applicable - Spill did not reach a separate storm drainpipe Lockwood Lane

162 Hillside Ave

610 Summit Ave

Throckmorton Lane

280 Buena Vista Ave

5 Monte Vista Ave

262 Summit Ave

Bernard Street @ Lovell Avenue

240 Cascade Drive

30 Bayview Avenue

142 Lovell Avenue

190 Marion Avenue

45 W Blithedale Ave

45 W Blithedale Ave

50 Summit Ave

390 Marion Ave

Marion Avenue

31 Millside Lane

114 Ryan Ave., Mill Valley, CA 94941

45 Thalia Street

50 Underhill Road

5 Monte Vista Ave

132 Marion Ave

10 Laurel Street

145 Cascade Drive

67 Molino Ave

62 Molino Ave

286 Marion Ave

352 W. Blithedale Avenue

385 E. Blithedale Ave

14 Lower Drive

197 Corte Madera Avenue

5 Monte Vista Avenue

155 Buena Vista Avenue

1 Beverly Terrace

195 Ethel Avenue

35 Bernard Avenue

49 Roque Moraes Ct

Molino Avenue @ Florence Avenue

12 Oak Lane

100 Summit Avenue

40 Bayview Avenue

309 Magee Ave

18 Tamalpais Ave

12 Oak Lane Steps

360 Marion Avenue

Bernard Avenue @ Lovell Avenue

405 Summit Avenue

60 Monte Vista Avenue

220 Marion Avenue

190 Marion Ave

215 Tamalpais Avenue

45 Thalia Street

1 Sunrise Avenue

309 Magee Avenue

37.901928	-122.550317 Marin
37.908364	-122.543356 Marin
37.917086	-122.559789 Marin
37.910556	-122.559208 Marin
37.909542	-122.538147 Marin
37.905786	-122.559239 Marin
37.910744	-122.553253 Marin
37.906194	-122.551956 Marin
37.908756	-122.559878 Marin
37.907486	-122.549397 Marin
37.906972	-122.553536 Marin
37.904908	-122.557089 Marin
37.907928	-122.54755 Marin
37.907928	-122.54755 Marin
37.906625	-122.551156 Marin
37.901786	-122.553561 Marin
37.902506	-122.553481 Marin
37.904228	-122.554617 Marin
37.90014	-122.52936 Marin
37.905025	-122.5392 Marin
37.912697	-122.521886 Marin
37.905797	-122.559269 Marin
37.905658	-122.558556 Marin
37.906561	-122.555658 Marin
37.906572	-122.557272 Marin
37.904028	-122.551281 Marin
37.903664	-122.551975 Marin
37.903775	-122.555661 Marin
37.917656	-122.553097 Marin
37.903433	-122.536178 Marin
37.9136	-122.522639 Marin
37.91215	-122.551961 Marin
37.905797	-122.559256 Marin
37.906511	-122.540053 Marin
37.913142	-122.554008 Marin
37.903014	-122.546136 Marin
37.907272	-122.549422 Marin
37.900119	-122.525311 Marin
37.902353	-122.549778 Marin
37.908464	-122.553014 Marin
37.907822	-122.549917 Marin
37.907306	-122.549689 Marin
37.911567	-122.552572 Marin
37.907983	-122.550569 Marin
37.908447	-122.553014 Marin
37.902653	-122.553947 Marin
37.906889	-122.549225 Marin
37.912058	-122.556214 Marin
37.906336	-122.561128 Marin
37.904494	-122.556742 Marin
37.904906	-122.557094 Marin
37.910556	-122.557153 Marin
37.905028	-122.539211 Marin
37.897917	-122.540469 Marin
37.911572	-122.552561 Marin

Golf Course - 4th hole

on Bayview Stairs between 309-315 Magee Ave

midway on stairs

Manhole

Other sewer system structure

Other sewer system structure

Other sewer system structure

Manhole

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Manhole

Manhole

Other sewer system structure

Other sewer system structure

Manhole

Manhole

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Other sewer system structure

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Other sewer system structure

Manhole

Other sewer system structure

Other (specify)

Manhole

Manhole

Other (specify)

Manhole

Other sewer system structure

Manhole

Other sewer system structure

Other (specify)

Manhole

Manhole

Other (specify)

Manhole

Manhole

Manhole

Manhole

Manhole

Manhole

Other (specify)

FL3 NA4B G42 Pipe DJ6 LG6 DE7 G14 ZZ1 Clean-out; DIA **UNK101** F9A DD5 Pipe Pipe FD5 **DA10** DA9 DA2A Rod hole LF11A SB1 DE5 DE4A 4 clean out DD1J FH1 FH3 DB2B Joint P10B S9 HE1 DE5 Pipe between BAT145 & LF14B HGH5 FO6B - Broken pipe sewer clean out V1 FK5 Pipe G-3, G-2 Clean out HE5 Clean out Pipe between manholes FG3 & FG4 DA8 ZZ1 Overflow at clean out DE12 007A DD4 FG12

LF11A CA18

HE7 - Clean out

ED_006495_00001080-02974

Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Street/curb and gutter

Storm drain

Street/curb and gutter

Street/curb and gutter

Street/curb and gutter

Storm drain

Unpaved surface

Separate storm drain

Unpaved surface

Separate storm drain

Unpaved surface

Street/curb and gutter; Other (specify below)

Unpaved surface

Separate storm drain; Street/curb and gutter; Unpaved surface

Separate storm drain; Street/curb and gutter; Unpaved surface

Unpaved surface

Unpaved surface

Street/curb and gutter; Unpaved surface

Combined storm drain (combined CS only);Unpaved surface

Surface water; Unpaved surface

Street/curb and gutter

Other (specify below)

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Other (specify below)

Unpaved surface

Separate storm drain; Street/curb and gutter

Other (specify below)

Street/curb and gutter

Unpaved surface

Unpaved surface

Street/curb and gutter; Unpaved surface

Unpaved surface

Street/curb and gutter

Unpaved surface

Separate storm drain

Surface water

Unpaved surface

Unpaved surface

Street/curb and gutter

Street/curb and gutter

Unpaved surface

Separate storm drain

Unpaved surface

Unpaved surface



2/24/2010 9:00	2/24/2010 9:05	2/24/2010 9:20	2/24/2010 9:35
4/19/2010 10:40	4/19/2010 10:45	4/19/2010 11:00	4/19/2010 11:20
4/20/2010 13:40	4/20/2010 13:45	4/20/2010 14:15	4/20/2010 14:23
4/26/2010 10:45	4/26/2010 11:10	4/26/2010 12:30	4/26/2010 17:00
6/16/2010 12:00	6/16/2010 12:05	6/16/2010 13:10	6/16/2010 13:30
6/23/2010 8:20	6/23/2010 8:20	6/23/2010 8:35	6/23/2010 9:45
7/19/2010 9:45	7/19/2010 9:50	7/19/2010 10:06	7/19/2010 10:16
7/19/2010 10:23	7/19/2010 10:23	7/19/2010 10:30	7/19/2010 10:50
7/27/2010 11:20	7/27/2010 11:20	7/27/2010 11:40	7/27/2010 11:45
8/14/2010 10:40	8/14/2010 11:35	8/14/2010 11:35	8/14/2010 13:20
9/1/2010 8:09	9/1/2010 8:09	9/1/2010 8:25	9/1/2010 8:37
9/8/2010 10:10	9/8/2010 10:10	9/8/2010 10:22	9/8/2010 10:28
9/23/2010 15:00	9/23/2010 15:00	9/23/2010 15:05	9/23/2010 15:11
9/25/2010 13:00	9/25/2010 13:00	9/25/2010 13:00	
			9/25/2010 0:00
9/27/2010 9:45	9/27/2010 9:45	9/27/2010 9:55	9/27/2010 10:00
10/1/2010 11:20	10/1/2010 11:22	10/1/2010 11:40	10/1/2010 11:45
10/27/2010 13:20	10/27/2010 13:30	10/27/2010 14:00	10/27/2010 14:05
11/1/2010 11:30	11/1/2010 11:30	11/1/2010 11:45	11/1/2010 11:55
11/28/2010 3:45	11/28/2010 3:45	11/28/2010 5:38	11/28/2010 5:38
11/30/2010 8:50	11/30/2010 8:50	11/30/2010 9:00	11/30/2010 9:10
12/13/2010 7:45	12/13/2010 7:45	12/13/2010 8:30	12/13/2010 9:15
12/19/2010 7:30	12/19/2010 7:30	12/19/2010 8:30	12/19/2010 9:15
1/8/2011 12:20	1/8/2011 12:20	1/8/2011 12:40	1/8/2011 12:55
1/12/2011 11:45	1/12/2011 11:45	1/12/2011 11:45	1/12/2011 12:30
1/19/2011 10:48	1/19/2011 10:48	1/19/2011 10:50	1/29/2011 10:50
2/23/2011 8:45	2/23/2011 8:45	2/23/2011 8:45	2/23/2011 8:55
2/21/2011 8:10	2/21/2011 8:15	2/21/2011 8:30	2/21/2011 9:55
4/5/2011 9:10	4/5/2011 9:10	4/5/2011 9:20	4/5/2011 9:25
4/8/2011 15:30	4/8/2011 16:30	4/8/2011 17:00	4/8/2011 17:30
4/19/2011 8:15	4/19/2011 8:15	4/19/2011 8:30	4/19/2011 8:40
5/29/2011 12:55	5/29/2011 12:55	5/29/2011 13:30	5/29/2011 14:00
9/12/2011 8:15	9/12/2011 8:16	9/12/2011 8:34	9/12/2011 8:39
9/18/2011 17:00	9/18/2011 17:00	9/28/2011 17:56	9/28/2011 17:56
9/26/2011 8:50	9/26/2011 8:51	9/26/2011 9:10	9/26/2011 9:30
10/1/2011 11:45	10/1/2011 11:45	10/1/2011 12:00	10/1/2011 13:00
9/29/2011 9:30	9/29/2011 9:35	9/29/2011 9:40	9/29/2011 21:00
11/11/2011 8:15	11/11/2011 8:15	11/11/2011 8:15	11/11/2011 8:45
1/21/2012 9:25	1/21/2012 9:25	1/21/2012 9:50	1/21/2012 11:50
1/23/2012 7:30	1/23/2012 7:30	1/23/2012 8:00	1/23/2012 8:20
2/28/2012 9:45	2/28/2012 9:45	2/28/2012 10:40	2/28/2012 11:10
3/4/2012 11:00	3/4/2012 11:00	3/4/2012 11:30	3/4/2012 11:30
3/5/2012 16:45	3/5/2012 16:45	3/5/2012 17:00	3/5/2012 17:15
3/15/2012 13:30	3/15/2012 13:30	3/15/2012 13:46	3/15/2012 13:52
3/15/2012 9:10	3/15/2012 9:10	3/15/2012 9:50	3/15/2012 10:05
3/19/2012 8:20	3/19/2012 8:20	3/19/2012 8:57	3/19/2012 9:05
3/23/2012 19:15	3/23/2012 19:15	3/23/2012 19:15	3/23/2012 20:15
4/12/2012 13:30	4/12/2012 13:30	4/12/2012 13:45	4/12/2012 13:55
4/12/2012 13:30	4/12/2012 13:30	4/12/2012 13:43	4/12/2012 13:33
5/30/2012 12:00	5/30/2012 20:15	5/30/2012 21:00	5/31/2012 12:40
7/28/2012 12:00	7/28/2012 12:00	7/28/2012 12:00	7/28/2012 1:00
8/3/2012 8:38	8/3/2012 8:38	8/3/2012 8:45	8/3/2012 9:05
8/20/2012 10:05	8/20/2012 10:05	8/20/2012 10:20	8/20/2012 10:25
8/16/2012 10:30	8/16/2012 10:30	8/16/2012 10:35	8/16/2012 10:40
8/22/2012 9:28	8/22/2012 9:50	8/22/2012 10:00	8/22/2012 10:05
9/10/2012 6:30	9/10/2012 6:35	9/10/2012 7:05	9/10/2012 7:12

Root intrusion

Root intrusion

Other (specify below)

Pipe structural problem/failure

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Root intrusion

Debri-General

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Other (specify below)

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Other (specify below)

Other (specify below)

Other (specify below)

Grease deposition (FOG)

Root intrusion

Root intrusion

Root intrusion

Root intrusion

Pipe structural problem/failure

Root intrusion

Other (specify below)

Other (specify below)

Root intrusion

Root intrusion

Root intrusion

Grease deposition (FOG)

Other (specify below)

Other (specify below)

Root intrusion

Other (specify below)

Other (specify below)

Grease deposition (FOG)

also paper
Grit/gravel
also paper also paper Paper Paper Paper
paper, grease Paper Paper grit/gravel
Paper grease and roots Paper, baby wipes
Paper Momentary water surge due to sewer cleaning upstream Dirt also paper, grit/gravel Paper; grit/gravel Clay sewer main joint separated due to slope failure Paper; Grit/Gravel
baby wipes
Baby wipes Root intrusion and Paper Paper
This stoppage was caused by roots being pushed into city main to clear private stoppage. Paper
also paper
also grit/gravel Paper Paper

Main Main Main Main Main

Main Main Main Main Main Main

Main Main Main Main

Main Main

Main Main

Main Main

Main

Main Main

Main Main

Main

Main Main

Main

Main

FL3 NA4B

G42

DJ6

LG6

DE7

G14

ZZ1

DIA

UNK101

F9A

DD5

J2 & J2AA

J2 & J2AA

FD5

DA10

DA9

DA2A

Rod hole

LF11A

SB1

DE5

DE4A

D12, DF1

DD1J FH1

FH3

DB2B

H19

P10B

S9

HE1

DE5

between BAT145 & LF14B

HGH5

FO6B

V1

FK5

between FG3, FG4

G-3, G-2

UNK101

HE5

G5

between FG3 & FG4

DA8

ZZ1

G26

DE12

007A

DD4

FG12


LF11A

CA18

HE7



```
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill):Restored flow
Cleaned-up (mitigated effects of spill); Restored flow; Other (specify below)
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill):Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill): Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill):Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Contained all or portion of spill
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill)
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Contained all or portion of spill;Restored flow;Returned all or portion of spill to sanit
Cleaned-up (mitigated effects of spill); Contained all or portion of spill; Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill):Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Inspected sewer using CCTV to determine cause;Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
Restored flow
Cleaned-up (mitigated effects of spill); Restored flow
Cleaned-up (mitigated effects of spill);Restored flow
```



9/1/2010 8:37


1/8/2011 12:55 1/12/2011 12:30


4/8/2011 17:30

10/1/2011 12:00

11/11/2011 8:45

4/12/2012 13:55





No

No

No

No

No

No

No



No

No No

Yes

No


No

No


N/A

N/A N/A N/A N/A N/A N/A N/A None N/A N/A N/A N/A N/A N/A N/A N/A Arroyo Corte Madera del Presidio Creek N/A Old Mill Creek N/A N/A N/A N/A

N/A N/A N/A N/A







112255 4/8/2011 17:30

